


CANADA FLIGHT SUPPLEMENT / GPH 205

Effective 0901Z 17 June 2021 to 0901Z 12 August 2021

AERODROME/FACILITY DIRECTORY B47


BALDWIN ON

CPB9

REF	N44 16 02 W79 20 26 0.3E 11°W UTC-5(4) Elev 750' VTA A5000	
OPR	I.P.C.F. Baldwin Airport 416-709-4861 or 416-877-5276 Reg Ltd hrs	
PF	B-1 C-2,3,4,5,6	
FLT PLN	FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
SERVICES	S 1,2,4,5	
RWY DATA	Rwy 01(013°)/19(193°) 2460x100 turf Thld 01 displ 430'	
RCR	Opr Ltd win maint. Soft when wet.	
COMM	ATF UNICOM Ltd hrs O/T tfc 122.8 5NM 3800 ASL	
PRO	Orange flag raised mid rwy when jumps in progress. Rgt hand circuits Rwy 01 (CAR 602.96).	
CAUTION	2 twrs lgtd aprx 3NM NE 900 ASL. P-line aprx 40 AGL aprx 500' fr Thld 01. Trees W & S fr Thld 01. Ditches along rwy sides. Parachuting over A/D 11,500 ASL & below, advertised by NOTAM. Many NORDO & ultra-light acft in vicinity. Rwy sfc uneven.	

BALDWIN WEST ON

CBW8

REF	N44 16 39 W79 21 42 Adj NW 11°W (2012) UTC-5(4) Elev 750' VTA A5000	
OPR	Donald Williams 905-955-4034 Reg PPR	
PF	B-1 C-2,3,4,5,6	
FLT PLN	FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
RWY DATA	Rwy 18(180°)/36(360°) 2000x75 turf RCR Opr Ltd win maint. Rwy soft in spring and when wet.	
COMM	ATF tfc 122.8 5NM 3800 ASL	
PRO	Rgt hand circuits Rwy 18 (CAR 602.96)	
CAUTION	Baldwin (CPB9) A/D 0.9NM ESE. Parachuting over CPB9 11,500 & blw advertised by NOTAM. Many NORDO & ultra-light acft in vic.	

BALSAM LAKE ON — See KIRKFIELD / BALSAM LAKE