## AIRPORT INFORMATION REPORT - 2002 ANDREW AIRPORT (CEJ2)





Andrew Airport Aerial Photographs taken July 10, 2002

#### **Airport Contact Information:**

Mr. Pat Skoreyko Municipal Administrator Village of Andrew Andrew, AB, AB T0B 0C0 Tel: (780) 365 3687

Fax: (780) 365 2061

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Andrew (EJ2)	Distance From Community (mile): 1 Latitude: 53.8667°, Longitude: -112.3500°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Mr. Pat Skoreyko Municipal Administrator Village of Andrew Box 180 Andrew, AB
Airport Organization Ownership Structure:	T0B 0C0 (780) 365 3687(780) , Fax: 365 2061
Organizational Structure:	Primary: "07-25", 2600x90 (Turf)
Role of Airport:	Secondary:
Taxiway Data Primary:	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	- Building Data
□ Landside Facility Data	ATB:
Entrance Road:	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

Lighting Data		──
Primary Edgelighting: TE (Th	nreshold and Runway End)	Water Supply:
	AP (Abbreviated PAPI - Aircraft u 10')	p Sewage:
Approach Slope Indicator 2:		Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: "J"; fre Windsock: 1 windsocks;		Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data		
Surface:	Subsu	ırface:
Peak Period Info	Spring Summer Fall	Winter Average
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		





Onsite Business Data						
FBO: No				AC Ma	aintenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintenar	nce Bu	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	dget	1997	1990	1999	2000	
Economic Activity Inforn	nation	-				
Airport Activity Info		1997	1998	1999	2000	2001
Airport Activity Info  Annual Aircraft Movements		1997	1998	1999	2000	2001
	:	1997	1998	1999	2000	2001
Annual Aircraft Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	:	1997		1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info   Airport Revenue Data  Total Annual Revenue:	: s:					
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	: s:					

Year	Project Name	Funding Source	Description	

## AIRPORT INFORMATION REPORT - 2002 APACHE/HAMBURG AIRPORT (CFM5)





Apache/Hamburg Airport Aerial Photographs taken August 20, 2002

#### **Airport Contact Information:**

Mr. Max/Curtis Mellfont/Lein Production Foreman Apache Canada Manning, AB, AB T0H 2M0 Tel: (780) 836 2822

Fax: (780) 836 2842

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

## Apache/Hamburg Airport (FM5)

Apache/Hamburg (FM5) Private - Public Use  Distance From Community (mile): 175 Latitude: 57.3500°, Longitude: -119.7667°  Owner and Operator Info Owner: Apache Canada Ltd. Operator: Apache Canada Ltd. Former Ownership: Shell Canada Date of Change: November 1, 1999  Airport Organization Ownership Structure:  Organizational Structure:  Runway Data  Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Owner and Operator Info Owner: Apache Canada Ltd. Operator: Apache Canada Ltd. Former Ownership: Shell Canada Date of Change: November 1, 1999  Airport Organization Ownership Structure:  Organizational Structure:  Role of Airport:  Contact Info  Mr. Max/Curtis Mellfont/Lein  Production Foreman Apache Canada Box 869 Manning, AB T0H 2M0 (780) 836 2822(780) , Fax: 836 2842  Runway Data  Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Owner: Apache Canada Ltd. Operator: Apache Canada Ltd. Former Ownership: Shell Canada Date of Change: November 1, 1999  Airport Organization Ownership Structure:  Organizational Structure:  Role of Airport:  Mr. Max/Curtis Mellfont/Lein Production Foreman Apache Canada Box 869 Manning, AB T0H 2M0 (780) 836 2822(780), Fax: 836 2842  Runway Data Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Operator: Apache Canada Ltd. Former Ownership: Shell Canada Date of Change: November 1, 1999  Airport Organization Ownership Structure:  Organizational Structure:  Organizational Structure:  Role of Airport:  Operator: Apache Canada Apache Canada Box 869 Manning, AB T0H 2M0 (780) 836 2822(780), Fax: 836 2842   Runway Data  Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Former Ownership: Shell Canada Date of Change: November 1, 1999  Airport Organization Ownership Structure:  Organizational Structure:  Runway Data  Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Date of Change: November 1, 1999  Airport Organization Ownership Structure:   Organizational Structure:   Runway Data  Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Manning, AB T0H 2M0 (780) 836 2822(780) , Fax: 836 2842  Organizational Structure:  Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Airport Organization Ownership Structure: Organizational Structure: Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Ownership Structure:   Organizational Structure:   Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Ownership Structure:   Organizational Structure:   Runway Data  Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Organizational Structure:   Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Organizational Structure:   Primary: "12-30", 4000x75 (Gravel) constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
constructed 1985; last rehabilitation 1995; Fair condition; replacement 2005 (\$42000)
Role of Airport: 1995; Fair condition; replacement 2005 (\$42000)
Role of Airport: (\$42000)
Role of All port.
Airport used for work and medi-vac purposes Secondary:
Taxiway Data
Primary:
Apron Data
Primary:
Secondary:
Third: Secondary:
Tillifu: Secondary
Fourth:
□ Building Data
Landside Facility Data
Entrance Road:
Disability Access:
Parking Lot:
Field Electrical Centre:
Fencing:

### Apache/Hamburg Airport (FM5)

Lighting Data	┌Water / Sewer Data ────
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: Yes

#### Drainage Data

Surface: constructed 1985; last rehabilitation 1995; Subsurface: constructed 1985; last rehabilitation poor condition;

1995; poor condition;

ı	Peak Period Info					
	_	Spring	Summer	Fall	Winter	Average
	Peak Apron Aircraft Parked:					
	Design Aircraft for Airport:					





### Apache/Hamburg Airport (FM5)

Onsite Business Data					
FBO: No			AC Maiı	ntenance:	No
Industrial Buildings: No			Crop Sp	oraying Ac	tivities:
Hangars: Yes, 1; Weibe constru private hanger/shop			Chemica	als Stored	on site:
Operation and Maintenanc	•	1000	1000	2000	2001
Total Annual Maintenance Budg	1997 jet	1998	1999	2000	2001
 ⊏Economic Activity Informa	tion				
Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Major Economic Industries in Road How is the Airport Vital to the Road Workers	rt Cargo Serv rt AME Servic rt Fire Suppre egion: Oil &	ice: 275 e: 275 ession Ser Gas	vice: 27!		ac for
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	07 1009	) 10	100	2000	2001
Total Annual Revenue:	97 1998	5 15	999	2000	2001
Airport Expenditure Data	1007 10	)OO	1000	2000	2001
Total Annual Expenditure	1997 19	998	1999	2000	2001

## Apache/Hamburg Airport (FM5)

Year	Project Name	Funding Source	Description	

## **AIRPORT INFORMATION REPORT - 2002 ATHABASCA AIRPORT (CYWM)**





Athabasca Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Ms. Isobele Barkley Secretary Athabasca Town and County Airport Commission Athabasca, AB, AB T9S 1M8 Tel: (780) 675 2273 Fax: (780) 675 5512

Prepared for:



**Aviation Strategy Action Group** 11810 Kingsway Avenue Edmonton, AB T5G 0X5

> Tel: 780-452-9955 Fax: 780-413-9918



Prepared by:

Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 18, 2003 Project No. 11451

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Athabasca Airport (YWM)

General Info

Athabasca (YWM) Distance From Community (mile): 3.1 Latitude: 54.7500°, Longitude: -113.2000°

Owner and Operator Info

Owner: Town & County of Athabasca Operator: Athabasca Airport Commission

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Athabasca/County of Athabasca No. 12

Organizational Structure:

Athabasca Airport Commission/2-Council members from Town of Athabasca/2-Council members from County of Athabasca/1-member@large Chairman of Committee Administration

Role of Airport:

To service the aviation public in the regional District of Athabasca and Points North.

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1977; Poor condition; replacement 2003 (\$149000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; fair condition;

Parking Lot: type gravel; last rehabilitation 2002;

fair condition;

Fencing: size 4'; type page wire;

Contact Info

Ms. Isobele Barkley

Secretary

Athabasca Town and County Airport

Commission 3602 - 48 Ave. Athabasca, AB T9S 1M8

(780) 675 2273(780) , Fax: 675 5512

**Runway Data** 

Primary: "16-34", 4000x100 (Asphalt)

constructed 1977; last rehabilitation 1993; Poor condition; replacement 2003

(\$794000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

poor condition; replacement 2003

(\$117000)

Secondary: ---

**Building Data** 

ATB: size 12x20; type wood frame; constructed

1979; good condition; replacement 1999

(\$15000)

Disability Access: good condition;

Field Electrical Centre: size 10x10; constructed

1987; fair condition;

## Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Athabasca Airport (YWM)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1978; last rehabilitation 199

fair condition; replacement 2005 (\$1250)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: ---

Windsock: 1 windsocks;

fair condition; replacement 2006

Water / Sewer Data

Water Supply: Well; constructed 1976; fair

condition;

Sewage: constructed 1976;

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: good condition; Subsurface: good condition;

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Athabasca Airport (YWM)

**Onsite Business Data** 

FBO: No			AC Mai	ntenance:	No	
Industrial Buildings: No			Crop S	oraying Act	civities: Tempora	ary;
Hangars: Yes, 5; Alberta Central Gingerich/Roydon Conti		ed	Chemica	als Stored o	on site:	
 <b>Operation and Maintenance</b>	Budget -					
•	1997	1998	1999	2000	2001	
Total Annual Maintenance Budget	:					
Economic Activity Information	on					
Major Economic Industries in Reg Mill)/Millar Western Industries (lu Industries How is the Airport Vital to the Reg to transport employeed to/from n	mber mill)/. gion: Very	Athabasca	a Universi	ty/Ail & Ga	s	
Airport Activity Info						
Annual Airena & Marramanhar	1997	1998	1999	2000	2001	
Annual Aircraft Movements:						
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data						
Total Annual Revenue:	1998	3 19	999	2000	2001	
Airport Expenditure Data						
19	97 19	998	1999	2000	2001	
Total Annual Expenditure						

## Athabasca Airport (YWM)

Year	Project Name	Funding Source	Description
1992		Federal	Runway Expansion and fencing
1991		Provincial	Slurry Seal Runway
1987		Provincial	Purchase and install NDB
1987		Provincial	Purchase and install DME
1987		Provincial	Supply Equipment Building
1984		Provincial	Terminal Building
1978		Provincial	Lighting
1977		Provincial	Construction
1976		Provincial	Land Purchase

## AIRPORT INFORMATION REPORT - 2002 BANFF AIRPORT (CYBA)



Banff Airport Photograph taken August 17, 2002

#### **Airport Contact Information:**

Front County Manager Banff National Park Banff, AB T1L 1K2 Tel: (403) 762 4506 Fax: (403) 762 3240

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
	ce From Community (mile): 1.7 e: 51.2000°, Longitude: -115.5333°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Front County Manager Banff National Park P.O. Box 900 Banff T1L 1K2
Airport Organization	(403) 762 4506(403) , Fax: 762 3240
Ownership Structure:	
Organizational Structure:	Runway Data Primary: "18-36", 3000x190 (Turf/Snow)
Role of Airport:	Secondary:
Taxiway Data	
Primary:	
,	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
	ATB:
Landside Facility Data	
Entrance Road:	
	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

┌Lighting Data	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
⊤Drainage Data ────	
Surface:	Subsurface:





Onsite Business Data						
FBO: No				AC Ma	aintenance:	No
Industrial Buildings: No				Crop S	Spraying Ad	ctivities:
Hangars: No				Chemi	cals Stored	on site:
Operation and Maintena	nce Bu	udget — 1997	1998	1999	2000	2001
Total Annual Maintenance Bu	dget	1997	1990	1999	2000	2001
Economic Activity Inforn	nation	-				
Airport Activity Info		1997	1998	1999	2000	2001
Airport Activity Info  Annual Aircraft Movements	:	1997	1998	1999	2000	2001
		1997	1998	1999	2000	2001
Annual Aircraft Movements		1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements		1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements		1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements		1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements		1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements Commercial Airline Info		1997		1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data  Total Annual Revenue:	s:   1997					
Annual Aircraft Movements Annual Passenger Movements Commercial Airline Info	s:   1997					

Year	Project Name	Funding Source	Description	

## AIRPORT INFORMATION REPORT - 2002 BARRHEAD AIRPORT (CCEP3)





Barrhead Airport Aerial Photographs taken October 08, 2002

#### **Airport Contact Information:**

Mr. Dale Uhrbach County Manager County of Barrhead Barrhead, AB, AB T7N 1N3 Tel: (780) 674 3331

Fax: (780) 674 2777

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Barrhead Airport (CEP3)

#### **General Info**

Barrhead (CEP3) Municipal Distance From Community (mile): 1.7 Latitude: 54.1000°, Longitude: -114.4333°

#### Owner and Operator Info

Owner: Town & County of Barrhead Operator: County of Barrhead Former Ownership: No Change

Date of Change: ---

#### **Airport Organization**

Ownership Structure:

County of Barrhead No.11/Town of Barrhead

#### Organizational Structure:

The County of Barrhead

#### Role of Airport:

Designed for light commercial & recreational aircraft operation

#### **Taxiway Data**

Primary: ---

Secondary: ---

Third: ---

Fourth: ---

#### **Landside Facility Data**

Entrance Road: size 26' wide; type oiled; constructed

1976; fair condition;

Parking Lot: size 80mx50m; type gravel;

constructed 1976; fair condition;

Fencing: size 80mx50m; type Chainlink;

#### Contact Info

Mr. Dale Uhrbach County Manager County of Barrhead 5306 49 Street Barrhead, AB

T7N 1N3

(780) 674 3331(780), Fax: 674 2777

#### **Runway Data**

Primary: "07-25", 3500x100 (Asphalt)

constructed 1976; last rehabilitation 1984; Fair condition; replacement 2003

(\$1236000)

Secondary: ---

#### **Apron Data**

Primary: ---

Secondary: ---

#### **Building Data**

ATB: size 24'x30'; type metal roof/exterior; constructed 1986; fair condition;

Disability Access: ---

Field Electrical Centre: ---

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Barrhead Airport (CEP3)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1976; poor condition; replacement 2005 (\$190000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1976; last rehabilitation 2002; fair

condition; replacement 2003

Water / Sewer Data

Water Supply: Well; constructed 1977; poor

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1976; poor condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Barrhead Airport (CEP3)

-0!4. D! D.4				
Onsite Business Data				
FBO: No	AC N	laintenance:	No	
Industrial Buildings: No		Crop	Spraying Ac	tivities:
Hangars: Yes, 6; SCO Hold Motors (1), Allan Bielert (1), Wilf S	Craig (1) Blaine	i Chem	nicals Stored	on site:
Operation and Mainten	•			
Total Annual Maintenance E	1997 Budget	1998 199	9 2000	2001
Economic Activity Info	rmation			
Road Distance to Nearest A Road Distance to Nearest A Road Distance to Nearest A Major Economic Industries Gas/Forestry/Manufacturing How is the Airport Vital to t use/municipal(RCMP)/Train	irport AME Servion irport Fire Suppr in Region: Agrio J he Region: gov	ce: 30 ession Service: culture/Oil & ernment	6 oose	
Airport Activity Info	1007	1000 1000	2000	2001
Annual Aircraft Movemen	1997 ts:	1998 1999	2000	2001
Annual Passenger Movemen	nts:			
Commercial Airline Info	)			
Airport Revenue Data	1997 199	8 1999	2000	2001
Total Annual Revenue:				
Airport Expenditure Da	ta			
	1997 1	998 1999	2000	2001
Total Annual Expenditure				

## Barrhead Airport (CEP3)

Year	Project Name	Funding Source	Description
1998		Provincial	Pavement Overlay
996	Airport Overlay	Alberta Transportation	Pavement overlay of runway and apron
986		Provincial	Terminal Building
1984		Provincial	Pavement Repairs
1983		Provincial	Lighting Repairs
980		Provincial	Runway Repairs
977		Provincial	Paving and Lighting
976		Provincial	Construction
975		Provincial	Land Purchase

## AIRPORT INFORMATION REPORT - 2002 BASHAW AIRPORT (CFK2)





Bashaw Airport Aerial Photographs taken October 09, 2002

#### **Airport Contact Information:**

Ms. Orlene Wigglesworth
Town Manager
Town of Bashaw
Bashaw, AB T0B 0H0
Tel: (780) 372 3911

Fax: (780) 372 2335

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918 Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 18, 2003 Project No. 11451

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Bashaw Airport (FK2)

**General Info** 

Bashaw (FK2) Distance From Community (mile): 1.5
Municipal Latitude: 52.5500°, Longitude: -112.9667°

Owner and Operator Info

Owner: Town of Bashaw Operator: Town of Bashaw

Former Ownership: Province of Alberta Date of Change: March 31, 1998

**Airport Organization** 

Ownership Structure:

Town of Bashaw

Organizational Structure:

Town of Bashaw/Airport Commission

Role of Airport:

To accommodate small airplanes, most of which are locally owned

**Taxiway Data** 

Primary: "A"; (Turf)

constructed 1986; Good condition;

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; fair condition;

Parking Lot: ---

Fencing: ---

Contact Info

Ms. Orlene Wigglesworth

Town Manager Town of Bashaw

Box 510 Bashaw T0B 0H0

(780) 372 3911(780), Fax: 372 2335

Runway Data

Primary: "10-28", 2950x75 (Turf)

constructed 1986; Good condition;

Secondary: ---

**Apron Data** 

Primary: "1"; (Turf)

constructed 1986; good condition;

Secondary: ---

Building Data

ATB: constructed 1986; replacement 2012

(\$100000)

Disability Access: type sidewalk;

Field Electrical Centre: ---

## Bashaw Airport (FK2)

Lighting Data	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply: Well;
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	─────────────────────────────────────
	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
<b>□Peak Period Info</b>	
	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





### Bashaw Airport (FK2)

Onsite Business Data				
FBO: No			AC Maintenan	ice: No
Industrial Buildings: No			Crop Spraying	Activities:
Hangars: Yes, 3; Don Harms, D Baron	oug Hunt, Oı	rest (	Chemicals Sto	red on site:
Operation and Maintenance	_	1000	1000 200	2001
Total Annual Maintenance Budge	1997 et	1998	1999 200	00 2001
Economic Activity Informat	ion			
Airport Activity Info	1997	1998	1999 200	0 2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	7 1000	1000	2000	2001
Total Annual Revenue:	7 1998	3 1999	9 2000	2001
Airport Expenditure Data	997 19	998 19	999 200	0 2001
Total Annual Expenditure	JJ/ 15	770 15	200	0 2001

## Bashaw Airport (FK2)

Funding Source	Description
Provincial	Site Clean up
Provincial	Terminal Building
Provincial	Complete grading and seeding
Provincial	Grading and Clean up
Provincial	Survey and Land Purchase
	Provincial Provincial

## AIRPORT INFORMATION REPORT - 2002 BASSANO AIRPORT (CEN2)





Bassano Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Mr. Jerry Neighbour Chief Administrative Officer Town of Bassano Bassano, AB T0J 0B0 Tel: (403) 641 3788

Fax: (403) 641 2585

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Bassano Airport (EN2)

General Info

Bassano (EN2) Distance From Community (mile): 0.5
Municipal Latitude: 50.8000°, Longitude: -112.4667°

**Owner and Operator Info** 

Owner: Town of Bassano Operator: Town of Bassano Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Bassano

Organizational Structure:

Committee

Role of Airport:

A small municipal airport with GA-3 hangars and crop

spraying.

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1985; last rehabilitation 1997;

Good condition; replacement 2015

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 10'; type gravel; constructed

1985; good condition; replacement

2020

Parking Lot: size 8 spaces; type gravel; constructed

1985; good condition; replacement

2020

Fencing:

Contact Info

Mr. Jerry Neighbour

Chief Administrative Officer

Town of Bassano

Box 299 Bassano TOJ 0B0

(403) 641 3788(403), Fax: 641 2585

**Runway Data** 

Primary: "07-25", 2950x75 (Asphalt)

constructed 1985; last rehabilitation 1997; Good condition; replacement 2015

Secondary: ---

**Apron Data** 

Primary: "Main"; 300x150 (Asphalt)

constructed 1985; last rehabilitation 1997; good condition; replacement 2015

Secondary: ---

**Building Data** 

ATB: size L shape-400 sq feet; type wood frame;

constructed 1986; good condition; replacement 2020 (\$100000)

Disability Access: ---

Field Electrical Centre: size 6'x8'; type wood frame;

constructed 1985; good condition; replacement 2015

(\$150000)

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Bassano Airport (EN2)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1985; good condition; replacement 2015 (\$143000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1985; good condition;

Water / Sewer Data

Water Supply: Other; constructed 1985; good

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1985; good condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Bassano Airport (EN2)

Onsite Business Data			
FBO: No		AC Maintenance:	No
Industrial Buildings: No		Crop Spraying Act	civities: Temporary; nothing in last 2 years
Hangars: Yes, 3; 1 aircraft per har owned lots - sold by tow		Chemicals Stored	on site: temporary only
Operation and Maintenance E	_		
Total Annual Maintenance Budget	1997 1998	1999 2000	2001
Economic Activity Informatio	n ————————————————————————————————————		
Airport Activity Info	1997 1998	1999 2000	2001
Annual Aircraft Movements:			
Annual Passenger Movements:			
Commercial Airline Info			
1997	1998 1	999 2000	2001
Total Annual Revenue:			
Airport Expenditure Data  199	7 1998	1999 2000	2001
Total Annual Expenditure	, 1990	2000	2001

## Bassano Airport (EN2)

Historic	Historic Capital Expenditures					
Year	Project Name	Funding Source	Description			
1997		Provincial	Fog Seal			
1996		Provincial	Crack Repair			
1986		Provincial	Miscellaneous clean up			
1986		Provincial	Terminal Building			
1985		Provincial	Base, paving and lighting			
1984		Provincial	Grading			
1981		Provincial	Land Purchase and site evaluation			

# **AIRPORT INFORMATION REPORT - 2002 BAWLF (BLACKWELLS) AIRPORT (CFR2)**





Bawlf (Blackwells) Airport Aerial Photographs taken July 12, 2002

#### **Airport Contact Information:**

Mr. Wilf BlackWell Bawlf, AB T0B 0J0 Tel: (780) 373 3953 Fax: (780) 373 2522

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info			
	e From Community (mile): 4 e: 52.9000°, Longitude: -112.5500°		
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:  Airport Organization	Contact Info  Mr. Wilf BlackWell  Box 6  Bawlf  T0B 0J0  (780) 373 3953(780) , Fax: 373 2522		
Ownership Structure:			
Organizational Structure:	Runway Data Primary: "16-34", 2700x50 (Turf)		
Role of Airport:	Secondary:		
⊤Taxiway Data			
Primary:	Apron Data		
Secondary:	Primary:		
Third:	Secondary:		
Fourth:			
	Building Data		
_l andeida Facility Data	ATB:		
Landside Facility Data			
Entrance Road:	Disability Access:		
Parking Lot:	,		
Fencing:	Field Electrical Centre:		

<b>□Lighting Data</b>	┌Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	7.5, 1.5.5.5,
ARCAL: Type: Windsock:	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
┌Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Act	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Mainten	ance B	u <b>dget</b> - 1997	1998	1999	2000	2001
Total Annual Maintenance E	Budget					
Economic Activity Info	rmation	1				
- Airport Activity Info						
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movement	ts:					
Annual Passenger Movemer	nts:					
Commercial Airline Info	)					
 ─Airport Revenue Data						
	1997	1998	:	1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Da		_		16	g	
Total Annual Expenditure	1997	19	98	1999	2000	2001
. Star / iii iaar Experiatore						

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 BEAVERLODGE AIRPORT (CEU2)





Beaverlodge Airport Aerial Photographs taken July 23, 2002

#### **Airport Contact Information:**

Mr. Ivan Hegland Town Manager Town of Beaverlodge Beaverlodge, AB T0H 0C0 Tel: (780) 354 2201

Fax: (780) 354 2207

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Beaverlodge Airport (EU2)

**General Info** 

Beaverlodge (EU2) Distance From Community (mile): 2

Latitude: 55.1833°, Longitude: -119.4500°

Owner and Operator Info

Owner: Town of Beaverlodge Operator: Town of Beaverlodge

Former Ownership: --- Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Beaverlodge

Organizational Structure:

---

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1980; Fair condition; replacement 2008 (\$74000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; good condition;

Parking Lot: type gravel; good condition;

Fencing: type barb wire;

Contact Info

Mr. Ivan Hegland Town Manager

Town of Beaverlodge Box 30

Box 30 Beaverlodge T0H 0C0

(780) 354 2201(780), Fax: 354 2207

**Runway Data** 

Primary: "07-25", 3000x75 (Asphalt)

constructed 1980; Poor condition; replacement 2005 (\$690000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1980; fair condition; replacement 2005 (\$101000)

Secondary: ---

**Building Data** 

ATB: type Atco Trailer; fair condition;

Disability Access: ---

Field Electrical Centre: type Tool Shed;

## Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Beaverlodge Airport (EU2)

Lighting Data	Water / Sewer Data
Primary Edgelighting: TE (Threshold and Runway End) fair condition; replacement 2008 (\$1620)	Water Supply: Well; good condition;
Approach Slope Indicator 1:	Sewage:

Approach Slope Indicator 2: --
Vicinity Protection,

Caveat, and Right of Way

Vicinity Protection: Yes
Caveat: No
Right of Way: No

Windsock: 1 windsocks;

poor condition; replacement 2008

Drainage Data
Surface: good condition; Subsurface: ---

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





### Beaverlodge Airport (EU2)

Consite Business Data ——					
FBO: No			AC Mai	intenance:	No
Industrial Buildings: No			Crop S	praying Act	tivities:
Hangars: No			Chemic	als Stored	on site:
Operation and Maintenance	_	1000	1000	2000	2004
Total Annual Maintenance Budget	1997	1998	1999	2000	2001
Economic Activity Information	on —				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
- Airmort Boyonus Data					
Airport Revenue Data	1998	19	99	2000	2001
Total Annual Revenue:					
Airport Expenditure Data	07 :-		1000	2225	2024
Total Annual Expenditure	97 19	98	1999	2000	2001

## Beaverlodge Airport (EU2)

Year	Project Name	Funding Source	Description
1988		Provincial	Complete airfield lighting
1987		Provincial	Final paving and initial airfield lighting installation
1986		Provincial	Grading for paved runway
1985		Provincial	Terminal Building, fencing and runway markers
1983		Provincial	Survey and soils test
1980		Provincial	Completion of gravel runway
1979		Provincial	Land Purchase, contribution of gravel runv

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 BEISEKER AIRPORT (CFV2)





Beiseker Airport Aerial Photographs taken October 24, 2002

#### **Airport Contact Information:**

Ms. Ruth Copeland-Brunelle Chief Administrative Officer Village of Beiseker Beiseker, AB T0M 0G0 Tel: (403) 947 3774

Fax: (403) 947 2146

#### Prepared for:



**Aviation Strategy Action Group** 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Beiseker Airport (FV2)

General Info

Beiseker (FV2) Distance From Community (mile): 2
Municipal Latitude: 51.4000°, Longitude: -113.4667°

Owner and Operator Info

Owner: Province of Alberta Operator: Village of Beiseker Former Ownership: ---Date of Change: ---

**Airport Organization** 

Ownership Structure:

Airport owned by the Province and operated by the Village of Beiseker. The Village will take ownership when possible.

Organizational Structure:

Airport committee once ownership is transferred to the Village.

Role of Airport:

The airport will be a base of operation for recreational pilots and aircraft

**Taxiway Data** 

Primary: "a"; 300x45 (Asphalt)

constructed 1984; last rehabilitation 1996; Fair condition; replacement 2004 (\$29000)

Secondary: "2"; 800x50 (Gravel)

constructed 1982; Fair condition;

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type GRAVEL; constructed 1982; fair

condition;

Parking Lot: size 30 vehicles; type gravel;

constructed 1982; fair condition;

Fencing: ---

Contact Info

Ms. Ruth Copeland-Brunelle Chief Administrative Officer

Village of Beiseker

Box 349 Beiseker TOM 0G0

(403) 947 3774(403), Fax: 947 2146

**Runway Data** 

Primary: "16-34", 2950x75 (Asphalt)

constructed 1984; last rehabilitation 1996; Poor condition; replacement 2004

(\$393000)

Secondary: "07-25", 850x75 (Turf)

constructed 1990; Fair condition;

replacement 2007 (\$1500)

**Apron Data** 

Primary: "1"; 250x125 (Asphalt)

constructed 1984; last rehabilitation 1996; poor condition; replacement 2004

(\$67000)

Secondary: ---

**Building Data** 

ATB: size 12x56; type mobile office; constructed 1971; last rehabilitation 1985; poor condition;

replacement 2009 (\$100000)

Disability Access: ---

Field Electrical Centre: size 6X6; type TOOL SHED;

constructed 1984; fair condition; replacement 2006

(\$150000)

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Beiseker Airport (FV2)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1982; poor condition; replacement 2006 (\$156000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1982; last rehabilitation 1998; poor

condition; replacement 2006

Water / Sewer Data

Water Supply: Well; constructed 1985; fair

condition;

Sewage: constructed 1985;

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1982; fair condition; Subsurface: ---

Peak Period Info
Spring Summer Fall Winter Average
Peak Apron Aircraft Parked: 9 11 5 1 6.5
Design Aircraft for Airport: ---





### Beiseker Airport (FV2)

. ,	
Onsite Business Data	
FBO: No	AC Maintenance: No
Industrial Buildings: No	Crop Spraying Activities: Temporary; Dyn-Agra-Beiseker
Hangars: Yes, 10;	Chemicals Stored on site: none at present
─Operation and Maintenance B	udaet
	1997 1998 1999 2000 2001
Total Annual Maintenance Budget	
Economic Activity Information	1
Drumheller Area Badlands	edEvac Service: 75 argo Service: 48 ME Service: 48 re Suppression Service: 3 n: Agrilcultural Industries/Tourist Industry in on: The Airport is hoome to a large skydiving
Airport Activity Info	1997 1998 1999 2000 2001
Annual Aircraft Movements:	
Annual Passenger Movements:	
Commercial Airline Info	
Airport Revenue Data	
Total Annual Revenue:	1998 1999 2000 2001
Total Alliadi Nevellae.	
Airport Expenditure Data	7 1009 1000 2000 2001
Total Annual Expenditure	1998 1999 2000 2001

## Beiseker Airport (FV2)

Year	Project Name	Funding Source	Description
1996		Provincial	Crack repair and fog seal asphalt surfaces
1985		Provincial	Completion of paving and lighting
1984		Provincial	Grading, paving and lighting
1984		Provincial	Terminal Building
1983		Provincial	Land Purchase and site evaluation

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 BIRCH MOUNTAIN AIRPORT (CFM2)





Birch Mountain Airport Aerial Photographs taken August 07, 2002

#### **Airport Contact Information:**

Alberta Sustainable Resource Development - Land and Forest Division Lac La Biche, AB T0A 2C0 Tel: (780) 623 5240

Fax: (780) 623 2570

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info			
	Distance From Community (mile):		
Latitud	e: 57.7000°, Longitude: -111.8333°		
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:  Airport Organization	Contact Info  Alberta Sustainable Resource Development - Land and Forest Division Box 450 Lac La Biche T0A 2C0 (780) 623 5240(780) , Fax: 623 2570		
Ownership Structure:			
Organizational Structure:	Runway Data  Primary: "08-26", 2700x75 (Turf)		
Role of Airport:	Secondary:		
⊤Taxiway Data			
Primary:	-Anron Data		
	Apron Data		
Secondary:	Primary:		
Third:	Secondary:		
Fourth:			
	Building Data		
□ andsido Eacility Data	ATB:		
Landside Facility Data			
Entrance Road:	D: 177		
	Disability Access:		
Parking Lot:			
Fencing:	Field Electrical Centre:		

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data      ──					
FBO: No			AC Mai	ntenance:	No
Industrial Buildings: No			Crop Sp	praying Act	civities:
Hangars: No			Chemica	als Stored	on site:
Operation and Maintenanc	e Budget -				
Total Annual Maintenance Budg	1997 et	1998	1999	2000	2001
Economic Activity Informa	tion				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:	1997	1990	1999	2000	2001
Annual Passenger Movements:					
Commercial Airline Info	<u>'</u>				
Airport Revenue Data	97 1998	3 19	00	2000	2001
Total Annual Revenue:	77 1996	19	JJ	<b>2000</b>	2001
Airport Expenditure Data	007 10	.00	1000	2000	2001
Total Annual Expenditure	.997 19	98 :	1999	2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 BJORGUM FARM AIRPORT (CFD9)





Bjorgum Farm Airport Aerial Photographs taken July 10, 2002

#### **Airport Contact Information:**

Mr. Keith Bjorgum Camrose, AB T4V 2N1 Tel: (780) 672 7218 Fax: (780) N/A

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

┌General Info ────		
		Community (mile): 3.5 33°, Longitude: -112.8000°
Owner and Operator Info		Contact Info
Owner: Keith Bjorgum Operator: Keith Bjorgum Former Ownership: No Change Date of Change:		Mr. Keith Bjorgum RR2 Camrose T4V 2N1 (780) 672 7218(780) , Fax: N/A
Airport Organization		
Ownership Structure:		
	⊏Run	way Data
Organizational Structure:	Prima	ary: "16-34", 2500x60 (Turf) Good condition;
Role of Airport:		
Private; recreational use	Seco	ndary:
Taxiway Data		
Primary:	Apro	on Data
Secondary:	Prima	ary:
Third:	Seco	ndary:
Fourth:		
	⊢Build	ding Data
	ATB:	
Landside Facility Data		
Entrance Road:		
	Disab	ility Access:
Parking Lot:		
Fencing:	Field	Electrical Centre:

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data					
FBO: No			AC Mair	ntenance:	No
Industrial Buildings: No			Crop Sp	oraying Act	tivities:
Hangars: No			Chemica	als Stored	on site:
Operation and Maintenance E	_	1000	1000	2000	2004
Total Annual Maintenance Budget	1997	1998	1999	2000	2001
Economic Activity Informatio	n —				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	1009	100	10	2000	2001
Total Annual Revenue:	1998	199	בי	2000	2001
Airport Expenditure Data	7 199	98 1	999	2000	2001
Total Annual Expenditure	, 1).	,,, 1		2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 BLACK DIAMOND/CU NIM AIRPORT (CEH2)**





Black Diamond/CU NIM Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. David Morgan CFI CU-NIM Gliding Club Calgary, AB T2P 2M6

Tel: (403) 938 2796 (or D. Fowlow 289 9477) Fax: (403) N/A

Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Black Diamond/CU NIM Airport (EH2)

General Info

	itance From Community (mile): 3 itude: 50.7167°, Longitude: -114.1833°
Owner and Operator Info Owner: Cu Nim Gliding Club Operator: Cu Nim Gliding Club Former Ownership: No Change Date of Change:	Contact Info  Mr. David Morgan  CFI  CU-NIM Gliding Club  P.O. Box 2275 Station M  Calgary
Airport Organization Ownership Structure:	T2P 2M6 (403) 938 2796 (or D. Fowlow 289 9477)(403) , Fax: N/A
Private Gliding Club  Organizational Structure:	Runway Data
Gliding Club	Primary: "07-25", 3014x300 (Turf) Fair condition; replacement 2020
Role of Airport:  Base of Operations for Gliding Club	Secondary: "14-32", 2230x200 (Turf) last rehabilitation 1995; Fair condition; replacement 2020
Taxiway Data Primary:	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
Landside Facility Data  Entrance Road:	ATB: size 25'x40'; type wood frame; good condition;
Littrance Road.	Disability Access:
Parking Lot: fair condition;	Field Floctrical Centres
Fencing:	Field Electrical Centre:

## Black Diamond/CU NIM Airport (EH2)

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply: Well;
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection,
	Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No

Drainage Data		
Surface:	Subsurface:	

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:	0				
Design Aircraft for Airport:	0				





### Black Diamond/CU NIM Airport (EH2)

Onsite Business Data					
FBO: No			AC Mair	ntenance:	No
Industrial Buildings: No			Crop Sp	oraying Act	ivities:
Hangars: Yes, 2;			Chemica	als Stored o	on site:
Operation and Maintenance	Budget -	1998	1999	2000	2001
Total Annual Maintenance Budge		1990	1999	2000	2001
Economic Activity Informati	on				
- Aims out A attivities links					
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
Total Armuri Bayerya	1998	199	99	2000	2001
Total Annual Revenue:					
Airport Expenditure Data				2055	200:
Total Annual Expenditure	97 19	98 1	1999	2000	2001
Total Alliadi Experiatare					

## Black Diamond/CU NIM Airport (EH2)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 BLACKIE/WILDERMAN FARM AIRPORT (CFT2)





Blackie/Wilderman Farm Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Wayne Wilderman Owner Blackie, AB TOL 0J0 Tel: (403) 684 3611 Fax: (403) 684 3329

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info					
Blackie/Wilderman Farm (FT2) Private	n Farm (FT2) Distance From Community (mile): 4 Latitude: 50.5500°, Longitude: -113.6000°				
Owner and Operator Info Owner: Wayne Wilderman Operator: Wayne Wilderman Former Ownership: No Change Date of Change:	Contact Info  Mr. Wayne Wilderman Owner P.O. Box 220 Blackie T0L 0J0				
<b>□</b> Airport Organization	(403) 684 3611(403) , Fax: 684 3329				
Ownership Structure:					
Private					
Organizational Structure:	Primary: "07-25", 2700x55 (Turf) constructed 1974; Good condition; replacement 2022				
Role of Airport:					
To sevice owners personal and business needs	Secondary:				
Taxiway Data					
Primary:	Apron Data				
	Primary:				
Secondary:	Times y				
·					
Third:	Secondary:				
Familia					
Fourth:					
	Building Data				
Landside Facility Data	ATB:				
•					
Entrance Road:					
	Disability Access:				
Parking Lot:					
Faraina	Field Electrical Centre:				
Fencing:					

Lighting Data	⊤Water / Sewer Data	
Primary Edgelighting: TE (Thr poor co	eshold and Runway End) Mater Supply: Well; for a supply with the supply with t	air condition;
Approach Slope Indicator 1: -	Sewage:	
Approach Slope Indicator 2:	Vicinity Protection Caveat, and Right	
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: N Caveat: No Right of Way: No	lo
─Drainage Data ────		
Surface:	Subsurface:	
Peak Period Info	Spring Summer Fall Winter Average	
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		





FBO: No				AC Ma	intenance:	No
TBO. NO				AC Ma	interiariee.	140
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
─Operation and Mainter	nance B	udget - 1997	1998	1999	2000	2001
Total Annual Maintenance	Budget					
Economic Activity Info	rmatio	n ———				
─Airport Activity Info		1997	1998	1999	2000	2001
Airport Activity Info  Annual Aircraft Movemer	nts:	1997	1998	1999	2000	2001
-		1997	1998	1999	2000	2001
Annual Aircraft Movemer	ents:	1997	1998	1999	2000	2001
Annual Aircraft Movemer Annual Passenger Moveme	ents:	1997	1998	1999	2000	2001
Annual Aircraft Movemer Annual Passenger Moveme	ents:	1997	1998	1999	2000	2001
Annual Aircraft Movemer Annual Passenger Moveme	ents:	1997	1998	1999	2000	2001
Annual Aircraft Movemer Annual Passenger Moveme	ents:					
Annual Aircraft Movemer Annual Passenger Moveme  Commercial Airline Inf  Airport Revenue Data	ents:	1997		1999	2000	2001
Annual Aircraft Movemer Annual Passenger Moveme  Commercial Airline Inf  Airport Revenue Data  Total Annual Revenue:	ents:					
Annual Aircraft Movemer Annual Passenger Moveme  Commercial Airline Inf  Airport Revenue Data	ents:	1998				

Year	Project Name	Funding Source	Description		

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 BONNYVILLE AIRPORT (CYBF)





Bonnyville Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Mr. Dwayne Harasem
Transportation Supervisor/Airport Manager
Town of Bonnyville
Bonnyville, AB T9N 2J7
Tel: (780) 826 3550

Fax: (780) 812-2133

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Bonnyville Airport (YBF)

**General Info** 

Bonnyville (YBF) Distance From Community (mile): 2
Municipal Latitude: 54.3000°, Longitude: -110.7500°

Owner and Operator Info

Owner: Town of Bonnyville Operator: Town of Bonnyville

Former Ownership: --- Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Bonnyville in partnership with the M.D. #87

Bonnyville

Organizational Structure:

---

Role of Airport:

Serve M.D. of Bonnyville #87 with business and commercial traffic. Also service for the town, local small business,

**Taxiway Data** 

Primary: "A"; (Asphalt)

replacement 2016 (\$19000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; fair condition;

Parking Lot: type gravel; fair condition;

Fencing: size 4inch barbed wire;

Contact Info

Mr. Dwayne Harasem

Transportation Supervisor/Airport Manager

Town of Bonnyville

Bag 1006 Bonnyville T9N 2J7

(780) 826 3550(780), Fax: 812-2133

**Runway Data** 

Primary: "07-25", 4433x75 (Asphalt)

last rehabilitation 2001; Good condition;

replacement 2016 (\$484000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

good condition; replacement 2016

(\$105000)

Secondary: ---

**Building Data** 

ATB: constructed 1984; good condition;

Disability Access:

Field Electrical Centre:

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Bonnyville Airport (YBF)

-		i۸	h	fi,	2	n,	ata	-
	ᆫ	ıu		LII	ıu	v	aιa	

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1978; poor condition; replacement 2004 (\$186000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 2 windsocks;

#### Water / Sewer Data

Water Supply: Well; constructed 1984; poor

condition;

Sewage: ---

### Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: fair condition; Subsurface: ---

#### Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

---





### Bonnyville Airport (YBF)

Onsite Business Data					
FBO: No			AC Maint	enance: 1	No
Industrial Buildings: No			Crop Spr	aying Activ	vities:
Hangars: No			Chemicals	s Stored or	n site:
Operation and Maintenanc	e Budget				
Total Annual Maintenance Budg	1997 et	1998	1999	2000	2001
Economic Activity Informa	tion				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:	1997	1990	1333	2000	2001
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	97 1998	3 199	ο 2	000	2001
Total Annual Revenue:		, 139	. Z		2001
Airport Expenditure Data	007 10	100	000	2000	2001
Total Annual Expenditure	.997 19	998 1	999	2000	2001

## Bonnyville Airport (YBF)

Year	Project Name	Funding Source	Description
2002		Provincial	pavement overlay - runway, taxiway and apron
1996		Provincial	Restore pavement markings
1995		Provincial	Completion of runway extension, taxiway widening.
1995		Provincial	Fog seal asphalt survaces (excluding extension)
1994		Provincial	Design work and purchase of additional airfield lighting
1993		Provincial	Preliminary survey and design for runway extension
1992		Provincial	Supply and install DME and NDB
1986		Provincial	Overlay
1985		Provincial	Runway extension
1984		Provincial	Terminal Building
1983		Provincial	Ramp extension and paving
1978		Provincial	
1976		Federal	
1976		Provincial	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 BOW ISLAND AIRPORT (CEF3)





Bow Island Airport Aerial Photographs taken August 13, 2002

#### **Airport Contact Information:**

Mr. Terry Schneider Town Manager Town of Bow Island Bow Island, AB T0K 0G0 Tel: (403) 545 2522

Fax: (403) 545 2522

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Bow Island Airport (EF3)

General Info

Bow Island (EF3)

Municipal

Distance From Community (mile): 1

**Runway Data** 

Secondary: ---

Latitude: 49.8833°, Longitude: -111.3333°

Contact Info

Town Manager Town of Bow Island

P.O. Box 100 Bow Island TOK 0G0

Mr. Terry Schneider

Primary: "05-23", 3000x75 (Asphalt)

(\$397000)

(403) 545 2522(403), Fax: 545 6642

constructed 1977; last rehabilitation 2002; Good condition; replacement 2012

Owner and Operator Info

Owner: Town of Bow Island

Operator: ---

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Bow Island

Organizational Structure:

Council/Municipal Airport Commission

Role of Airport:

To service emergency medical response landings, commercial

landings, and private operator's.

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1977; last rehabilitation 2001;

Poor condition; replacement 2002 (\$35000)

Secondary: ---

Third: ---

Fourth: ---

Apron Data

Primary: ---

Secondary: ---

**Landside Facility Data** 

Entrance Road: constructed 1977; fair condition;

Parking Lot: type gravel; fair condition;

Fencing: size 4'; type barbed wire; replacement 2020

**Building Data** 

ATB: size 12x40; type ATCO trailer; constructed

1985; fair condition;

Disability Access:

Field Electrical Centre: size 6'x8'; type wood frame;

constructed 1977; fair condition; replacement 2010

(\$150000)

## Bow Island Airport (EF3)

Lighting Data	⊤Water / Sewer Data	
	hreshold and Runway End) ructed 1977; good condition; cement 2010 (\$168000)  Water Supply: Other; constructed condition; replaced	
Approach Slope Indicator 1:	Sewage:	
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No	
ARCAL: Type: "K"; fr Windsock: 1 windsocks; constructed	req 123.2 Caveat: No Right of Way: No	
Drainage Data		
Surface:	Subsurface:	
Peak Period Info	Spring Summer Fall Winter Average	
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		





### Bow Island Airport (EF3)

Onsite Business Data						
FBO: No			AC Ma	intenance:	No	
Industrial Buildings: No		Crop Spraying Activities: Permanent;				
Hangars: Yes, 3;			Chemic	als Stored	on site: No	
Operation and Maintenance	Budget -					
•	1997	1998	1999	2000	2001	
Total Annual Maintenance Budget						
Economic Activity Information	on —					
Road Distance to Nearest Airport I Road Distance to Nearest Airport I Road Distance to Nearest Airport I Road Distance to Nearest Airport I How is the Airport Vital to the Reg emergencies/commercial/agricultu	Cargo Serv AME Servic Fire Suppre jion: med	ice: 0 e: 0 ession Se evac	rvice: 0	erators		
Airport Activity Info	1997	1998	1999	2000	2001	
Annual Aircraft Movements:	1997	1990	1999	2000		
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data						
Total Annual Revenue:	1998	3 1	999	2000	2001	
Airport Expenditure Data	<b>.</b>	200	1000	2002	2004	
Total Annual Expenditure	9/ 19	98	1999	2000	2001	

## Bow Island Airport (EF3)

Year	Project Name	Funding Source	Description
2001		Provincial	crack repairs
1996		Provincial	Crack repair (routing, sealing)
1993		Provincial	Fog Seal asphalt surfaces
1991		Provincial	Slurry Seal runway
1985		Provincial	Terminal Building
1977		Provincial	Construction
1976		Provincial	Land Purchase

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 BOYLE AIRPORT (CFM7)





Boyle Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Ms. Barb Kowalchuk C.A.O. Village of Boyle Boyle, AB TOA 0M0 Tel: (780) 689 3642 Fax: (780) 689 3998

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info  Boyle (FM7)	Distance From Community (mile): 1 Latitude: 54.5667°, Longitude: -112.8167°
Municipal	· · · ·
Owner and Operator Info Owner: Village of Boyle Operator: Village of Boyle Former Ownership: No Change Date of Change:	Ms. Barb Kowalchuk C.A.O. Village of Boyle Box 9 Boyle
Airport Organization Ownership Structure:	TOÁ 0M0 (780) 689 3642(780) , Fax: 689 3998
Village of Boyle	
	Runway Data
Organizational Structure:	Primary: "08-26", 3000x75 (Turf)
Role of Airport:	Secondary:
⊤Taxiway Data	
Primary:	- Anven Dete
	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
	ATB:
Landside Facility Data	
Entrance Road: type gravel; fair condition;	
	Disability Access:
Parking Lot:	
	Field Electrical Centre:
Fencing:	Ticia Electrical Centre.

Spring

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

Summer

Fall

Winter

Average

Lighting Data	─────────────────────────────────────
Primary Edgelighting: RR (Retro-reflective Markers)	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface: Su	ubsurface:
Peak Period Info	





Onsite Business Data					
FBO: No	AC Ma	AC Maintenance: No			
Industrial Buildings: No Crop Spraying Activities:					
Hangars: Yes, 2; McEwan's Fuels & Fertilizers. Chemicals Stored on site: Phil Jones					
 ─Operation and Maintenal	aca Buda	ot			
Operation and maintenal	_	97 199	8 1999	2000	2001
Total Annual Maintenance Bu	dget				
Economic Activity Inforn	nation				
Airport Activity Info					
	199	97 1998	1999	2000	2001
Annual Aircraft Movements	:				
Annual Passenger Movement	S:				
Commercial Airline Info					
Airport Revenue Data	1997	1998	1999	2000	2001
Total Annual Revenue:	L <i>JJ</i> /	1330	1777	2000	2001
Airport Expenditure Data		1000	4000	2022	2001
Total Annual Expenditure	1997	1998	1999	2000	2001
- I - I - I - I - I - I - I - I - I - I					

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## **AIRPORT INFORMATION REPORT - 2002 BRANT (DIXON FARM) AIRPORT (CEX9)**





Brant (Dixon Farm) Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

J. S. Dixon Owner Brant, AB TOL 0L0 Tel: (403) 684 3656 Fax: (403) N/A

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Brant (Dixon Farm) (EX9) Private	Distance From Community (mile): 6 Latitude: 50.4167°, Longitude: -113.5333°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	J. S. Dixon Owner Box 155 Brant TOL 0L0
Airport Organization Ownership Structure:  Private	(403) 684 3656(403) , Fax: N/A
Organizational Structure:	Primary: "16-34", 4000x250 (Turf) Good condition; replacement 2020
Role of Airport:  Private - Farm Strip	Secondary:
Taxiway Data Primary:	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	☐Building Data
<b>□</b> Landside Facility Data	ATB:
Entrance Road:	Disability Access:
Parking Lot:	Field Flactoical Contract
Fencing:	Field Electrical Centre:

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1: -	Sewage:
Approach Slope Indicator 2: -	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 1 windsocks; good conditio	on;
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





<b>□Onsite Business Data</b>	a ———					
FBO: No	a			AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
				5. 5p 5	, p. a., g ,	
Hangars: Yes, 1; Private	- 2 planes			Chemic	als Stored	on site:
Operation and Mainte	enance B	_				
Total Annual Maintenanc	o Budget	1997	1998	1999	2000	2001
Total Allitual Maintenanc	e buuget					
Economic Activity In	formation	1				
- Airport Activity Info						
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movem	ents:					
Annual Passenger Moven	nents:					
Commercial Airline I	nfo					
Airport Revenue Data		1000		000	2000	2001
Total Annual Revenue:	1997	1998	1	.999	2000	2001
Airport Expenditure I	<b>Data</b> 1997	' 199	98	1999	2000	2001
Total Annual Expenditure		100	. •			

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 BROOKS AIRPORT (CYBP)





Brooks Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Mr. Kevin Bridges Town Manager Town of Brooks Brooks, AB T1R 1B7 Tel: (403) 362 3333

Fax: (403) 362 4787

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### **Brooks Airport (YBP)**

General Info

Brooks (YBP) Distance From Community (mile): 3
Municipal Latitude: 50.6333°, Longitude: -111.9333°

Owner and Operator Info

Owner: town of Brooks Operator: M. Landry

Former Ownership: No Change

Date of Change: ---

Airport Organization

Ownership Structure:

Town - Council

Organizational Structure:

Airport Commission

Role of Airport:

To service FBO, aircraft crop spraying

**Taxiway Data** 

Primary: "A"; 150x15 (Asphalt)

constructed 1975; last rehabilitation 2000; Good condition; replacement 2010 (\$44000)

Secondary: "B"; (Asphalt)

last rehabilitation 1989; Good condition;

replacement 2010 (\$28000)

Third: "C"; (Gravel)

replacement 2020

Fourth: ---

**Landside Facility Data** 

Entrance Road: replacement 2020

Parking Lot: replacement 2020

Fencing: replacement 2020

Contact Info

Mr. Kevin Bridges Town Manager Town of Brooks

Bag 880 Brooks T1R 1B7

(403) 362 3333(403), Fax: 362 4787

**Runway Data** 

Primary: "12-30", 2800x75 (Asphalt)

constructed 1975; last rehabilitation 2000; Good condition; replacement 2010

(\$371000)

Secondary: "02-20", 2400x50 (Gravel)

last rehabilitation 1989; replacement

2020

**Apron Data** 

Primary: "Main";

constructed 1976; last rehabilitation 2000; replacement 2010 (\$81000)

Secondary: "FBO-A";

last rehabilitation 1989; replacement

2010

Building Data

ATB: constructed 1980; good condition;

replacement 2020

Disability Access: ---

Field Electrical Centre: constructed 1980; good

condition;

## Brooks Airport (YBP)

Lighting Data	⊤Water / Sewer Data
Primary Edgelighting: TE (The last re	habilitation 1988; good condition; Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Caveat, and Right of Way
ARCAL: Type: "K"; fr Windsock: 1 windsocks;	ingite of way. The
Drainage Data	
Surface: good condition;	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	<u> </u>
Design Aircraft for Airport:	





### Brooks Airport (YBP)

Onsite Business Data						
FBO: No				AC Ma	intenance:	No
Industrial Buildings: No	Industrial Buildings: No Crop Spraying Activities:					
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintena	nce Bu	dget				
T. I.A. IM.:	–	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	idget					
Economic Activity Inform	nation					
Airport Activity Info						
Annual Aircraft Movements		1997	1998	1999	2000	2001
Annual Passenger Movement	S:					
Commercial Airline Info						
Airport Revenue Data						
	1997	1998		1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Data						
Total Appual Exponditure	1997	199	98	1999	2000	2001
Total Annual Expenditure						

## Brooks Airport (YBP)

storic	Capital Expen	aitures	
Year	Project Name	Funding Source	Description
2000		Provincial	Slurry seal (town paid for markings)
1991		Provincial	Complete 1989 work.
1989		Provincial	Upgrading 2 apron areas and installation of complete storm sewer system
1988		Provincial	Supply and install new runway lighting
1987		Provincial	Purchase and installation of DME
1986		Provincial	Drainage repairs
1986		Provincial	Purchase of NDB
1985		Provincial	Runway overlay
1980		Provincial	Terminal Buiding
1976		Provincial	Paving of runway, taxiway and apron
1968		Federal	Initial development

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 CALGARY/OKOTOKS AIR PARK AIRPORT (CFX2)





Calgary/Okotoks Air Park Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Robert Harrity Chief Instructor Skywings Okotoks Okotoks, AB T1S 1A5 Tel: (403) 938 5252

Fax: (403) 938 5253

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877





### Calgary/Okotoks Air Park Airport (FX2)

General Info	
	ce From Community (mile): 15
	e: 50.7333°, Longitude: -113.9333°
	-044
Owner and Operator Info	Contact Info
Owner: Benicon Developing	Mr. Robert Harrity
Operator: Sky Wings	Chief Instructor
Former Ownership: Family	Skywings Okotoks Box 293
Date of Change: June 1, 1998	Okotoks
Airport Organization	T1S 1A5
	(403) 938 5252(403) , Fax: 938 5253
Ownership Structure:	
	Runway Data
Organizational Structure:	Primary: "16-34", 3025x50 (Asphalt)
	constructed 1978; last rehabilitation
	1989; Good condition; replacement 2013
Role of Airport:	(\$300000)
To service the aviation needs of the community. Also	Secondary:
provides a flight school.	Secondary.
Ti Deta	
Taxiway Data	
Primary: "A"; (Asphalt)	Apron Data
Poor condition; replacement 2003 (\$33000)	
	Primary:
Secondary:	
Third:	Secondary:
Fourth:	
	Building Data
	ATB: fair condition;
Landside Facility Data	ATD. Tall Collulion,
Entrance Road: poor condition;	
	Disability Access:
Parking Lot: size 1200; type Asphalt; fair condition;	
	Field Electrical Centre:
Fencing:	
	<sub>1</sub>

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Calgary/Okotoks Air Park Airport (FX2)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1999; fair condition; replacement 2025 (\$92000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: ---

Windsock: 1 windsocks;

last rehabilitation 200; good condition;

Water / Sewer Data

Water Supply: Well; poor condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: last rehabilitation 1999; fair condition; Subsurface: ---

Peak Period InfoSpringSummerFallWinterAveragePeak Apron Aircraft Parked:5555Design Aircraft for Airport:---



**Onsite Business Data** 

## Alberta Regional/Local Airport Inventory Study Airport Summary Report



### Calgary/Okotoks Air Park Airport (FX2)

FBO: Yes, 1; Sky Wings Aviation				AC Maintenance: No				
Industrial Buildings: No				Crop Spraying Activities:				
Hangars: Yes, 1; Benicon Developing				Chemicals Stored on site:				
─Operation and Maintenance	1997	1998	1999	2000	2001			
Total Annual Maintenance Budge		1330	1333	2000				
Economic Activity Informati	on							
Road Distance to Nearest Airport Sched. Pax Service: 35 Road Distance to Nearest Airport Cargo Service: 35 Road Distance to Nearest Airport AME Service: 35 Road Distance to Nearest Airport Fire Suppression Service: 0 How is the Airport Vital to the Region: Convenience for students/business passengers living in south end of Calgary and outlying areas								
Airport Activity Info	1997	1998	1999	2000	2001			
Airport Activity Info  Annual Aircraft Movements:	1997	1998	1999	2000	2001			
_	1997	1998	1999	2000	2001			
Annual Aircraft Movements:	1997	1998	1999	2000	2001			
Annual Aircraft Movements: Annual Passenger Movements:	1997	1998	1999	2000	2001			
Annual Aircraft Movements: Annual Passenger Movements:	1997	1998	1999	2000	2001			
Annual Aircraft Movements: Annual Passenger Movements:	1997	1998	1999	2000	2001			
Annual Aircraft Movements: Annual Passenger Movements:  Commercial Airline Info	1997	1998	1999	2000	2001			
Annual Aircraft Movements:  Annual Passenger Movements:  Commercial Airline Info  Airport Revenue Data								
Annual Aircraft Movements:  Annual Passenger Movements:  Commercial Airline Info			1999	2000	2001			
Annual Aircraft Movements:  Annual Passenger Movements:  Commercial Airline Info  Airport Revenue Data  1997								
Annual Aircraft Movements:  Annual Passenger Movements:  Commercial Airline Info  Airport Revenue Data  1997  Total Annual Revenue:  Airport Expenditure Data	7 1998							

### Calgary/Okotoks Air Park Airport (FX2)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 CALGARY/SPRINGBANK AIRPORT (CYBW)





Calgary/Springbank Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Mr. Larry Stock Airport Manager Calgary Airport Authority Calgary, AB T32 3S4 Tel: (403) 286 1494

Fax: (403) 288-4488

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Calgary/Springbank Airport (YBW)

#### General Info

Calgary/Springbank (YBW)

Distance From Community (mile): 8 Latitude: 51.1000°, Longitude: -114.3667°

#### Owner and Operator Info

Owner: Transport Canada

Operator: Calgary Airport Authority Former Ownership: No Change

Date of Change: ---

#### Airport Organization

Ownership Structure:

Crown land leased to local authority.

#### Organizational Structure:

---

#### Role of Airport:

The operation and development of the Springbank Airport will be directed to supporting private and commercial flight

#### **Taxiway Data**

Primary: "A"; 3000x35 (Asphalt)

Fair condition; replacement 2010 (\$225000)

Secondary: "C"; 3400x35 (Asphalt)

Fair condition; replacement 2010

(\$250000)

Third: "D"; (Asphalt)

Fourth: ---

#### **Landside Facility Data**

Entrance Road:

Parking Lot:

Fencing:

#### Contact Info

Mr. Larry Stock Airport Manager

Calgary Airport Authority 175 MacClaurin Drive

Calgary T32 3S4

(403) 286 1494(403), Fax: 288-4488

#### **Runway Data**

Primary: "07-25", 3400x100 (Asphalt)

constructed 1969; last rehabilitation 1986; Fair condition; replacement 2010

(\$700000)

Secondary: "16-34", 3000x75 (Asphalt)

constructed 1969; last rehabilitation 1988; Fair condition; replacement 2012

(\$660000)

#### **Apron Data**

Primary: "1"; 464x311 (Asphalt)

last rehabilitation 1986; fair condition;

Secondary: ---

#### **Building Data**

ATB: ---

Disability Access:

Field Electrical Centre:

algaly/Spriligualik Alliport (TBVV)						
Lighting Data	⊤Water / Sewer Data					
Primary Edgelighting: TE (Threshold and Runway End) last rehabilitation 1989; good conditi	on; Water Supply: Well; constructed 1970; poor condition;					
Approach Slope Indicator 1:	Sewage: Well; constructed 1970; replacement 2002					
Approach Slope Indicator 2:	<b>Vicinity Protection</b> ,					
PP	Caveat, and Right of Way					
ARCAL: Type: "K"; freq 118.2 Windsock: 1 windsocks; fair condition;	Vicinity Protection: No Caveat: No Right of Way: No					
Drainage Data						
Surface: Sul	bsurface:					

	Dramage Data	
	Surface:	Subsurface:
ļ		

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





### Calgary/Springbank Airport (YBW)

Onsite Business Data					
FBO: Yes, 1;			AC Ma	intenance:	Yes, 3;
T   1   1   1   1   1   1   1   1   1			6 6		
Industrial Buildings: No			Crop S	Spraying Act	tivities:
Hangara Vac 41.			Chamia	als Stored	an sita.
Hangars: Yes, 41;			Chemic	ais Stored	on site:
Operation and Maintenance	•	1000	1000	2000	2004
Tatal Assural Maintenance Dudget	1997	1998	1999	2000	2001
Total Annual Maintenance Budget					
Economic Activity Information	on —				
Road Distance to Nearest Airport		Service:	35		
Road Distance to Nearest Airport					
Road Distance to Nearest Airport	Cargo Servi	ce: 35			
Airport Activity Info					
	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
1997	1998	19	999	2000	2001
Total Annual Revenue:					
- Alima and From the D. (					
Airport Expenditure Data 19	97 19	08	1999	2000	2001
Total Annual Expenditure	<i>51</i> 19	<b>70</b>	בבבד	2000	2001

## Calgary/Springbank Airport (YBW)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 CALLING LAKE AIRPORT (CFK4)





Calling Lake Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Ms. Nancy Cardinal
Office Administrator Community Resources
Municipal District
Calling Lake, AB T0G 0K0
Tel: (780) 331 3860

Fax: (780) 331 3860

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

### Calling Lake Airport (FK4)

General Info	
Calling Lake (FK4) Municipal	Distance From Community (mile): 4 Latitude: 55.3167°, Longitude: -113.2500°
Owner and Operator Info Owner: M.D. of Opportunity #17 Operator: M.D. of Opportunity 317 Former Ownership: Province of Alberta Date of Change:	Ms. Nancy Cardinal Office Administrator Community Resources Municipal District Box 22 Calling Lake
Airport Organization Ownership Structure:	T0G 0K0 (780) 331 3860(780) , Fax: 331 3950
Organizational Structure:	Primary: "10-28", 2950x78 (Turf)
Role of Airport:  Provides medevac, local and commercial use.	Secondary:
Taxiway Data Primary:	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
Landside Facility Data	ATB:
Entrance Road:	
	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

## Calling Lake Airport (FK4)

Lighting Data	⊢Water / Sewer Data			
Primary Edgelighting:	Water Supply:			
Approach Slope Indicator 1:	Sewage:			
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way			
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No			
⊏Drainage Data				

Drainage Data					
Surface:	constructed 1988; good condition;	Subsurface:			

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





### Calling Lake Airport (FK4)

Consite Business Data —				
FBO: No			AC Maintena	nce: No
Industrial Buildings: No			Crop Sprayin	g Activities:
Hangars: No			Chemicals Sto	ored on site:
Operation and Maintenance	e Budget			
Total Annual Maintenance Budg	1997 et	1998	1999 20	000 2001
Economic Activity Information	tion			
Airport Activity Info	1997	1998	1999 200	00 2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data				
199	7 1998	3 199	9 2000	2001
Total Annual Revenue:				
<b>□</b> Airport Expenditure Data =				
	997 19	998 19	999 200	2001
Total Annual Expenditure				

### Calling Lake Airport (FK4)

Year	Project Name	Funding Source	Description
1987		Provincial	Seeding, miscellaneous work
1986		Provincial	Completion of Turf Runway
1985		Provincial	Grading
1984		Provincial	Brushclearing

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 CAMROSE AIRPORT (CEQ3)





Camrose Airport Aerial Photographs taken July 10, 2002

#### **Airport Contact Information:**

Mr. Ted Gillespie City Engineer City of Camrose Camrose, AB T4V 0S8 Tel: (780) 672 4428

Fax: (780) 672 4428

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Camrose Airport (EQ3)

General Info

Camrose (EQ3)

Distance From Community (mile): 0

Latitude: 53.0333°, Longitude: -112.8167°

Owner and Operator Info

Owner: City of Camrose Operator: City of Camrose Former Ownership: No Change

Date of Change: ---

Airport Organization

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

last rehabilitation 1993; Fair condition;

replacement 2011 (\$209000)

Secondary: "B"; (Asphalt)

constructed 1993; last rehabilitation 1993; Fair condition; replacement 2011

Third: "CA"; (Asphalt)

last rehabilitation 1993; Fair condition;

replacement 2011

Fourth: ---

**Landside Facility Data** 

Entrance Road: constructed 1979; last rehabilitation

2000; fair condition;

Parking Lot: type gravel; constructed 1979; good

condition;

Fencing: size 4inch page wire;

Contact Info

Mr. Ted Gillespie City Engineer City of Camrose 5204 50 Ave.

Camrose T4V 0S8

(780) 672 4428(780) , Fax: 672 6316

Runway Data

Primary: "13-31", 4500x100 (Asphalt)

constructed 1979; last rehabilitation 1993; replacement 2011 (\$683000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

last rehabilitation 1993; fair condition;

replacement 2011 (\$97000)

Secondary: ---

Building Data

ATB: constructed 1980; good condition;

Disability Access: size 4ft.; type ? Walk; constructed

1980; good condition;

Field Electrical Centre: size in basement;

constructed 1979; last rehabilitation 1993; good

condition;

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Camrose Airport (EQ3)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

last rehabilitation 1993; good condition;

Approach Slope Indicator 1: AP (Abbreviated PAPI - Aircraft up

10')

constructed 1993; good condition;

Approach Slope Indicator 2: AP (Abbreviated PAPI - Aircraft up

10')

constructed 1993; good condition;

ARCAL: Type: "K"; freq 122.8

Windsock: 2 windsocks;

good condition;

Water / Sewer Data

Water Supply: Municipal Service; constructed

1979; good condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: good condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Camrose Airport (EQ3)

**□Onsite Business Data** 

FBO: Yes, 1; Camrose Flight Cen	ter	AC I	Maintenance:	Yes, 1;	
Industrial Buildings: No		Cro	o Spraying Ad		anent; 1; Wetaskiwin Applicators
Hangars: Yes, ;		Cher	nicals Stored	on site: seaso	
Operation and Maintenance	1997	1998 199	9 2000	2001	
Total Annual Maintenance Budget		1330 133	2000		
Economic Activity Information	on —				
Major Economic Industries in Regi	on: Busine	ess/Agriculture	Services		
Airport Activity Info					
Annual Aircraft Movements:	1997	1998 199	9 2000	2001	
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
Total Annual Revenue:	1998	1999	2000	2001	
rotai Aililuai Kevellue:					
Airport Expenditure Data	<b>.</b>	20 4000	2222	2021	
Total Annual Expenditure	97 199	98 1999	2000	2001	
1 ocal / lilliadi Experialcare					

### Camrose Airport (EQ3)

Historic	Historic Capital Expenditures					
Year	Project Name	Funding Source	Description			
2001		Municipal	Air side signal			
2000		Municipal	landscaping/Train management to keep approach clear			
1994		Federal	Install DME			
1994		Federal	Runway construction			
1991		Provincial	Land Purchase			
1989		Municipal	Taxiway			
1988		Provincial	Terminal Building			
1980		Provincial	Terminal Building			
1979		Municipal	Av gas facility			
1978		Provincial	Construction			
1978		Federal	Construction			
1976		Provincial	Land Purchase			

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 CARDSTON AIRPORT (CEA6)





Cardston Airport Aerial Photographs taken August 12, 2002

#### **Airport Contact Information:**

Mr. Gregory Burt Municipal Administrator Town of Cardston Cardston, AB T0K 0K0 Tel: (403) 653 3366

Fax: (403) 653 2499

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 18, 2003 Project No. 11451

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Cardston Airport (EA6)

General Info

Cardston (EA6) Distance From Community (mile): 4
Municipal Latitude: 49.1667°, Longitude: -113.2333°

Owner and Operator Info

Owner: Town of Cardston Operator: Town of Cardston

Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Cardston

Organizational Structure:

Committee

Role of Airport:

Provides service for recreation and crop spraying.

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1976; last rehabilitation 2002; Good condition; replacement 2008 (\$48000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 12ft; constructed 1978; good

condition;

Parking Lot: ---

Fencing: size 4 ft; type farm; replacement 2020

Contact Info

Mr. Gregory Burt Municipal Administrator Town of Cardston

Box 280 Cardston T0K 0K0

(403) 653 3366(403), Fax: 653 2499

**Runway Data** 

Primary: "05-23", 3500x75 (Asphalt)

constructed 1976; last rehabilitation 2002; Good condition; replacement 2008

(\$463000)

Secondary: ---

**Apron Data** 

Primary: ---

Secondary: ---

**Building Data** 

ATB: ---

Disability Access: ---

Field Electrical Centre: size 6ft. X 8ft.; type wood

frame, steel; constructed 1978; good condition; replacement 2022 (\$150000)

#### Cardston Airport (EA6)

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

<b>□Lighting Data</b>		□ □ Water / Sewer Dat	ta <del></del>
	reshold and Runway End) ucted 1978; good condition; ement 2008 (\$201000)	Water Supply:	
Approach Slope Indicator 1:		Sewage:	
Approach Slope Indicator 2:		Vicinity Protectio Caveat, and Right	
ARCAL: Type: "K"; fre	eq 123.2	Vicinity Protection: Caveat: No Right of Way: No	No
Windsock: 1 windsocks; constructed 1 2008	.978; good condition; replacement		
□ Drainage Data			
Surface: good condition;	Subsur	face:	
Peak Period Info	Spring Summer Fall V	Vinter Average	





### Cardston Airport (EA6)

. ,							
Onsite Business Data							
FBO: No				AC Ma	intenance:	No	
Industrial Buildings: No				Crop S	Spraying Ad	ctivities: Ter	mporary; 1;
Hangars: Yes, 3; private ow	nership			Chemi	cals Stored	on site: tem	nporary stora
Operation and Maintena	nce B	_					 ]
Total Annual Maintenance D		1997	1998	1999	2000	2001	
Total Annual Maintenance B	uuget						
Economic Activity Infor	mation	)					
Road Distance to Nearest Air Road Distance to Nearest Air Road Distance to Nearest Air Road Distance to Nearest Air Road Distance to Nearest Air Major Economic Industries in How is the Airport Vital to the	rport Me rport Ca rport AN rport Fion Region	edEvac Serv Argo Serv ME Servic re Suppre n: Agric	ervice: ice: 75 e: 75 ession Se ulture	75 ·vice: 7!		sm	
Airport Activity Info		1997	1998	1999	2000	2001	
Annual Aircraft Movements	s:						
Annual Passenger Movement	ts:						
Commercial Airline Info							_ ]
-Airport Revenue Data -	1997	1998	2 1	999	2000	2001	
Total Annual Revenue:	133/	1330	, 1		2000	2001	
Airport Expenditure Dat							
Total Annual Expenditure	1997	19	998	1999	2000	2001	_

### Cardston Airport (EA6)

Year	Project Name	Funding Source	Description	
2002		Provincial	Paving	
1984		Provincial	Slurry Seal Work	
1978		Provincial	Lighting	
1977		Provincial	Paving	
1974		Federal	Construction	

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 CARSTAIRS/BISHELL'S AIRPORT (CGB2)**





Carstairs/Bishell's Airport Aerial Photographs taken October 24, 2002

#### **Airport Contact Information:**

G & A Bishell Carstairs, AB T0M 0N0 Tel: (403) 337 2564 Fax: (403) N/A

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

> Tel: 780-452-9955 Fax: 780-413-9918

> > Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

### Carstairs/Bishell's Airport (GR2)

General Info			
	stance From Community (mile): 2 titude: 51.5828°, Longitude: -114.0519°		
Owner and Operator Info Owner: G & A Bishell Operator: G & A Bishell Former Ownership: No Change Date of Change:	G & A Bishell Box 144 Carstairs T0M 0N0		
Airport Organization	(403) 337 2564(403) , Fax: N/A		
Ownership Structure:			
Ouganizational Structures	Runway Data		
Organizational Structure:	Primary: "16-34", 2700x100 (Turf) constructed 1996; Good condition;		
Role of Airport:  Provides service for private, emergency and public use. Als utilized be the Ultralite Flying Club for various events	Secondary: "07-25", 1400x60 (Turf) constructed 2001;		
Taxiway Data Primary: "North-South"; 2300x50 (Turf) constructed 1996; Good condition;	Apron Data		
Secondary:	Primary: Secondary:		
Third:			
Fourth:			
	Building Data		
Landside Facility Data	ATB: size 50x90; type steel; constructed 1998; good condition;		
Entrance Road: type gravel; good condition;	Disability Access:		
Parking Lot: size 10 car; good condition;			
Fencing:	Field Electrical Centre:		

### Carstairs/Bishell's Airport (GB2)

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply: Well; good condition;
Approach Slope Indicator 1: -	Sewage:
Approach Slope Indicator 2: -	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 0 windsocks;	
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	<del></del>





### Carstairs/Bishell's Airport (GB2)

Onsite Business Data					
FBO: No			AC Mainten	ance: No	
Industrial Buildings: No			Crop Sprayi	ng Activities:	
Hangars: Yes, 2; G & A Bishell		(	Chemicals St	tored on site:	1
Operation and Maintenance	Budget 1997	1998	1999 2	.000 200	1
Total Annual Maintenance Budget		1550	1999 2	.000 200	_
Economic Activity Information	on —				
Airport Activity Info	1997	1998	1999 20	000 2001	
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	1998	1999	9 2000	) 2001	
Total Annual Revenue:	1550	1993	, 2000	. 2001	
Airport Expenditure Data	77 40	00 10	200	200	
Total Annual Expenditure	<i>51</i> 19	98 19	999 20	000 200	71

### Carstairs/Bishell's Airport (GB2)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 CASTOR AIRPORT (CER2)





Castor Airport Aerial Photographs taken October 09, 2002

#### **Airport Contact Information:**

Mr. Michael Yakielashek Chief Administrative Officer Town of Castor Castor, AB T0C 0X0 Tel: (403) 882 3215

Fax: (403) 882 2700

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

> Tel: 780-452-9955 Fax: 780-413-9918

> > Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Castor Airport (ER2)

General Info

Castor (ER2) Distance From Community (mile): 1
Municipal Latitude: 52.2167°, Longitude: -111.9333°

Owner and Operator Info

Owner: Town of Castor Operator: Town of Castor Former Ownership: ---Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Castor as a Municipal Corporation is sole owner of the Castor Municipal airport

Organizational Structure:

Municipal Council (CAO)

Role of Airport:

Mostly used by local aircraft. Corporations such as ATCO use the site as well as emergency transporter such as STARS.

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 79; last rehabilitation 1991; Poor condition; replacement 2004 (\$23000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; fair condition;

Parking Lot: ---

Fencing: size 4'; type Barbed wire;

Contact Info

Mr. Michael Yakielashek Chief Administrative Officer

Town of Castor Box 479

Castor TOC 0X0

(403) 882 3215(403), Fax: 882 2700

**Runway Data** 

Primary: "13-31", 3000x75 (Asphalt)

constructed 1979; last rehabilitation 1991; Poor condition; replacement 2004

(\$463000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 79; last rehabilitation 91; poor condition; replacement 2004

(\$63000)

Secondary: ---

**Building Data** 

ATB: type wood; constructed 1980; last rehabilitation 2000; fair condition; replacement 2009 (\$100000)

Disability Access: ---

Field Electrical Centre: size 6x6; type tool shed;

poor condition; replacement

2005 (\$150000)

### Castor Airport (ER2)

Lighting Data		┌Water / Sewer Data
	nreshold and Runway End) ructed 1979; poor condition; rement 2004 (\$176000)	Water Supply: Well; constructed 1979; good condition;
Approach Slope Indicator 1:		Sewage:
Approach Slope Indicator 2:		Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No
ARCAL: Type: "K"; fr	ea 123 2	Caveat: No
Windsock: 1 windsocks	•	Right of Way: No
Drainage Data		
Surface:	9	Subsurface:
Peak Period Info		
	Spring Summer Fall	Winter Average
Peak Apron Aircraft Parked:		
Decian Aircraft for Airports		





### Castor Airport (ER2)

Consite Business Data				
FBO: No		A	C Maintenanc	e: No
Industrial Buildings: No		C	Crop Spraying	Activities:
Hangars: No		C	hemicals Store	ed on site:
Operation and Maintenance	_			
Total Annual Maintenance Budge	1997 et	1998	1999 2000	2001
Economic Activity Informat	ion			
Airport Activity Info	1997	1998 1	999 2000	2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	7 1998	1999	2000	2001
Total Annual Revenue:	, 1990	1339	2000	2001
Airport Expenditure Data	007 10	00 10	2000	2001
Total Annual Expenditure	997 19	98 199	99 2000	2001

### Castor Airport (ER2)

Year	Project Name	Funding Source	Description
1991		Provincial	Runway repairs and overlay
1984		Provincial	Terminal Building
1979		Provincial	Engineering and soils surver
1979		Provincial	Grading, base, paving and lighting
1978		Provincial	Land Purchase

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 CHEADLE AIRPORT (CFQ4)





Cheadle Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Mr. George Jackson Calgary, AB T2P 2G7 Tel: (403) 936 5616 Fax: (403) 936 2367

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877





Cheadle (FQ4) Private	Distance From Community (mile): 4 Latitude: 51.0500°, Longitude: -113.6167°			
Owner and Operator Info		Contact Info		
Owner: same as above Operator: same as above Former Ownership: No Change Date of Change:		Mr. George Jackson Site 16 Box 10 RR7 Calgary T2P 2G7 (403) 936 5616(403) , Fax: 936 2367		
<b>─Airport Organization</b>				
Ownership Structure: Private				
	Run	way Data		
Organizational Structure:	Prima	ry: "07-25", 4000x100 (Turf) constructed 1974; Good condition;		
Role of Airport:				
	Secon	ndary:		
⊤Taxiway Data <del>−−−−−</del>				
Primary: "A"; (Turf) constructed 1974; Good condition;	Apro	on Data		
constructed 1974, Good condition,		ry: "none";		
Secondary:		in, Hone ,		
Third:	Secor	ndary:		
Fourth:				
	⊤Build	ling Data		
_ l andaida Escility Data	ATB:			
Landside Facility Data				
Entrance Road:				
	Disab	ility Access:		
Parking Lot:				
	Eigld	Electrical Centre:		
Fencing:	rieia	Liecurcai Ceriue		

Lighting Data	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





<b>□Onsite Business Data</b>						
FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Act	tivities:
Hangars: Yes, 1; private u	se - 1 pla	ane		Chemic	cals Stored	on site:
Operation and Mainter	nance B	_	1000	1000	2000	2001
Total Annual Maintenance	Budget	1997	1998	3 1999	2000	2001
Economic Activity Info	rmation	1				
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movemer	nts:	2007	1330	1333	2000	
Annual Passenger Moveme	ents:					
Commercial Airline Inf	0					
Airport Revenue Data	1997	1998		1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Da	ata 1997	7 199	 	1999	2000	2001
Total Annual Expenditure	1997	193	<i>,</i> 0	1977	2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 CHINCHAGA AIRPORT (CED2)





Chinchaga Airport Aerial Photographs taken August 20, 2002

#### **Airport Contact Information:**

Mr. Rene Lavoie Aviation Manager Chevron Canada Calgary Calgary, AB T2P 0L7 Tel: (403) 571 5903

Fax: (403) 571 5907

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Chinchaga (ED2) Private	Distance From Community (mile): Latitude: 57.5500°, Longitude: -119.1333°
Owner and Operator Info Owner: Chevron Canada	Contact Info  Mr. Rene Lavoie
Operator: Chevron Canada Former Ownership: No Change Date of Change:	Aviation Manager Chevron Canada Calgary 500 - 5 Avenue SW Calgary
Airport Organization Ownership Structure:	T2P 0L7 (403) 571 5903(403) , Fax: 571 5907
Private	- Punway Data
Organizational Structure:	Primary: "07-25", 4129x75 (Gravel)
Role of Airport:  Provides air support for plant operations	Secondary:
Taxiway Data Primary:	Apron Data
	Primary:
Secondary:	Filliary
Third:	Secondary:
Fourth:	
	Building Data
Landside Facility Data	ATB:
Entrance Road:	
	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

<u> </u>
Water / Sewer Data
End) Water Supply:
Sewage:
Vicinity Protection, Caveat, and Right of Way
Vicinity Protection: No Caveat: No Right of Way: No
Subsurface:
Fall Winter Average





Onsite Business Data						
FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintena	nce Bu	dget				
T. I.A. IM.:	–	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	idget					
Economic Activity Inform	nation					
Airport Activity Info						
Annual Aircraft Movements		1997	1998	1999	2000	2001
Annual Passenger Movement	S:					
Commercial Airline Info						
Airport Revenue Data						
	1997	1998		1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Data						
Total Appual Exponditure	1997	199	98	1999	2000	2001
Total Annual Expenditure						

Year	Project Name	Funding Source	Description	

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 CHIPEWYAN LAKE AIRPORT (CEG5)





Chipewyan Lake Airport Aerial Photographs taken August 08, 2002

#### **Airport Contact Information:**

Mr. Martin Holst Manager of Transportation Municipal District #17 Wabasca, AB T0G 2K0 Tel: (780) 891 3778

Fax: (780) 891 3778

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Chipewyan Lake Airport (EG5)

de: 56.9500°, Longitude: -113.5000°
Contact Info
Mr. Martin Holst  Manager of Transportation  Municipal District #17  Box 60  Wabasca
T0G 2K0
(780) 891 3778(780) , Fax: 891 3772
Runway Data Primary: "10-28", 3000x100 (Turf)
Secondary:
7
Apron Data
Primary:
Secondary:
Building Data
ATB:
]
Disability Access:
Field Electrical Centre:

### Chipewyan Lake Airport (EG5)

Lighting Data	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1: -	
Approach Slope Indicator 2: -	──Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 0 windsocks;	
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





### Chipewyan Lake Airport (EG5)

Onsite Business Data      ──				
FBO: No		ļ	AC Maintenand	ce: No
Industrial Buildings: No Crop Spraying Activities:				Activities:
Hangars: No Chemicals Stored on site:				ed on site:
Operation and Maintenance	e Budget			
Total Annual Maintenance Budg	1997 et	1998	1999 200	0 2001
Economic Activity Information				
Airport Activity Info	1997	1998 1	1999 2000	2001
Annual Aircraft Movements:	1997	1990	1999 2000	2001
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	97 1998	3 1999	2000	2001
Total Annual Revenue:	,, 1990	, 1999	2000	2001
Airport Expenditure Data	.007 10	100	00 2000	2001
Total Annual Expenditure	.997 19	98 19	99 2000	2001

## Chipewyan Lake Airport (EG5)

Year	Project Name	Funding Source	Description
1995		Provincial	Grading of extension
1994		Provincial	Prelim engineering for runway extension
1994		Provincial	Grading for runway extension of 500 feet.
1993		Provincial	Supply retroreflective lighting system
1966		Provincial	Construction

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 CHIPMAN AIRPORT (CFU3)





Chipman Airport Aerial Photographs taken July 10, 2002

#### **Airport Contact Information:**

Edmonton Soaring Club Edmonton, AB T5J 2K1 Tel: (780) 363 3860 Fax: (780) N/A

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info			
	e From Community (mile): 1.1 e: 53.7167°, Longitude: -112.6333°		
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Edmonton Soaring Club P.O. Box 472 Edmonton T5J 2K1 (780) 363 3860(780), Fax: N/A		
Airport Organization Ownership Structure:			
Organizational Structure:	Primary: "10-28", 2600x450 (Turf)		
Role of Airport:	Secondary:		
Taxiway Data Primary:	Apron Data		
Secondary:	Primary:		
Third:	Secondary:		
Fourth:	Politica Pata		
	Building Data  ATB:		
Landside Facility Data	AID.		
Entrance Road:	Disability Access:		
Parking Lot:			
Fencing:	Field Electrical Centre:		

<b>□Lighting Data</b>	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Troumty 1 rotoonon,
ARCAL: Type: Windsock: 0 windsocks;	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data					
FBO: No			AC Maint	enance: 1	No
Industrial Buildings: No			Crop Spr	aying Activ	vities:
Hangars: No			Chemicals	s Stored or	n site:
Operation and Maintenanc	e Budget				
Total Annual Maintenance Budg	1997 et	1998	1999	2000	2001
Economic Activity Informa	tion				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:	1997	1990	1333	2000	2001
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	97 1998	3 199	ο 2	000	2001
Total Annual Revenue:		, 139	. Z		2001
Airport Expenditure Data	007 10	100	000	2000	2001
Total Annual Expenditure	.997 19	998 1	999	2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 CHRISTINA BASIN AIRPORT (CFF2)





Christina Basin Airport Aerial Photographs taken August 09, 2002

#### **Airport Contact Information:**

Mr. Brian Stanton
W.A.O.O.

Alberta Sustainable Resource Development - Land and Forest Division
Lac La Biche, AB T0A 2C0
Tel: (780) 623 5240

Fax: (780) 623 2570

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info			
	re From Community (mile): e: 55.5833°, Longitude: -111.8167°		
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Mr. Brian Stanton W.A.O.O. Alberta Sustainable Resource Development - Land and Forest Division Box 450		
Airport Organization Ownership Structure:	Lac La Biche T0A 2C0 (780) 623 5240(780) , Fax: 623 2570		
Organizational Structure:	Runway Data Primary: "09-27", 2400x100 (Gravel)		
Role of Airport:	Secondary:		
Taxiway Data			
Primary:	Apron Data		
Secondary:	Primary:		
Third:	Secondary:		
Fourth:			
	Building Data		
	ATB:		
Landside Facility Data			
Entrance Road:	Disability Access:		
Parking Lot:			
Fencing:	Field Electrical Centre:		

<b>□Lighting Data</b>	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Troumty 1 rotoonon,
ARCAL: Type: Windsock: 0 windsocks;	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Consite Business Data ——					
FBO: No			AC Mai	intenance:	No
Industrial Buildings: No			Crop S	praying Act	tivities:
Hangars: No			Chemic	als Stored	on site:
Operation and Maintenance	Budget -	1998	1999	2000	2001
Total Annual Maintenance Budge		1330	1333	2000	
Economic Activity Informati	on				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
Total Annual Revenue:	7 1998	3 19	99	2000	2001
Airport Expenditure Data	997 19	98	1999	2000	2001
Total Annual Expenditure	,,, 13		1777	2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 CLARESHOLM INDUSTRIAL AIRPORT (CEJ4)





Claresholm Industrial Airport Aerial Photographs taken August 12, 2002

#### **Airport Contact Information:**

Mr. Larry Flexhaug Town Coordinator Town of Claresholm Claresholm, AB T0L 0T0 Tel: (403) 625 3381

Fax: (403) 625 3869

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Claresholm Industrial Airport (EJ4)

**General Info** 

Claresholm Industrial (EJ4) Distance From Community (mile): 2.5

Latitude: 50.0000°, Longitude: -113.6333°

Owner and Operator Info

Owner: Town of Claresholm Operator: Town of Claresholm

Former Ownership: Transport Canada

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Council

Organizational Structure:

Airport Committee

Role of Airport:

Industrial airport

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1942; last rehabilitation 2001;

Good condition; replacement 2009

Secondary: "B"; (Asphalt)

constructed 1942; last rehabilitation

2001; replacement 2009

Third: "C";

constructed 1983; Good condition;

replacement 2009

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 10ft; type gravel; constructed

1986; fair condition;

Parking Lot: size 30x60; type gravel; constructed

1986; fair condition;

Fencing:

Contact Info

Mr. Larry Flexhaug Town Coordinator Town of Claresholm

Box 1000 Claresholm TOL 0T0

(403) 625 3381(403), Fax: 625 3869

**Runway Data** 

Primary: "03-21", 3100x100 (Asphalt)

constructed 1942; last rehabilitation 2001; Good condition; replacement 2009

(\$547000)

Secondary: ---

**Apron Data** 

Primary: ---

Secondary: ---

**Building Data** 

ATB: size 24x24; type wood frame; constructed

1986; good condition; replacement 2020

(\$100000)

Disability Access: constructed 1986;

Field Electrical Centre: size 6x8; type wood frame;

constructed 1976; fair condition; replacement 2007

(\$150000)

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Claresholm Industrial Airport (EJ4)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1976; fair condition; replacement 2007 (\$241000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123

Windsock: 1 windsocks;

constructed 1976; fair condition; replacement 2

Water / Sewer Data

Water Supply: Municipal Service; constructed

1986; good condition; replacement 2020

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1942; good condition; Subsurface: constructed 1942; good condition;

replacement 2009 (\$15000)

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

---



**Consite Business Data** 

# Alberta Regional/Local Airport Inventory Study Airport Summary Report



### Claresholm Industrial Airport (EJ4)

FBO: No		AC	Maintenance:	Yes, 1;	
Industrial Buildings: No		Cro	op Spraying Ad		mporary; Morkin's Crop aying
Hangars: Yes, 5;		Che	micals Stored	-	
Operation and Maintenance B	udget				
Total Annual Maintenance Budget	1997	1998 19	99 2000	2001	
Economic Activity Information	1				
Airport Activity Info					
	1997	1998 199	99 2000	2001	
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					]
Total Annual Revenue:	1998	1999	2000	2001	
Airport Expenditure Data					
Total Annual Expenditure	7 199	8 1999	2000	2001	-

## Claresholm Industrial Airport (EJ4)

Year	Project Name	Funding Source	Description
2001		Provincial	Major crack repair and slurry seal of runwa and main taxiway
1992		Provincial	Purchase and install of NDB
1986		Provincial	Pavement overlay
1986		Provincial	Terminal Building
1981		Provincial	Chip Seal Coat
1980		Provincial	Construction of Taxiway
1976		Provincial	Lighting
1975		Federal	runway overlay, taxiway and parking aproi

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 CLEARWATER RIVER AIRPORT (CFS8)**





Clearwater River Airport Aerial Photographs taken October 24, 2002

#### **Airport Contact Information:**

Mr. Ruf May
Olds-Didsbury Flying Association
Didsbury, AB T0M 0W0
Tel: (403) 335 2380/3841
Fax: (403) 335 9597

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

### Clearwater River Airport (FS8)

Classicator Divor (ECO)	Dictance From	Community (mile)		
Clearwater River (FS8)		Community (mile): 33°, Longitude: -115.2333°		
		· · ·		
Owner and Operator Info	Contact Info			
Owner: Olds/Didsbury Flying Assoc.	Mr. Ruf May			
Operator: same Former Ownership: Province of Alberta		Olds-Didsbury Flying Association Box 477		
Date of Change:		Didsbury		
Date of changer		TOM OWO		
<b>□</b> Airport Organization <b>□</b>		(403) 335 2380/3841(403) , Fax: 335 9597		
Ownership Structure:				
O.D.F.A (Ruf May)				
	Run	way Data		
Organizational Structure:		ary: "04-22", 3300x75 (Turf)		
		last rehabilitation 1994; Good condition;		
		,		
Role of Airport:				
Provides services for emergency, recreational, Forest Fi	ire Seco	ndary:		
Protection, and Search and Rescue flights.				
Taxiway Data				
Primary:				
,	Apro	Apron Data		
	Prima	Primary:		
Secondary:				
Third:	Secoi	ndary:		
Fourth:				
	⊢Build	ding Data		
	ATB:			
Landside Facility Data				
Entrance Road: type gravel; fair condition;				
,, 3 , , , , , , , , , , , ,	Disah	ility Access:		
	Disan	mity Access.		
Parking Lot:				
	Field	Electrical Centre:		
Fencing:				

## Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Clearwater River Airport (FS8)

Lighting Data

Primary Edgelighting: ---

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: ---

Windsock: 1 windsocks;

poor condition; replacement 2004

Water / Sewer Data

Water Supply: ---

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: --- Subsurface: ---

Peak Period InfoSpringSummerFallWinterAveragePeak Apron Aircraft Parked:11111Design Aircraft for Airport:------





### Clearwater River Airport (FS8)

Onsite Business Data						
FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintena	nce Bu	dget				
T. I.A. IM.:	–	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	idget					
Economic Activity Inform	nation					
Airport Activity Info						
Annual Aircraft Movements		1997	1998	1999	2000	2001
Annual Passenger Movement	S:					
Commercial Airline Info						
Airport Revenue Data						
	1997	1998		1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Data						
Total Appual Exponditure	1997	199	98	1999	2000	2001
Total Annual Expenditure						

## Clearwater River Airport (FS8)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 COLD LAKE REGIONAL AIRPORT (CEN5)**





Cold Lake Regional Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Mr. Mark Power
Chief Administrative Officer
City of Cold Lake
Cold Lake, AB T9M 1A1
Tel: (780) 594 4494
Fax: (780)

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

> Tel: 780-452-9955 Fax: 780-413-9918

> > Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Cold Lake Regional Airport (EN5)

General Info

Cold Lake Regional (EN5)

Municipal

Distance From Community (mile): 4

Latitude: 54.4833°, Longitude: -110.2667°

Owner and Operator Info

Owner: City of Cold Lake Operator: City of Cold Lake

Former Ownership: Province of Alberta Date of Change: August 22, 1997

**Airport Organization** 

Ownership Structure:

City of Cold Lake

Organizational Structure:

Municipal Government

Role of Airport:

Provides non-scheduled air aervice for the region as well as

flying schools amd recreational flying

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1979; Fair condition; replacement 2004 (\$48000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; last rehabilitation 2001;

fair condition;

Parking Lot:

Fencing: size 4ft; type barb wire;

Contact Info

Mr. Mark Power

Chief Administrative Officer

5319 48 Avenue

Cold Lake T9M 1A1

(780) 594 4494(780)

**Runway Data** 

Primary: "07-25", 3000x75 (Asphalt)

constructed 1979; Fair condition; replacement 2004 (\$397000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1979; fair condition;

replacement 2004

Secondary: ---

**Building Data** 

ATB: size 20x40; type Atco Trailer; constructed

1984; last rehabilitation 2001; poor condition;

Disability Access: ---

Field Electrical Centre: type tool shed; fair condition;

replacement 2004 (\$150000)

### Cold Lake Regional Airport (EN5)

old Lake Regional Allport (LINO)	
Lighting Data	─────────────────────────────────────
Primary Edgelighting: TE (Threshold and Runway End) constructed 1979; poor condition; replacement 2004 (\$128000)	Water Supply: Other; fair condition;
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: "K"; freq 122.8  Windsock: 1 windsocks; fair condition; replacement 2004	Vicinity Protection: No Caveat: Yes Right of Way: No
⊤Drainage Data	
_	urface:
Peak Period Info	

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





### Cold Lake Regional Airport (EN5)

Onsite Business Data								
FBO: No				AC Ma	intenance:	No		
Industrial Buildings: No	ndustrial Buildings: No			Crop S	Crop Spraying Activities:			
Hangars: Yes, 10; Clem La Wayne Tokwz, T Robinson, Electr Zentner, Mike C Leo Puiard & Ely	Fim Cran ic Servic otton-Fro	nb, Al es Ltd., De ontier Flyin	enis g,	Chemic	cals Stored	on site:		
Operation and Mainter	nance F	Rudaet -						
	101100	1997	1998	1999	2000	2001		
Total Annual Maintenance	Budget	1997	1990	1999	2000			
Economic Activity Info	ormatio	n						
Airport Activity Info								
		1997	1998	1999	2000	2001		
Annual Aircraft Moveme	nts:							
Annual Passenger Moveme	ents:							
Commercial Airline In	fo							
Airport Revenue Data	1997	1998		1999	2000	2001		
Total Annual Revenue:	1001	1590	·		2000			
Airport Expenditure D								
	199	7 19	98	1999	2000	2001		
Total Annual Expenditure								

### Cold Lake Regional Airport (EN5)

Year	Project Name	Funding Source	Description
1992		Provincial	Brush clearing approaches
1984		Provincial	Terminal Building
1979		Provincial	Land purchase and construction

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 CONKLIN (LEISMER) AIRPORT (CET2)





Conklin (Leismer) Airport Aerial Photographs taken August 09, 2002

#### **Airport Contact Information:**

Mr. Brian Stanton
W.A.O.O.

Alberta Sustainable Resource Development - Land and Forest Division
Lac La Biche, AB T0A 2C0

Tel: (780) 623 5240 Fax: (780) 623 2570

#### Prepared for:



**Aviation Strategy Action Group** 

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877





General Info	
	ce From Community (mile): 8 le: 55.7000°, Longitude: -111.2833°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:  Airport Organization	Mr. Brian Stanton W.A.O.O. Alberta Sustainable Resource Development - Land and Forest Division Box 450 Lac La Biche T0A 2C0
Ownership Structure:	(780) 623 5240(780) , Fax: 623 2570
Organizational Structure:	Runway Data  Primary: "08-26", 5000x100 (Clay)
Role of Airport:	Secondary:
Taxiway Data	
Primary:	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
Landside Facility Data	ATB:
Entrance Road:	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1: -	Sewage:
Approach Slope Indicator 2: -	─────────────────────────────────────
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
□ Peak Period Info	
	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





<b>Consite Business Data</b> −						
FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	praying Act	civities:
Hangars: No				Chemic	als Stored (	on site:
☐ Operation and Maintena	ance Bud	dget -				
		1997	1998	1999	2000	2001
Total Annual Maintenance B						
Economic Activity Infor	mation -					
Airport Activity Info	1	.997	1998	1999	2000	2001
Annual Aircraft Movement	s:					
Annual Passenger Movemen	its:					
Commercial Airline Info	)					
Airport Revenue Data	1997	1998		1999	2000	2001
Total Annual Revenue:	133/	1330		1333	2000	2001
Airport Expenditure Dat						
Total Annual Expenditure	1997	199	8	1999	2000	2001
. Star / William Experialtare						

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 CONSORT AIRPORT (CFG3)





Consort Airport Aerial Photographs taken October 09, 2002

#### **Airport Contact Information:**

Ms. Sandra King Administrator Village of Consort Consort, AB T0C 1B0 Tel: (403) 577 3623

Fax: (403) 577 2024

#### Prepared for:



**Aviation Strategy Action Group** 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Consort Airport (FG3)

#### General Info

Consort (FG3) Municipal Distance From Community (mile): 1.5 Latitude: 52.0167°, Longitude: -110.7500°

#### **Owner and Operator Info**

Owner: Village of Consort

Operator: ---

Former Ownership: Province of Alberta

Date of Change: April 1, 1995

#### **Airport Organization**

Ownership Structure:

Municipally Owned

#### Organizational Structure:

Municipally Government

#### Role of Airport:

A public airport primarily used by private and emergency aircraft (STARS).

#### **Taxiway Data**

Primary: ---

Secondary: ---

Third: ---

Fourth: ---

#### **Landside Facility Data**

Entrance Road: type Gravel; constructed 1977; fair

condition;

Parking Lot: type Gravel; constructed 1977; fair

condition;

Fencing: size 4'; type Barbed Wire;

#### Contact Info

Ms. Sandra King Administrator Village of Consort

Box 490 Consort

T0C 1B0

(403) 577 3623(403), Fax: 577 2024

#### **Runway Data**

Primary: "13-31", 3000x75 (Asphalt)

constructed 1977; last rehabilitation 1998; Poor condition; replacement 2003

(\$397000)

Secondary: ---

#### **Apron Data**

Primary: ---

Secondary: ---

#### **Building Data**

ATB: size 24' x 32'; constructed 1985; last rehabilitation 1985; good condition; replacement 2010 (\$100000)

Disability Access: ---

Field Electrical Centre: ---

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Consort Airport (FG3)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1977; poor condition; replacement 2005 (\$155000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1977; last rehabilitation 2002; good

condition;

Water / Sewer Data

Water Supply: ---

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: --- Subsurface: ---

Peak Period InfoSpringSummerFallWinterAveragePeak Apron Aircraft Parked:11111Design Aircraft for Airport:------





#### Consort Airport (FG3)

O	nsite	Bu	sines	s Data

FBO: No AC Maintenance: No

Industrial Buildings: No Crop Spraying Activities: Temporary; ?

Hangars: Yes, 4; Private Chemicals Stored on site: None

**Operation and Maintenance Budget** 

1997 1998 1999 2000 2001

Total Annual Maintenance Budget

#### **Economic Activity Information**

Road Distance to Nearest Airport Fire Suppression Service: 2

Major Economic Industries in Region: Oil & Gas/Farming/Ranching/Business/Tourism

How is the Airport Vital to the Region: Because of our distance from major centres, availability of access for medevac is critical. Airport used frequently by oil

company executives.

**Airport Activity Info** 

1997 1998 1999 2000 2001

**Annual Aircraft Movements:** 

Annual Passenger Movements:

**Commercial Airline Info** 

N/A (, )

**Airport Revenue Data** 

1997 1998 1999 2000 2001

Total Annual Revenue:

**Airport Expenditure Data** 

1997 1998 1999 2000 2001

**Total Annual Expenditure** 

## Consort Airport (FG3)

Year	Project Name	Funding Source	Description
1999		Provincial	Fog coat / 1998 microsurfacing ?
1992	Non-Dir Beacon	Provincial	Purchase and install NDB
1992	Dist. Measuring Equipment	Provincial	Purchase and install DME
1988	Slurry Seal	Provincial	Slurry Seal runway
1985	Terminal Building	Provincial	Terminal Building (24' x 32')
1977	Airport Construction	Federal/Provincial	Construction and airport lighting
1977		Federal	Construction
1975		Provincial	Land purchase

### AIRPORT INFORMATION REPORT - 2002 CORONATION AIRPORT (CYCT)





Coronation Airport Aerial Photographs taken October 09, 2002

#### **Airport Contact Information:**

Mr. John Vogelaar Town Manager Town of Coronation Coronation, AB T0C 1C0 Tel: (403) 578 3679

Fax: (403) 578 3020

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Coronation Airport (YCT)

General Info

Coronation (YCT) Distance From Community (mile): 1

Latitude: 52.0667°, Longitude: -111.4500°

Owner and Operator Info

Owner: ---Operator: ---

Former Ownership: --- Date of Change: ---

**Airport Organization** 

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1977; last rehabilitation 1991; Fair condition; replacement 2004 (\$30000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type Paved; fair condition;

Parking Lot: type Paved; fair condition;

Fencing: size 4' Barbed Wire;

Contact Info

Mr. John Vogelaar Town Manager Town of Coronation

Box 219

Coronation T0C 1C0

(403) 578 3679(403), Fax: 578 3020

**Runway Data** 

Primary: "11-29", 3000x75 (Asphalt)

constructed 1977; last rehabilitation 1991; Fair condition; replacement 2004

(\$397000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1977; last rehabilitation 1991; fair condition; replacement 2004

(\$49000)

Secondary: ---

Building Data

ATB: constructed 1984; fair condition; replacement

2009 (\$100000)

Disability Access: ---

Field Electrical Centre: size 6x6; type Tool Shed; fair

condition; replacement 2005

(\$150000)

### Coronation Airport (YCT)

Lighting Data		┌Water / Sewer Data
	nreshold and Runway End) ucted 1977; fair condition; ement 2005 (\$155000)	Water Supply:
Approach Slope Indicator 1:		Sewage:
Approach Slope Indicator 2:		Vicinity Protection, Caveat, and Right of Way
ADOM T 11/41/16	422.0	Vicinity Protection: No Caveat: No
ARCAL: Type: "K"; fr	eq 122.8	Right of Way: No
Windsock: 1 windsocks; constructed 2 2005	1977; poor condition; replaceme	ent
Drainage Data		
Surface:	Sub	surface:
Peak Period Info	Carrier Common 5 !!	Western A
	Spring Summer Fall	Winter Average
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		





### Coronation Airport (YCT)

Onsite Business Data					
FBO: No			AC Mair	ntenance:	No
Industrial Buildings: No			Crop Sp	oraying Act	tivities:
Hangars: No			Chemica	als Stored	on site:
Operation and Maintenance E	_	1000	1000	2000	2004
Total Annual Maintenance Budget	1997	1998	1999	2000	2001
Economic Activity Informatio	n —				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	1009	100	10	2000	2001
Total Annual Revenue:	1998	199	בי	2000	2001
Airport Expenditure Data	7 199	98 1	999	2000	2001
Total Annual Expenditure	, 1).	,,, 1		2000	2001

### Coronation Airport (YCT)

Year	Project Name	Funding Source	Description
1992		Provincial	Purchase and installation of NDB
1991		Provincial	Slurry Seal runway
1984		Provincial	Terminal Building
1977		Provincial	Grading, paving and lighting
1977		Federal	Construction
1975		Provincial	Land purchase

### AIRPORT INFORMATION REPORT - 2002 COUTTS/ROSS INT'L AIRPORT (CEP4)





Coutts/Ross Int'l Airport Aerial Photographs taken August 13, 2002

#### **Airport Contact Information:**

Montana Aeronautics Commission Helena, MT 59604 Tel: (406) 444 2506

Fax: (406) 444 2519

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

□General Info	
	Dietorio Francisco Community (mile), 0.5
Coutts/Ross Int'l (EP4) Private - Public Use	Distance From Community (mile): 0.5 Latitude: 49.0000°, Longitude: -111.9667°
Filvate - Fublic OSE	Lautade. 15.0000 , Longitude. 111.5007
Owner and Operator Info	Contact Info
Owner:	Montana Aeronautics Commission
Operator: Montana Aeronautics Commission	P.O. Box 5178
Former Ownership:	Helena
Date of Change:	59604
Airport Organization	(406) 444 2506(406) , Fax: 444 2519
Ownership Structure:	
	Runway Data
Organizational Structure:	Primary: "07-25", 2900x80 (Turf)
Role of Airport:	
	Secondary:
Taxiway Data	
Primary:	- Anyon Doto
	Apron Data
	Primary:
Secondary:	
Third:	Secondary:
Countle	
Fourth:	
	┌Building Data
	ATB:
Landside Facility Data	
Entrance Road:	
	Disability Access
	Disability Access:
Parking Lot:	
	Field Electrical Centre:
Fencing:	

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1: -	Sewage:
Approach Slope Indicator 2: -	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 1 windsocks; fair condition;	
⊤Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data					
FBO: No			AC Mainten	ance: No	
Industrial Buildings: No			Crop Spray	ing Activities	s:
Hangars: No		(	Chemicals S	stored on site	e:
Operation and Maintenance	_	1000	1000	2000	21
Total Annual Maintenance Budge	1997 et	1998	1999 2	2000 200	)1
Economic Activity Informat	ion				
Airport Activity Info	1997	1998	1999 2	000 200	1
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
Total Annual Revenue:	7 1998	3 1999	9 200	0 200:	
Airport Expenditure Data					
	997 19	98 19	999 2	000 20	001
Total Annual Expenditure					

Year	Project Name	Funding Source	Description	

### AIRPORT INFORMATION REPORT - 2002 COWLEY AIRPORT (CYYM)





Cowley Airport Aerial Photographs taken August 09, 2002

#### **Airport Contact Information:**

Mr. Tony Burton
Exec Director
Alberta Soaring Council
Claresholm, AB T0L 0T0
Tel: (403) 625 4563

Fax: (403) 625 4563

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Cowley Airport (YYM)

## Cowley (YYM) Private - Public Use Distance From Community (mile): 4.8 Latitude: 49.6333°, Longitude: -114.1000° Contact Info Owner: Gov't of Alberta Operator: Alberta Soaring Council Contact Info Mr. Tony Burton Exec Director

#### Airport Organization

Ownership Structure:

Airfield is Crown land "owned" by province

Former Ownership: Province of Alberta

Date of Change: January 1, 1994

Organizational Structure:

Council

Role of Airport:

Airfield is a historic soaring site, since the 1950s, particularly in the use of excellent mountain lee wave for high altitude

# Taxiway Data Primary: -- Secondary: -- Third: -- Fourth: ---

#### **Landside Facility Data**

Entrance Road: size 12'; type gravel;

Parking Lot: type grass;

Fencing: type 4' barbed wire;

#### Alberta Soaring Council Box 1916

Claresholm T0L 0T0

(403) 625 4563(403), Fax: 625 4563

#### **Runway Data**

Primary: "11-29", 4330x300 (Turf)

constructed 1938; Good condition;

replacement 2020

Secondary: "03-21", 3600x300 (Turf)

constructed 1938; Fair condition;

replacement 2020

Apron Data
Primary:
Secondary:

#### **Building Data**

ATB: ---

Disability Access: ---

Field Electrical Centre: ---

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Cowley Airport (YYM)

Lighting Data

Primary Edgelighting: ---

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: ---

Windsock: 1 windsocks;

poor condition;

Water / Sewer Data

Water Supply: Well; good condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: --- Subsurface: ---

Peak Period Info
Spring Summer Fall Winter Average

Peak Apron Aircraft Parked: 30 15

Design Aircraft for Airport: ---





### Cowley Airport (YYM)

Onsite Business Data					
FBO: No			AC Mainter	nance:	No
Industrial Buildings: No Crop Spraying Activities:					vities:
Hangars: No		(	Chemicals S	Stored o	n site:
Operation and Maintenance I	_	1000	1000	2000	2001
Total Annual Maintenance Budget	1997	1998	1999 2	2000	2001
Economic Activity Information	on				
Road Distance to Nearest Airport S How is the Airport Vital to the Reg considerable amount of tourist mo	MedEvac Se Cargo Service AME Service gion: Natio	ervice: 70 ce: 70 e: 70 nal soaring		ng a	
Airport Activity Info	1997	1998	1999 2	.000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	1998	1999	) 200	ın	2001
Total Annual Revenue:	1998	1995	200	iU	2001
Airport Expenditure Data	97 19	98 19	99 2	000	2001
Total Annual Expenditure					

### Cowley Airport (YYM)

Year	Project Name	Funding Source	Description	

### AIRPORT INFORMATION REPORT - 2002 COWPER AIRPORT (CFM3)





Cowper Airport Aerial Photographs taken August 09, 2002

#### **Airport Contact Information:**

Mr. Brian Stanton
W.A.O.O.

Alberta Sustainable Resource Development - Land and Forest Division
Lac La Biche, AB T0A 2C0

Tel: (780) 623 5240 Fax: (780) 623 2570

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Cowper (FM3)	Distance From Community (mile): Latitude: 55.9500°, Longitude: -110.5000°		
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Mr. Brian Stanton W.A.O.O. Alberta Sustainable Resource Development - Land and Forest Division Box 450		
Airport Organization	Lac La Biche T0A 2C0		
Ownership Structure:	(780) 623 5240(780) , Fax: 623 2570		
Organizational Structure:	Runway Data Primary: "03-21", 2500x100 (Turf)		
Role of Airport:	Secondary:		
⊤Taxiway Data			
Primary:	Apron Data		
	Primary:		
Secondary:	Filliary		
Third:	Secondary:		
Fourth:			
	Building Data		
Landside Facility Data	ATB: size 896; constructed 1977; last rehabilitation 1986; replacement 2012		
Entrance Road:	Disability Access: type sidewalk; constructed 1977;		
Parking Lot:			
Fencing:	Field Electrical Centre: size 6x6; type metal; replacement 2005		

Lighting Data	─Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 0 windsocks;	
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data					
FBO: No			AC Mai	ntenance:	No
Industrial Buildings: No			Crop S	praying Act	ivities:
Hangars: No			Chemic	als Stored (	on site:
Operation and Maintenance	e Budget -				
•	1997	1998	1999	2000	2001
Total Annual Maintenance Budg	et				
Economic Activity Information	tion				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:	1337	1330	1333	2000	
Annual Passenger Movements:					
Commercial Airline Info	<u>'</u>				
Airport Revenue Data					
199	97 1998	3 19	99	2000	2001
Total Annual Revenue:					
Airport Expenditure Data					
1	.997 19	98	1999	2000	2001
Total Annual Expenditure					

Year	Project Name	Funding Source	Description	

### **AIRPORT INFORMATION REPORT - 2002 DE WINTON/HIGHWOOD AIRPORT (CED6)**

#### **Airport Contact Information:**

Mr. Roger Blackwood National Air Inc. De Winton, AB T0L 0X0 Tel: (403) 938 7582

Fax: (403) 938 7582

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877





	d (ED6) Distance From Community (mile): 5 Latitude: 50.8000°, Longitude: -113.8833°			
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:  Airport Organization	Contact Info  Mr. Roger Blackwood National Air Inc. Box 53 De Winton TOL 0X0 (403) 938 7582(403) , Fax: 938 7586			
Ownership Structure:				
Organizational Structure:	Runway Data Primary: "16-34", 2350x75 (Gravel)			
Role of Airport:	Secondary:			
Taxiway Data Primary:				
Trimary.	Apron Data			
Secondary:	Primary:			
Third:	Secondary:			
Fourth:				
	Building Data			
Landside Facility Data	ATB:			
Entrance Road:	Disability Access:			
Parking Lot:				
Fencing:	Field Electrical Centre:			

<b>□Lighting Data</b>	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Troumty 1 rotoonon,
ARCAL: Type: Windsock: 0 windsocks;	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data					
FBO: No			AC Mair	ntenance:	No
Industrial Buildings: No			Crop Sp	raying Acti	vities:
Hangars: No			Chemica	ls Stored o	n site:
Operation and Maintenanc	e Budget				
Total Annual Maintenance Budg	1997 et	1998	1999	2000	2001
Economic Activity Informa	tion				
Airport Activity Info	1007	1000	1000	2000	2001
Annual Aircraft Movements:	1997	1998	1999	2000	2001
Annual Passenger Movements:					
Commercial Airline Info	<u> </u>				
Airport Revenue Data	97 1998	3 199	90 °	2000	2001
Total Annual Revenue:		. 15			2001
Airport Expenditure Data					
Total Annual Expenditure	1997 19	998 :	1999	2000	2001

Year	Project Name	Funding Source	Description	

### AIRPORT INFORMATION REPORT - 2002 DE WINTON/SOUTH CALGARY AIRPORT (CEH4)





De Winton/South Calgary Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Mr. Jesse Knight Cordillera Petr of Canada Calgary Calgary, AB T2T 2V8 Tel: (403) 243 5326

Fax: (403) 243 0086

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

> Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3

February 18, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info			
	te From Community (mile): 7 e: 50.8167°, Longitude: -113.8167°		
Owner and Operator Info	Contact Info		
Owner: Jesse Knight	Mr. Jesse Knight		
Operator: Jesse Knight Former Ownership: No Change	Cordillera Petr of Canada Calgary 1107 - 50 Avenue SW		
Date of Change:	Calgary		
	T2T 2V8		
Airport Organization	(403) 243 5326(403) , Fax: 243 0086		
Ownership Structure:			
	Runway Data		
Organizational Structure:	Primary: "10-28", 3015x150 (Asphalt)		
	Fair condition; replacement 2010 (\$900000)		
Role of Airport:	(455555)		
	Secondary:		
Taxiway Data			
Primary:			
	Apron Data		
	Primary:		
Secondary:			
Third:	Secondary:		
Fourth:			
	Building Data		
	ATB:		
Landside Facility Data			
Entrance Road:			
	Disability Access:		
Dayling Late			
Parking Lot:			
	Field Electrical Centre:		
Fencing:			

Lighting Data	⊤Water / Sewer Data	
Primary Edgelighting:	Water Supply:	
Approach Slope Indicator 1: -	Sewage:	
Approach Slope Indicator 2: -	Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No	
ARCAL: Type:	Caveat: No	
Windsock: 0 windsocks;	Right of Way: No	
Drainage Data		
Surface:	Subsurface:	
Peak Period Info	Spring Summer Fall Winter Average	
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		





Onsite Business Data						
FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintena	nce Bu	dget				
T. I.A. IM.:	–	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	idget					
Economic Activity Inform	nation					
Airport Activity Info						
Annual Aircraft Movements		1997	1998	1999	2000	2001
Annual Passenger Movement	S:					
Commercial Airline Info						
Airport Revenue Data						
	1997	1998		1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Data						
Total Appual Exponditure	1997	199	98	1999	2000	2001
Total Annual Expenditure						

Year	Project Name	Funding Source	Description	

### AIRPORT INFORMATION REPORT - 2002 DEBOLT AIRPORT (CFG4)





DeBolt Airport Aerial Photographs taken July 24, 2002

#### **Airport Contact Information:**

Mr. Gordon Frank Manager Municipal District of Greenview Valleyview, AB T0H 3N0 Tel: (780) 524 7600

Fax: (780) 524 4307

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

	Distance From Community (mile): 1 Latitude: 55.2333°, Longitude: -118.0333°			
	, •			
Owner and Operator Info Owner: Municipal District #16 Operator: Former Ownership: Date of Change:	Contact Info  Mr. Gordon Frank Manager Municipal District of Greenview Box 1079 Valleyview T0H 3N0			
Airport Organization	(780) 524 7600(780) , Fax: 524 4307			
Ownership Structure:  Municipal District of Greenview				
	Runway Data			
Organizational Structure:	Primary: "16-34", 2931x150 (Turf) constructed 1980;			
Role of Airport:				
Provides local service.	Secondary:			
Taxiway Data Primary:				
rillialy	Apron Data			
	Primary:			
Secondary:				
Third:	Secondary:			
Fourth:				
	Building Data			
	ATB:			
Landside Facility Data				
Entrance Road: last rehabilitation 1998; good condition;	Disability Access:			
Parking Lot:				
Fencing:	Field Electrical Centre:			
i chang.				

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No
ARCAL: Type:	Caveat: No Right of Way: No
Windsock: 1 windsocks; replacement 2002	<b>3</b> • • • • • • • • • • • • • • • • • • •

□ Drainage Data	
Surface:	Subsurface:

Spring	Summer	Fall	Winter	Average
2				
	2	2	2	2





Onsite Business Data					
FBO: No			AC Mair	ntenance:	No
Industrial Buildings: No			Crop Sp	oraying Act	ivities:
Hangars: No			Chemica	ıls Stored o	on site:
Operation and Maintenance	_	1000	1000	2000	2001
Total Annual Maintenance Budge	1997 t	1998	1999	2000	2001
Economic Activity Informati	on				
Airport Activity Info					
All port Activity IIIIo	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	7 1998	199	90	2000	2001
Total Annual Revenue:	1530				2001
Airport Expenditure Data					
	997 19	98 1	.999	2000	2001
Total Annual Expenditure					

Year	Project Name	Funding Source	Description
1987		Provincial	Complete airfield lighting
1986		Provincial	Airfield lighting installation
1985		Provincial	Grading work
1984		Provincial	Land acquisistion (\$68,900) and surveys

### AIRPORT INFORMATION REPORT - 2002 DEL BONITA/WHETSTONE INT'L AIRPORT (CEQ4)





Del Bonita/Whetstone Int'l Airport Aerial Photographs taken August 13, 2002

#### **Airport Contact Information:**

Montana Aeronautics Helena, MT 59604 Tel: (406) 444 2506

Fax: (406) 444 2519

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
	Distance From Community (mile): 2 Latitude: 49.0000°, Longitude: -112.7667°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Montana Aeronautics P.O. Box 5178 Helena 59604 (406) 444 2506(406) , Fax: 444 2519
Airport Organization	
Ownership Structure:	
	□ Runway Data
Organizational Structure:	Primary: "07-25", 4200x60 (Turf) Poor condition; replacement 2005 (\$6000)
Role of Airport:	
Customs Clearance	Secondary:
□ Taxiway Data	
Primary:	
,	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	┌Building Data
	ATB:
Landside Facility Data	
Entrance Road:	
	Disability Access:
Parking Lot:	
Fencing: type 3' farm;	Field Electrical Centre:

<b>□Lighting Data</b>	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 1 windsocks; fair condition	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Consite Business Data ——					
FBO: No			AC Mai	ntenance:	No
Industrial Buildings: No			Crop Sp	oraying Ac	tivities: Temporary
Hangars: No	Hangars: No Chemicals				on site:
Operation and Maintenance	Budget -				
Total Annual Maintenance Budge	1997 t	1998	1999	2000	2001
Economic Activity Informati	ion				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
Total Annual Revenue:	7 1998	3 199	99	2000	2001
Airport Expenditure Data	997 19	98 1	1999	2000	2001
Total Annual Expenditure					

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 DIDSBURY (CANADIAN SKYDIVE CENTRE) AIRPORT (CEC7)





Didsbury (Canadian Skydive Centre) Airport Aerial Photographs taken October 24, 2002

#### **Airport Contact Information:**

Mr. Randy Fewchuk Calgary, AB T2K 5H6 Tel: (403) 274 9503 Fax: (403) N/A

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info				
	e From Community (mile): 1.9 e: 51.6333°, Longitude: -114.1167°			
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Mr. Randy Fewchuk President Canadaian Skydive Centre Unit C 1107 - 78 Avenue NW Calgary T2K 5H6			
Ownership Structure:	(403) 274 9503(403) , Fax: N/A			
Organizational Structure:	Primary: "14-32", 2424x100 (Turf)			
Role of Airport:	Secondary:			
Taxiway Data Primary:	□ Apron Data			
Secondary:	Primary:			
Third:	Secondary:			
Fourth:				
	Building Data			
Landside Facility Data	ATB:			
Entrance Road:				
Parking Lot:	Disability Access:			
9 Lot	Field Electrical Centre:			
Fencing:	1.5.5 2.550.150.			

Lighting Data		┌Water / Sewer Data
Primary Edgelighting:		Water Supply: Other;
Approach Slope Indicator 1:		Sewage: good condition;
Approach Slope Indicator 2:		Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:		Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 0 windsocks; replacement		
Drainage Data		
Surface:	S	Subsurface:
Peak Period Info	Spring Summer Fall	Winter Average
Peak Apron Aircraft Parked:		
Design Aircraft for Airport		





□Onsite Business Data ──				
FBO: No		AC M	laintenance:	No
Industrial Buildings: No Crop Spraying Activities:				
Hangars: No Chemicals Stored on site:				on site:
3				
Operation and Maintenand	_			
Total Annual Maintenance Bud	1997 get	1998 1999	9 2000	2001
 ⊏Economic Activity Informa	ation			
Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo How is the Airport Vital to the	ort AME Servic ort Fire Suppre	ce: 7 ession Service: 4	1	
Airport Activity Info	1007	1000 1000	2000	2001
Annual Aircraft Movements:	1997	1998 1999	2000	2001
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data				
	997 199	8 1999	2000	2001
Total Annual Revenue:				
Airport Expenditure Data				965
Total Annual Expenditure	1997 19	998 1999	2000	2001
L COULTE INTO LAPORIUM C				

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 DOIG AIRPORT (CFX3)





Doig Airport Aerial Photographs taken August 20, 2002

#### **Airport Contact Information:**

Mr. Tom Archibald
Fire Manager
Alberta Sustainable Resource Development - Land and Forest Division
Peace River, AB T8S 1T4
Tel: (780) 624 6221
Fax: (780) 618 4350

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

> Tel: 780-452-9955 Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 18, 2003 Project No. 11451

General Info						
	Distance From Community (mile):					
Latitud	e: 56.9500°, Longitude: -119.5167°					
Owner and Operator Info	Contact Info					
Owner:	Mr. Tom Archibald					
Operator:	Fire Manager					
Former Ownership:	Alberta Sustainable Resource					
Date of Change:	Development - Land and Forest Division					
_	Provincial Building, 2nd Floor, 9621 - 96					
┌Airport Organization	Ave.					
Ownership Structure:	Peace River T8S 1T4					
	(780) 624 6221(780) Fay: 618 4350					
	Runway Data					
Organizational Structure:						
Organizational Structure.	Primary: "10-28", 3000x100 (Turf)					
	Fair condition; replacement 2008 (\$7000)					
B. L. CA:						
Role of Airport:						
	Secondary:					
⊤Taxiway Data <del>−−−−−</del>						
Primary:						
,	Apron Data					
	Primary:					
Secondary:						
Third:	Secondary:					
Fourth:						
	Building Data					
	ATB:					
Landside Facility Data	AID.					
Entrance Road:						
	Disability Access:					
Doubing Late						
Parking Lot:						
	Field Flectrical Centres					
Fancina	Field Electrical Centre:					
Fencing:						

Lighting Data	┌Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	☐ Vicinity Protection, ☐ Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
┌Peak Period Info	
Spring Summer	Fall Winter Average

eak Period Info ———	Spring	Summer	Fall	Winter	Average
_	Spring	Summer	ı alı	VVIIICEI	Average
ak Apron Aircraft Parked:					
esign Aircraft for Airport:					
	eak Period Info  ak Apron Aircraft Parked: esign Aircraft for Airport:	Spring ak Apron Aircraft Parked:	Spring Summer ak Apron Aircraft Parked:	Spring Summer Fall ak Apron Aircraft Parked:	Spring Summer Fall Winter ak Apron Aircraft Parked:





Onsite Business Data					
FBO: No			AC Mair	ntenance:	No
Industrial Buildings: No Crop Spraying Activities:					vities:
Hangars: No Chemicals Stored on site:					n site:
Operation and Maintenand	ce Budget	1998	1999	2000	2001
Total Annual Maintenance Budg		1990	1333	2000	2001
Economic Activity Informa	ntion				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	97 199	8 19	00	2000	2001
Total Annual Revenue:	<i>51</i> 199	J 19	נכ	2000	2001
Airport Expenditure Data	1997 1	998	1999	2000	2001
Total Annual Expenditure				2000	

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 DONNELLY AIRPORT (CFM4)





Donnelly Airport Aerial Photographs taken July 24, 2002

#### **Airport Contact Information:**

Ms. Lynn Pele Secretary Smoky River Regional Airport Commission Falher, AB T0H 1M0 Tel: (780) 837 2221 Fax: (780) 837 2453

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Donnelly Airport (FM4)

#### General Info

Donnelly (FM4) Municipal

Distance From Community (mile): 1.5 Latitude: 55.7167°, Longitude: -117.1000°

Contact Info

Ms. Lynn Pele

P.O. Box 210 Falher T0H 1M0

Secretary

#### Owner and Operator Info

Owner: MD of Smoky River No. 130 Operator: MD of Smoky River No. 130 Former Ownership: Province of Alberta Date of Change: September 1, 1997

#### **Airport Organization**

#### Ownership Structure:

Owned jointly by the Village of Girouxville, Village of Donnelly, Town of Falher, Town of McClennan and MD of Smoky River.

#### Organizational Structure:

Smoky River Airport Commission consisting of a representative from each municipality and one member at large appointed by the MD MD is the administrative hody

#### Role of Airport:

A community airport home to three hangars. Utilized by Smoky River Air Cadets, aerial crop sprayers and medevac

#### **Taxiway Data**

Primary: "A"; (Asphalt)

constructed 1979; last rehabilitation 2000; Good condition; replacement 2014 (\$53000)

Secondary: ---

Third: ---

Fourth: ---

**Runway Data** 

Primary: "07-25", 2953x75 (Asphalt)

constructed 1979; last rehabilitation 2000; Good condition; replacement 2014

Smoky River Regional Airport Commission

(780) 837 2221(780), Fax: 837 2453

(\$391000)

Secondary: ---

#### Landside Facility Data

Entrance Road: ---

Parking Lot: ---

Fencing: type 4' barded wire;

#### **Apron Data**

Primary: "1"; 262x132 (Asphalt)

constructed 1979; last rehabilitation 2000; good condition; replacement 2014

(\$135000)

Secondary: ---

#### **Building Data**

ATB: size 42x20; type trailer; constructed 1983; last rehabilitation 2001; good condition;

Disability Access: ---

Field Electrical Centre: ---

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Donnelly Airport (FM4)

		` `	
	<b>.</b>		
Lighting	Data		

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1979; last rehabilitation 200

good condition;

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1979; last rehabilitation 2000; good

condition;

Water / Sewer Data

Water Supply: Well; good condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: Yes

**Drainage Data** 

Surface: good condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

---





### Donnelly Airport (FM4)

**Onsite Business Data** 

FBO: No		AC Maintena	nce: No	
Industrial Buildings: No		Crop Sprayin	g Activities:	Temporary; 2; DIS Holdings, Loyd Haffey
Hangars: Yes, 3; Gordon McKinnon Motors, Velocity North	, Lamert	Chemicals Sto	ored on site:	None
Operation and Maintenance B	•			
Total Annual Maintenance Budget	1997 1998	1999 20	00 2001	
Economic Activity Information	1			
Major Economic Industries in Regio How is the Airport Vital to the Regio Services/Recreation			:	
Airport Activity Info	1997 1998	1999 200	00 2001	
Annual Aircraft Movements:	1997 1990	1999 200	2001	_
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data  1997	1998 1	999 2000	2001	
Total Annual Revenue:	1550 1	2000	2001	_
Airport Expenditure Data	7 1000	1000 300	)O 300	
Total Annual Expenditure	7 1998	1999 200	00 200	<u>,,                                    </u>

## Donnelly Airport (FM4)

Year	Project Name	Funding Source	Description
2000		Provincial	Pavement overlay
1991		Provincial	Purchase and install NDB, DME and radio equipment building
1989		Provincial	Slurry seal runway
1984		Provincial	Terminal Building
1982		Provincial	Towards new terminal building
1979		Provincial	Construction, paving and lighting
1978		Provincial	Land acquisition

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 DRAYTON VALLEY INDUSTRIAL AIRPORT (CER3)





Drayton Valley Industrial Airport Aerial Photographs taken October 08, 2002

#### **Airport Contact Information:**

Mr. Manjeet Saran Town Engineer Town of Drayton Valley Drayton Valley, AB T7A 1A1 Tel: (780) 542 5327

Fax: (780) 542 5327

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Drayton Valley Industrial Airport (ER3)

**General Info** 

Drayton Valley Industrial (ER3)

Municipal

Distance From Community (mile): 2.5 Latitude: 53.2667°, Longitude: -114.9667°

Owner and Operator Info

Owner: Town of Drayton Valley Operator: Town of Drayton Valley Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Owned by the Town of Drayton Valley

Organizational Structure:

Council/Town Engineer/Airport Manager(Contracted part-time)

Role of Airport:

Services private and industry uses.

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1974; Fair condition; replacement 2006 (\$60000)

Secondary: "B"; (Asphalt)

constructed 1974; Fair condition; replacement 2006 (\$60000)

Third: "C"; (Asphalt)

constructed 1995; Good condition;

replacement 2010 (\$18000)

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 30ft; type gravel; fair condition;

Parking Lot: size 100x50ft; type gravel; fair

condition;

Fencing: size 4ft; type barb wire;

Contact Info

Mr. Manjeet Saran Town Engineer

Town of Drayton Valley

Box 6837 Drayton Valley T7A 1A1

(780) 542 5327(780), Fax: 542 5753

**Runway Data** 

Primary: "14-32", 5066x75 (Asphalt)

constructed 1974; Fair condition; replacement 2006 (\$524000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1974; fair condition; replacement 2005 (\$150000)

Secondary: "11"; (Asphalt)

constructed 1974; fair condition; replacement 2005 (\$60000)

**Building Data** 

ATB: size 24x40ft; type wood; constructed 1978;

last rehabilitation 1994; good condition;

Disability Access: ---

Field Electrical Centre: size 6x6; type tool shed;

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Drayton Valley Industrial Airport (ER3)

## Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1981; fair condition; replacement 2005 (\$181000)

Approach Slope Indicator 1: AP (Abbreviated PAPI - Aircraft up

10')

good condition;

Approach Slope Indicator 2: AP (Abbreviated PAPI - Aircraft up

10')

good condition;

ARCAL: Type: "J"; freq 122.8

Windsock: 1 windsocks;

constructed 1974; fair condition; replacement 2

#### Water / Sewer Data

Water Supply: Well; constructed 1974; fair

condition;

Sewage: ---

#### Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: ---

# Peak Period Info Spring Summer Fall Winter Peak Apron Aircraft Parked:

Design Aircraft for Airport:

--

Average





### Drayton Valley Industrial Airport (ER3)

-Onoita Businasa Data					
Onsite Business Data			46.14	. ,	N.
FBO: No			АС Ма	intenance:	No
Industrial Buildings: No			Crop S	Spraying Ac	tivities:
Hangars: Yes, 6;			Chemic	als Stored	on site:
Operation and Maintenan	ce Budget	-			
-	1997	1998	1999	2000	2001
Total Annual Maintenance Bud	lget				
Economic Activity Inform	ation				
Major Economic Industries in Gen plant)	Region: Oil	& Gas/For	estry/Pow	er Generat	ion (Co-
How is the Airport Vital to the	Region: Fo	r recreatio	nal and in	dustrial pu	rposes
Airport Activity Info					
All port Activity IIIIo	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements	:				
—Commonaial Airlina Info—					
Commercial Airline Info					
Airport Revenue Data					
1	997 19	98 1	.999	2000	2001
Total Annual Revenue:					-
Airport Expenditure Data					
	1997	1998	1999	2000	2001
Total Annual Expenditure					

### Drayton Valley Industrial Airport (ER3)

#### **Historic Capital Expenditures** Year Project Name **Funding Source** Description Pave connecting taxiway between aircraft 1995 Provincial parking aprons 1987 Provincial Supply Radio Equipment Building Supply and install DME 1987 Provincial Purchase and install of NDB 1986 Provincial Terminal Building 1984 Provincial 1983 Terminal Building Provincial 1981 Provincial Reconstruction of runway to 4000' 1976 Provincial Construction 1975 Provincial Construction 1973 Federal Construction 1972 Provincial Land Purchase

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 DRUMHELLER MUNICIPAL AIRPORT (CEG4)





Drumheller Municipal Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Mr. Mark Kinniburgh City of Drumheller Drumheller, AB T0J 0Y3 Tel: (403) 823 6300

Fax: (403) 823 7739

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133

Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Drumheller Municipal Airport (EG4)

**General Info** 

Drumheller Municipal (EG4) Distance From Community (mile): 3

Municipal Latitude: 51.5000°, Longitude: -112.7500°

Owner and Operator Info

Owner: ---

Operator: Fox Coulee Aviation Inc.

Former Ownership: --- Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town

Organizational Structure:

Commision (Mayor and 5 members appointed by council)

Role of Airport:

GA, Satellite School, Aerial Applicators

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1968; last rehabilitation 1988; Poor condition; replacement 2004 (\$35000)

Secondary: "B"; (Asphalt)

Poor condition; replacement 2004

(\$30000)

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 2 lane; type Gravel; good

condition;

Parking Lot: size 10; type Gravel; good condition;

Fencing: ---

Contact Info

Fox Coulee Aviation Inc.

Box 1208 Drumheller T0J 0Y0

(403) 823 3000(403), Fax: 823 3666

Runway Data

Primary: "16-34", 3500x75 (Asphalt)

constructed 1968; last rehabilitation 1988; Fair condition; replacement 2004

(\$473000)

Secondary: ---

**Apron Data** 

Primary: "Main"; 446x128 (Asphalt)

constructed 1968; last rehabilitation 1988; poor condition; replacement 2004

(\$112000)

Secondary: ---

**Building Data** 

ATB: size 2500; type wood frame; constructed

1980; good condition; replacement 2020

(\$100000)

Disability Access:

Field Electrical Centre: constructed 1984; good

condition; replacement 2015

(\$150000)

## Drumheller Municipal Airport (EG4)

Lighting Data		Water / Sewer Data
	nreshold and Runway End) ructed 1975; last rehabilitation 198- condition; replacement 2015 (\$202	Water Supply: Other; good condition;
Approach Slope Indicator 1:		Sewage:
Approach Slope Indicator 2:		Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No
		Caveat: No Right of Way: No
Drainage Data		
Surface:	Subsurfa	ace:
Peak Period Info	Spring Summer Fall W	inter Average
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		





### Drumheller Municipal Airport (EG4)

Onsite Business Data							
FBO: Yes,;				AC Ma	intenance:	No	
Industrial Buildings: No				Crop S	Spraying Ac	tivities: Perm	nanent; 2;
Hangars: Yes, ;				Chemic	als Stored	on site: yes	
─Operation and Mainten	ance B	u <b>dget</b> – 1997	1998	1999	2000	2001	
Total Annual Maintenance	Budget						
Economic Activity Info	rmation	1					
Airport Activity Info		1997	1998	1999	2000	2001	
Annual Aircraft Movemer	nts:	1337	1330	1333	2000	2001	
Annual Passenger Moveme	nts:						
Commercial Airline Inf	о						
Airport Revenue Data	1997	1998	1	.999	2000	2001	
Total Annual Revenue:							
Airport Expenditure Da	a <b>ta</b> 1997	19	98	1999	2000	2001	
Total Annual Expenditure							

## Drumheller Municipal Airport (EG4)

Year	Project Name	Funding Source	Description
1990		Provincial	Parking apron repairs
1988		Provincial	Slurry seal runway
1987		Provincial	Purchase and install DME
1986		Provincial	Install NDB
1985		Provincial	Purchase NDB
1984		Provincial	Upgrade lighting
1984		Provincial	Final payment on paving contract
1983		Provincial	Expand development area, overlay existing pavement and extend runwayby 500'
1980		Provincial	Additional development lots
1980		Provincial	Terminal Building
1975		Provincial	Airport lighting
1973		Provincial	Paving runway, taxiway and apron
1968		Provincial	Contruction of gravel runway, taxiway and apron

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 DRUMHELLER/OSTERGARD'S AIRPORT (CDO2)





Drumheller/Ostergard's Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Fox Coulee Aviation Inc. Drumheller, AB T0J 0Y0 Tel: (403) 823 3000

Fax: (403) 823 3666

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
	nce From Community (mile): 10 de: 51.4963°, Longitude: -112.7486°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:  Airport Organization Ownership Structure:	Contact Info  Mr. Mark Kinniburgh City of Drumheller 703 - 2 Avenue W Drumheller T0J 0Y3 (403) 823 6300(403) , Fax: 823 7739
Organizational Structure:	Runway Data Primary: "12-30", 2400x75 (Turf)
Role of Airport:	Secondary:
Taxiway Data Primary:	☐ Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	Politalia a Poto
	Building Data
Landside Facility Data	ATB:
Entrance Road:	
Entrance Road:	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

<b>□Lighting Data</b>	┌Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	7.5, 1.5.5.5,
ARCAL: Type: Windsock:	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
┌Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data						
FBO: No				AC Ma	aintenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintenar	nce Bu	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	dget	1997	1990	1999	2000	
Economic Activity Inforn	nation	-				
Airport Activity Info		1997	1998	1999	2000	2001
Airport Activity Info  Annual Aircraft Movements		1997	1998	1999	2000	2001
	:	1997	1998	1999	2000	2001
Annual Aircraft Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	:	1997		1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info   Airport Revenue Data  Total Annual Revenue:	: s:					
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	: s:					

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 EDMONTON CITY CENTRE AIRPORT (CYXD)





Edmonton City Centre Airport Aerial Photographs taken October 15, 2002.

#### **Airport Contact Information:**

Mr. Doug Francoeur Airport Manager City Centre Airport Edmonton, AB T5G 2T8 Tel: (780) 477 1992

Fax: (780) 496 1756

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918 Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 18, 2003 Project No. 11451

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Edmonton City Centre Airport (YXD)

**General Info** 

Edmonton City Centre (YXD) Distance From Community (mile): 0

Passenger - Local Latitude: 53.5667°, Longitude: -113.5167°

Owner and Operator Info

Owner: City of Edmonton

Operator: Edmonton Regional Airport Authority

Former Ownership: City of Edmonton

Date of Change: June 1, 1995

**Airport Organization** 

Ownership Structure:

Land is owned by City of Edmonton, Leased to Edmonton

Airports until 2052

Organizational Structure:

---

Role of Airport:

Corporate, GA, Medevac, Small and Schedule Flights, Flight

Training

**Taxiway Data** 

Primary: "ALPHA"; (Asphalt)

last rehabilitation 1999; Good condition;

replacement 2013

Secondary: "BRAVO"; (Asphalt)

Fair condition; replacement 2006

(\$210000)

Third: "Delta"; (Asphalt)

constructed 1926; Poor condition; replacement 2003 (\$1000000)

Fourth: "CHARLIE"; (Asphalt)

Good condition; replacement 2007 (\$350000)

**Landside Facility Data** 

Entrance Road: ---

Parking Lot: size 1000 cars; type parkade;

Fencing: type chain link;

Contact Info

Mr. Doug Francoeur Airport Manager City Centre Airport

10908 - 120 Avenue Edmonton

T5G 2T8

(780) 477 1992(780), Fax: 496 1756

Runway Data

Primary: "12-30", 5868x200 (Asphalt)

constructed 1926; last rehabilitation 2000; Good condition; replacement 2015

Secondary: "16-34", 5700x200 (Asphalt)

constructed 1926; last rehabilitation 1998; Good condition; replacement

2013

**Apron Data** 

Primary: "Westside"; (Asphalt)

good condition; replacement 2013

Secondary: "East Side"; (Asphalt)

good condition; replacement 2013

**Building Data** 

ATB: ---

Disability Access: ---

Field Electrical Centre: good condition;

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Edmonton City Centre Airport (YXD)

		<b>-</b> .	
$^-$ L	iahtina	Data	

Primary Edgelighting: TE (Threshold and Runway End)

good condition;

Approach Slope Indicator 1: P2 (PAPI - Aircraft up to 25')

constructed 1999;

Approach Slope Indicator 2: P2 (PAPI - Aircraft up to 25')

constructed 1999; good condition;

ARCAL: Type: ---

Windsock: 3 windsocks;

good condition;

Water / Sewer Data

Water Supply: Municipal Service;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: fair condition; Subsurface: fair condition;

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:



**□Onsite Business Data** 

# Alberta Regional/Local Airport Inventory Study Airport Summary Report



### Edmonton City Centre Airport (YXD)

FBO: Yes, 2; ESSO Avitat; Shell	AC Maintenance: Yes, 20;							
Industrial Buildings: Yes, 3; Amisl School; WCB	Crop Spraying Activities: 0;							
Hangars: Yes, 19;			Chemic	als Stored	on site:			
<b>□</b> Operation and Maintenance	Budget =							
Operation and maintenance	1997	1998	1999	2000	2001			
Total Annual Maintenance Budge	t							
Economic Activity Informati	on							
Road Distance to Nearest Airport Sched. Pax Service: 93 Road Distance to Nearest Airport MedEvac Service: 93 Road Distance to Nearest Airport Cargo Service: 93 Road Distance to Nearest Airport AME Service: 50 Road Distance to Nearest Airport Fire Suppression Service: 93 Major Economic Industries in Region: Oil & Gas/Farming/Industry								
Airport Activity Info								
Annual Aircraft Movements:	1997	1998	1999	2000	2001			
Annual Passenger Movements:			Annual Passenger Movements:					
Commercial Airline Info								
Commercial Airline Info								
Commercial Airline Info								
 Airport Revenue Data				2000	2004			
	' 1998	19	999	2000	2001			
Airport Revenue Data  1997  Total Annual Revenue:  Airport Expenditure Data								
Airport Revenue Data  1997  Total Annual Revenue:  Airport Expenditure Data		98	1999	2000	2001			

## Edmonton City Centre Airport (YXD)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 EDMONTON/COOKING LAKE AIRPORT (CEZ3)





Edmonton/Cooking Lake Airport Aerial Photographs taken October 08, 2002

#### **Airport Contact Information:**

Mr. Andy Shanks Manager, General Aviation Services Edmonton/Villeneuve, AB T5J 2T2 Tel: (780) 890 8213

Fax: (780) 890 8213

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Edmonton/Cooking Lake Airport (EZ3)

General Info

Distance From Community (mile): 16 Edmonton/Cooking Lake (EZ3)

Latitude: 53.4333°, Longitude: -113.1167°

Owner and Operator Info

Owner: Edmonton Airports Operator: Edmonton Airports

Former Ownership: Province of Alberta

Date of Change: April 1, 1996

**Airport Organization** 

Ownership Structure:

**Edmonton Airports** 

Organizational Structure:

CEO/V.P Operations/Manager General Aviation/Airport

Manager

Role of Airport:

Sea-Plane Base

**Taxiway Data** 

Primary: "Main"; 1591x49 (Asphalt)

constructed 1987; replacement 2006

(\$190000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; fair condition;

Parking Lot: size 5600; type gravel; fair condition;

Fencing: ---

Contact Info

Mr. Andy Shanks

Manager, General Aviation Services

P.O. Box 9860 Edmonton/Villeneuve

T5J 2T2

(780) 890 8213(780), Fax: 890 8550

**Runway Data** 

Primary: "10-28", 2950x75 (Asphalt)

constructed 1984; last rehabilitation 1986; Fair condition; replacement 2006

(\$390000)

Secondary: ---

**Apron Data** 

Primary: "1"; 395x130 (Asphalt)

constructed 1985; fair condition; replacement 2006 (\$62000)

Secondary: ---

**Building Data** 

ATB: size 91; type atco trailers;

Disability Access:

Field Electrical Centre: constructed 1985;

replacement 2015 (\$150000)

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Edmonton/Cooking Lake Airport (EZ3)

#### **Lighting Data**

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1985; last rehabilitation 199 good condition; replacement 2015 (\$231

Approach Slope Indicator 1: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1985; last rehabilitatic 1996; fair condition; replacement

2010 (\$60000)

Approach Slope Indicator 2: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1985; last rehabilitatic 1996; fair condition; replacement

2010 (\$60000)

ARCAL: Type: "K"; freq 123.2

Windsock: 2 windsocks;

constructed 1985; last rehabilitation 1996; fair

condition; replacement 2005

#### Water / Sewer Data

Water Supply: Well;

Sewage: ---

#### Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: last rehabilitation 1992; fair condition; Subsurface: ---

# Peak Period Info Spring Summer Fall Winter Average Peak Apron Aircraft Parked: Design Aircraft for Airport: ----



Onsite Business Data

## Alberta Regional/Local Airport Inventory Study Airport Summary Report



### Edmonton/Cooking Lake Airport (EZ3)

FBO: No			AC Ma	intenance:	Yes, 2; Maint	tenance Bldg; Garag
Industrial Buildings: Yes, 2; Maintel Garage	Crop Spraying Activities:					
Hangars: No			Chemic	als Stored	on site:	
Operation and Maintenance B	Sudget -					
Total Annual Maintenance Budget	1997	1998	1999	2000	2001	
Economic Activity Information	n					
Airport Activity Info	1997	1998	1999	2000	2001	
Annual Aircraft Movements:						
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data						
1997	1998	19	999	2000	2001	
Total Annual Revenue:						
Airport Expenditure Data						
Total Annual Expenditure	7 19	98	1999	2000	2001	
Total Allinda Experiatore						

#### Edmonton/Cooking Lake Airport (EZ3)

#### **Historic Capital Expenditures** Project Name **Funding Source** Description Year 1999 Provincial Extension, float plane ramp 1994 Provincial Development area upgrading 1994 Provincial Floatplane base depth survey 1993 Provincial Drainage improvements 1992 Provincial Upgrade electrical distribution system Utility upgrading 1991 Provincial 1990 Provincial Development area upgrading 1989 Provincial Taxiway paving 1988 Provincial Development area paving Purchase and installation of AWOS 1988 Provincial 1987 Provincial Development area improvements 1986 Provincial Completion of maintnance garage Completion of runway paving 1986 Provincial Purchase and install of airfield lighting 1986 Provincial Grading, paving and construction of 1985 Provincial maintenance garage Land purchase and survey 1984 Provincial 1982 Site clean up and dock installation Provincial 1981 Provincial Clearing and miscellaneous work

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 EDMONTON/GARTNER AIRPORT (CFQ7)**





Edmonton/Gartner Airport Aerial Photographs taken July 04, 2002

#### **Airport Contact Information:**

Mr. Lionel Gartner Nisku, AB T9E 7S7 Tel: (780) 980-2483 Fax: (780) N/A

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info				
Edmonton/Gartner (FQ7) Distance Latitud	nce From Community (mile): 15 de: 53.2833°, Longitude: -113.4500°			
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Mr. Lionel Gartner 1609 - 8 Street Nisku T9E 7S7 (780) 980-2483(780) , Fax: N/A			
Airport Organization				
Ownership Structure:				
Organizational Structure: Role of Airport:	Primary: "09-27", 3000x50 (Turf) Good condition;			
	Secondary:			
⊤Taxiway Data				
Primary:	Apron Data			
Secondary:	Primary:			
Third:	Secondary:			
Fourth:				
	Building Data			
Landside Facility Data	ATB:			
Entrance Road:				
	Disability Access:			
Parking Lot:				
Fencing:	Field Electrical Centre:			

Lighting Data	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Caveat, and Right of Way
ARCAL: Type: "J"; fre Windsock: 0 windsocks;	Tagin of Way.
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data								
FBO: No			AC Mai	ntenance:	No			
Industrial Buildings: No			Crop Sp	praying Act	ivities:			
Hangars: No Chemicals Stored on site:								
Operation and Maintenance	_	1000	1000	2000	2001			
Total Annual Maintenance Budge	1997 t	1998	1999	2000	2001			
Economic Activity Informati	on							
- Airmont Activity Info								
Airport Activity Info	1997	1998	1999	2000	2001			
Annual Aircraft Movements:								
Annual Passenger Movements:								
Commercial Airline Info								
Airport Revenue Data								
1997	7 1998	199	99	2000	2001			
Total Annual Revenue:								
Airport Expenditure Data								
Total Annual Expenditure	997 19	98 1	1999	2000	2001			
Total Alliadi Experialtare								

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 EDMONTON/JOSEPHBURG AIRPORT (CFB6)





Edmonton/Josephburg Airport Aerial Photographs taken October 08, 2002

#### **Airport Contact Information:**

Mr. Kevin Glebe Co-ordinator, Agriculture Services Strathcona County Sherwood Park, AB T8A 3W7 Tel: (780) 417 7130

Fax: (780) 464 0557

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Edmonton/Josephburg Airport (FB6)

**General Info** 

Edmonton/Josephburg (FB6)

Distance From Community (mile): 0.7

Latitude: 53,7333°, Longitude: -113,0833°

**Owner and Operator Info** 

Owner: Strathcona County

Operator: Strathcona County Environmental Operations

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Strathcona County

Organizational Structure:

Strathcona County/Environmental Operations/Agricultural

Services

Role of Airport:

To provide a transportation node for our Industrial Heartland.

**Taxiway Data** 

Primary: "approach ramp";

constructed 1990; Fair condition; replacement 2005 (\$18000)

Secondary: "Taxiway B"; 400x28 (Asphalt)

constructed 1990; last rehabilitation 2002; Fair condition; replacement 2005

Third: "Taxiway C"; 300x20 (Asphalt)

constructed 1990; Fair condition; replacement

2005 (\$13000)

Fourth: "Taxiway D"; 300x20 (Asphalt)

constructed 1990; Fair condition; replacement 2005 (\$13000)

**Landside Facility Data** 

Entrance Road: type Gravel; constructed 1990; good

condition;

Parking Lot: type Gravel; constructed 1990; good

condition;

Fencing: type Chain Link;

Contact Info

Mr. Kevin Glebe

Co-ordinator, Agriculture Services

Strathcona County 2001 Sherwood Drive Sherwood Park

T8A 3W7

(780) 417 7130(780), Fax: 464 0557

Runway Data

Primary: "08-26", 3000x75 (Asphalt)

constructed 1990; Fair condition; replacement 2005 (\$480000)

Secondary: ---

**Apron Data** 

Primary: ---

Secondary: ---

**Building Data** 

ATB: size 500ft square; type Atco Trailer;

constructed 1990; fair condition; replacement

2008 (\$100000)

Disability Access: ---

Field Electrical Centre: size 100 ft. square; type

Brytex Building; constructed 1990; good condition; replacement 2011 (\$150000)

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Edmonton/Josephburg Airport (FB6)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1990; good condition; replacement 2011 (\$128000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.5

Windsock: 2 windsocks;

constructed 1990; last rehabilitation 2001; good

condition; replacement 2011

Water / Sewer Data

Water Supply: Other; constructed 1991; good

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: ---

 Peak Period Info

 Spring
 Summer
 Fall
 Winter
 Average

 Peak Apron Aircraft Parked:
 10
 15
 6
 5
 9

 Design Aircraft for Airport:
 -- --





#### Edmonton/Josephburg Airport (FB6)

**Onsite Business Data** 

FBO: Yes, 3; Sureflight Av. Maint. Strathcona

Flying Sch, LCM

Industrial Buildings: No

Hangars: Yes, 11;

AC Maintenance: Yes, ; Sureflight Aviation

Maintenance

Crop Spraying Activities: Temporary; 2;

Chemicals Stored on site: none

**Operation and Maintenance Budget** 

1997 1998 1999 2000 2001

Total Annual Maintenance Budget

**Economic Activity Information** 

Road Distance to Nearest Airport MedEvac Service: 7

Road Distance to Nearest Airport Fire Suppression Service: 1.5

Major Economic Industries in Region: Business/Tourism/Oil & Gas Industry How is the Airport Vital to the Region: Quick transportation service to the

Industrial Heartland hub.

**Airport Activity Info** 

1997 1998 1999 2000 2001

**Annual Aircraft Movements:** 

Annual Passenger Movements:

**Commercial Airline Info** 

LCM Aviation Services (Cessna 301/401/Navajo/KingAir, Hot Shot/Charter)

Airport Revenue Data

1997 1998 1999 2000 2001

Total Annual Revenue:

**Airport Expenditure Data** 

1997 1998 1999 2000 2001

**Total Annual Expenditure** 

## Edmonton/Josephburg Airport (FB6)

Year	Project Name	Funding Source	Description	
1998		Provincial	Major crack repairs	
1991		Federal	Construction	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 EDMONTON/ST. ALBERT AIRPORT (CES3)





Edmonton/St. Albert Airport Aerial Photographs taken July 04, 2002

#### **Airport Contact Information:**

Mr. Dan Pandur Operator Snowbird Aviation Inc. St. Albert, AB T8N 1M8 Tel: (780) 418 4159

Fax: (780) 418 4159

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-452-9955

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 18, 2003 Project No. 11451

### Edmonton/St. Albert Airport (ES3)

General Info				
	stance From Community (mile): 3.5 atitude: 53.6833°, Longitude: -113.7000°			
Owner and Operator Info Owner: Proex Trading Co. Operator: Former Ownership: Date of Change:	Contact Info  Mr. Dan Pandur Operatorner Snowbird Aviation Inc. Box 11 Site 6 RR1 St. Albert			
Airport Organization Ownership Structure:	T8N 1M8 (780) 418 4159(780) , Fax: 418 4159			
Organizational Structure:	Primary: "08-26", 3200x75 (Gravel) Good condition;			
Role of Airport:	Secondary:			
Taxiway Data Primary: "A"; (Gravel) Good condition;	Apron Data			
Secondary: "ECHO"; (Gravel) Fair condition;	Primary:			
Third: "Charlie"; (Turf) Fair condition;	Secondary:			
Fourth:	- Puilding Data			
_ Landeide Escility Data	ATB:			
Entrance Road:	Disability Access:			
Parking Lot:	Disability Access.			
Fencing: size 8'; type chain link;	Field Electrical Centre:			

## Edmonton/St. Albert Airport (ES3)

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: Yes Caveat: Yes Right of Way: No
Windsock: 1 windsocks; fair condition;	
□Drainage Data	
Surface: fair condition;	Subsurface:
Peak Period Info	
_	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





### Edmonton/St. Albert Airport (ES3)

**Onsite Business Data** 

FBO: Yes, 2; Avialta Helicopters, Delta AC Maintenance: No Helicopters						
Industrial Buildings: No Crop Spraying Activities:						
Hangars: Yes, 3; Delta Helicopt Snowbird Aviation	ers, Avialta,	C	Chemicals Store	ed on site:		
☐Operation and Maintenance	e Budget					
	1997	1998	1999 2000	2001		
Total Annual Maintenance Budge	et					
Economic Activity Information	tion					
Airport Activity Info	1997	1998	1999 2000	2001		
Annual Aircraft Movements:						
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data	7 1000	1000	2000	2001		
Total Annual Revenue:	7 1998	1999	2000	2001		
Airport Expenditure Data	997 19	98 19	99 2000	2001		
Total Annual Expenditure		<i>5</i> 5 15	2000	2001		

## Edmonton/St. Albert Airport (ES3)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 EDMONTON/TWIN ISLAND AIRPARK AIRPORT (CEE6)





Edmonton/Twin Island Airpark Airport Aerial Photographs taken July 04, 2002

#### **Airport Contact Information:**

Mr. Eric Senger Airport Manager Twin Island Residents Association Sherwood Park, AB T8C 1H6 Tel: (780) 922 2596

Fax: (780) 922 5780

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info			
	ce From Community (mile): 12 e: 53.4667°, Longitude: -113.1500°		
Owner and Operator Info  Owner: Twin Island Residents Association Operator: Former Ownership: No Change Date of Change:	Contact Info  Mr. Eric Senger Airport Manager Twin Island Residents Association 1 - 52112 - RR222 Sherwood Park T8C 1H6		
Airport Organization Ownership Structure: Condominium	(780) 922 2596(780) , Fax: 922 5780		
Organizational Structure: Role of Airport: To provide service to local residents.	Runway Data  Primary: "06-24", 2900x100 (Turf) constructed 1971; Good condition;  Secondary:		
Primary: "A"; 340x80 (Turf) Good condition;	Apron Data Primary:		
Secondary:			
Third:	Secondary:		
Fourth:	Building Data		
Landside Facility Data	ATB:		
Entrance Road:	Disability Access:		
Parking Lot:			
Fencing:	Field Electrical Centre:		

Lighting Data	⊤Water / Sewer Data					
Primary Edgelighting: TE (The fair co	hreshold and Runway End) Water Supply: ondition;					
Approach Slope Indicator 1:	Sewage:					
Approach Slope Indicator 2:	Caveat, and Right of Way					
ARCAL: Type: Windsock: 1 windsocks; constructed : condition;	Vicinity Protection: No Caveat: No Right of Way: Yes  1971; last rehabilitation 1977; good					
Drainage Data						
Surface: Subsurface:						
Peak Period Info	Spring Summer Fall Winter Average					
Peak Apron Aircraft Parked:						
Design Aircraft for Airport:						





Onsite Business Data						
FBO: No				AC Maintenance: No		
Industrial Buildings: No	Crop S	Crop Spraying Activities:				
Hangars: Yes, ;			Chemi	cals Stored	on site: None	
Operation and Maintenar			200 1000	2000	2001	
Total Annual Maintenance Bud		997 19	998 1999	2000	2001	
Economic Activity Inform	ation					
Road Distance to Nearest Airport Sched. Pax Service: 5 Road Distance to Nearest Airport MedEvac Service: 5 Road Distance to Nearest Airport Cargo Service: 60 Road Distance to Nearest Airport AME Service: 5 Road Distance to Nearest Airport Fire Suppression Service: 5 Major Economic Industries in Region: Oil & Gas How is the Airport Vital to the Region: It isn't vital						
Airport Activity Info	19	97 19	98 1999	2000	2001	
Annual Aircraft Movements:						
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data	997	1998	1999	2000	2001	
Total Annual Revenue:	-		<del>-</del>			
Airport Expenditure Data						
Total Annual Expenditure	1997	1998	1999	2000	2001	

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 EDMONTON/VILLENEUVE AIRPORT (CZVL)





Edmonton/Villeneuve Airport Aerial Photographs taken July 04, 2002

#### **Airport Contact Information:**

Mr. Andy Shanks Manager, General Aviation Services Edmonton/Villeneuve, AB T5J 2T2 Tel: (780) 890 8213

Fax: (780) 890 8550

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc.

204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Edmonton/Villeneuve (ZVL) Municipal	Distance From Community (mile): 1 Latitude: 53.6667°, Longitude: -113.8500°
Owner and Operator Info	Contact Info
Owner: Edmonton Airports	Mr. Andy Shanks
Operator: Edmonton Airports	Manager, General Aviation Services
Former Ownership:	P.O. Box 9860
Date of Change:	Edmonton/Villeneuve T5J 2T2
Airport Organization	(780) 890 8213(780) , Fax: 890 8550
Ownership Structure:	
<del></del>	
	Runway Data
Organizational Structure:	Primary: "08-26", 3500x100 (Asphalt) Poor condition; replacement 2004 (\$1236000)
Role of Airport:	
'	Secondary: "16-34", 3500x100 (Asphalt) Fair condition; replacement 2006
Taxiway Data	
Primary: "A";	Augus Data
Fair condition; replacement 2006	Apron Data
	Primary:
Secondary: "B"; Fair condition; replacement 2006	
Third:	Secondary:
Fourth:	
roului:	
	Building Data
Landside Facility Data	ATB:
Entrance Road: good condition;	
	Disability Access:
Parking Lot: good condition;	
	Field Electrical Centre:
Fencing: size 4; type chain link;	

Lighting Data		Water / Se	wer Data	
Primary Edgelighting: TE (Threshold and Runway End) good condition;			Water Suppl	y:
Approach Slope Indicator 1:		Sewage:	-	
Approach Slope Indicator 2:			Vicinity Pr	otection, d Right of Way
ARCAL: Type: "K"; freq 120 Windsock: 1 windsocks; good condition;			Vicinity Pro Caveat: N Right of Wa	
□Drainage Data				
Surface: good condition;  Subsurface:				
<b>□</b> Peak Period Info <del></del>				
	Spring Summer	Fall Wi	nter Average	
Peak Apron Aircraft Parked:				
Design Aircraft for Airport:				





□Onsite Business Data ──					
FBO: No			AC Maintena	ance: No	
Industrial Buildings: No			Crop Sprayii	ng Activities:	
Hangars: No		•	Chemicals St	tored on site:	
Operation and Maintenanc	e Budget	1998	1999 2	000 2001	1
Total Annual Maintenance Budg		1990	1999 2	000 2001	
Economic Activity Informa	tion				
Airport Activity Info	1997	1998	1999 20	000 2001	
Annual Aircraft Movements:				<u></u>	
Annual Passenger Movements:					
Commercial Airline Info					]
Airport Revenue Data	97 199	8 1999	9 2000	) 2001	
Total Annual Revenue:	,, 199	<u> </u>	2000	, 2001	
Airport Expenditure Data	1997 1	998 19	999 20	000 2001	
Total Annual Expenditure	<u></u>	<del>-</del> ·			_

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 EDRA AIRPORT (CEV2)





Edra Airport Aerial Photographs taken August 08, 2002

#### **Airport Contact Information:**

Mr. Brian Stanton
W.A.O.O.

Alberta Sustainable Resource Development - Land and Forest Division
Lac La Biche, AB T0A 2C0

Tel: (780) 623 5240 Fax: (780) 623 2570

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

## Edra Airport (EV2)

General Info			
	ce From Community (mile): le: 57.8500°, Longitude: -113.2500°		
Latitud	e. 57.6500°, Longitude115.2500°		
Owner and Operator Info  Owner: Operator: Former Ownership: Date of Change:	Mr. Brian Stanton W.A.O.O. Alberta Sustainable Resource Development - Land and Forest Division Box 450 Lac La Biche		
Airport Organization Ownership Structure:	T0A 2C0 (780) 623 5240(780) , Fax: 623 2570		
Organizational Structure:	Runway Data Primary: "12-30", 3200x100 (Turf)		
Role of Airport:	Secondary:		
Taxiway Data Primary:	Apron Data		
Secondary:	Primary:		
Third:	Secondary:		
Fourth:			
	Building Data		
Landside Facility Data	ATB:		
Entrance Road:			
	Disability Access:		
Parking Lot:			
Fencing:	Field Electrical Centre:		

### Edra Airport (EV2)

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 0 windsocks;	
□ Drainage Data	
Surface:	Subsurface:
Peak Period Info Spring Summer	Fall Winter Average





### Edra Airport (EV2)

□Onsite Business Data —				
FBO: No		A	AC Maintenance	: No
Industrial Buildings: No		(	Crop Spraying A	ctivities:
Hangars: No		С	hemicals Storec	on site:
Operation and Maintenance	e Budget	1998	1999 2000	2001
Total Annual Maintenance Budg		1990	1999 2000	2001
Economic Activity Informa	tion			
Airport Activity Info	1997	1998 1	.999 2000	2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	97 199	8 1999	2000	2001
Total Annual Revenue:	97 199	0 1333	2000	2001
Airport Expenditure Data	1997 1	998 199	99 2000	2001
Total Annual Expenditure	<u> </u>			

## Edra Airport (EV2)

Historic	Historic Capital Expenditures					
Year	Project Name	Funding Source	Description			

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 EDSON AIRPORT (CYET)





Edson Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Gerald Pellerin Airport Manager Town of Edson Edson, AB T7E 1T7 Tel: (780) 723 4010

Fax: (780) 723 3508

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

> Tel: 780-452-9955 Fax: 780-413-9918



Prepared by:

Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 18, 2003 Project No. 11451

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Edson Airport (YET)

General Info

Distance From Community (mile): 0 Edson (YET) Latitude: 53.5833°, Longitude: -116.4667°

Owner and Operator Info

Owner: Town of Edson Operator: Gerald Pellerin

Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Edson

Organizational Structure:

Town Council/Town Manager/Airport Manager

Role of Airport:

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1985; Poor condition; replacement 2003 (\$53000)

Secondary: "B"; (Asphalt)

constructed 1985; Poor condition; replacement 2003 (\$48000)

Third: "C"; (Asphalt)

constructed 1985; Poor condition; replacement 2003 (\$48000)

Fourth: "D"; (Asphalt)

constructed 1985; Poor condition;

replacement 2003 (\$51000)

**Landside Facility Data** 

Entrance Road: type gravel; constructed 1980; fair

condition;

Parking Lot: type gravel; constructed 1980; fair

condition;

Fencing: size 4ft; type barb wire;

Contact Info

Mr. Gerald Pellerin Airport Manager Town of Edson P.O. Box 6300

Edson T7E 1T7

(780) 723 4010(780), Fax: 723 3508

**Runway Data** 

Primary: "07-25", 6000x100 (Asphalt)

constructed 1976; last rehabilitation 1982; replacement 2003 (\$1100000)

Secondary: ---

**Apron Data** 

Primary: "A"; (Asphalt)

constructed 1985; poor condition; replacement 2003 (\$248000)

Secondary: "B"; (Asphalt)

poor condition; replacement 2003

(\$180000)

**Building Data** 

ATB: constructed 1980; fair condition;

Disability Access: ---

Field Electrical Centre: ---

## Edson Airport (YET)

Design Aircraft for Airport:

Lighting Data			Water / Se	wer Data —	$\neg$
	nreshold and Runway E ructed 1978; fair conditi rement 2005 (\$340000)	Water Suppl	y: Well; good condition;		
Approach Slope Indicator 1:	V1 (2-BAR VASIS - Airc fair condition; replacem (\$60000)	. a. t a.p to =	Sewage:	_	
Approach Slope Indicator 2:	V1 (2-BAR VASIS - Airc	raft up to 1	Vicinity Pr	otection	
	constructed 1985; fair of	condition;	•	d Right of Way	
	replacement 2006 (\$60	1000)	Vicinity Prof	tection: Yes	
ARCAL: Type: "K"; freq 123.2			Caveat: No Right of Wa		
Windsock: 2 windsocks;	•		ragne or wo	iy. 140	
	1978; fair condition;				
Drainage Data					
Surface:		Subsurface	2:		
Peak Period Info		E II			
	Spring Summer	Fall Winte	er Average		
Peak Apron Aircraft Parked					





### Edson Airport (YET)

□Onsite Business Data ──				
FBO: No			AC Maintena	ance: No
Industrial Buildings: No Crop Spraying Activities:				
Hangars: Yes, 2; Highlands, Te	bacha		Chemicals St	ored on site:
Operation and Maintenanc	e Budget - 1997	1998	1999 20	000 2001
Total Annual Maintenance Budg		1990	1999 20	2001
Economic Activity Informa	tion			
Airport Activity Info	1997	1998	1999 20	000 2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	97 1998	3 199	9 2000	2001
Total Annual Revenue:	1990	199	<i>5</i> 2000	2001
Airport Expenditure Data	1007 10	100 11	200	00 2001
Total Annual Expenditure	1997 19	998 19	999 20	2001

## Edson Airport (YET)

Year	Project Name	Funding Source	Description
1991		Provincial	Expansion of airfield lighting
1986		Provincial	Installation of VASIS
1986		Provincial	Purchase and install of NDB
1986		Provincial	Purchase and install of DME
1982		Provincial	Runway overlay
1981		Provincial	Taxiway and miscellaneous work
1979		Provincial	Repair runway pavement
1978		Provincial	Installation of airfield lighting
1978		Provincial	Terminal Building
1976		Provincial	Grading, base and paving

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 ELK POINT AIRPORT (CEJ6)





Elk Point Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Mr. Myron Goyan Manager Elk Point Municipal Airport Commission Elk Point, AB T0A 1A0 Tel: (780) 724 3810

Fax: (780) 724 2762

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Elk Point Airport (EJ6)

General Info

Elk Point (EJ6)

Distance From Community (mile): 5

Latitude: 53.9000°, Longitude: -110.7667°

Mr. Myron

Contact Info

Myron Goyan

Owner and Operator Info

Owner: Town of Elk Point Operator: Town of Elk Point Former Ownership: ---

Former Ownership: --- Manager
Date of Change: --- Elk Point Municipal Airport Commission

Airport Organization Box 448
Elk Point
T0A 1A0

Alberta Provincial Government

Ownership Structure:

Organizational Structure:

Town of Elk Point/County of St. Paul #49

Role of Airport:

---

Taxiway Data

Primary: "A"; (Asphalt)

constructed 1984; replacement 1987

(\$30000)

Secondary: ---

Third: ---

Fourth: ---

**Apron Data** 

Secondary: ---

**Runway Data** 

Primary: "1";

constructed 1984; fair condition; replacement 2007 (\$67000)

(780) 724 3810(780), Fax: 724 2762

constructed 1984; Fair condition; replacement 2007 (\$393000)

Primary: "07-25", 4492x75 (Asphalt)

Secondary: ---

**Landside Facility Data** 

Entrance Road: type paved; fair condition;

replacement 2007 (\$21000)

Parking Lot: type paved; fair condition; replacement

2007 (\$16000)

Fencing: size 4'; type barb wire;

**Building Data** 

ATB: type trailer; constructed 1983; good

condition;

Disability Access: ---

Field Electrical Centre: type tool shed;

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Elk Point Airport (EJ6)

Lighting	Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1984; fair condition; replacement 2007 (\$156000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 2 windsocks;

fair condition; replacement 2007

#### Water / Sewer Data

Water Supply: Well; constructed 1984; good

condition;

Sewage: ---

#### <sup>−</sup>Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: fair condition; Subsurface: ---

### Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

---





### Elk Point Airport (EJ6)

Onsite Business Data				
FBO: No		AC M	aintenance:	No
Industrial Buildings: No		Crop	Spraying Ac	tivities:
Hangars: Yes, 2;		Chemi	cals Stored	on site:
─Operation and Maintenance I	Budget			
	1997	1998 1999	2000	2001
Total Annual Maintenance Budget				
Economic Activity Information	n —			
How is the Airport Vital to the Reg Companies travelling to the area	ion: For Me	dical Emergeno	cies and Oil	
Airport Activity Info	1997 1	1998 1999	2000	2001
Annual Aircraft Movements:	1997	1990 1999	2000	2001
Annual Passenger Movements:				
Commercial Airline Info				
<del></del>				
Airport Revenue Data				
1997	1998	1999	2000	2001
Total Annual Revenue:				
Airport Expenditure Data				
199	97 1998	1999	2000	2001
Total Annual Expenditure				

#### Elk Point Airport (EJ6)

#### **Historic Capital Expenditures** Year Project Name **Funding Source** Description 1996 Provincial Restore pavement markings 1995 Provincial Completion of runway extension 1995 Provincial Fog seal asphalt surfaces (excluding extension) Design work and purchase of additional 1994 Provincial airfiled lighting Prelim survey for runway extension 1993 Provincial 1987 Purchase and install of NDB Provincial 1987 Provincial Purchase and install of DME 1987 Provincial Install Radio Equipment Building 1984 Provincial Paving and lighting 1984 terminal Building Provincial 1983 Provincial Land purchase (\$101,000) and grading

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 EMBARRAS AIRPORT (CFN4)





Embarras Airport Aerial Photographs taken August 07, 2002

#### **Airport Contact Information:**

Mr. Brian Stanton W.A.O.O.

Alberta Sustainable Resource Development - Land and Forest Division Lac La Biche, AB T0A 2C0

Tel: (780) 623 5240 Fax: (780) 623 2570

Prepared for:



**Aviation Strategy Action Group** 

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info						
	N4) Distance From Community (mile): 34 Latitude: 58.2000°, Longitude: -111.3833°					
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:  Airport Organization	Mr. Brian Stanton W.A.O.O. Alberta Sustainable Resource Development - Land and Forest Division Box 450 Lac La Biche					
Ownership Structure:	T0A 2C0 (780) 623 5240(780) , Fax: 623 2570					
Organizational Structure:	Primary: "11-29", 4400x200 (Turf)					
Role of Airport:	Secondary:					
Taxiway Data						
Primary:	Apron Data					
	Primary:					
Secondary:	rillidiy					
Third:	Secondary:					
Fourth:						
	Building Data					
□ Landside Facility Data	ATB:					
Entrance Road:						
Littrafice Road	Disability Access:					
Parking Lot:						
Fencing:	Field Electrical Centre:					

<b>□Lighting Data</b>	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Troumty 1 rotoonon,
ARCAL: Type: Windsock: 0 windsocks;	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Consite Business Data ——					
FBO: No			AC Mai	intenance:	No
Industrial Buildings: No			Crop S	praying Act	tivities:
Hangars: No			Chemic	als Stored	on site:
Operation and Maintenance	_	1000	1000	2000	2004
Total Annual Maintenance Budget	1997	1998	1999	2000	2001
Economic Activity Information	on —				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
- Airmort Boyonus Data					
Airport Revenue Data	1998	19	99	2000	2001
Total Annual Revenue:					
Airport Expenditure Data	07 :-		1000	2225	2024
Total Annual Expenditure	97 19	98	1999	2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 EMPRESS AIRPORT (CYEA)





Empress Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Ms. Wendi Miller Secretary Village of Empress Empress, AB T0J 1E0 Tel: (403) 565 3938

Fax: (403) 565 2010

#### Prepared for:



**Aviation Strategy Action Group** 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### **Empress Airport (YEA)**

**General Info** 

Empress (YEA) Distance From Community (mile): 2
Municipal Latitude: 50.9333°, Longitude: -110.0167°

Owner and Operator Info

Owner: Village of Empress
Operator: Village of Empress

Former Ownership: ---Date of Change: ---

**Airport Organization** 

Ownership Structure:

Village Council

Organizational Structure:

Municipal Government

Role of Airport:

Crop spray hanger on site/ Emergency, Medical and

Recreation

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1983; last rehabilitation 1999;

Fair condition; replacement 2008 (\$37000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

**Entrance Road:** 

Parking Lot: size 100x100; type gravel;

Fencing: size 4ft; type 3 strand barb wire;

replacement 2020

Contact Info

Ms. Wendi Miller

Secretary

Village of Empress

P.O. Box 159

Empress

T0J 1E0

(403) 565 3938(403) , Fax: 565 2010

Runway Data

Primary: "11-29", 2950x75 (Asphalt)

constructed 1983; last rehabilitation 1999; Fair condition; replacement 2008

(\$410000)

Secondary: ---

**Apron Data** 

Primary: "Main"; 300x150 (Asphalt)

constructed 1983; last rehabilitation 1999; fair condition; replacement 2008

(\$67000)

Secondary: ---

**Building Data** 

ATB: ---

Disability Access:

Field Electrical Centre: size 8x8; type wood frame;

constructed 1983; fair

condition;

### Empress Airport (YEA)

Lighting Data	⊤Water / Sewer Data		
Primary Edgelighting: TE (Threshold and Runway End) constructed 1983; good condition; replacement 2013 (\$158000)	Water Supply:		
Approach Slope Indicator 1:	Sewage:		
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way		
ARCAL: Type: "K"; freq 123.2	Vicinity Protection: No Caveat: No Right of Way: No		
Windsock: 1 windsocks; constructed 1983; last rehabilitation 2002; good condition: replacement 2013			

D	rai	in	ลต	e	D	ata	
$\boldsymbol{-}$	·		ч	·	$\boldsymbol{-}$	utu	

Surface: constructed 1983; good condition; Subsurface: constructed 1983; good condition;

Peak Period Info					
	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





### Empress Airport (YEA)

**□Onsite Business Data** 

FBO: No			AC Ma	intenance:	No
Industrial Buildings: No			Crop S	praying Ac	tivities: Temporary
Hangars: Yes, 1; Town of Empress			Chemic	als Stored	on site:
□ Operation and Maintenance Bu	udaet				
	1997	1998	1999	2000	2001
Total Annual Maintenance Budget					
Economic Activity Information					
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	1998	199	99	2000	2001
Total Annual Revenue:	1,7,0	17.		2000	
Airport Expenditure Data				_	
Total Annual Expenditure	1998	3 1	1999	2000	2001
Total Annual Expenditure					

## Empress Airport (YEA)

Year	Project Name	Funding Source	Description
1999		Provincial	Fog coat
1995		Provincial	Fog seal asphalt surfaces
1994		Provincial	Fog seal asphalt surfaces
1984		Provincial	Paving and lighting
1984		Provincial	Terminal Building
1983		Provincial	Land development and grading

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 EMPRESS/MCNEILL CONOCO AIRPORT (CFL2)





Empress/McNeill Conoco Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Mr. David Pidlisary
Team Leader
Conoco Canada Ltd, Empress Plant
Medicine Hat, AB T1A 7N2
Tel: (403) 838 8338

Fax: (403) 838 3969

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Empress/McNeill Conoco (FL2)	Distance From Community (mile): Latitude: 50.6833°, Longitude: -110.0500°
Owner and Operator Info Owner: Conoco Operator: Conoco Former Ownership: Date of Change: March 1, 2000	Contact Info  Mr. David Pidlisary(?)  Team Leader  Conoco Canada Ltd, Empress Plant  Box 1347  Medicine Hat
Airport Organization	T1A 7N2 (403) 838 8338(403) , Fax: 838 3969
Ownership Structure:	(403) 636 6336(403), Fax. 636 3909
Organizational Structure:	Primary: "02-20", 3500x75 (Asphalt) Good condition; replacement 2013 (\$463000)
Role of Airport: Business Use	Secondary:
Taxiway Data Primary:	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data  ATB:
Landside Facility Data	AID
Entrance Road:	
	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

<u> </u>	·	
Lighting Data		─────────────────────────────────────
Primary Edgelighting: RR (Ret fair con		Water Supply:
Approach Slope Indicator 1:	-	Sewage:
Approach Slope Indicator 2:	-	Vicinity Protection, Caveat, and Right of Way
4004L T		Vicinity Protection: No Caveat: No
ARCAL: Type:		Right of Way: No
Windsock: 2 windsocks; good condition	);	
⊤Drainage Data <del></del>		
Surface: poor condition;	Sub	surface:
Peak Period Info	Spring Summer Fall	Winter Average
Peak Apron Aircraft Parked:	-	
Design Aircraft for Airport:		





Onsite Business Data							
FBO: No			AC Mainten	ance: No			
Industrial Buildings: No Crop Spraying Activities:							
Hangars: No	Hangars: No						
Operation and Maintenance	_	1000	1000	2000	21		
Total Annual Maintenance Budge	1997 et	1998	1999 2	2000 200	)1		
Economic Activity Information							
Airport Activity Info	1997	1998	1999 2	000 200	1		
Annual Aircraft Movements:							
Annual Passenger Movements:							
Commercial Airline Info							
Airport Revenue Data							
Total Annual Revenue:	7 1998	3 1999	9 200	0 200:			
Airport Expenditure Data							
	997 19	98 19	999 2	000 20	001		
Total Annual Expenditure							

Year	Project Name	Funding Source	Description	

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY **ASSESSMENT OF FACILITIES**

## **AIRPORT INFORMATION REPORT - 2002 FAIRVIEW AIRPORT (CEB5)**





Fairview Airport Aerial Photographs taken July 23, 2002

#### **Airport Contact Information:**

Mr. Kevin Miner C.A.O. M.D. of Fairview Fairview, AB T0H 1L0 Tel: (780) 835 4903

Fax: (780) 835 3131

#### Prepared for:



**Aviation Strategy Action Group** 

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133

Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Fairview Airport (EB5)

General Info

Fairview (EB5) Distance From Community (mile): 1.5
Municipal Latitude: 56.0833°, Longitude: -118.4333°

Owner and Operator Info

Owner: ---Operator: ---

Former Ownership: Transport Canada

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Municipal

Organizational Structure:

**Board** 

Role of Airport:

Rural Airport

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1974; last rehabilitation 2002; Good condition; replacement 2016 (\$25000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 66; type gravel; constructed

1930; last rehabilitation 1999; good

condition;

Parking Lot: type gravel; good condition;

Fencing: size 4ft; type barb wire;

Contact Info

Mr. Kevin Miner

C.A.O.

M.D. of Fairview

Box 189 Fairview T0H 1L0

(780) 835 4903(780), Fax: 835 3131

**Runway Data** 

Primary: "04-22", 3492x75 (Asphalt)

constructed 1974; last rehabilitation 2001; Good condition; replacement 2016

(\$395000)

Secondary: ---

**Apron Data** 

Primary: ---

Secondary: ---

**Building Data** 

ATB: size 12x40ft; type ATCO trailer; constructed

1985; last rehabilitation 1997; fair condition;

Disability Access: size 36 inch; type glass; last

rehabilitation 1997; good

condition;

Field Electrical Centre: size 10x10 ft.; type tool

shed; fair condition;

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Fairview Airport (EB5)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

last rehabilitation 1983; fair condition;

replacement 2005 (\$126000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 122.8

Windsock: 1 windsocks;

constructed 1978; last rehabilitation 1998; fair

condition; replacement 2005

Water / Sewer Data

Water Supply: Municipal Service; constructed

1996; good condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: Yes Right of Way: No

**Drainage Data** 

Surface: last rehabilitation 2000; Subsurface: ---

 Peak Period Info

 Spring
 Summer
 Fall
 Winter
 Average

 Peak Apron Aircraft Parked:
 2
 4
 4
 2
 3

 Design Aircraft for Airport:
 -- --





### Fairview Airport (EB5)

⊂Onsite Business Data			
Offsite Busiliess Data			
FBO: No		AC Maintenance: N	0
Industrial Buildings: No		Crop Spraying Activi	ities: Temporary; 2; Rural Aviation
			and Precision Spraying
Hangars: Yes, 5; private owner	ership	Chemicals Stored on	site: none
Operation and Maintenan			
	1997 199	8 1999 2000	2001
Total Annual Maintenance Buc	dget		
 ⊏Economic Activity Inform	ation		
Major Economic Industries in I		orestry/Agriculture/Federa	al
government/Medical evac.	regioni on a cas, i	oresa y// igriculture/r ederi	
How is the Airport Vital to the		anding center for industry	<i>'</i>
leaders, Spray plane services			
Airport Activity Info			
7 m por critourity inite	1997 1998	3 1999 2000	2001
Annual Aircraft Movements:			
Annual Passenger Movements	:		
3			
Commercial Airline Info			
─Airport Revenue Data   ──			
19	997 1998	1999 2000 2	2001
Total Annual Revenue:			
Airport Expenditure Data	1007 1000	1000 2000	2001
Total Appual France ditues	1997 1998	1999 2000	2001
Total Annual Expenditure			

#### Fairview Airport (EB5)

#### **Historic Capital Expenditures** Year Project Name **Funding Source** Description 2002 Provincial Pavement overlay - runway/apron/taxiway 1992 Provincial Pave runway extension and additional lighting 1991 Provincial Purchase runway lighting material 1989 Provincial Taxiway improvement paving Supply and install DME 1987 Provincial Extend runway gravel safety area 1986 Provincial 1985 Provincial Terminal Building 1984 Provincial Install NDB Overlay runway, install new airfiled lighting 1983 Provincial 1979 Repair of apron and taxiway and rectify Provincial drainage problem 1976 Provincial Permanent airport lighting 1973 Provincial Construction

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 FONTAS AIRPORT (CFK3)





Fontas Airport Aerial Photographs taken August 20, 2002

#### **Airport Contact Information:**

Mr. Tom Archibald
Fire Manager
Alberta Sustainable Resource Development - Land and Forest Division
Peace River, AB T8S 1T4
Tel: (780) 624 6221
Fax: (780) 618 4350

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

> Tel: 780-452-9955 Fax: 780-413-9918

Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 18, 2003 Project No. 11451

## Fontas Airport (FK3)

General Info					
Fontas (FK3) Distance	ce From Community (mile): le: 57.8000°, Longitude: -119.4500°				
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Mr. Tom Archibald Fire Manager Alberta Sustainable Resource Development - Land and Forest Division Provincial Building, 2nd Floor, 9621 - 96				
Ownership Structure:	Ave. Peace River T8S 1T4 (780) 624 6221(780) Fax: 618 4350				
Organizational Structure:	Runway Data  Primary: "09-27", 2300x100 (Turf)  Poor condition; replacement 2005				
Role of Airport:	Secondary:				
Taxiway Data Primary:	Apron Data				
Secondary:	Primary:				
Third:	Secondary:				
Fourth:	┌Building Data				
Landside Facility Data	ATB:				
Entrance Road:	Disability Access:				
Parking Lot:	Field Electrical Centre:				
Fencing:	Ficial Electrical Certaics.				

## Fontas Airport (FK3)

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	<b>∇Vicinity Protection</b> ,
	Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 0 windsocks;	ragine of way. Two
,	
Drainage Data	
Surface: Subsu	ırface:

Spring	Summer	Fall	Winter	Average
Spring	Summer	ı un	VVIIICCI	Average
	Spring	Spring Summer	Spring Summer Fall	Spring Summer Fall Winter





### Fontas Airport (FK3)

□Onsite Business Data ──						
FBO: No			AC Mai	ntenance:	No	
Industrial Buildings: No			Crop Spraying Activities:			
Hangars: No			Chemicals Stored on site:			
Operation and Maintenance	_					
Total Annual Maintenance Budg	1997 jet	1998	1999	2000	2001	
Economic Activity Information						
Airport Activity Info	1997	1998	1999	2000	2001	
Annual Aircraft Movements:	1557	1550	1333	2000	2001	
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data	97 1998	8 19	00	2000	2001	
Total Annual Revenue:	J, 1390	0 19	JJ	2000	2001	
Airport Expenditure Data	1007 10	200	1000	2000	2001	
Total Annual Expenditure	1997 19	998	1999	2000	2001	

## Fontas Airport (FK3)

Year	Project Name	Funding Source	Description	

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 FOREMOST AIRPORT (CFD4)





Foremost Airport Aerial Photographs taken August 13, 2002

#### **Airport Contact Information:**

Ms. Kelly Calhoun Village Administrator Village of Foremost Foremost, AB T0K 0X0 Tel: (403) 867 3733

Fax: (403) 867 2031

#### Prepared for:



**Aviation Strategy Action Group** 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Foremost Airport (FD4)

General Info

Foremost (FD4) Distance From Community (mile): 2

Municipal Latitude: 49.4833°, Longitude: -111.5000°

Owner and Operator Info

Owner: Village of Foremost Operator: Village of Foremost

Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

---

Organizational Structure:

Airport Committee/Flying Club

Role of Airport:

Crop Spraying/Recreational Flying/Corporate/Oil

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1981; last rehabilitation 1995;

replacement 2014 (\$33000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 10FT; type GRAVEL; constructed

1981;

Parking Lot: ---

Fencing: size 5FT; type BARB WIRE; replacement

2020

Contact Info

Ms. Kelly Calhoun Village Administrator Village of Foremost

Box 159 Foremost T0K 0X0

(403) 867 3733(403), Fax: 867 2031

**Runway Data** 

Primary: "05-23", 3000x75 (Asphalt)

constructed 1981; last rehabilitation 1995; Good condition; replacement 2014

(\$400000)

Secondary: ---

**Apron Data** 

Primary: "MAIN"; 300x150 (Asphalt)

constructed 1981; last rehabilitation 1995; good condition; replacement 2014

(\$67000)

Secondary: ---

Building Data

ATB: size 25X25; type WOOD FRAME; constructed

1984; fair condition; replacement 2020

(\$100000)

Disability Access: ---

Field Electrical Centre:

Airport Summary Report

#### Foremost Airport (FD4)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1981; good condition; replacement 2014 (\$160000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1981; good condition; replacement

2014

Water / Sewer Data

Water Supply: Other; constructed 1984; fair

condition; replacement 2020

Sewage: ---

<sup>-</sup>Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1981; good condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Foremost Airport (FD4)

**□Onsite Business Data** 

FBO: No				AC Ma	intenance:	No	
Industrial Buildings: No				Crop S	Spraying Ac	tivities: Per	manent;
Hangars: Yes, 2; Larry Ga Spraying	rber, Garbo	er Air		Chemio	cals Stored	on site: on	site trailer in summer
Operation and Mainter	nance Bu	_					 ]
Total Annual Maintenance	Budget	1997	1998	1999	2000	2001	
Economic Activity Info	ormation						]
Airport Activity Info		1997	1998	1999	2000	2001	
Annual Aircraft Moveme	nts:						
Annual Passenger Moveme	ents:						
Commercial Airline Inf	fo						
Airport Revenue Data	1007	1000	10	000	2000	2001	
Total Annual Revenue:	1997	1998	15	999	2000	2001	
Airport Expenditure D	ata 1997	199	ng.	1999	2000	2001	
Total Annual Expenditure	1557	199	,,,	1000	2000	2001	_

## Foremost Airport (FD4)

Capital Expend	aitures	
Project Name	Funding Source	Description
	Provincial	Fog seal asphalt surfaces
	Provincial	Purchase and install NDB
	Provincial	Radio Equipment Building
	Provincial	Purchase and install DME
	Provincial	Seeding
	Provincial	Terminal Building
	Provincial	Base paving and lighting
	Provincial	Land purchase
		Provincial Provincial Provincial Provincial Provincial Provincial Provincial Provincial

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 FORESTBURG AIRPORT (CEF6)





Forestburg Airport Aerial Photographs taken October 09, 2002

#### **Airport Contact Information:**

Ms. Sharon Butler Administrator Village of Forestburg Forestburg, AB T0B 1N0 Tel: (780) 582 3668

Fax: (780) 582 2233

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Forestburg Airport (EF6)

**General Info** 

Forestburg (EF6) Distance From Community (mile): 0.5
Municipal Latitude: 52.5667°, Longitude: -112.0833°

Owner and Operator Info

Owner: Village of Forestburg

Operator: ---

Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Village of Forestburg

Organizational Structure:

Municipal Government

Role of Airport:

---

**Taxiway Data** 

Primary: ---

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; good condition;

Parking Lot: type gravel; good condition;

Fencing: size 4'; type Barb wire;

Contact Info

Ms. Sharon Butler Administrator

Village of Forestburg

Box 210 Forestburg T0B 1N0

(780) 582 3668(780), Fax: 582 2233

**Runway Data** 

Primary: "10-27", 2950x50 (Asphalt)

constructed 1987; last rehabilitation 1998; Good condition; replacement 2007

(\$435000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1987; last rehabilitation 1998; good condition; replacement 2007

(\$78000)

Secondary: ---

**Building Data** 

ATB: size 24x36; type wood; constructed 1987;

good condition; replacement 2012 (\$100000)

Disability Access: type sidewalk; good condition;

Field Electrical Centre: size 6x6; type tool shed;

constructed 1987; fair condition; replacement 2007

(\$150000)

Airport Summary Report

#### Forestburg Airport (EF6)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1987; fair condition; replacement 2007 (\$159000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1987; good condition;

Water / Sewer Data

Water Supply: Well; constructed 1987; good

condition; replacement 2012

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: good condition; Subsurface: ---

Summer

Fall

Peak Period Info
Spring

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

\_\_

Average

Winter





### Forestburg Airport (EF6)

Onsite Business Data

FBO: No			AC Mai	ntenance:	No	
Industrial Buildings: No			Crop Sp	oraying Act	ivities: Tem	porary;
Hangars: Yes, 2; Walter Brickm Forestburg Transit Mix			Chemica	als Stored o	on site:	
-Onevetion and Maintenance	- Budget -					
Operation and Maintenance	е <b>Бийде</b> і 1997	1998	1999	2000	2001	
Total Annual Maintenance Budge	et					
Economic Activity Informat	tion					
Airport Activity Info	1007	1000	1000	2000	2001	
Annual Aircraft Movements:	1997	1998	1999	2000	2001	
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data						
199	7 199	8 19	99	2000	2001	
Total Annual Revenue:						
Airport Expenditure Data	007	200	1000	2000	2001	
Total Annual Expenditure	997 19	998	1999	2000	2001	

## Forestburg Airport (EF6)

Year     Project Name     Funding Source     Description       1999     Provincial     Slurry Seal       1988     Provincial     Site Clean up       1987     Provincial     Supply and install navigational aids (Radio equipment building, NDB and DME)       1986     Provincial     Land Purchase (\$112,600), grading and airfiled lighting       1984     Provincial     Terminal Building	-Historic	Historic Capital Expenditures					
1988 Provincial Site Clean up  1987 Provincial Supply and install navigational aids (Radio equipment building, NDB and DME)  1986 Provincial Land Purchase (\$112,600), grading and airfiled lighting	Year	Project Name	Funding Source	Description			
1987 Provincial Supply and install navigational aids (Radio equipment building, NDB and DME)  1986 Provincial Land Purchase (\$112,600), grading and airfiled lighting	1999		Provincial	Slurry Seal			
equipment building, NDB and DME)  1986 Provincial Land Purchase (\$112,600), grading and airfiled lighting	1988		Provincial	Site Clean up			
airfiled lighting	1987		Provincial	Supply and install navigational aids (Radio equipment building, NDB and DME)			
1984 Provincial Terminal Building	1986		Provincial	Land Purchase (\$112,600), grading and airfiled lighting			
	1984		Provincial	Terminal Building			

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 FORT CHIPEWYAN AIRPORT (CYPY)





Fort Chipewyan Airport Aerial Photographs taken August 08, 2002

#### **Airport Contact Information:**

Mr. Aloyes Lencucha Superintendent E/.PW-Ft. Chip Regional Municipality of Wood Buffalo Fort Chipewyan, AB T9H 2K4 Tel: (780) 697-3600

Fax: (780) 697-3881

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877



Airport Summary Report



#### Fort Chipewyan Airport (YPY)

General Info

Fort Chipewyan (YPY) Distance From Community (mile): 3

Municipal Latitude: 58.7667°, Longitude: -111.1167°

Owner and Operator Info

Owner: Regional Municipality of Wood Buffalo Operator: Regional Municipality of Wood Buffalo

Former Ownership: Transport Canada

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Owned by Regional Municipality of Wood Bufflo

Organizational Structure:

Airport Admin./Airport Manager

Role of Airport:

Scheduled passenger service; forestry base with fixed &

rotary; private and commercial fixed wing

**Taxiway Data** 

Primary: "A-1"; 515x75 (Asphalt)

constructed 1966; last rehabilitation 2001;

Good condition;

Secondary: "B-1"; 150x15

constructed 1966; Good condition;

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 7.5; type asphalt; constructed

1962; last rehabilitation 2001; good

condition; replacement 2015

Parking Lot: size 40x70m; type asphalt; constructed

1962; last rehabilitation 1977; fair condition; replacement 2008 (\$39000)

Fencing: type 4' chainlink & 6' Chainlink;

Contact Info

Mr. Aloyes Lencucha

Superintendent E/.PW-Ft. Chip

Regional Municipality of Wood Buffalo

P.O. Box 370 Fort Chipewyan

T9H 2K4

(780) 697-3600(780), Fax: 697-3881

**Runway Data** 

Primary: "03-21", 5000x150 (Asphalt)

constructed 1966; last rehabilitation 2001; Good condition; replacement 2016

(\$1463000)

Secondary: ---

**Apron Data** 

Primary: "1"; 300x200 (Asphalt)

constructed 1966; last rehabilitation 2001; good condition; replacement 2016

(\$129000)

Secondary: ---

**Building Data** 

ATB: size 1500 sq ft; type wood frame;

constructed 1964; last rehabilitation 2001;

fair condition;

Disability Access: poor condition;

Field Electrical Centre: size 15x30 ft; type

automated; constructed 1998; good condition;

Airport Summary Report

#### Fort Chipewyan Airport (YPY)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

last rehabilitation 1998; good condition;

Approach Slope Indicator 1: P2 (PAPI - Aircraft up to 25')

last rehabilitation 1998; good

condition;

Approach Slope Indicator 2: P2 (PAPI - Aircraft up to 25')

last rehabilitation 1998; good

condition;

ARCAL: Type: "K"; freq 123.2

Windsock: 3 windsocks;

good condition;

Water / Sewer Data

Water Supply: Other; constructed 1966; fair

condition; replacement 2003

(\$4000)

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: constructed 1966; last rehabilitation 1988; Subsurface: size 150; constructed 1966; last

good condition; rehabilitation 1988; good condition;

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

---





#### Fort Chipewyan Airport (YPY)

	Business	

FBO: No AC Maintenance: No

Industrial Buildings: No Crop Spraying Activities:

Hangars: No Chemicals Stored on site:

**Operation and Maintenance Budget** 

1997 1998 1999 2000 2001

Total Annual Maintenance Budget

#### **Economic Activity Information**

How is the Airport Vital to the Region: Primary means of transportation April to Dec. of each year.

#### **Airport Activity Info**

1997 1998 1999 2000 2001

Annual Aircraft Movements:

Annual Passenger Movements:

#### **Commercial Airline Info**

Air Mikisew (Twin Engine, Schedule 6 days/wk)

Northwest Air Lease (Twin Engine, Schedule 2 days/wk)

McMurray Aviation (Single Engine, non-scheduled)

Big River Air (Single Engine, non-scheduled)

Peace Air (Twin Engine, non-scheduled)

Nor-Rose (Single Engine, Freight only)

#### **Airport Revenue Data**

1997 1998 1999 2000 2001

Total Annual Revenue:

#### **Airport Expenditure Data**

1997 1998 1999 2000 2001

**Total Annual Expenditure** 

## Fort Chipewyan Airport (YPY)

Historic	Capital Expend	ditures	
Year	Project Name	Funding Source	Description
2001	Runway overlay		
1993		Provincial	Relocate aircraft power pedestals
1989		Provincial	Microwave Landing System
1988		Provincial	Microwave Landing System
1987		Provincial	Microwave Landing System installation and related work
1986		Provincial	Purchase Microwave Landing System
1985		Provincial	Pavement overlay
1978		Provincial	Completion of runway work
1977		Provincial	Initial groundwork and removal of zoning obstructions

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 FORT MACLEOD AIRPORT (CEY3)**





Fort Macleod Airport Aerial Photographs taken August 09, 2002

#### **Airport Contact Information:**

Mr. Lane McLaren Town Manager Town of Fort Macleod Fort Macleod, AB T0L 0Z0 Tel: (403) 553 4425

Fax: (403) 553 2426

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Fort Macleod Airport (EY3)

General Info

Fort Macleod (EY3) Distance From Community (mile): 1

Municipal Latitude: 49.7000°, Longitude: -113.4167°

Owner and Operator Info

Owner: Town of Fort Macleod Operator: Town of Fort McLeod Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town

Organizational Structure:

Airport Committee

Role of Airport:

Recreation/Agricultural Service

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1970; Good condition;

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 12ft; type gravel; fair condition;

Parking Lot: size 6 spaces; type asphalt;

Fencing: size 4'; type barb wire (farm);

Contact Info

Mr. Lane McLaren
Town Manager
Town of Fort Madage

Town of Fort Macleod

Box 1420 Fort Macleod T0L 0Z0

(403) 553 4425(403), Fax: 553 2426

**Runway Data** 

Primary: "06-24", 3000x75 (Asphalt)

constructed 1970; Good condition;

replacement 2015

Secondary: ---

**Apron Data** 

Primary: "main"; 300x200 (Asphalt)

constructed 1970; good condition;

replacement 2015

Secondary: ---

**Building Data** 

ATB: size 15' x 30'; type wood; constructed 1970;

good condition; replacement 2020

Disability Access:

Field Electrical Centre: size 6x8; type wood;

constructed 1970; good condition; replacement 2015

Airport Summary Report

#### Fort Macleod Airport (EY3)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1970; good condition; replacement 2015 (\$161000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

good condition; replacement 2015

Water / Sewer Data

Water Supply: Municipal Service; good

condition; replacement 2020

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: good condition; Subsurface: good condition;

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Fort Macleod Airport (EY3)

**□Onsite Business Data** 

FBO: No		AC I	Maintenance:	No	
Industrial Buildings: No		Crop	o Spraying Ac	tivities: Ten	nporary;
Hangars: No		Cher	nicals Stored	on site: tem	porary storage
Operation and Maintenance	Budget -				
	1997	1998 199	9 2000	2001	
Total Annual Maintenance Budget					
Economic Activity Information	on —				
Airport Activity Info	1007	1000 100	2000	2004	
Annual Aircraft Movements:	1997	1998 1999	9 2000	2001	
Annual Passenger Movements:					
Annual Passenger Movements.					
Commercial Airline Info					
Airport Revenue Data	1000	1000	2000	2001	
Total Annual Revenue:	1998	1999	2000	2001	
Airport Expenditure Data  19	97 199	8 1999	2000	2001	
Total Annual Expenditure	57 199	1333	2000	2001	-

## Fort Macleod Airport (EY3)

Year	Project Name	Funding Source	Description
1985		Provincial	Terminal Building
1984		Provincial	Terminal Building
1984		Provincial	Slurry Seal runway
1979		Provincial	Relocation of former Pincher Creek Termi Building to Fort Macleod Airport
1979		Provincial	Drainage, grading and paving of new runv and lighting

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 FORT MCMURRAY AIRPORT (CYMM)**





Fort McMurray Airport Aerial Photographs taken August 08, 2002

#### **Airport Contact Information:**

Mr. Darryl Wightman
Airport Manager
Fort McMurray Airport
Fort McMurray, AB T9H 5B4
Tel: (780) 790 3900

Fax: (780) 790 3900

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Fort McMurray Airport (YMM)

General Info

Fort McMurray (YMM) Distance From Community (mile): 7

Passenger/Commercial - Regional Latitude: 56.6500°, Longitude: -111.2167°

Owner and Operator Info

Owner: Municipality of Wood Buffalo

Operator: Fort McMurray Airport Commission

Former Ownership: Transport Canada

Date of Change: March 31, 1999

**Airport Organization** 

Ownership Structure:

Corporation

Organizational Structure:

Mayor/Municipal Manager

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; 5600x75 (Asphalt)

constructed 1979; Poor condition; replacement 2003 (\$2000000)

Secondary: "B"; 475x75 (Asphalt)

constructed 1955; last rehabilitation 1984; Poor condition; replacement 2003

Third: "C"; 475x50 (Asphalt)

constructed 1955; last rehabilitation 1984; Poor condition; replacement 2003 (\$66000)

Fourth: "D"; 405x75 (Asphalt)

constructed 1979; replacement 2003

(\$104000)

**Landside Facility Data** 

Entrance Road: size asphalt; replacement 2005

(\$180000)

Parking Lot: replacement 2005 (\$208000)

Fencing: size 6ft; type chain link around terminal

area;

Contact Info

Mr. Darryl Wightman Airport Manager

Fort McMurray Airport Site 1 Box 9 RR1

Fort McMurray

T9H 5B4

(780) 790 3900(780), Fax: 790 3904

**Runway Data** 

Primary: "07-25", 6000x150 (Asphalt)

constructed 1954; last rehabilitation 1984; Poor condition; replacement 2003

(\$1700000)

Secondary: ---

**Apron Data** 

Primary: "II"; (Concrete)

good condition;

Secondary: "I"; (Asphalt)

poor condition; replacement 2005

(\$250000)

**Building Data** 

ATB: constructed 1986; good condition;

Disability Access:

Field Electrical Centre: constructed 1982; good

condition;

## Fort McMurray Airport (YMM)

Lighting Data		──
Primary Edgelighting: TE (TI constr	nreshold and Runway End) ructed 2001; good condition;	Water Supply: Municipal Service; good condition;
Approach Slope Indicator 1:	P2 (PAPI - Aircraft up to 25') constructed 2001; good condition	Sewage:
	P2 (PAPI - Aircraft up to 25') constructed 2001; good condition	Caveat, and right of way
ARCAL: Type:		Vicinity Protection: Yes Caveat: Yes Right of Way: Yes
Windsock: 2 windsocks; constructed	2001; good condition;	
□ Drainage Data		
Surface:	Subsu	rface:
Peak Period Info	Spring Summer Fall	Winter Average
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		



Airport Summary Report



#### Fort McMurray Airport (YMM)

**Onsite Business Data** 

FBO: Yes, 4; Shell, McMurray Aviation,

Universal Aviation, Bor

Industrial Buildings: Yes, ;

Hangars: Yes, 12;

AC Maintenance: Yes, 2; Mikisew Air and McMurray

Aviation

Crop Spraying Activities:

Chemicals Stored on site:

Operation and Maintenance Budget

1997 1998 2000 2001 1999

Total Annual Maintenance Budget

**Economic Activity Information** 

Major Economic Industries in Region: Oil & Gas/Forestry

How is the Airport Vital to the Region: The is only one road in/out of Region

**Airport Activity Info** 

1997 1998 1999 2000 2001

**Annual Aircraft Movements:** 

Annual Passenger Movements:

**Commercial Airline Info** 

WestJet (737, scheduled)

Jazz (F28, scheduled)

Mikisew (J31, scheduled)

Canadian Airline (North West) (J31, scheduled)

Corporate Express (Saab 340, scheduled)

McMurray Aviation (Caravan, scheduled)

**Airport Revenue Data** 

1997 1998 1999 2000 2001

Total Annual Revenue:

**Airport Expenditure Data** 

1997 2000 1998 1999 2001

**Total Annual Expenditure** 

## Fort McMurray Airport (YMM)

Year	Project Name	Funding Source	Description	

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 FORT MCMURRAY/MILDRED LAKE AIRPORT (CER4)





Fort McMurray/Mildred Lake Airport Aerial Photographs taken August 07, 2002

#### **Airport Contact Information:**

Travel Manager/Chief Pilot Syncrude Fort McMurray, AB T9H 3H5 Tel: (780) 791 1918/790 5094 Fax: (780) 790 6446

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc.

204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info Fort McMurray/Mildred Lake (ER4)	Distance From Community (mile): 2.2 Latitude: 57.0500°, Longitude: -111.5667°
Owner and Operator Info	Contact Info
Owner: Syncrude Canada Ltd. Operator: Syncrude Canada Ltd. Former Ownership: No Change Date of Change:	Mr. Dale Henderson Travel Manager/Chief Pilot Syncrude P.O. Bag 4023 MD 9000 Fort McMurray
Airport Organization	T9H 3H5 (780) 791 1918/790 5094(780) , Fax: 790
Ownership Structure:	6446
	⊢Runway Data
Organizational Structure:	Primary: "11-29", 5000x100 (Gravel) constructed 1958; last rehabilitation 1999; Good condition;
Role of Airport:	
	Secondary:
Taxiway Data	
Primary:	
	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
	ATB:
Landside Facility Data	
Entrance Road:	
	Disability Access:
Parking Lot:	
Enging	Field Electrical Centre:
Fencing:	

Lighting Data	□ Water / Sewer Data
Primary Edgelighting: T (Three	
Approach Slope Indicator 1: -	
Approach Slope Indicator 2: -	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 1 windsocks; fair condition;	
⊤Drainage Data <del></del>	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemicals Stored on site:		
Operation and Mainten	ance B	udget <sup>—</sup> 1997	1998	1999	2000	2001
Total Annual Maintenance E	Budget					
Economic Activity Info	rmation	1				
- Airport Activity Info						
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movemen	ts:					
Annual Passenger Movemer	nts:					
Commercial Airline Info	<b>)</b>					
 ☐Airport Revenue Data						
	1997	1998		1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Da						
Total Annual Expenditure	1997	19	98	1999	2000	2001
rotai Ailiuai Experiulture						

Year	Project Name	Funding Source	Description	

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 FORT VERMILION AIRPORT (CEZ4)





Fort Vermilion Airport Aerial Photographs taken August 22, 2002

#### **Airport Contact Information:**

Mr. Alan Cronkhite
Project Services Technologist
Municipal District of Mackenzie 23
P.O. Box 1690
La Crete, AB T0H 2H0
Tel: (780) 928 3983
Fax: (780) 928 3636

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Fort Vermilion Airport (EZ4)

General Info

Fort Vermilion (EZ4)

Municipal

Distance From Community (mile): 2.3 Latitude: 58.4000°, Longitude: -115.9500°

Owner and Operator Info

Owner: MD 23 Operator: ---

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

To provide service to the surrounding communities

**Taxiway Data** 

Primary: ---

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 10m; type asphalt; fair

condition; replacement 2007 (\$9000)

Parking Lot: size 30mx10m; type gravel; last

rehabilitation 2001; good condition;

Fencing: ---

Contact Info

Mr. Ian Cosh

(780) 928 3636(780), Fax: 928-3983

**Runway Data** 

Primary: "07-25", 3000x100 (Asphalt)

constructed 1978; last rehabilitation 2000; Good condition; replacement 2009

(\$585000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1978; last rehabilitation 2001; good condition; replacement 2009

(\$171000)

Secondary: ---

**Building Data** 

ATB: size 10mx14m; type 1 level; constructed

1983; good condition;

Disability Access: good condition;

Field Electrical Centre: ---

Airport Summary Report

#### Fort Vermilion Airport (EZ4)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1987; good condition; replacement 2007 (\$144000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1987; fair condition; replacement 2

Water / Sewer Data

Water Supply: Well;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: good condition; Subsurface: ---

Peak Period Info Spring Summer Fall Winter Average Peak Apron Aircraft Parked: 9 9 7 8 Design Aircraft for Airport: Dash 8 Dash 8 Dash 8 Dash 8



PRYDE SCHROPP McCOMB INC

#### Fort Vermilion Airport (EZ4)

**Onsite Business Data** 

FBO: No AC Maintenance: Yes, ; Little Red Air Service

Industrial Buildings: Yes, ; MD #23 Maintenance

Crop Spraying Activities:

Hangars: Yes, 1; Little Red Air Service Chemicals Stored on site:

Operation and Maintenance Budget

1997 1998 2000 2001 1999

Total Annual Maintenance Budget

**Economic Activity Information** 

Road Distance to Nearest Airport Sched. Pax Service: 90

Road Distance to Nearest Airport MedEvac Service: 90

Road Distance to Nearest Airport Cargo Service: 90

Road Distance to Nearest Airport AME Service: 90

Road Distance to Nearest Airport Fire Suppression Service: 90

Major Economic Industries in Region: Forestry/Oil & Gas

How is the Airport Vital to the Region: Provides services to the reserves, which

are otherwise isolated

**Airport Activity Info** 

1997 1998 1999 2000 2001

**Annual Aircraft Movements:** 

Annual Passenger Movements:

**Commercial Airline Info** 

Little Red Air Service (C-206 Islander, King Air 100, Charter/Medivac)

**Airport Revenue Data** 

1997 1998 1999 2000 2001

Total Annual Revenue:

Airport Expenditure Data

1997 1998 1999 2000 2001

**Total Annual Expenditure** 

# Fort Vermilion Airport (EZ4)

Year	Project Name	Funding Source	Description	
2002	•	Provincial	Airport overlay	
1991		Provincial	Purchase and install NDB	
1988		Provincial	Runway overlay and parking apron expansion	
1987		Provincial	Upgrade airfield lighting	
1986		Provincial	Purchase and install DME	
1985		Provincial	Site Clean up	
1984		Provincial	Terminal Building	
1984		Provincial	Airport Equipment Building	
1983		Provincial	Construction of air Terminal Building	
1978		Provincial	Paving of runway, taxiway and apron	
1977		Provincial	Installation of airport lighting	
1967		Provincial	Provincial share of construction of a new gravel runway, taxiway and aircraft parking	

### AIRPORT INFORMATION REPORT - 2002 FOX CREEK AIRPORT (CED4)





Fox Creek Airport Aerial Photographs taken July 22, 2002

#### **Airport Contact Information:**

Mr. Larry Baran Town Manager Town of Fox Creek Fox Creek, AB T0H 1P0 Tel: (780) 622 3896

Fax: (780) 622 4247

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Fox Creek Airport (ED4)

General Info

Fox Creek (ED4) Distance From Community (mile): 2
Municipal Latitude: 54.3833°, Longitude: -116.7667°

Owner and Operator Info

Owner: Town of Fox Creek Operator: Town of Fox Creek

Former Ownership: Transport Canada Date of Change: August 1, 1996

**Airport Organization** 

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

Fair condition; replacement 2004 (\$20000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel;

Parking Lot: ---

Fencing: size 4 ft. barb wirealong highway/rest

nothing;

Contact Info

Mr. Larry Baran Town Manager Town of Fox Creek

Box 149 Fox Creek T0H 1P0

(780) 622 3896(780), Fax: 622 4247

**Runway Data** 

Primary: "10-28", 2950x75 (Asphalt)

last rehabilitation 1987; Fair condition;

replacement 2004 (\$393000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

fair condition; replacement 2004

(\$146000)

Secondary: ---

**Building Data** 

ATB: type atco trailer;

Disability Access: ---

Field Electrical Centre: type tool shed; poor

condition; replacement 2010

(\$150000)

### Fox Creek Airport (ED4)

Lighting Data			<b>−Water / Se</b>	wer Data
	nreshold and Runway Ei habilitation 1987; fair c ement 2010 (\$173000)		Water Suppl	y:
Approach Slope Indicator 1:			Sewage:	
Approach Slope Indicator 2:			Vicinity Pi	otection, nd Right of Way
ARCAL: Type: "K"; fro	•		Vicinity Pro Caveat: N Right of Wa	
Windsock: 1 windsocks; fair condition	; replacement 2010			
Drainage Data				
Surface: fair condition;		Subsurfa	ce:	
Peak Period Info				7
	Spring Summer	Fall Wi	nter Average	
Peak Apron Aircraft Parked:				
Design Aircraft for Airport:				





#### Fox Creek Airport (ED4)

Onsite Business Data				
FBO: No		A	AC Maintenanc	e: No
Industrial Buildings: No		(	Crop Spraying A	Activities:
Hangars: No		C	hemicals Store	ed on site:
Operation and Maintenance	_	1000	1000 2000	2004
Total Annual Maintenance Budg	1997 et	1998	1999 2000	2001
Economic Activity Information	tion			
Airport Activity Info	1997	1998 1	.999 2000	2001
Annual Aircraft Movements:		1330	2000	
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data				2004
Total Annual Revenue:	7 1998	3 1999	2000	2001
Airport Expenditure Data				
	997 19	998 199	99 2000	2001
Total Annual Expenditure				

### Fox Creek Airport (ED4)

Year	Project Name	Funding Source	Description
1994		Provincial	Preliminary survey for runway extension
1993		Provincial	Preliminary survey
1991		Provincial	Purchase and install NDB
1991		Provincial	Purchase and install DME
1988		Provincial	Completion of runway paving
1987		Provincial	Paving of runway
1987		Provincial	New airfield lighting installation
1986		Provincial	Grading of new runway (3000' x 75')
1978		Provincial	Completion of lighting installation
1977		Provincial	Installation of airfield lighting on gravel runway

### AIRPORT INFORMATION REPORT - 2002 FOX LAKE AIRPORT (CEC3)





Fox Lake Airport Aerial Photographs taken August 22, 2002

#### **Airport Contact Information:**

Mr. Craig Halonen Operations Manager Little Red Air Service Fort Vermillion, AB T0H 1N0 Tel: (780) 927 4630

Fax: (780) 927 3667

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Fox Lake (EC3)	Distance From Community (mile): 1 Latitude: 58.4667°, Longitude: -114.5500°
Owner and Operator Info	Contact Info
Owner: Little Red River Cree Nation	Mr. Craig Halonen
Operator: Little Red Air Service Ltd.	Operations Manager
Former Ownership: Date of Change:	Little Red Air Service Box 584
Date of Change.	Fort Vermillion
Airport Organization	T0H 1N0
Ownership Structure:	(780) 927 4630(780) , Fax: 927 3667
	⊢Runway Data
Organizational Structure:	Primary: "08-26", 3500x100 (Gravel)
	Good condition;
Role of Airport:	
	Secondary:
Taxiway Data	
Primary: "A"; (Gravel)	Apron Data
Good condition;	
Cocondomy "P", (Croyel)	Primary: "1"; (Gravel) good condition;
Secondary: "B"; (Gravel)  Good condition;	good condition,
,	
Third:	Secondary: "Run Up Pad"; (Concrete)
	good condition;
Fourth:	
	┌Building Data
	ATB:
Landside Facility Data	
Entrance Road:	
	Disability Access:
Parking Lot:	
	Field Electrical Centre:
Fencing:	Field Electrical Certife:
i cilcing.	

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Caveat, and Right of Way
ARCAL: Type: Windsock: 1 windsocks; fair condition	
□ Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Act	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Mainten	ance B	u <b>dget</b> - 1997	1998	1999	2000	2001
Total Annual Maintenance E	Budget					
Economic Activity Info	rmation	1				
- Airport Activity Info						
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movement	ts:					
Annual Passenger Movemer	nts:					
Commercial Airline Info	)					
Airport Revenue Data						
	1997	1998	:	1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Da		_		16	g	
Total Annual Expenditure	1997	19	98	1999	2000	2001
. Star / iii iaar Experiatore						

Year	Project Name	Funding Source	Description	

# **GARDEN RIVER AIRPORT (CFU4)**





Garden River Airport Aerial Photographs taken August 21, 2002

#### **Airport Contact Information:**

Mr. Craig Halonen
Operations Manager
Little Red Air Service
Fort Vermillion, AB T0H 1N0

Tel: (780) 927 4630 Fax: (780) 927 3667

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Garden River (FU4) Distance	ce From Community (mile): 1 le: 58.7167°, Longitude: -113.8833°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Mr. Craig Halonen Operations Manager Little Red Air Service Box 584 Fort Vermillion
Airport Organization Ownership Structure:	T0H 1N0 (780) 927 4630(780) , Fax: 927 3667
Organizational Structure:	Primary: "07-25", 3000x75 (Turf) Good condition;
Role of Airport:	Secondary:
Taxiway Data Primary:	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	- Puilding Data
Landside Facility Data	ATB:
Entrance Road:	Disability Access:
Parking Lot:	Field Electrical Centre:
Fencing:	Ficia Licerical centre.

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Consite Business Data ——					
FBO: No			AC Mai	intenance:	No
Industrial Buildings: No			Crop S	praying Act	tivities:
Hangars: No			Chemic	als Stored	on site:
Operation and Maintenance	Budget -	1998	1999	2000	2001
Total Annual Maintenance Budge		1330	1333	2000	
Economic Activity Informati	on				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
Total Annual Revenue:	7 1998	3 19	99	2000	2001
Airport Expenditure Data	997 19	98	1999	2000	2001
Total Annual Expenditure	,,, 13		1777	2000	2001

Year	Project Name	Funding Source	Description	

### AIRPORT INFORMATION REPORT - 2002 GLENDON AIRPORT (CFP5)





Glendon Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Mr. Dave Woycenko Bonnyville, AB T9N 2J1 Tel: (780) 635 2165 Fax: (780) 635 2165

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

From Community (mile): 2.5 54.2667°, Longitude: -111.0667°  Contact Info  Mr. Dave Woycenko Box 7698 Bonnyville T9N 2J1 (780) 635 2165(780) , Fax: 635 2165  Runway Data  Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:
Contact Info  Mr. Dave Woycenko Box 7698 Bonnyville T9N 2J1 (780) 635 2165(780) , Fax: 635 2165  Runway Data  Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:
Mr. Dave Woycenko Box 7698 Bonnyville T9N 2J1 (780) 635 2165(780) , Fax: 635 2165  Runway Data  Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:
Mr. Dave Woycenko Box 7698 Bonnyville T9N 2J1 (780) 635 2165(780) , Fax: 635 2165  Runway Data  Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:
Box 7698 Bonnyville T9N 2J1 (780) 635 2165(780) , Fax: 635 2165  Runway Data  Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:
Bonnyville T9N 2J1 (780) 635 2165(780) , Fax: 635 2165  Runway Data Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:
T9N 2J1 (780) 635 2165(780) , Fax: 635 2165  Runway Data  Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:
Runway Data Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:
Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:
Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:  Apron Data
Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:  Apron Data
Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:  Apron Data
Primary: "16-34", 2200x70 (Turf) constructed 1995; Good condition;  Secondary:  Apron Data
constructed 1995; Good condition;  Secondary:  Apron Data
Secondary: Apron Data
Apron Data
Apron Data
Apron Data
•
•
•
•
Linux Day (
Primary:
Secondary:
Secondary.
Building Data
ATB:
Di 199 A
Disability Access:
Field Electrical Centre:

Lighting Data	Water / Sewer Data	
Primary Edgelighting:	Water Supply:	
Approach Slope Indicator 1:	Sewage:	
Approach Slope Indicator 2:	Vicinity Protection,  Caveat, and Right of Way	
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No	
Windsock: 0 windsocks;	;	
□Drainage Data □		
Surface:	Subsurface:	
Peak Period Info	Spring Summer Fall Winter Average	
Peak Apron Aircraft Parked:		
Design Aircraft for Airport		





FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: Yes, 1; Dave Woy	cenko			Chemic	cals Stored	on site:
Operation and Maintena	ance B	udget 1997	1998	1999	2000	2001
Total Annual Maintenance B	Budget	1337	1330	1333	2000	
Economic Activity Infor	mation	1				
Airport Activity Info						
Annual Aircraft Movement	rs:	1997	1998	1999	2000	2001
Annual Passenger Movemer						
Commercial Airline Info						
Commercial Airline Info						
Commercial Airline Info						
Commercial Airline Info						
Commercial Airline Info	)					
		1998		1999	2000	2001
Airport Revenue Data	1997			1999	2000	2001

Year	Project Name	Funding Source	Description	

### AIRPORT INFORMATION REPORT - 2002 GORDON LAKE AIRPORT (CFW2)





Gordon Lake Airport Aerial Photographs taken August 08, 2002

#### **Airport Contact Information:**

Mr. Brian Stanton
W.A.O.O.

Alberta Sustainable Resource Development - Land and Forest Division
Lac La Biche, AB T0A 2C0
Tel: (780) 623 5240

Fax: (780) 623 2570

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info			
	nce From Community (mile): de: 56.6167°, Longitude: -110.5000°		
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:  Airport Organization Ownership Structure:	Contact Info  Mr. Brian Stanton W.A.O.O. Alberta Sustainable Resource Development - Land and Forest Division Box 450 Lac La Biche T0A 2C0 (780) 623 5240(780) , Fax: 623 2570		
Organizational Structure:	Runway Data Primary: "15-33", 2200x50 (Turf)		
Role of Airport:	Secondary:		
Taxiway Data Primary:	Apron Data		
Secondary:	Primary:		
Third:	Secondary:		
Fourth:	⊤Building Data		
Landside Facility Data  Entrance Road:	ATB:		
Parking Lot:	Disability Access:		
Fencing:	Field Electrical Centre:		

· · · · · · · · · · · · · · · · · · ·	
<b>□Lighting Data</b>	┌Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1: -	Sewage:
Approach Slope Indicator 2: -	Caveat, and Right of Way
	Vicinity Protection: No  Caveat: No
ARCAL: Type:	Right of Way: No
Windsock: 0 windsocks;	
Drainage Data	
Surface:	Subsurface:
Peak Period Info	
	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Triadstrial Ballatrigs. No				Стор	praying ne	avides.
Hangars: No				Chemic	als Stored	on site:
Operation and Mainte	nance E	Budget -				
T		1997	1998	1999	2000	2001
Total Annual Maintenance	Budget					
Economic Activity Info	ormatio	n —				
Airport Activity Info						
Appual Aireath Moveme	ntai	1997	1998	1999	2000	2001
Annual Aircraft Moveme						
Annual Passenger Movem	ents:					
Commercial Airline In	fo					
Airport Revenue Data						
T	1997	1998	1	999	2000	2001
Total Annual Revenue:						
Airport Expenditure D						
Total Annual Expenditure	199	7 19	98	1999	2000	2001
I LOTAL Annual Evnenditure						

Year	Project Name	Funding Source	Description	

### AIRPORT INFORMATION REPORT - 2002 GRANDE AIRPORT (CFA5)





Grande Airport Aerial Photographs taken August 09, 2002

#### **Airport Contact Information:**

Mr. Brian Stanton
W.A.O.O.

Alberta Sustainable Resource Development - Land and Forest Division
Lac La Biche, AB T0A 2C0
Tel: (780) 623 5240

Fax: (780) 623 2570

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918 Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 18, 2003 Project No. 11451

General Info	Dictance From Community (mile)
Grande (FA5)	Distance From Community (mile): Latitude: 56.3000°, Longitude: -112.2333°
Owner and Operator Info	Contact Info
Owner:	Mr. Brian Stanton
Operator:	W.A.O.O.
Former Ownership: Date of Change:	Alberta Sustainable Resource Development - Land and Forest Division
Date of Changer	Box 450
Airport Organization	Lac La Biche
Ownership Structure:	T0A 2C0 (780) 623 5240(780) , Fax: 623 2570
	(700) 023 32 10(700) , Tax. 023 2370
	┌Runway Data
Organizational Structure:	Primary: "03-21", 2400x100 (Turf)
Dala of Airrants	
Role of Airport:	Secondary:
	Secondary.
Taxiway Data	
Primary:	
Timary.	┌Apron Data
	Primary:
Secondary:	
Thinds	Cocondana
Third:	Secondary:
Fourth:	
	Building Data
	ATB:
Landside Facility Data	
Entrance Road:	
	Disability Access:
Parking Lot:	
	Field Electrical Centre:
Fencing:	l leid Liectrical Certifie
. Changi	

<b>□Lighting Data</b>	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Troumty 1 rotoonon,
ARCAL: Type: Windsock: 0 windsocks;	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data					
FBO: No			AC Mair	ntenance:	No
Industrial Buildings: No			Crop Sp	oraying Act	tivities:
Hangars: No			Chemica	als Stored	on site:
Operation and Maintenance E	_	1000	1000	2000	2004
Total Annual Maintenance Budget	1997	1998	1999	2000	2001
Economic Activity Informatio	n —				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	1009	100	10	2000	2001
Total Annual Revenue:	1998	199	בי	2000	2001
Airport Expenditure Data	7 199	98 1	999	2000	2001
Total Annual Expenditure	, 1).	,,, 1		2000	2001

Year	Project Name	Funding Source	Description	

# **GRANDE CACHE AIRPORT (CEQ5)**





Grande Cache Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Daryl Taitinger
Airport Manager
Grande Cache Airport
Grande Cache, AB T0E 0Y0
Tel: (780) 827 5229

Fax: (780) 827 5229

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

#### Grande Cache Airport (EQ5)

General Info

	e: 53.9167°, Longitude: -118.8667°		
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:  Airport Organization Ownership Structure:	Contact Info  Mr. Daryl Taitinger Airport Manager Grande Cache Airport P.O. Box 300 Grande Cache T0E 0Y0 (780) 827 5229(780) , Fax: 827 2275		
Organizational Structure: Role of Airport:	Primary: "08-26", 5000x100 (Asphalt) constructed 1980; last rehabilitation 1990; Poor condition; replacement 2003 (\$1765000)  Secondary:		
Primary: "A"; (Asphalt)	Primary: "1"; (Asphalt) constructed 1980; last rehabilitation 1990; poor condition; replacement 2003 (\$278000)  Secondary: "forestry"; (Asphalt) fair condition;		
Entrance Road:  Parking Lot:	ATB:  Disability Access:		
Fencing:	Field Electrical Centre:		

### Grande Cache Airport (EQ5)

Design Aircraft for Airport:

	• •				
Lighting Data			─Water / Sev	wer Data	
Primary Edgelighting: TE (Ti constr replace	Water Supply: Well;				
Approach Slope Indicator 1:	V1 (2-BAR VASIS - Aircreconstructed 1983; fair coreplacement 2006 (\$600)	ondition;	Sewage:	-	
Approach Slope Indicator 2:			<b>Vicinity Pr</b>	otection,	
	constructed 1983; fair coreplacement 2006 (\$600		Caveat, an	d Right of Way	
	Teplacement 2000 (4000	,,,,,	Vicinity Prot		
ARCAL: Type: "K"; fr	eq 123.2		Caveat: No Right of Wa		
Windsock: 1 windsocks; constructed	; 1983; fair condition; repl	acement 2		,	
Drainage Data					
Surface:		Subsurfa	ce:		
Peak Period Info	Spring Summer	Fall Wir	nter Average		
Peak Apron Aircraft Parked:	Spring Summer	i dii VVII	Average		
. ca					





#### Grande Cache Airport (EQ5)

Onsite Business Data					
FBO: No			AC Mai	ntenance:	No
Industrial Buildings: No			Crop S <sub>l</sub>	praying Act	tivities:
Hangars: No			Chemica	als Stored	on site:
Operation and Maintenanc	e Budget -				
Total Annual Maintenance Budg	1997 et	1998	1999	2000	2001
Economic Activity Informa	tion				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:	1997	1990	1999	2000	2001
Annual Passenger Movements:					
Commercial Airline Info	<u>'</u>				
Airport Revenue Data	97 1998	3 19 <sup>6</sup>	00	2000	2001
Total Annual Revenue:	77 1990	) 19	99	2000	2001
Airport Expenditure Data	007 10	.00	1000	2000	2001
Total Annual Expenditure	.997 19	98 :	1999	2000	2001

### Grande Cache Airport (EQ5)

Year	Project Name	Funding Source	Description		
1996		Provincial	Replace two hazard beacon light units an install solar power panels		
1993		Provincial	Construct new hazard beacon platforms		
1990		Provincial	Runway pavement repairs		
1988		Provincial	Purchase and install AWOS		
1987		Provincial	Purchase and install DME		
1987		Provincial	Runway repairs		
1986		Provincial	NDB purchase and install		
1983		Provincial	VASIS installation and aviation hazard beacons		
1980		Provincial	Terminal Building		
1980		Provincial	Completion of paving and lighting, construction of maintenance garage		
1979		Provincial	Access road construction, initial grading a stockpiling		
1978		Provincial	Preliminary tree-clearing and site prepara		

# **GRANDE PRAIRIE AIRPORT (CYQU)**





Grande Prairie Airport Aerial Photographs taken July 22, 2002

#### **Airport Contact Information:**

Mr. Brian Grant C.E.O. Grande Prairie Airport Grande Prairie, AB T8V 7Z5 Tel: (780) 539 5270 Fax: (780) 532 1520

Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Grande Prairie Airport (YQU)

General Info

Grande Prairie (YQU) Distance From Community (mile): 3

Passenger/Commercial - Regional Latitude: 55.1333°, Longitude: -118.8167°

Owner and Operator Info

Owner: City of Grande Prairie Operator: City of Grande Prairie Former Ownership: Transport Canada

Date of Change: February 1, 1997

**Airport Organization** 

Ownership Structure:

City of Grande Prairie leased to Grande Prairie Airport

Commission

Organizational Structure:

Airport Commission/CEO/Manager Finance & Marketing/

Manager Operations & Terminal Services

Role of Airport:

The Grande Prairie Airport serves the city, surrounding area and broad region of northern Alberta and Northeast British

**Taxiway Data** 

Primary: "A1"; (Asphalt)

Fair condition; replacement 2004 (\$82000)

Secondary: "A2-4"; (Asphalt)

Fair condition; replacement 2004

(\$492000)

Third: "A5";

last rehabilitation 2001; Good condition;

Fourth: "B";

last rehabilitation 2001; Good condition;

**Landside Facility Data** 

Entrance Road: poor condition; replacement 2006

(\$1200000)

Parking Lot:

Fencing:

Contact Info

Mr. Brian Grant

C.E.O.

Grande Prairie Airport

Suite 220 10610 Airport Drive

Grande Prairie

T8V 7Z5

(780) 539 5270(780), Fax: 532 1520

Runway Data

Primary: "11-29", 6500x200 (Asphalt)

last rehabilitation 2001; Good condition;

replacement 2016

Secondary: "07-25", 6200x200 (Asphalt)

Poor condition; replacement 2003

(\$2600000)

**Apron Data** 

Primary: "1"; (Concrete)

fair condition; replacement 2006

(\$1500000)

Secondary: "11"; (Asphalt)

poor condition; replacement 2004

(\$416000)

**Building Data** 

ATB:

Disability Access: type ground level;

Field Electrical Centre:

Airport Summary Report

#### Grande Prairie Airport (YQU)

	•	`	′
⁻Lighting Data <sup>──</sup>			

Primary Edgelighting: TE (Threshold and Runway End)

last rehabilitation 2001; good condition;

Approach Slope Indicator 1: P2 (PAPI - Aircraft up to 25')

constructed 1996;

Approach Slope Indicator 2: P2 (PAPI - Aircraft up to 25')

constructed 2001; good condition;

ARCAL: Type: "J"; freq 118.1

Windsock: 3 windsocks;

good condition;

Water / Sewer Data

Water Supply: On Site Treatment; good

condition;

Sewage: Well; good condition;

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: Yes Right of Way: Yes

Drainage [	Data
------------	------

Surface: Subsurface:

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

---





### Grande Prairie Airport (YQU)

**Onsite Business Data** 

FBO: Yes, 3; Shell; ESSO; Swa	n Aeromotive	2	AC Ma	intenance:	Yes, 1;
Industrial Buildings: No			Crop S	Spraying Ac	tivities: Temporary;
Hangars: Yes, 12; Doug Marsha Swan Aeromotive (2), Adventure Aviation, H Helicopters, Precision Chandelle Aviation, Da	Weyerhause ighland Helicopters,	er,	Chemic	als Stored	on site: no
Operation and Maintenance	e Budget				
Total Annual Maintenance Budg	1997 et	1998	1999	2000	2001
 ⊏Economic Activity Informat	tion				
Road Distance to Nearest Airpor Road Distance to Nearest Airpor Major Economic Industries in Re Services How is the Airport Vital to the R Country	t Fire Suppre egion: Agric	ession Ser culture/Fo	restry/Oil	·	
Airport Activity Info	1007	1000	1000	2000	2001
Annual Aircraft Movements:	1997	1998	1999	2000	2001
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	100	0 10	200	2000	2004
Total Annual Revenue:	97 1998	8 19	999	2000	2001
Airport Expenditure Data	.997 19	200	1000	2000	2001
Total Annual Expenditure	75/ I	998	1999	2000	2001

## Grande Prairie Airport (YQU)

Year	Project Name	Funding Source	Description		

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 GRIMSHAW AIRPORT (CFD5)





Grimshaw Airport Aerial Photographs taken July 23, 2002

#### **Airport Contact Information:**

Ms. Cathie Bailey Chief Administrator Officer Town of Grimshaw Grimshaw, AB T0H 1W0 Tel: (780) 332 4626

Fax: (780) 332 4020

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info						
	Distance From Community (mile): 0 Latitude: 56.2000°, Longitude: -117.6167°					
Owner and Operator Info Owner: Town of Grimshaw Operator: Town of Grimshaw Former Ownership: No Change Date of Change:  Airport Organization Ownership Structure:	Contact Info  Ms. Cathie Bailey Chief Administrator Officer Town of Grimshaw P.O. Box 377 Grimshaw T0H 1W0 (780) 332 4626(780) , Fax: 332 1250					
Organizational Structure: Role of Airport:	Primary: "07-25", 3000x75 (Turf) Fair condition; replacement 2007 (\$6000)  Secondary:					
Taxiway Data Primary:	Apron Data Primary:					
Secondary: Third:	Secondary:					
Fourth:  Landside Facility Data	Building Data  ATB:					
Entrance Road: Parking Lot:	Disability Access:					
Fencing:	Field Electrical Centre:					

<b>□Lighting Data</b>	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Troumty 1 rotoonon,
ARCAL: Type: Windsock: 0 windsocks;	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data					
FBO: No			AC Mai	ntenance:	No
Industrial Buildings: No			Crop Sp	praying Act	ivities:
Hangars: No			Chemica	als Stored (	on site:
Operation and Maintenance	_	1000	1000	2000	2001
Total Annual Maintenance Budge	1997 t	1998	1999	2000	2001
Economic Activity Informati	on				
- Airmont Activity Info					
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
1997	7 1998	199	99	2000	2001
Total Annual Revenue:					
Airport Expenditure Data					
Total Annual Expenditure	997 19	98 1	1999	2000	2001
Total Alliadi Experialtare					

Year	Project Name Funding Source		Description		

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 GRIST LAKE AIRPORT (CFY2)





Grist Lake Airport Aerial Photographs taken August 09, 2002

#### **Airport Contact Information:**

Grist Haven Lodge Cold Lake, AB T9M 1P3 Tel: (780) 594 1254

Fax: (780) 594 3433

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
	Distance From Community (mile): Latitude: 55.4000°, Longitude: -110.4833°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Grist Haven Lodge  Box 1350  Cold Lake  T9M 1P3  (780) 594 1254(780) , Fax: 594 3433
Airport Organization Ownership Structure:	
Organizational Structure:	Primary: "13-31", 3000x75 (Sand)
Role of Airport:	Secondary:
Taxiway Data Primary:	☐ Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
Landside Facility Data	ATB:
Entrance Road:	Disability Access:
Parking Lot:	Sisability / Recessi
Fencing:	Field Electrical Centre:

Lighting Data	□ Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
⊤Drainage Data <del>−−−−</del>	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	Spring Summer Fall William Average
Design Aircraft for Airport:	





FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Act	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Mainten	ance B	u <b>dget</b> - 1997	1998	1999	2000	2001
Total Annual Maintenance E	Budget					
Economic Activity Info	rmation	1				
- Airport Activity Info						
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movement	ts:					
Annual Passenger Movemer	nts:					
Commercial Airline Info	)					
 ─Airport Revenue Data						
	1997	1998	:	1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Da		_		16	g	
Total Annual Expenditure	1997	19	98	1999	2000	2001
. Star / iii iaar Experiatore						

Year	Project Name	Funding Source	Description		

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 HANNA AIRPORT (CEL4)





Hanna Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Mr. J. Duff Carrol Town Manager Town of Hanna Hanna, AB T0J 1P0 Tel: (403) 854 4433

Fax: (403) 854 2772

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Hanna Airport (EL4)

General Info Hanna (EL4)

Distance From Community (mile): 1

Latitude: 51.6333°, Longitude: -111.9000°

Owner and Operator Info

Owner: Town of Hanna Operator: Town of Hanna Former Ownership: ---Date of Change: ---

Airport Organization

Ownership Structure:

Town of Hanna

Organizational Structure:

Committee

Role of Airport:

General Aviation/Crop Spraying - Temporary/Medevac/Flying

School/Corporate(ATCA Plant, Luscar Mining)

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1971; last rehabilitation 1993; Fair condition; replacement 2009 (\$30000)

Secondary: "B"; (Asphalt)

constructed 1971; Fair condition; replacement 2009 (\$11000)

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 2lane; type asphalt; constructed

1971; fair condition; replacement

2008 (\$29000)

Parking Lot: size 20; type asphalt; constructed

1971; good condition;

Fencing: size 4ft; type 3 strand barb wire;

Contact Info

Mr. J. Duff Carrol Town Manager Town of Hanna P.O. Box 430 Hanna

наппа ТОЈ 1РО

(403) 854 4433(403), Fax: 854 2772

**Runway Data** 

Primary: "12-30", 3535x75 (Asphalt)

constructed 1971; last rehabilitation 1993; Good condition; replacement 2009

(\$469000)

Secondary: "02-20", 1800x100 (Turf)

Fair condition; replacement 2010

(\$17000)

**Apron Data** 

Primary: "main"; 300x150

constructed 1971; last rehabilitation 1993; good condition; replacement 2009

(\$97000)

Secondary: ---

**Building Data** 

ATB: size 2500; type wood frame; constructed

1980; good condition; replacement 2020

(\$100000)

Disability Access:

Field Electrical Centre: good condition;

Airport Summary Report

#### Hanna Airport (EL4)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

last rehabilitation 1998; good condition;

replacement 2009 (\$193000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

good condition; replacement 2008

Water / Sewer Data

Water Supply: Municipal Service; good

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: good condition; Subsurface: ---

Spring

Summer

Fall

Peak Period Info

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

--

Average

Winter





### Hanna Airport (EL4)


-Oneita Business Data						
Onsite Business Data  FBO: No			AC Ma	intenance:	No	
1561 116			710114			
Industrial Buildings: No			Crop S	praying Act	tivities: Ten	nporary; very limited
Hangars: Yes, ; see areal photo			Chemic	als Stored	on site:	
Operation and Maintenance B	_	4000	1000		2004	
Total Annual Maintenance Budget	1997	1998	1999	2000	2001	
☐ Economic Activity Information	1					]
•						
- Airmort Activity Info						
Airport Activity Info	1997	1998	1999	2000	2001	
Annual Aircraft Movements:						
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data						]
1997	1998	19	99	2000	2001	
Total Annual Revenue:						
Airport Expenditure Data	100	NO.	1000	2000	2001	
Total Annual Expenditure	' 199	)o	1999	2000	2001	-
·						

## Hanna Airport (EL4)

Year	Project Name	Funding Source	Description
1993		Provincial	Overlay asphalt surfaces
1992		Provincial	Pavement evaluation and testing
1987		Provincial	Purchase & install of NDB
1986		Provincial	Runway repairs
1980		Provincial	Extension of runway, additional airfield lighting, parking lot and access road.
1980		Provincial	Construction of Air Terminal Building
1977		Provincial	Repaving runway 2700' x 75' taxiway and parking apron, also airport lighting project
1975		Federal	Runway paving
1971		Federal	Original construction

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 HARDISTY AIRPORT (CEA5)





Hardisty Airport Aerial Photographs taken July 12, 2002

#### **Airport Contact Information:**

Ms. Debbie Johannesson Administrator Town of Hardisty Hardisty, AB T0B 1V0 Tel: (780) 888 3623

Fax: (780) 888 2200

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Hardisty Airport (EA5)

General Info

Hardisty (EA5) Distance From Community (mile): 3.5
Municipal Latitude: 52.6500°, Longitude: -111.3833°

Owner and Operator Info

Owner: Town of Hardisty Operator: Town of Hardisty Former Ownership: No Change

Date of Change: ---

Airport Organization

Ownership Structure:

---

Organizational Structure:

Municipal Government/Private

Role of Airport:

Minimal use, mainly oilfield related and pipeline inspection.

**Taxiway Data** 

Primary: "A"; (Asphalt)

last rehabilitation 1975; Poor condition;

replacement 2003 (\$39000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type Gravel; fair condition;

Parking Lot: ---

Fencing: size 4 strand; type Barb Wire;

Contact Info

Ms. Debbie Johannesson

Administrator Town of Hardisty

Box 10 Hardisty T0B 1V0

(780) 888 3623(780), Fax: 888 2200

Runway Data

Primary: "07-25", 3000x75 (Asphalt)

Poor condition; replacement 2003

(\$439000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

poor condition; replacement 2003

(\$63000)

Secondary: ---

**Building Data** 

ATB: type Wood Frame; constructed 1987; fair

condition;

Disability Access: ---

Field Electrical Centre: type Tool Shed; replacement

2005

Airport Summary Report

#### Hardisty Airport (EA5)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

fair condition; replacement 2005 (\$1570)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

poor condition; replacement 2002

Water / Sewer Data

Water Supply: Well; constructed 1987; fair

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: fair condition; Subsurface: size 10; fair condition;

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Hardisty Airport (EA5)

Onsite Business Data				
FBO: No		AC	Maintenance:	No
Industrial Buildings: No		Cro	pp Spraying Ad	tivities:
Hangars: Yes, ; John Golka		Che	micals Stored	on site:
Operation and Maintenance	Budaet -			
	1997	1998 19	99 2000	2001
Total Annual Maintenance Budget				
Economic Activity Information	on —			
Road Distance to Nearest Airport Road Distance to Nearest Airport Road Distance to Nearest Airport	Sched. Pax MedEvac Se	ervice: 5	5	
Airport Activity Info				
	1997	1998 199	99 2000	2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data				
1997	1998	1999	2000	2001
Total Annual Revenue:				
Airport Expenditure Data	07 40	00 1000	2000	2004
Total Annual Expenditure	97 19	98 1999	2000	2001

### Hardisty Airport (EA5)

Year	Project Name	Funding Source	Description
1999	,	municipal	Standard painted airport markings
1990		Provincial	Fencing installation
1988		Provincial	Purchase and install NDB
1988		Provincial	Radio Equipment Building
1988		Provincial	Slurry seal runway
1986		Provincial	Terminal Building
1978		Provincial	Paving and lighting
1975		Federal	Initial construction, earth moving, grading and levelling
1975		Provincial	Land purchase

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 HESPERO AIRPORT (CFB3)





Hespero Airport Aerial Photographs taken October 10, 2002

#### **Airport Contact Information:**

Mr. Ron Skocdopole Skocdopole Construction Eckville, AB T0M 0X0 Tel: (403) 746 5743

Fax: (403) 746 3330

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Hespero (FB3)	Distance From Community (mile): 2
Private - Public Use	Latitude: 52.3000°, Longitude: -114.4667°
Owner and Operator Info	□ Contact Info
Owner:	Mr. Ron Skocdopole
Operator:	Skocdopole Construction
Former Ownership: Date of Change:	RR4 Eckville
Date of Change	TOM 0X0
Airport Organization	(403) 746 5743(403) , Fax: 746 3330
Ownership Structure:	
	┌Runway Data
Organizational Structure:	Primary: "11-29", 2800x100 (Turf)
	Good condition;
	,
Role of Airport:	
	Secondary: "02-20", 2600x100 (Turf)
	Good condition;
⊤Taxiway Data <del>−−−−</del>	
Primary:	
	Apron Data
	Primary:
Secondary:	
The board.	Secondary:
Third:	Secondary
Fourth:	
	- Duilding Date
	Building Data
Landside Facility Data	ATB:
•	
Entrance Road:	
	Disability Access:
Parking Lots	
Parking Lot:	
	Field Electrical Centre:
Fencing:	

Lighting Data	┌Water / Sewer Data
Primary Edgelighting: TE (The constr	reshold and Runway End) wcted 1975; fair condition;  Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





□Onsite Business Data ──					
FBO: No			AC Maintena	ance: No	
Industrial Buildings: No			Crop Sprayii	ng Activities:	
Hangars: No		•	Chemicals St	tored on site:	
Operation and Maintenanc	e Budget	1998	1999 2	000 2001	1
Total Annual Maintenance Budg		1990	1999 2	000 2001	
Economic Activity Informa	tion				
Airport Activity Info	1997	1998	1999 20	000 2001	
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					]
Airport Revenue Data	97 199	8 1999	9 2000	) 2001	
Total Annual Revenue:	,, 133	<u> </u>	2000	, 2001	
Airport Expenditure Data	1997 1	998 19	999 20	000 2001	
Total Annual Expenditure	<u></u>	<del>-</del> ·			_

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 HIGH LEVEL AIRPORT (CYOJ)





High Level Airport Aerial Photographs taken August 20, 2002

#### **Airport Contact Information:**

Mr. Jim Lindsay Airport Manager High Level Airport High Level, AB T0H 1Z0 Tel: (780) 926 3659

Fax: (780) 926 2939

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### High Level Airport (YOJ)

General Info

Distance From Community (mile): 6 High Level (YOJ) Latitude: 58.6214°, Longitude: 117.1647°

Owner and Operator Info

Owner: Town of High Level Operator: Town of High Level

Former Ownership: Province of Alberta

Date of Change: June 1, 1996

**Airport Organization** 

Ownership Structure:

Town of High Level

Organizational Structure:

Role of Airport:

Regional Hub

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1964; last rehabilitation 1999;

Good condition;

Secondary: "Private-Forestry"; (Asphalt) constructed 1975; last rehabilitation

1999; Good condition;

Third: "Hanger access"; 265x15 (Gravel)

constructed 1975; Fair condition; replacement

2004

Fourth: ---

**Landside Facility Data** 

Entrance Road: constructed 1964; last rehabilitation

1986; fair condition;

Parking Lot: constructed 1964; last rehabilitation

1986; fair condition;

Fencing: size 8ft; type wildlife;

Contact Info

Mr. Jim Lindsay Airport Manager High Level Airport 9813 - 102 Street

High Level T0H 1Z0

(780) 926 3659(780), Fax: 926 2939

**Runway Data** 

Primary: "13-31", 5000x150 (Asphalt)

constructed 1964; last rehabilitation 1999; Good condition; replacement 2010

(\$1500000)

Secondary: ---

**Apron Data** 

Primary: ---

Secondary: ---

**Building Data** 

ATB: ---

Disability Access:

Field Electrical Centre: size 14 sq m; type wood

frame; constructed 1970; last rehabilitation 1986; fair

condition;

Airport Summary Report

#### High Level Airport (YOJ)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1975; last rehabilitation 199

good condition;

Approach Slope Indicator 1: P2 (PAPI - Aircraft up to 25')

constructed 1975; last rehabilitatic

1999; good condition;

Approach Slope Indicator 2: P2 (PAPI - Aircraft up to 25')

constructed 1975; last rehabilitatic

1999; fair condition;

ARCAL: Type: ---

Windsock: 2 windsocks;

constructed 1964; last rehabilitation 1999; good

condition;

Water / Sewer Data

Water Supply: Municipal Service; fair

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: Yes

**Drainage Data** 

Surface: constructed 1975; Subsurface: ---

Peak Period Info
Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:
Design Aircraft for Airport: 737 737 737 737 ---



Airport Summary Report



#### High Level Airport (YOJ)

**Onsite Business Data** 

FBO: Yes, 1; LITTLE RED AIR SERVICE AC Maintenance: Yes,;

Industrial Buildings: Yes, 1; NATIONAL Crop Spraying Activities: Temporary;

Hangars: Yes, 7; Chemicals Stored on site:

Operation and Maintenance Budget

1997 2000 2001 1998 1999

Total Annual Maintenance Budget

#### **Economic Activity Information**

Road Distance to Nearest Airport Sched. Pax Service: 140

CAR/TRUCK RENTAL

Road Distance to Nearest Airport MedEvac Service: 80

Road Distance to Nearest Airport Cargo Service: 140 Road Distance to Nearest Airport AME Service: 280

Road Distance to Nearest Airport Fire Suppression Service: 12 Major Economic Industries in Region: Oil & Gas/Farming/Wood

Products/Government

How is the Airport Vital to the Region: EFFICIENT ACCESS TO MAJOR CENTRES, HEAD OFFICES; SHOPPING ETC. ESSENTIAL MEDEVAS SERVICES 24 HRS/DAY

**Airport Activity Info** 

1997 1998 1999 2000 2001

**Annual Aircraft Movements:** 

**Annual Passenger Movements:** 

#### **Commercial Airline Info**

Air Canada Jazz (B1900, Schedule)

Quikair (Metro, Schedule)

Peace Air (Pilatus PC12, Schedule)

Little redAir Service (Mixed, Charter/Medevac)

Delta Helicopters (Mixed Helicopters, Charter)

Canadian helicopters (Mixed Helicopters, )

**Airport Revenue Data** 

1997 1999 2000 2001 1998

Total Annual Revenue:

**Airport Expenditure Data** 

1997 1998 1999 2000 2001

**Total Annual Expenditure** 

#### High Level Airport (YOJ)

#### Historic Capital Expenditures Year Project Name **Funding Source** Description 2000 Provincial pavement overlay (per transition agreement) 1997 Provincial Fog seal and repainting 1993 Provincial Completion of reseeding 1992 Reseeding agricultural lease area Provincial Storages Building repairs, misc. small 1990 Provincial projects Air Terminal Building area improvments 1989 Provincial 1989 Provincial Lighting 1989 Provincial Access Road 1988 Provincial 1988 Provincial 1988 Provincial Air Terminal Building 1988 Provincial Airfiled lighting improvments Air Terminal Building 1987 Provincial Upgrade airfield lighting, microwaved landing 1987 Provincial system power cables and rewire VASIS 1986 Provincial Purchase microwave landing system 1977 Provincial Air Tanker base completion 1976 Runway and Air Tanker Base paving and Provincial parking apron expansion

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 HIGH PRAIRIE AIRPORT (CZHP)





High Prairie Airport Aerial Photographs taken July 24, 2002

#### **Airport Contact Information:**

Mr. Brian Martinson Community Development Officer Town of High Prairie High Prairie, AB T0G 1E0 Tel: (780) 523 3388

Fax: (780) 523 5930

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### High Prairie Airport (ZHP)

**General Info** 

High Prairie (ZHP)

Municipal

Distance From Community (mile): 5 Latitude: 55.4000°, Longitude: -116.4667°

Owner and Operator Info

Owner: Town of High Prairie Operator: Brian Martinson

Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Owned by Town of High Prairie

Organizational Structure:

Town of High Prairie (owned)/MD of Big Lakes (share costs)

Role of Airport:

Provide local and medi-vac service for surrounding area.

**Taxiway Data** 

Primary: "A"; 514x48 (Asphalt)

constructed 1978; Fair condition; replacement 2012 (\$20000)

Secondary: "west"; 514x48 (Asphalt)

Good condition;

Third: "east"; (Gravel)

Good condition;

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 24'; type asphalt; constructed

1978; fair condition;

Parking Lot: size 134'x190'; type asphalt;

constructed 1978; last rehabilitation

2000; good condition;

Fencing: ---

Contact Info

Mr. Brian Martinson

Community Development Officer

Town of High Prairie

P.O. Box 179 High Prairie

T0G 1E0

(780) 523 3388(780) , Fax: 523 5930

**Runway Data** 

Primary: "07-25", 3933x75 (Asphalt)

constructed 1978; last rehabilitation 2000; Good condition; replacement 2009

(\$500000)

Secondary: ---

**Apron Data** 

Primary: ---

Secondary: ---

**Building Data** 

ATB: size 68'x40'; type wood; constructed 1978;

last rehabilitation 1996; fair condition;

Disability Access: type cement; fair condition;

Field Electrical Centre: fair condition; replacement

2010 (\$150000)

Airport Summary Report

### High Prairie Airport (ZHP)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1977; last rehabilitation 198

fair condition; replacement 2010 (\$1630)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 122.8

Windsock: 1 windsocks;

constructed 1978; fair condition; replacement 2

Water / Sewer Data

Water Supply: Other; constructed 1978; poor

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No Right of Way: No

**Drainage Data** 

Surface: constructed 1978; poor condition; Subsurface: ---

Peak Period Info
Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:
Design Aircraft for Airport:





### High Prairie Airport (ZHP)

O '' D ' D '							
Onsite Business Data							
FBO: No			AC Maintenance: No				
Industrial Buildings: Yes, 5;			Crop Sp	oraying Act	tivities:		
Hangars: No	Hangars: No Chemicals Stored of						
Operation and Maintenand	ce Budget						
	1997	1998	1999	2000	2001		
Total Annual Maintenance Bud	get						
Economic Activity Informa	ation ———						
Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Major Economic Industries in R How is the Airport Vital to the I	ort MedEvac S ort Cargo Serv ort AME Servic ort Fire Suppre Region: Oil &	ervice: 3 ice: 0 ee: 0 ession Servi Gas/Lumbe	ce: 3	ng			
Airport Activity Info							
-	1997	1998	1999	2000	2001		
Annual Aircraft Movements:							
Annual Passenger Movements:							
Commercial Airline Info							
Airport Revenue Data							
-	97 1998	3 199	9	2000	2001		
Total Annual Revenue:							
Airport Expenditure Data	1007 11	200 1	000	2000	2004		
	1997 19	998 1	999	2000	2001		
Total Annual Expenditure							

## High Prairie Airport (ZHP)

Year	Project Name	Funding Source	Description
2002		Provincial	Pavement overlay
2000		Provincial	Runway extension
1989		Provincial	Runway pavement repairs
1987		Provincial	Upgrade airfield lighting
1986		Provincial	Complete upgrading of NDB
1986		Provincial	Install DME
1984		Provincial	Upgrade NDB
1982		Provincial	reconstruct runway, drainage improvemen
1978		Provincial	Completion of lighting
1977		Provincial	Air Terminal Building
1977		Federal	Construction
1977		Provincial	Airport construction, paving and lighting

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 HIGH RIVER AIRPORT (CEN4)





High River Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Gary Hudson Highwood Airport Commission Muncipal District of Foothills High River, AB T1V 1M7 Tel: (403) 652 2110

Fax: (403) 652 2110

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### High River Airport (EN4)

General Info

High River (EN4) Distance From Community (mile): 2.5
Municipal Latitude: 50.5333°, Longitude: -113.8333°

**Owner and Operator Info** 

Owner: Town of High River & MD of Foothills

Operator: Highwood Airport

Former Ownership: Province of Alberta

Date of Change: August 1, 1998

**Airport Organization** 

Ownership Structure:

Town of High River, MD of Foothills No. 31

Organizational Structure:

Highwood Airport Commission/Town of High River/MD of

Foothills/3 members at large (independent)

Role of Airport:

---

**Taxiway Data** 

Primary: "Main"; 76x45 (Asphalt)

constructed 1978; Poor condition;

replacement 2003

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

**Entrance Road:** 

Parking Lot: size 14 stalls; type gravel; good

condition;

Fencing: type barbed wire;

Contact Info

Mr. Gary Hudson

Highwood Airport Commission Muncipal District of Foothills

Box 5605

High River T1V 1M7

(403) 652 2110(403), Fax: 652 2396

Runway Data

Primary: "06-24", 3000x75 (Asphalt)

constructed 1978; last rehabilitation 1999; Good condition; replacement 2015

Secondary: "14-32", 2950x75 (Stabilized Gravel)

Poor condition; replacement 2005

(\$31000)

**Apron Data** 

Primary: "Main"; 76x45 (Asphalt)

constructed 1978; poor condition;

replacement 2003

Secondary: ---

**Building Data** 

ATB: ---

Disability Access: ---

Field Electrical Centre: size 6'x8'; type wood frame;

constructed 1978; fair condition; replacement 2008

condition, replacement

(\$150000)

## High River Airport (EN4)

Lighting Data		Water / Sewer Data
	nreshold and Runway End) ucted 1978; fair condition; ement 2008 (\$121000)	Water Supply: Well; poor condition;
Approach Slope Indicator 1:		Sewage:
Approach Slope Indicator 2:		Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No
ARCAL: Type:		Caveat: No Right of Way: No
Windsock: 1 windsocks;	1978; good condition; replacement	ragine of way. 140
Drainage Data		
Surface:	Subsurfa	ace:
Peak Period Info	Spring Summer Fall W	inter Average
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		





### High River Airport (EN4)

Total Annual Expenditure

igh River Airport (EN4)						
Onsite Business Data						
FBO: Yes, 1; High River flight of	centre		AC Mai	intenance:	Yes, 1; Hig	gh River flight centre
Industrial Buildings: Yes, 1; Mar	go Supplies		Crop S	praying Ac		nporary; as required l iculture
Hangars: Yes, 11;			Chemic	als Stored	on site: non	e
Operation and Maintenance	e Budget - 1997	1998	1999	2000	2001	
Total Annual Maintenance Budg		1990	1999	2000	2001	
Economic Activity Information	tion					]
Road Distance to Nearest Airpor Road Distance to Nearest Airpor Road Distance to Nearest Airpor Road Distance to Nearest Airpor Road Distance to Nearest Airpor Major Economic Industries in Re	t MedEvac Serv t Cargo Serv t AME Servic t Fire Suppre	ervice: 7 ice: 90 e: 90 ession Ser	vice: 7	s ltd.		
Airport Activity Info	1997	1998	1999	2000	2001	
Annual Aircraft Movements:						
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data						]
199	7 1998	3 19	999	2000	2001	
Total Annual Revenue:						
Airport Expenditure Data	997 10	198	1999	2000	2001	

## High River Airport (EN4)

<b>Year</b>	Project Name	Funding Source	Description
1999	-	Provincial	Pavement overlay
1995		Provincial	Residual payment for slurry seal
1992		Provincial	Slurry seal paved surfaces
1986		Provincial	Grant towards construction of crosswind runway
1984		Provincial	Supplementary Terminal Building
1982		Provincial	Terminal Building
1978		Provincial	Grading, base, paving and lighting
1977		Provincial	Land purchase

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 HINTON/ENTRANCE AIRPORT (CEE4)





Hinton/Entrance Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Marcel Franche Fuel Manager Hinton Flying Club Hinton, AB T0E 1C0 Tel: (780) 865 1343

Fax: (780) 865 3513

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

## Hinton/Entrance Airport (EE4)

General Info					
	e From Community (mile): 6 e: 53.3833°, Longitude: -117.7000°				
Owner and Operator Info	Contact Info				
Owner:	Mr. Marcel Franche				
Operator:	Fuel Manager				
Former Ownership:	Hinton Flying Club				
Date of Change:	Box 2545 Hinton				
Airport Organization	T0E 1C0				
-	(780) 865 1343(780) , Fax: 865 3513				
Ownership Structure:					
	Runway Data				
Organizational Structure:					
	Primary: "04-22", 3700x150 (Turf)				
Role of Airport:					
	Secondary:				
	<u> </u>				
Taxiway Data					
Primary:					
	Apron Data				
	Primary:				
Secondary:					
Third:	Secondary:				
Fourth:					
Todium.					
	Building Data				
Landside Facility Data	ATB:				
•					
Entrance Road:					
	Disability Access:				
Daulding Late					
Parking Lot:					
	Field Electrical Centre:				
Fencing:	ricia Electrical Certae.				

### Hinton/Entrance Airport (EE4)

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

Lighting Data					Vater / Se	wer Data	
Primary Edgelighting:				W	/ater Suppl	y:	
Approach Slope Indicator 1:	-			Se	ewage:	-	
Approach Slope Indicator 2:	-				icinity Pr	otection, d Right of Way	
ARCAL: Type: Windsock: 0 windsocks;					Vicinity Prot Caveat: N Right of Wa		
Drainage Data							
Surface:			Subs	surface:			
Peak Period Info	Spring	Summer	Fall	Winter	Average		





### Hinton/Entrance Airport (EE4)

Onsite Business Data					
FBO: No			AC Main	tenance:	No
Industrial Buildings: No			Crop Spi	raying Acti	vities:
Hangars: No			Chemical	s Stored o	n site:
Operation and Maintenand	_				
Total Annual Maintenance Budg	1997 iet	1998	1999	2000	2001
Economic Activity Informa	tion				
- Almo - mt					
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
Total Appual Boyonua	97 199	8 199	99 2	2000	2001
Total Annual Revenue:					
Airport Expenditure Data					
	1007 1	000	1000	2000	2004
Total Annual Expenditure	1997 1	998 :	1999	2000	2001

## Hinton/Entrance Airport (EE4)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## **AIRPORT INFORMATION REPORT - 2002 HINTON/JASPER-HINTON AIRPORT (CEC4)**





Hinton/Jasper-Hinton Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Frank Besinger Operations Manager Yellow Head County Edson, AB T7E 1N9 Tel: (780) 865 4474/723 2525

Fax: (780) 712-4025

#### Prepared for:



Aviation Strategy Action Group

11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Hinton/Jasper-Hinton Airport (EC4)

**General Info** 

Hinton/Jasper-Hinton (EC4)

Municipal

Distance From Community (mile): 9.5 Latitude: 53.3167°, Longitude: -117.7500°

Owner and Operator Info

Owner: Yellowhead County Operator: Yellowhead County

Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Yellowhead County

Organizational Structure:

County Council/Chief Administrative Officer/Airport Manager/Airfield Maintenance Supervisor/Airport Opertor

Role of Airport:

Jasper/Hinton Airport is operational 24hrs/day/7-days/wk and

is capable of supporting VFR Operations

**Taxiway Data** 

Primary: "C"; 650x50 (Asphalt)

constructed 1978; Fair condition; replacement 2005 (\$72000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; constructed 1978; fair

condition;

Parking Lot: type gravel; constructed 1978; fair

condition;

Fencing: size 10ft; type wildlife; replacement 2001

Contact Info

Mr. Frank Besinger Operations Manager Yellow Head County 2716 - First Avenue

Edson T7E 1N9

(780) 865 4474/723 2525(780), Fax: 712-

4025

**Runway Data** 

Primary: "02-20", 4500x100 (Asphalt)

constructed 1978; Fair condition; replacement 2005 (\$1380000)

Secondary: ---

**Apron Data** 

Primary: "1"; 250x200 (Asphalt)

constructed 1978; fair condition; replacement 2005 (\$174000)

Secondary: ---

**Building Data** 

ATB: constructed 1978; fair condition;

Disability Access: ---

Field Electrical Centre: type 1-new regulator; last

rehabilitation 2001; fair

condition;

Airport Summary Report

### Hinton/Jasper-Hinton Airport (EC4)

#### Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1978; last rehabilitation 199 fair condition; replacement 2006 (\$1920)

Approach Slope Indicator 1: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1978; fair condition; replacement 2006 (\$60000)

Approach Slope Indicator 2: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1978; fair condition; replacement 2006 (\$60000)

ARCAL: Type: "K"; freq 123.2

Windsock: 2 windsocks;

good condition;

#### Water / Sewer Data

Water Supply: Well; constructed 1978; fair

condition;

Sewage: fair condition;

### Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: ---

# Peak Period Info Spring Summer Fall Winter Average Peak Apron Aircraft Parked: Design Aircraft for Airport: ---





### Hinton/Jasper-Hinton Airport (EC4)

Onsite Business Data

FBO: No		AC	Maintenance	: No
Industrial Buildings: No		Cro	p Spraying A	ctivities: Temporary
Hangars: No		Che	micals Stored	on site:
Operation and Maintenance	Budget 1997	1998 19	99 2000	2001
Total Annual Maintenance Budge		1990 19	99 2000	2001
Economic Activity Informat	ion			
Road Distance to Nearest Airport Road Distance to Nearest Airport Major Economic Industries in Re How is the Airport Vital to the Re Aircraft	t Fire Suppre gion: Fores	ssion Service: try/Mining/Oil	20 & Gas Private and Co	orportate
<b>□</b> Airport Activity Info				
Annual Aircraft Movements:	1997	1998 199	99 2000	2001
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	7 1998	1999	2000	2001
Total Annual Revenue:	, 1550	. 1000	2000	2001
Airport Expenditure Data	207 :-	00 4055	2022	2004
Total Annual Expenditure	997 19	98 1999	2000	2001

## Hinton/Jasper-Hinton Airport (EC4)

Year	Project Name	Funding Source	Description
1999		Provincial	Fog Coat
1998		Provincial	Major crack repair
1994		Provincial	Upgrade DME to precision DME standard
1994		Provincial	Fog seal paved surfaces
1994		Provincial	Install precision DME
1988		Provincial	purchase and install AWOS
1985		Provincial	Install microwave landing system
1984		Provincial	Purchase of microwave landing system ar VASIS and NDB
1978		Provincial	Grading, base and paving, Maintenance garage, air Terminal Building and residence
1977		Provincial	Preliminary soils survey

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 INDUS/WINTERS AIRE PARK AIRPORT (CFY4)





Indus/Winters Aire Park Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Mr. Ralph C. Winters Calgary, AB T2P 2G6 Tel: (403) 936 5347/936 5767 Fax: (403) 936 5108

### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info			
Indus/Winters Aire Park (FY4) Private - Public Use		ommunity (mile): 1 0°, Longitude: -113.7833°	
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:		Mr. Ralph C. Winters Box 12 Site 9 RR5 Calgary T2P 2G6 (403) 936 5347/936 5767(403) , Fax: 936	
Airport Organization		5108	
Ownership Structure: Private			
	Runw	ay Data —	
Organizational Structure:  Flight Club	Primary	y: "09-27", 1930x75 (Turf) Fair condition; replacement 2020	
Role of Airport:			
Small GA Airport	Second	Secondary: "16-34", 2450x75 (Turf) Fair condition; replacement 2020	
Taxiway Data			
Primary:			
	Apron	Data —	
Secondary:	Primary	y:	
Third:	Second	lary:	
Fourth:			
	⊢Buildi	ng Data	
	ATB: -		
Landside Facility Data			
Entrance Road:			
	Disabili	ty Access:	
Parking Lot:			
	Field El	ectrical Centre:	
Fencing:			
	1.1		

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1: -	Sewage:
Approach Slope Indicator 2: -	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
,	
<b>□Drainage Data</b>	
Surface:	Subsurface:
Peak Period Info	
1 Jun 1 Jilou IIII	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data							
FBO: No			AC Ma	intenance:	No		
Industrial Buildings: No			Crop S	Crop Spraying Activities:			
Hangars: Yes, ;			Chemicals Stored on site:				
<b>├</b> Operation and Maintenance E	_						
Total Annual Maintenance Budget	1997	1998	1999	2000	2001		
Economic Activity Informatio	n ——						
Airport Activity Info	1997	1998	1999	2000	2001		
Annual Aircraft Movements:							
Annual Passenger Movements:							
Commercial Airline Info							
Airport Revenue Data	1000	, ,	1000	2000	2001		
Total Annual Revenue:	1998	<u> </u>	1999	2000	2001		
Airport Expenditure Data	7 10	00	1000	2000	2001		
Total Annual Expenditure	, 19	98	1999	2000	2001		

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 INNISFAIL AIRPORT (CEM4)





Innisfail Airport Aerial Photographs taken October 10, 2002

#### **Airport Contact Information:**

Mr. Art Fox Innisfail Flying Club Innisfail, AB T4G 1T6 Tel: (403) 227 3584 Fax: (403) N/A

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Innisfail Airport (EM4)

**General Info** 

Innisfail (EM4) Distance From Community (mile): 3.9 Latitude: 52.0833°, Longitude: -114.0333°

Owner and Operator Info

Owner: Red Deer County Operator: Innisfail Flying Club

Former Ownership: Transport Canada

Date of Change: ---

**Airport Organization** 

Ownership Structure:
Red Deer County

Organizational Structure:

---

Role of Airport:

To provide training area/Commercial use/Private user/Area for business development/Aviation/Other

**Taxiway Data** 

Primary: "A"; 1000x100 (Asphalt)

constructed 1941; last rehabilitation 1982;

Poor condition; replacement 2004

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel/paved; constructed 1941;

fair condition; replacement 2006

Parking Lot: type paved; fair condition; replacement

2006 (\$23000)

Fencing: size 4ft; type barb wire;

Contact Info

Mr. Art Fox

Innisfail Flying Club c/o Site 22, Box 18, RR #1

Innisfail T4G 1T6

(403) 227 3584(403), Fax: N/A

Runway Data

Primary: "16-34", 3025x100 (Asphalt)

constructed 1941; last rehabilitation 1984; Fair condition; replacement 2006

(\$389000)

Secondary: "10-28", 3025x100 (Asphalt)

Poor condition; replacement 2003

(\$389000)

**Apron Data** 

Primary: "1"; 300x200 (Asphalt)

constructed 1941; last rehabilitation 1982; poor condition; replacement 2004

(\$81000)

Secondary: ---

**Building Data** 

ATB: type D/W Atco Trailer; constructed 1984; fair

condition; replacement 2011 (\$100000)

Disability Access: ---

Field Electrical Centre: size 6x6; type tool

shed/locked;

Airport Summary Report

### Innisfail Airport (EM4)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1978; fair condition; replacement 2006 (\$225000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123

Windsock: 1 windsocks;

constructed 1978; fair condition; replacement 2

Water / Sewer Data

Water Supply: Well; constructed 1941; good

condition;

Sewage: Other; fair condition;

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1941; good condition; Subsurface: constructed 1941; good condition;

Peak Period Info
Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:
Design Aircraft for Airport:

---





### Innisfail Airport (EM4)

□Onsite Business Data —							
FBO: No			AC Maint	tenance:	No		
Industrial Buildings: Yes, 2;			Crop Spraying Activities:				
Hangars: Yes, 10; 2-Innisfail Fl Schurback/Merv Final Rasmussen/Alvie Har Moore/Clint Lewis/Bri	ly/Don nd/DND/Roy	i	Chemicals	s Stored o	n site: no		
Operation and Maintenance	e Budget	1998	1000	2000	2001		
Total Annual Maintenance Budg		1990	1999	2000	2001		
Economic Activity Informa	tion						
Road Distance to Nearest Airport MedEvac Service: 115 Road Distance to Nearest Airport Cargo Service: 15 Road Distance to Nearest Airport AME Service: 15 Road Distance to Nearest Airport Fire Suppression Service: 10 Major Economic Industries in Region: Service/Industrial Industries How is the Airport Vital to the Region: Unique Glider Training Area/Spouse copilot courses/Alternate for F.B.O. at Red Deer/130 stuents throgh Young Eagles Program/Local Flying Club/Business Flghts/Police Flights							
Airport Activity Info	1997	1998	1999	2000	2001		
Annual Aircraft Movements:							
Annual Passenger Movements:							
Commercial Airline Info							
Airport Revenue Data	97 199	3 199	10 2	000	2001		
Total Annual Revenue:	57 155	3 133	2	.000	2001		
Airport Expenditure Data	1997 19	998 1	999	2000	2001		
Total Annual Expenditure	1991 1	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		2000	2001		

## Innisfail Airport (EM4)

Year	Project Name	Funding Source	Description
2002			Repaired runway lights
2001			Rebuilt entrance road
1999			leveled & reseeded runway grass areas 16 34 and 28-10
1984		Provincial	Remedial overlay work
1984		Provincial	Terminal Building
1982		Provincial	Runway (16-34) and taxiway lighting
1982		Provincial	Chip seal overlay on 16-34 and taxiway

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 IRMA AIRPORT (CFU8)





Irma Airport Aerial Photographs taken July 11, 2002

#### **Airport Contact Information:**

Mr. Gordon Oracheski Irma, AB T0B 2H0 Tel: (780) 754 2410/3772 Fax: (780) 754 2424

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

## Irma Airport (FU8)

General Info	
	Distance From Community (mile): 2.2 atitude: 52.9167°, Longitude: -111.1667°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Mr. Gordon Oracheski Box 368 Irma T0B 2H0 (780) 754 2410/3772(780) , Fax: 754 2424
Airport Organization	
Ownership Structure:	
Private - Gordon Oracheski Organizational Structure:	Runway Data  Primary: "10-28", 2500x65 (Oiled Gravel)
Private  Role of Airport:	constructed 1998; last rehabilitation 1999; Fair condition; replacement 2002 (\$23000)
Private Strip	Secondary:
Taxiway Data Primary:	☐ Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	-Puilding Data
	Building Data
Landside Facility Data	ATB:
Entrance Road: constructed 2002;	
Entrance Road. Constructed 2002,	Disability Access:
Parking Lot:	
Fencing: size 4'; type barbed wire;	Field Electrical Centre:

Airport Summary Report

### Irma Airport (FU8)

-1	Li	a	ht	in	a	D	ata

Primary Edgelighting: RR (Retro-reflective Markers)

constructed 1999; good condition;

Approach Slope Indicator 1: AP (Abbreviated PAPI - Aircraft up

10')

Approach Slope Indicator 2: AV (Abbreviated VASIS)

constructed 1999;

ARCAL: Type: ---

Windsock: 1 windsocks;

constructed 2002; good condition;

Spring

Summer

Fall

### Water / Sewer Data

Water Supply: Well; constructed 1990; good

condition;

Sewage: ---

### Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: ---

Subsurface: ---

Winter

#### **Peak Period Info**

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

Average





### Irma Airport (FU8)

Onsite Business Data								
FBO: No				AC Ma	intenance:	No		
Industrial Buildings: Yes, 1;	Industrial Buildings: Yes, 1;							
Hangars: No					cals Stored	on site:		
─Operation and Mainten	ance B	Sudget - 1997	1998	1999	2000	2001		
Total Annual Maintenance I	Budget							
Economic Activity Information								
Road Distance to Nearest Airport Sched. Pax Service: 130 Road Distance to Nearest Airport MedEvac Service: 50 Road Distance to Nearest Airport Cargo Service: 130 Road Distance to Nearest Airport AME Service: 130 Road Distance to Nearest Airport Fire Suppression Service: 5 Major Economic Industries in Region: Oil & Gas How is the Airport Vital to the Region: numerous visitor for area families; oilfield work								
Airport Activity Info		1997	1998	1999	2000	2001		
Annual Aircraft Movemen	ts:	1337	1330	1333	2000			
Annual Passenger Moveme	nts:							
Commercial Airline Infe	0							
A: 15 51								
─Airport Revenue Data	1997	1998	 B1	1999	2000	2001		
Total Annual Revenue:								
Airport Expenditure Da		7 10	100	1000	2000	2001		
Total Annual Expenditure	1997	, 15	98	1999	2000	2001		

## Irma Airport (FU8)

Year	Project Name	Funding Source	Description	
1998	Oil	Private	gravel and oil strip	
1998	Electrical	Private	installed electrc lights	
1995	Land Level	Private	level land	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 JANVIER AIRPORT (CEP5)





Janvier Airport Aerial Photographs taken August 09, 2002

#### **Airport Contact Information:**

Mr. Wes Holodeniuk Superintendent Municipal District of Wood Buffalo Fort McMurray, AB T9H 5A1 Tel: (780) 799 7930/559 2235 Fax: (780) 799 5909

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Janvier Airport (EP5)

#### General Info

Janvier (EP5) Distance From Community (mile):

Municipal Latitude: 55.9000°, Longitude: -110.7333°

#### Owner and Operator Info

Owner: Regional Municipality of Wood Buffalo Operator: Regional Municipality of Wood Buffalo

Former Ownership: Province of Alberta

Date of Change: April 1, 1995

#### **Airport Organization**

Ownership Structure:

Regional Municipality of Wood Buffalo

#### Organizational Structure:

Regional Municpality of Wood Buffalo (owned)/Road & Transportation (maintenance)

#### Role of Airport:

The airport is primarily used for medical services, forest fire fighting, oil companies and for exploration.

### **Taxiway Data**

Primary: ---

Secondary: ---

Third: ---

Fourth: ---

#### **Landside Facility Data**

Entrance Road: size 10m; type gravel; constructed

1982; good condition;

Parking Lot: size 40x30m; type gravel; constructed

1982; good condition;

Fencing:

#### Contact Info

Mr. Wes Holodeniuk Superintendent

Municipal District of Wood Buffalo

9909 Franklin Avenue Fort McMurray

T9H 5A1

(780) 799 7930/559 2235(780), Fax: 799

5909

#### **Runway Data**

Primary: "13-31", 4500x100 (Gravel)

constructed 1982; Good condition;

Secondary: ---

#### **Apron Data**

Primary: ---

Secondary: ---

#### **Building Data**

ATB: ---

Disability Access: ---

Field Electrical Centre: size 8x10x7; type aluminum

shed; constructed 1982; fair

condition;

## Janvier Airport (EP5)

Lighting Data	┌Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 1 windsocks; constructed 1984; good condition;	
Drainage Data	haufeas

Diamag	e Data		
Surface:	constructed 1982;	Subsurface:	

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





## Janvier Airport (EP5)

Onsite Business Data	
FBO: No	AC Maintenance: No
Industrial Buildings: No	Crop Spraying Activities:
Hangars: No	Chemicals Stored on site:
Operation and Maintenance Budg	
Total Annual Maintenance Budget	97 1998 1999 2000 2001
Economic Activity Information	
Major Economic Industries in Region: Now is the Airport Vital to the Region: Janvier as it provides them with emerge fighting	The airport is important to the residents of
Airport Activity Info	07 1998 1999 2000 2001
Annual Aircraft Movements:	77 1990 1999 2000 2001
Annual Passenger Movements:	
Commercial Airline Info	
Airport Revenue Data	1000 1000 2000 2001
Total Annual Revenue:	1998 1999 2000 2001
Airport Expenditure Data  1997	1998 1999 2000 2001
Total Annual Expenditure	

## Janvier Airport (EP5)

Year	Project Name	Funding Source	Description
1994		Provincial	Breaking and seeding
1993		Provincial	Brush clearing
1984		Provincial	Airfield lighting improvements
1977		Provincial	Completion of grading and gravelling
1976		Provincial	Granding, base and gravel, for 4500' x 100 runway

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 JASPER-HINTON AIRPORT (CYJA)**





Jasper-Hinton Airport Aerial Photographs

### **Airport Contact Information:**

Mr. Don Corrigan C.A.O. Yellowhead County Edson, AB T7E 1N9 Tel: (780) 723 4800 Fax: (780) 723 5066

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Jasper-Hinton (YJA) Municipal	Distance From Community (mile): 7.2 Latitude: 53.0000°, Longitude: -118.0667°
Owner and Operator Info Owner: Yellowhead County Operator: Yellowhead County Former Ownership: Province of Alberta Date of Change: June 2, 1995	Contact Info  Mr. Don Corrigan C.A.O.  Yellowhead County 2716 1st Avenue Edson
Airport Organization Ownership Structure:  Municipal	T7E 1N9 (780) 723 4800(780) , Fax: 723 5066
Organizational Structure:	Primary: "13-31", 4500x100 (Turf) Fair condition; replacement 2008 (\$11000)
Role of Airport:  To provide air service.	Secondary:
Taxiway Data Primary:	Annan Bata
Secondary:	Primary:
Third:	Secondary:
Fourth:	Building Data
□ Landside Facility Data	ATB: good condition;
Entrance Road: type Gravel; fair condition;	Disability Access:
Parking Lot: fair condition;	
Fencing: size 10; type Chain-Link; replacement (\$100000)	Field Electrical Centre:

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply: Well; fair condition;
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No
ARCAL: Type:	Caveat: No Right of Way: No
Windsock: 0 windsocks; fair condition;	ragne or tray.

Drainage Data	
Surface: good condition;	Subsurface:

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





Consite Business Data —				
FBO: No		AC N	laintenance:	No
Industrial Buildings: No		Crop	Spraying Ac	tivities:
Hangars: No		Chem	nicals Stored	on site:
Operation and Maintenanc	_	1000 100	2000	2004
Total Annual Maintenance Budg	1997 et	1998 199	9 2000	2001
Economic Activity Informa	tion			
Airport Activity Info	1997	1998 1999	2000	2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	97 1998	1999	2000	2001
Total Annual Revenue:	1930		2000	
Airport Expenditure Data				
	.997 19	98 1999	2000	2001
Total Annual Expenditure				

Year	Project Name	Funding Source	Description	
2001	Rny/taxiway, apr, term., other bldg's,		\$107,630	
2000	Runway/taxiway, terminal, other bldg's		\$10,800	
1999	Apron, terminal, other bldgs, vehicles		\$38,700	
1998	Runway/taxiway, terminal, other bldg's		\$14,600	
1997	Runway/taxiway, terminal, other bldg's		\$20,600	

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 JOHN D'OR PRAIRIE AIRPORT (CFG5)**





John D'Or Prairie Airport Aerial Photographs taken August 22, 2002

### **Airport Contact Information:**

Mr. Craig Halonen
Operations Manager
Little Red Air Service
Fort Vermillion, AB T0H 1N0
Tel: (780) 927 4630

Fax: (780) 927 3667

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

□General Info	
John D'Or Prairie (FG5)	Distance From Community (mile): 0
	Latitude: 58.4833°, Longitude: -115.1333°
Owner and Operator Info	□ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □
Owner: Little Red River Cree Nation	Mr. Craig Halonen
Operator: Little Red Air Service Ltd.	Operations Manager
Former Ownership: Date of Change:	Little Red Air Service Box 584
Dute of change.	Fort Vermillion
Airport Organization	T0H 1N0
Ownership Structure:	(780) 927 4630(780) , Fax: 927 3667
	┌Runway Data
Organizational Structure:	Primary: "06-24", 3360x90 (Turf)
	Good condition;
D. L. CA:	
Role of Airport:	Secondary:
	Secondary.
- Tavingay Data	
Taxiway Data Primary:	
Trimary.	Apron Data
	Primary:
Secondary:	
Th:d.	Secondary:
Third:	Secondary
Fourth:	
	Building Data
	ATB:
Landside Facility Data	
Entrance Road:	
	Disability Access:
	Disability Access.
Parking Lot:	
	Field Floetwicel Contract
Fencing:	Field Electrical Centre:
i Chang.	

•	
Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1: -	Sewage:
Approach Slope Indicator 2: -	Caveat, and Right of Way
	Vicinity Protection: No  Caveat: No
ARCAL: Type:	Right of Way: No
Windsock: 0 windsocks;	
Drainage Data	
Surface:	Subsurface:
Peak Period Info	
	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





<b>Consite Business Data</b> −						
FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	praying Act	civities:
Hangars: No				Chemic	als Stored (	on site:
☐ Operation and Maintena	ance Bud	dget -				
		1997	1998	1999	2000	2001
Total Annual Maintenance B						
Economic Activity Infor	mation -					
Airport Activity Info	1	.997	1998	1999	2000	2001
Annual Aircraft Movement	s:					
Annual Passenger Movemen	its:					
Commercial Airline Info	)					
Airport Revenue Data	1997	1998		1999	2000	2001
Total Annual Revenue:	133/	1330		1333	2000	2001
Airport Expenditure Dat						
Total Annual Expenditure	1997	199	8	1999	2000	2001
. Star / William Experialtare						

Year	Project Name	Funding Source	Description	

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 JOHNSON LAKE AIRPORT (CFL9)**





Johnson Lake Airport Aerial Photographs taken August 7, 2002

### **Airport Contact Information:**

Mr. Brian Stanton
W.A.O.O.
Alberta Sustainable Resource Development - Land and Forest Division
Lac La Biche, AB T0A 2C0
Tel: (780) 623 5240
Fax: (780) 623 2570

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Johnson Lake (FL9)	Distance From Community (mile): Latitude: 57.5667°, Longitude: -110.3167°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Mr. Brian Stanton W.A.O.O. Alberta Sustainable Resource Development - Land and Forest Division Box 450
Airport Organization Ownership Structure:	Lac La Biche T0A 2C0 (780) 623 5240(780) , Fax: 623 2570
Organizational Structure:	Primary: "07-25", 2500x75 (Turf)
Role of Airport:	Secondary:
Taxiway Data Primary:	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	Parilable v. Pata
	Building Data  ATB:
Landside Facility Data	AID
Entrance Road:	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Consite Business Data —								
FBO: No		AC N	laintenance:	No				
Industrial Buildings: No	Industrial Buildings: No Crop Spraying Activities:							
Hangars: No	Hangars: No Chemicals Stored on site:							
Operation and Maintenance Budget								
Total Annual Maintenance Budg	1997 et	1998 199	9 2000	2001				
Economic Activity Informa	tion							
Airport Activity Info	1997	1998 1999	2000	2001				
Annual Aircraft Movements:								
Annual Passenger Movements:								
Commercial Airline Info								
Airport Revenue Data	97 1998	1999	2000	2001				
Total Annual Revenue:	1930		2000					
Airport Expenditure Data								
	.997 19	98 1999	2000	2001				
Total Annual Expenditure								

Year	Project Name	Funding Source	Description	

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 KAKWA AIRPORT (CFA6)





Kakwa Airport Aerial Photographs taken August 14, 2002

### **Airport Contact Information:**

Alberta Sustainable Resource Development - Land and Forest Division Grande Prairie, AB T8V 3J2

Tel: (780) 538 8080 Fax: (780) 538 1941

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

## Kakwa Airport (FA6)

General Info	
	re From Community (mile): e: 54.4167°, Longitude: -118.9833°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Alberta Sustainable Resource Development - Land and Forest Division 10811 - 84 Ave. Grande Prairie T8V 3J2
Airport Organization Ownership Structure:	(780) 538 8080(780) , Fax: 538 1941
Organizational Structure:	Runway Data Primary: "03-21", 3000x100 (Turf)
Role of Airport:	Secondary:
Taxiway Data Primary:	<b>□</b> Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
Landside Facility Data	ATB:
Entrance Road:	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

## Kakwa Airport (FA6)

Peak Apron Aircraft Parked: Design Aircraft for Airport:

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface: Subsurfa	ce:
Peak Period Info	nter Average





## Kakwa Airport (FA6)

Onsite Business Data								
FBO: No			AC Mai	ntenance:	No			
Industrial Buildings: No Crop Spraying Activities:								
Hangars: No	langars: No Chemicals Stored on site:							
Operation and Maintenance	_	1000	1000	2000	2001			
Total Annual Maintenance Budge	1997 t	1998	1999	2000	2001			
Economic Activity Informati	on							
- Airmont Activity Info								
Airport Activity Info	1997	1998	1999	2000	2001			
Annual Aircraft Movements:								
Annual Passenger Movements:								
Commercial Airline Info								
Airport Revenue Data								
1997	7 1998	199	99	2000	2001			
Total Annual Revenue:								
Airport Expenditure Data								
Total Annual Expenditure	997 19	98 1	1999	2000	2001			
Total Alliadi Experialtare								

## Kakwa Airport (FA6)

Year	Project Name	Funding Source	Description	

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 KILLAM/KILLAM-SEDGEWICK AIRPORT (CEK6)





Killam/Killam-Sedgewick Airport Aerial Photographs taken July 12, 2002

### **Airport Contact Information:**

Mr. Russell Wardrope
Chief Administrative Officer
Town Of Killam
Killam-Sedgewick, AB T0B 2L0

Tel: (780) 385 3977 Fax: (780) 385 2120

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451

### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Killam/Killam-Sedgewick Airport (EK6)

General Info

Killam/Killam-Sedgewick (EK6) Distance From Community (mile): 3

Municipal Latitude: 52.8000°, Longitude: -111.7667°

Owner and Operator Info

Owner: Province of Alberta Operator: K/S Airport Commission Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Killam are stewardships of the airport since Feb 6,

1996. Owned by the province

Organizational Structure:

K/S Airport Commission

Role of Airport:

To accommodate fixed wing air ambulance, agricultural pest control, sport Leisure flying and local fire suppression.

**Taxiway Data** 

Primary: "A"; (Asphalt)

Poor condition; replacement 2005 (\$27000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: constructed 1982;

Parking Lot: type Asphalt; constructed 1982; last

rehabilitation 2006; fair condition;

Fencing: type Barbed Wire;

Contact Info

Mr. Russell Wardrope Chief Administrative Officer

Town Of Killam P.O Box 189

Killam/Killam-Sedgewick

T0B 2L0

(780) 385 3977(780), Fax: 385 2120

Runway Data

Primary: "11-29", 2950x75 (Asphalt)

constructed 1982; Poor condition; replacement 2005 (\$393000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1982; poor condition; replacement 2005 (\$61000)

Secondary: ---

**Building Data** 

ATB: size 24' x 40'; type wood; constructed 1982;

good condition; replacement 2012 (\$100000)

Disability Access: ---

Field Electrical Centre: ---

## Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Killam/Killam-Sedgewick Airport (EK6)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1982; fair condition; replacement 2005 (\$154000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

good condition; replacement 2008

Water / Sewer Data

Water Supply: Well; constructed 1982; good

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: poor condition; replacement 2005

(\$15000)

Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:



Onsite Business Data

# Alberta Regional/Local Airport Inventory Study Airport Summary Report



## Killam/Killam-Sedgewick Airport (EK6)

FBO: No			AC Mai	ntenance:	No	
Industrial Buildings: No			Crop S	praying Act		Temporary; A-1 Custom Applicators
Hangars: Yes, 2; D. Larson, G. S	Sparrow		Chemica	als Stored o	on site:	None
Operation and Maintenance	•	4000	4000	2000		
Total Annual Maintenance Budge	1997 et	1998	1999	2000	2001	<u>L</u>
 □Economic Activity Informat	ion					
Road Distance to Nearest Airpor Road Distance to Nearest Airpor Road Distance to Nearest Airpor Road Distance to Nearest Airpor Major Economic Industries in Re How is the Airport Vital to the Ro Control, Aerial Fire Fighting, Spo	t MedEvac S t Cargo Serv t AME Servic gion: Agric egion: Fixe	ervice: 5 ice: 150 :e: 150 ulture/Oil d Wing Air	& Gas Ambular		Pest	
Airport Activity Info	1997	1998	1999	2000	2001	
Annual Aircraft Movements:						
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data	7 1998	2 10	99	2000	2001	
Total Annual Revenue:	/ 1990	5 19	99	2000	2001	
Airport Expenditure Data						
Total Annual Expenditure	997 19	998	1999	2000	200	)1

# Killam/Killam-Sedgewick Airport (EK6)

Year	Project Name	Funding Source	Description	
1991	Runway repair	Prov.	\$100,000.	
1988	Fuel Tanks	Iron Creek Flying Club	\$5,119.	
1982	Terminal	Prov.	\$20,313.	
1982	Runway	Prov.		

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 LA CRETE AIRPORT (CFN5)





La Crete Airport Aerial Photographs taken August 22, 2002

### **Airport Contact Information:**

Mr. Floyd Lafferty Lead Head, North Municipal District of Mackenzie La Crete, AB T0H 2H0 Tel: (780) 927 3718/928 3983

Fax: (780) 927 4266

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### La Crete Airport (FN5)

**General Info** 

La Crete (FN5) Distance From Community (mile): 2.5
Municipal Latitude: 58.1667°, Longitude: -116.3333°

Owner and Operator Info

Owner: M.D. No 23 Operator: M.D. No 23

Former Ownership: No Change

Date of Change: ---

Airport Organization

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

Provides air service to surrounding area.

**Taxiway Data** 

Primary: "A"; 42x15 (Turf)

constructed 1986; Fair condition;

replacement 2005

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 8m top; type local road gravel;

good condition;

Parking Lot: size 30x60; type turf; good condition;

Fencing: size 4ft; type barb wire;

Contact Info

Mr. Floyd Lafferty Lead Head, North

Municipal District of Mackenzie

P.O. Bag 3 La Crete TOH 2H0

(780) 927 3718/928 3983(780), Fax: 927

4266

**Runway Data** 

Primary: "06-24", 2950x75 (Turf)

constructed 1986; Good condition;

Secondary: ---

**Apron Data** 

Primary: "1"; 43x83 (Turf)

constructed 1986; fair condition;

replacement 2005

Secondary: ---

**Building Data** 

ATB: ---

Disability Access: ---

Field Electrical Centre: size 8x12; good condition;

## Alberta Regional/Local Airport Inventory Study

Airport Summary Report

## La Crete Airport (FN5)

ARCAL: Type: "K"; freq 123.2

fair condition; replacement 2008

Windsock: 1 windsocks;

Lighting Data	Water / Sewer Data
Primary Edgelighting: TE (Threshold and Runway End) constructed 1987; fair condition; replacement 2008 (\$153000)	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No

Surface: good condition; Subsurface: good condition;

Caveat: No

Right of Way: No

Peak Period Info
Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:
Design Aircraft for Airport:
---





## La Crete Airport (FN5)

Onsite Business Data					
FBO: No			AC Mainten	ance: No	
Industrial Buildings: No Crop Spraying Activit					s:
Hangars: No		(	Chemicals S	stored on site	e:
Operation and Maintenance	_	1000	1000	2000	21
Total Annual Maintenance Budge	1997 et	1998	1999 2	2000 200	)1
Economic Activity Informat	ion				
Airport Activity Info	1997	1998	1999 2	000 200	1
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
Total Annual Revenue:	7 1998	3 1999	9 200	0 200:	
Airport Expenditure Data					
	997 19	98 19	999 2	000 20	001
Total Annual Expenditure					

## La Crete Airport (FN5)

Year	Project Name	Funding Source	Description			
1987		Provincial	Install airfield lighting			
1986		Provincial	Complete turf runway an dinitiate runway lighting installation			
1985		Provincial	Grading for turf runway			
1985		Provincial	Land purchase			
1984		Provincial	Preliminary survey, soils test			

# ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 LAC LA BICHE AIRPORT (CYLB)





Lac La Biche Airport Aerial Photographs taken August 15, 2002

### **Airport Contact Information:**

Mr. David Sarsfield Chief Administrative Officer Town of Lac La Biche Lac La Biche, AB T0A 2C0 Tel: (780) 623 4323

Fax: (780) 623 4323

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451

### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

## Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Lac La Biche Airport (YLB)

-Ge	nera	l Info	
- GE	ııtıa	I IIIIC	,

Lac La Biche (YLB)

Distance From Community (mile): 1.5 Latitude: 54.7500°, Longitude: -112.0000°

Contact Info

P.O. Box 387 Lac La Biche TOA 2C0

Mr. David Sarsfield

Town of Lac La Biche

Chief Administrative Officer

### Owner and Operator Info

Owner: ---Operator: ---

Former Ownership: --- Date of Change: ---

### Airport Organization

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

---

### **Taxiway Data**

Primary: "A"; (Asphalt)

constructed 1976; last rehabilitation 1990; Fair condition; replacement 2005 (\$107000)

Secondary: ---

Third: ---

Fourth: ---

### Runway Data

Primary: "11-29", 5700x100 (Asphalt)

constructed 1976; last rehabilitation 1990; Fair condition; replacement 2005

(780) 623 4323(780), Fax: 623 3510

(\$1006000)

Secondary: ---

#### - Duilding D

Entrance Road: type gravel; fair condition;

Parking Lot: type gravel; fair condition;

Fencing: size 4ft; type barb wire;

**Landside Facility Data** 

### Apron Data

Primary: "1"; (Asphalt)

constructed 1976; last rehabilitation 1990; fair condition; replacement 2005

(\$447000)

Secondary: ---

### Building Data

ATB: constructed 1982; fair condition;

Disability Access: ---

Field Electrical Centre: type ????;

## Alberta Regional/Local Airport Inventory Study

Airport Summary Report

### Lac La Biche Airport (YLB)

Lighting	Data
Liantina	Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1977; last rehabilitation 198 fair condition; replacement 2006 (\$3500)

Approach Slope Indicator 1: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1977; poor condition; replacement 2006 (\$60000)

Approach Slope Indicator 2: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1977; poor condition; replacement 2006 (\$60000)

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

fair condition; replacement 2006

Water / Sewer Data

Water Supply:

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: fair condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





## Lac La Biche Airport (YLB)

Onsite Business Data									
FBO: No			AC Main	itenance:	No				
Industrial Buildings: No			Crop Spraying Activities:						
Hangars: No		Chemicals Stored on site:							
Operation and Maintenance Budget									
Total Annual Maintenance Budg	1997 et	1998	1999	2000	2001				
Economic Activity Information									
Airport Activity Info	1007	1000	1000	2000	2001				
Annual Aircraft Movements:	1997	1998	1999	2000	2001				
Annual Passenger Movements:									
Commercial Airline Info	<u>'</u>								
Airport Revenue Data	97 1998	3 199	99 5	2000	2001				
Total Annual Revenue:					2001				
Airport Expenditure Data									
Total Annual Expenditure	1997 19	998 1	1999	2000	2001				

### Lac La Biche Airport (YLB)

Year Project Name	Funding Source	Description
1991	Provincial	Brush clearing
1990	Provincial	Pavement repairs and overlay
1989	Provincial	Runway repairs
1987	Provincial	Airfield lighting improvements
1987	Provincial	Develoment area work
1987	Provincial	Purchase and install DME
1984	Provincial	Complete development area improvement and construct new airport maintenance
1982	Provincial	Upgrade and expand airport development area
1977	Provincial	Final paving and airfield lighting
1976	Provincial	Gradin, base, paving and drainage for runway and air tanker base

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 LACOMBE AIRPORT (CEG3)





Lacombe Airport Aerial Photographs taken October 10, 2002

#### **Airport Contact Information:**

Mr. Penny Nielsen President Lacombe Flying Club Lacombe, AB T4L 1M2 Tel: (403) 782 3320

Fax: (403) 782 3320

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

PRYDE SCHROP



Prepared by:

Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Lacombe Airport (EG3)

General Info

Distance From Community (mile): 0.9 Lacombe (EG3) Latitude: 52.4833°, Longitude: -113.7167°

Owner and Operator Info

Owner: Town of Lacombe Operator: Lacombe Flying Club

Former Ownership: ---

Date of Change: January 27, 1975

**Airport Organization** 

Ownership Structure:

Town of Lacombe

Organizational Structure:

Lacombe Flying Club

Role of Airport:

Mainly serves recreational use but also used by some government, private and commercial aircraft.

**Taxiway Data** 

Primary: "A"; 123x30 (Asphalt)

last rehabilitation 2001; Good condition;

replacement 2012 (\$49000)

Secondary: "ATB"; (Asphalt)

Third: "GA taxiways"; (Asphalt)

Fair condition;

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 15ft; type gravel; fair condition;

Parking Lot: size 150ft; type gravel; fair condition;

Fencing: size perimeter; type chain link;

Contact Info

Mr. Penny Nielsen

President

Lacombe Flying Club

5115 - 59 St. Lacombe

T4L 1M2

(403) 782 3320(403), Fax: 782 3320

**Runway Data** 

Primary: "16-34", 3000x74 (Asphalt)

constructed 1962; last rehabilitation 2001; Good condition; replacement 2012

(\$399000)

Secondary: "16-34", 2800x74 (Turf)

constructed 1962; Fair condition;

replacement 2008 (\$5000)

**Apron Data** 

Primary: "1"; 210x92 (Asphalt)

last rehabilitation 2001; replacement

2012 (\$44000)

Secondary: ---

**Building Data** 

ATB: size 24x26; type Stucco frame; constructed

1970; fair condition; replacement 2010

(\$100000)

Disability Access: type sidewalk;

Field Electrical Centre: size 8x8; type wood hip roof

blda: fair condition:

replacement 2007 (\$150000)

### Lacombe Airport (EG3)

Design Aircraft for Airport:

20011100 / port (=00)		
<b>□Lighting Data</b>		─────────────────────────────────────
	nreshold and Runway End) ucted 1977; good condition; ement 2007 (\$178000)	Water Supply: constructed 2002; good condition;
Approach Slope Indicator 1:		Sewage:
Approach Slope Indicator 2:		Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: "K"; fr Windsock: 1 windsocks; good condition		Vicinity Protection: No Caveat: No Right of Way: No
⊤Drainage Data		
Surface:	Sub	osurface:
Peak Period Info	Spring Summer Fall	Winter Average
Peak Apron Aircraft Parked:		





### Lacombe Airport (EG3)

<b>□Onsite Business Data</b>							
FBO: Yes, ;				AC Ma	intenance:	No	
To describe Desiration on No.							
Industrial Buildings: No					Spraying Ac	tivities:	
Hangars: Yes, 30;					als Stored	on site: none	
Operation and Mainter	ance B	_					
Total Annual Maintenance	Budaet	1997	1998	1999	2000	2001	
Economic Activity Info	rmation	1					
Road Distance to Nearest A	Airport Al	ME Service	: 25				
☐Airport Activity Info							
All port Activity illio		1997	1998	1999	2000	2001	
Annual Aircraft Movemer	nts:						
Annual Passenger Moveme	nts:						
_							
Commercial Airline Inf	0						
- Airport Boyonya Data							
Airport Revenue Data	1997	1998		1999	2000	2001	
Total Annual Revenue:	177/	1330		1222	2000	2001	
Total Allilual Reveilue:							
Airport Expenditure Da							
	1997	7 199	98	1999	2000	2001	
Total Annual Expenditure							

### Lacombe Airport (EG3)

Year	Project Name	Funding Source	Description
2002	New Taxiway	Town of Lacombe	
2000	Runway overlay	Prov. Gov't	
1973	New Runway	Fed. Gov't & County	Build and Pave runway
	Taxiway	Prov. Gov't	
	Chain Link Fence	Prov. Gov't	
	Terminal Bldg.	Lacombe Flying Club	Erect Terminal Building
	Runway overlay	Prov. Gov't	
	Machine Garage	Prov. Gov't	

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY **ASSESSMENT OF FACILITIES**

### **AIRPORT INFORMATION REPORT - 2002 LETHBRIDGE AIRPORT (CYQL)**





Lethbridge Airport Aerial Photographs

#### **Airport Contact Information:**

Mr. Scott Butchart Airport Manager County of Lethbridge Airport Lethbridge, AB T1K 7N3 Tel: (403) 329 4466

Fax: (403) 329 8736

#### Prepared for:



**Aviation Strategy Action Group** 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918



Prepared by:

Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 21, 2003 Project No. 11451

Airport Summary Report

### Lethbridge Airport (YQL)

**General Info** 

Lethbridge (YOL) Distance From Community (mile): 4

Passenger/Commercial - Regional Latitude: 49.6333°, Longitude: -112.8000°

Owner and Operator Info

Owner: County of Lethbridge Operator: County of Lethbridge Former Ownership: Transport Canada

Date of Change: January 1, 1997

**Airport Organization** 

Ownership Structure:

County of Lethbridge

Organizational Structure:

County Department

Role of Airport:

In operating the Lethbridge County Airport, the County of Lethbridge aims to: Retain ownership of airport lands for

**Taxiway Data** 

Primary: "A"; (Asphalt)

replacement 2005 (\$150000)

Secondary: "B"; (Asphalt)

replacement 2005 (\$150000)

Third: "C"; (Asphalt)

replacement 2005 (\$100000)

Fourth: ---

**Landside Facility Data** 

Entrance Road: fair condition; replacement 2005

(\$1000000)

Parking Lot: replacement 2005 (\$100000)

Fencing:

Contact Info

Mr. Scott Butchart Airport Manager

County of Lethbridge Airport Suite 219 - 417 Stubb Ross Road

Lethbridge T1K 7N3

(403) 329 4466(403), Fax: 329 8736

**Runway Data** 

Primary: "05-23", 6500x200 (Asphalt)

Fair condition; replacement 2004

(\$2000000)

Secondary: "12-30", 5500x150 (Asphalt)

last rehabilitation 2001; Good

condition;

**Apron Data** 

Primary: "I"; (Concrete)

good condition;

Secondary: "II"; (Asphalt)

poor condition; replacement 2005

(\$250000)

**Building Data** 

ATB:

Disability Access:

Field Electrical Centre:

┌Lighting Data	─────────────────────────────────────
Primary Edgelighting: TE (Threshold and Runway End) constructed 1996; good condition;	Water Supply: Municipal Service;
Approach Slope Indicator 1:	Sewage: Well;
Approach Slope Indicator 2: P2 (PAPI - Aircraft up to 25') good condition;	Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No
ARCAL: Type: "K"; freq 121	Caveat: No Right of Way: No
Windsock: 4 windsocks;	
Drainage Data	
Surface: Subsu	ırface:

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





### Lethbridge Airport (YQL)

<b>□Onsite Business Data</b>								
FBO: Yes, ;	1			AC M	aintenance	: No		
Industrial Buildings: No					Crop Spraying Activities: Permanent			
Hangars: Yes, ;	Hangars: Yes, ;					l on site:		
Operation and Mainte	enance B	udget -						
	Г	1997	1998	1999	2000	2001		
Total Annual Maintenance	e Budget							
Economic Activity Information								
Airport Activity Info		1007	1000	1000	2000	2001		
Annual Aircraft Moveme	ents:	1997	1998	1999	2000	2001		
Annual Passenger Movem	nents:							
Commercial Airline Ir	nfo						_ _	
Airport Revenue Data								
Total Appual Poyonya	1997	1998	3	1999	2000	2001		
Total Annual Revenue:								
Airport Expenditure [								
Total Annual Expenditure	1997	' 19	98	1999	2000	2001	_	
Total Alliual Experiulture	·							

### Lethbridge Airport (YQL)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 LLOYDMINSTER AIRPORT (CYLL)





Lloydminster Airport Aerial Photographs taken July 11, 2002

#### **Airport Contact Information:**

Mr. Denis Foss Airport Manager Lloydminster Airport Lloydminster, AB S9V 0Y4 Tel: (780) 875 9215/871 1252

Fax: (780) 875 3319

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Lloydminster Airport (YLL)

**General Info** 

Lloydminster (YLL) Distance From Community (mile): 2
Passenger - Local Latitude: 53.3167°, Longitude: -110.0667°

Owner and Operator Info

Owner: City of Lloydminster Operator: City of Lloydminster

Former Ownership: Province of Alberta

Date of Change: April 1, 1996

**Airport Organization** 

Ownership Structure:

Municipality Owned

Organizational Structure:

Municipal Government

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1980; last rehabilitation 2000;

Good condition; replacement 2015

Secondary: "GA";

Fair condition; replacement 2006

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type asphalt; constructed 1980; last

rehabilitation 1985; fair condition;

replacement 2006

Parking Lot: type asphalt; constructed 1980; fair

condition; replacement 2006 (\$43000)

Fencing: size 10ft; type chain link; replacement 2003

Contact Info

Mr. Denis Foss Airport Manager Lloydminster Airport

Box 387 Lloydminster S9V 0Y4

(780) 875 9215/871 1252(780), Fax: 875

3319

**Runway Data** 

Primary: "07-25", 5577x150 (Asphalt)

constructed 1980; last rehabilitation 2000; Good condition; replacement 2015

(\$1607000)

Secondary: "12-30", 1500x100 (Turf)

constructed 1982; Good condition;

**Apron Data** 

Primary: "1"; 600x180 (Asphalt)

constructed 1980; last rehabilitation

2000; good condition;

Secondary: ---

**Building Data** 

ATB: size 5000sq ft; type Brick; constructed 1981;

good condition;

Disability Access: type sidewalk; constructed 1981;

good condition;

Field Electrical Centre: good condition;

Airport Summary Report

### Lloydminster Airport (YLL)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1981; last rehabilitation 200

good condition; replacement 2025

Approach Slope Indicator 1: P2 (PAPI - Aircraft up to 25')

constructed 1981; last rehabilitatic

2000; good condition; replacemen

2025

Approach Slope Indicator 2: P2 (PAPI - Aircraft up to 25')

constructed 1981; last rehabilitatic 2000; good condition; replacemen

2025

ARCAL: Type: ---

Windsock: 2 windsocks;

constructed 1980; last rehabilitation 2000; good

condition; replacement 2025

Water / Sewer Data

Water Supply: Municipal Service; constructed

1980; good condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1982; good condition; Subsurface: constructed 1982; good condition;

Peak Period Info
Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:
Design Aircraft for Airport:
---



Airport Summary Report



#### Lloydminster Airport (YLL)

**Onsite Business Data** 

FBO: Yes, 3; Border City Aviation, Lloyd Air

2000, Lloydminster

Industrial Buildings: No Crop Spraying Activities:

Hangars: Yes, 8; Border City Aviation,

Lloydminster Aircraft Services

Chemicals Stored on site:

AC Maintenance: Yes, 2;

Operation and Maintenance Budget

1997 1998 2000 2001 1999

Total Annual Maintenance Budget

**Economic Activity Information** 

Road Distance to Nearest Airport Sched. Pax Service: 8

Road Distance to Nearest Airport MedEvac Service: 8

Road Distance to Nearest Airport Cargo Service: 8

Road Distance to Nearest Airport AME Service: 8

Road Distance to Nearest Airport Fire Suppression Service: 8

Major Economic Industries in Region: Oil & Gas/Rail/Oil Seed Processing/Light

Manufacturing/Farming

How is the Airport Vital to the Region: Only air link to major Alberta Centres.

Only Airport of this class that can serve passengers.

**Airport Activity Info** 

1997 1998 1999 2000 2001

**Annual Aircraft Movements:** 

Annual Passenger Movements:

**Commercial Airline Info** 

Central Mountain Air (BE1900, Daily - except Saturday)

Peace Air (, Mon-Fri)

**Airport Revenue Data** 

1997 1998 1999 2000 2001

Total Annual Revenue:

**Airport Expenditure Data** 

1997 1998 1999 2000 2001

**Total Annual Expenditure** 

### Lloydminster Airport (YLL)

listorio	Capital Expen	ditures	
Year	Project Name	Funding Source	Description
1996		Provincial	Contribution to crack repair and fog seal asphalt surfaces
1993		Provincial	Fog Seal pavement
1992		Provincial	Constructionof security screening room
1986		Provincial	Install microwave landing system
1985		Provincial	Purchase of microwave landing system
1984		Provincial	Development area clean up
1982		Provincial	Terminal Building Terminal Building
1982		Provincial	Completion of hangar development area
1981		Provincial	Paving and airfield lighting
1980		Provincial	Grading and base for runway, taxiway and access road
1979		Provincial	Land purchase for airport

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 LOON RIVER AIRPORT (CFS6)





Loon River Airport Aerial Photographs taken August 8, 2002

#### **Airport Contact Information:**

Alberta Sustainable Resource Development - Land and Forest Division Slave Lake, AB T0G 2A0

Tel: (780) 849 7400 Fax: (780) 849 3299

> Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info					
	ce From Community (mile): le: 57.1333°, Longitude: -115.0667°				
Owner and Operator Info	☐ Contact Info				
Owner: Operator: Former Ownership: Date of Change:	Alberta Sustainable Resource Development - Land and Forest Division 301 Birch Road NE Slave Lake T0G 2A0				
Airport Organization	(780) 849 7400(780) , Fax: 849 3299				
Ownership Structure:					
Organizational Structure:	Runway Data Primary: "13-31", 5900x100 (Gravel)				
Role of Airport:	Secondary:				
⊤Taxiway Data ────					
Primary:	<b>△Apron Data</b>				
Secondary:	Primary:				
Third:	Secondary:				
Fourth:					
	Building Data				
Landside Facility Data	ATB:				
Entrance Road:					
Entrance Road:	Disability Access:				
Parking Lot:					
Fencing:	Field Electrical Centre:				

Lighting Data	□ Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data						
FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintena	nce Bu	dget				
T. I.A. IM.:	–	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	idget					
Economic Activity Inform	nation					
Airport Activity Info						
Annual Aircraft Movements		1997	1998	1999	2000	2001
Annual Passenger Movement	S:					
Commercial Airline Info						
Airport Revenue Data						
	1997	1998		1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Data						
Total Appual Exponditure	1997	199	98	1999	2000	2001
Total Annual Expenditure						

Year	Project Name	Funding Source	Description	

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 MANNING AIRPORT (CFX4)





Manning Airport Aerial Photographs taken July 24, 2002

#### **Airport Contact Information:**

Mr. Roger Smiley Airport Manager Manning Airport Manning, AB T0H 2M0 Tel: (780) 836 3235

Fax: (780) 836 3663

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Manning Airport (FX4)

General Info

Manning (FX4) Distance From Community (mile): 1.8
Municipal Latitude: 56.9500°, Longitude: -117.6500°

Owner and Operator Info

Owner: MD Of Northern Lights #22 Operator: MD Of Northern Lights #22 Former Ownership: Province of Alberta

Date of Change: July 1, 1995

**Airport Organization** 

Ownership Structure:

Municipal District of Northern Lights #22

Organizational Structure:

Public Works/Airport Manager

Role of Airport:

Provides a base for Forestry Fire Tanker Operators, industrial charters, local economic air support and Air Ambulance

**Taxiway Data** 

Primary: "A"; (Asphalt)

last rehabilitation 2001; Good condition;

replacement 2012 (\$57000)

Secondary: "B Forestry"; 60x15 (Asphalt)

constructed 1982; replacement 2003

(\$3000)

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type paved; constructed 1983; poor

condition; replacement 2004 (\$31000)

Parking Lot: type paved; constructed 1983; poor

condition; replacement 2004 (\$33000)

Fencing: type barb wire;

Contact Info

Mr. Roger Smiley Airport Manager Manning Airport

Box 10 Manning T0H 2M0

(780) 836 3235(780), Fax: 836 3663

**Runway Data** 

Primary: "07-25", 5577x100 (Asphalt)

constructed 1982; last rehabilitation 2001; Good condition; replacement 2012

(\$1071000)

Secondary: ---

**Apron Data** 

Primary: "1"; 120x60 (Asphalt)

constructed 1982; last rehabilitation

2001; good condition;

Secondary: "B-Forestry"; 100x60

constructed 1982;

**Building Data** 

ATB: constructed 1983; fair condition;

Disability Access: type sidewalk;

Field Electrical Centre: constructed 1983;

Airport Summary Report

### Manning Airport (FX4)

		 ١.	_	- ' /
	- 1			
Lighting	Data			

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1983; fair condition; replacement 2005 (\$217000)

Approach Slope Indicator 1: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1986; fair condition; replacement 2005 (\$60000)

Approach Slope Indicator 2: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1986; fair condition; replacement 2005 (\$60000)

ARCAL: Type: "K"; freq 123.2

Windsock: 2 windsocks;

constructed 1983; good condition; replacement

2004

Water / Sewer Data

Water Supply: Other; good condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

Drainage	Data
----------	------

Surface: Subsurface: ---

Peak Period InfoSpringSummerFallWinterAveragePeak Apron Aircraft Parked:C3C3C3C3---





### Manning Airport (FX4)

Onsite Business Data						
FBO: Yes, 1; Swan Aero F	Refueling		AC M	laintenance:	No	
Industrial Buildings: No			Crop	Spraying Ac	tivities: not a	at present
Hangars: Yes, 4; Jack Hai Ed Walisser, Pre			Chem	nicals Stored	on site: 0	
☐ Operation and Mainter	nance Bud	get -				
		•	998 199	9 2000	2001	
Total Annual Maintenance	Budget					
Economic Activity Info	rmation -					
Road Distance to Nearest A Road Distance to Nearest A Road Distance to Nearest A Road Distance to Nearest A Major Economic Industries How is the Airport Vital to	Airport Carg Airport AME Airport Fire S in Region:	o Service: Service: Suppressic Oil & Gas	0 0 n Service: /Forest/Logg	ging/Farming		
Airport Activity Info		997 19	998 1999	2000	2001	
Annual Aircraft Moveme	nts:					
Annual Passenger Moveme	ents:					
Commercial Airline Inf	ō					
Airport Revenue Data						
Total Annual Revenue:	1997	1998	1999	2000	2001	
Airport Expenditure Da						
Total Annual Expenditure	1997	1998	1999	2000	2001	

### Manning Airport (FX4)

Year	Project Name	Funding Source	Description
2002		Provincial	Airport pavement overlay
1995		Provincial	Completion of runway drainage repairs
1994		Provincial	Runway drainage repairs
1994		Provincial	Fog seal asphalt surfaces
1993		Provincial	Runway drainage improvements
1988		Provincial	Purchase and install AWOS
1986		Provincial	Installation of VASIS
1986		Provincial	Purchase and install NDB
1986		Provincial	Purchase and install DME
1983		Provincial	Terminal Building and Maintenance Garag
1983		Provincial	Paving, airfield lighting and site clean up
1982		Provincial	Grading, base and construction of Air Tan Base
1981		Provincial	Initial Grading

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 MAREK FARMS AIRPORT (CFF9)





Marek Farms Airport Aerial Photographs taken July 10, 2002

#### **Airport Contact Information:**

Mr. Leon / Roman Marek Owners Marek Farms Ltd. Camrose, AB T4V 1X3 Tel: (780) 672 3509

Fax: (780) 672 3509

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

### Marek Farms Airport (FF9)

General Info	
Marek Farms (FF9)	Distance From Community (mile): 1.5
Private	Latitude: 53.0333°, Longitude: -112.7833°
Owner and Operator Info	Contact Info
Owner: Marek Farms Ltd.	Mr. Leon / Roman Marek
Operator: Marek Farms Ltd.	Owners
Former Ownership: No Change	Marek Farms Ltd. Box 1304
Date of Change:	Camrose
Airport Organization	T4V 1X3
Ownership Structure:	(780) 672 3509(780) , Fax: 672 3509
ownership structure.	
	Runway Data
Organizational Structure:	
	Primary: "16-34", 2000x60 (Turf) constructed 1990; Good condition;
	constructed 1990, dood condition,
Role of Airport:	
	Secondary:
Taxiway Data	
Primary:	
, randary.	<b>⊺Apron Data</b>
	Primary:
Secondary:	
Third:	Secondary:
Fourth:	
Tourin	
	Building Data
Landaida Fasilita P. (	ATB:
Landside Facility Data	
Entrance Road:	
	Disability Access:
Parking Lot:	
	Field Electrical Centre:
Fencing:	i leiu Liectricai Ceritie
i Griding.	

### Marek Farms Airport (FF9)

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

Lighting Data	┌Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 2 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
During at Data	
Drainage Data	
Surface: constructed 1990; good condition; S	Subsurface:
Peak Period Info Spring Summer Fall	Winter Average





### Marek Farms Airport (FF9)

Consite Business Data ——					
FBO: No			AC Mai	intenance:	No
Industrial Buildings: No			Crop S	praying Act	tivities:
Hangars: No			Chemic	als Stored	on site:
Operation and Maintenance	Budget -	1998	1999	2000	2001
Total Annual Maintenance Budge		1330	1333	2000	
Economic Activity Informati	on				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					
Total Annual Revenue:	7 1998	3 19	99	2000	2001
Airport Expenditure Data	997 19	98	1999	2000	2001
Total Annual Expenditure	,,, 13		1777	2000	2001

### Marek Farms Airport (FF9)

Year	Project Name	Funding Source	Description	

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 MARGARET LAKE AIRPORT (CFV6)





Margaret Lake Airport Aerial Photographs taken August 21, 2002

#### **Airport Contact Information:**

Little Red River Band AB

Tel: (780) 759 3929 Fax: (780) 759 3912

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Margaret Lake (FV6) Distar	nce From Community (mile):
Latitu	de: 58.9500°, Longitude: -115.2500°
Owner and Operator Info	☐ Contact Info
Owner:	Little Red River Band
Operator:	(780) 759 3929(780) , Fax: 759 3912
Former Ownership:	
Date of Change:	
Airport Organization	
Ownership Structure:	
	⊤Runway Data
Organizational Structure:	Primary: "10-28", 4000x100 (Turf)
	Good condition;
Role of Airport:	Considering
	Secondary:
Taxiway Data	
Primary:	Apron Data
Secondary:	Primary:
Secondary.	
Third:	Secondary:
Fourth:	
	┌Building Data
	ATB:
Landside Facility Data	7
Entrance Road:	
	Disability Access:
Parking Lot:	
	Field Electrical Centre:
Fencing:	
r chang.	

Lighting Data	┌Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 1 windsocks; fair condition	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data						
FBO: No				AC Ma	aintenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintenar	nce Bu	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	dget	1997	1990	1999	2000	
Economic Activity Inforn	nation	-				
Airport Activity Info		1997	1998	1999	2000	2001
Airport Activity Info  Annual Aircraft Movements		1997	1998	1999	2000	2001
	:	1997	1998	1999	2000	2001
Annual Aircraft Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	:	1997		1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info   Airport Revenue Data  Total Annual Revenue:	: s:					
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	: s:					

Year	Project Name	Funding Source	Description	

## AIRPORT INFORMATION REPORT - 2002 MAYERTHORPE AIRPORT (CEV5)





Mayerthorpe Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Greg Gayton Chief Administrative Officer Town of Mayerthorpe Mayerthrorpe, AB T0E 1N0 Tel: (780) 786 2416

Fax: (780) 786 2416

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Mayerthorpe Airport (EV5)

**General Info** 

Mayerthorpe (EV5)

Municipal

Distance From Community (mile): 1.3

Latitude: 53.9333°, Longitude: -115.1833°

Owner and Operator Info

Owner: Province of Alberta

Operator: Town of Mayerthorpe, County of Lac Ste. Anne

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Province of Alberta

Organizational Structure:

Town of Mayerthorpe/Lac Ste Anne County.

Role of Airport:

Provides services for private and commercial uses.

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1977; Poor condition; replacement 2003 (\$38000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; fair condition;

Parking Lot: ---

Fencing: size 4' barbed wire;

Contact Info

Mr. Greg Gayton

Chief Administrative Officer

Town of Mayerthorpe

PO Box 420 Mayerthrorpe

T0E 1N0

(780) 786 2416(780), Fax: 786 4590

**Runway Data** 

Primary: "11-29", 2950x75 (Asphalt)

constructed 1982; Poor condition; replacement 2003 (\$393000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1997; poor condition;

Secondary: ---

**Building Data** 

ATB: size 754 sqft; type wood frame; constructed

1984; fair condition;

Disability Access: ---

Field Electrical Centre: type Tool Shed; fair

condition;

## Mayerthorpe Airport (EV5)

Lighting Data	┌Water / Sewer Data	٦
	water Supply: Well; constructed 1985; fair ucted 1982; fair condition; condition; condition;	
Approach Slope Indicator 1:	Sewage:	
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way Vicinity Protection: Yes	
ARCAL: Type: "K"; fr Windsock: 1 windsocks; fair condition	eq 123.2 Caveat: No Right of Way: No	
Drainage Data		
Surface:	Subsurface:	
Peak Period Info	Spring Summer Fall Winter Average	
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		





### Mayerthorpe Airport (EV5)

**Onsite Business Data** 

FBO: No				AC Ma	intenance:	No	
Industrial Buildings: No				Crop S	Spraying Ac		mporary; 1; Spraying for asshoppers
Hangars: No				Chemic	cals Stored	on site: no	ne
Operation and Maintena	ance Bu	dget					
		1997	1998	1999	2000	2001	
Total Annual Maintenance B	ludget						
Economic Activity Infor	mation						
- Alma - ut							
Airport Activity Info		1997	1998	1999	2000	2001	
Annual Aircraft Movement	s:						
Annual Passenger Movemer	its:						
Commercial Airline Info	)						
Airport Revenue Data	1007	1000		000	2000	2001	
Total Annual Revenue:	1997	1998	· I	999	2000	2001	
─Airport Expenditure Dat	ta 1997	19	98	1999	2000	2001	
Total Annual Expenditure							_

## Mayerthorpe Airport (EV5)

Year	Project Name	Funding Source	Description
1986		Provincial	Pavement repairs and drainage improvements
1984		Provincial	Terminal Building
1982		Provincial	Assistance for establishment of caretaker residence
1982		Provincial	Land purchase (\$54,811), base, grading, paving and lighting

# AIRPORT INFORMATION REPORT - 2002 MEDICINE HAT AIRPORT (CYXH)





Medicine Hat Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Edward Jollymore Airport Manager Medicine Hat Airport Medicine Hat, AB T1A 8E6 Tel: (403) 502 8049

Fax: (403) 502 6049

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Medicine Hat Airport (YXH)

**General Info** 

Medicine Hat (YXH)

Distance From Community (mile): 2

Latitude: 50.0167°, Longitude: -110.7167°

Owner and Operator Info

Owner: City of Medicine Hat Operator: City of Medicine Hat Former Ownership: DND 1941-1947

Date of Change: ---

**Airport Organization** 

Ownership Structure:

City Department

Organizational Structure:

City Council/Board of Commissioners/Commissioner-Public Services/General Manager-Municipal Works/Manager Utilities

8. Equipment/Airport Manager/Airport Superintendent

Role of Airport:

Serves Local & Regional Air Transportation need. Economic

Asset & Driver

**Taxiway Data** 

Primary: "A"; 515x75 (Asphalt)

constructed 1965; last rehabilitation 1996; Fair condition; replacement 2010 (\$39000)

Secondary: "B"; 984x75 (Asphalt)

constructed 1941; last rehabilitation 1996; Good condition; replacement 2010

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 2 lane; type asphalt; constructed

1965; last rehabilitation 1999; good

condition; replacement 2020

Parking Lot: size 100 stalls; type Asphalt;

constructed 1941; good condition;

replacement 2020

Fencing: size 6'; type Chain Link; replacement 2020

Contact Info

Mr. Edward Jollymore Airport Manager Medicine Hat Airport 580 1st Street SE Medicine Hat

T1A 8E6

(403) 502 8049(403), Fax: 527 8728

**Runway Data** 

Primary: "03-21", 5000x150 (Asphalt)

constructed 1941; last rehabilitation 1996; Fair condition; replacement 2010

(\$1881000)

Secondary: "09-27", 2820x100 (Asphalt)

constructed 1941; last rehabilitation 1996; Fair condition; replacement 2010

(\$707000)

**Apron Data** 

Primary: "ATB"; (Asphalt)

constructed 1980; poor condition; replacement 2003 (\$125000)

Secondary: "Tie Down"; (Turf)

constructed 1941; last rehabilitation 2001; good condition; replacement

2016 (\$123000)

**Building Data** 

ATB: type Linear; constructed 1980; fair condition;

replacement 2020 (\$100000)

Disability Access: constructed 1980; good condition;

Field Electrical Centre: constructed 1945; poor

condition; replacement 2004

(\$150000)

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Medicine Hat Airport (YXH)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1996; good condition;

replacement 2020

Approach Slope Indicator 1: P1 (PAPI - Aircraft up to 10')

constructed 1996; good condition;

replacement 2020 (\$60000)

Approach Slope Indicator 2: P1 (PAPI - Aircraft up to 10')

constructed 1996; good condition;

replacement 2020 (\$60000)

ARCAL: Type: ---

Windsock: 3 windsocks;

last rehabilitation 1996; good condition;

replacement 2020

Water / Sewer Data

Water Supply: Municipal Service; constructed

1941; good condition; replacement 2022

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: constructed 1941; last rehabilitation 1995; Subsurface: constructed 1941; last rehabilitation

good condition; 1995; good condition; replacement

2005

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:	DH-8-300	DH8-300	DH8-300	DH8-300	





#### Medicine Hat Airport (YXH)

**Onsite Business Data** 

FBO: Yes, 1; Bar XH Air AC Maintenance: No

Industrial Buildings: No Crop Spraying Activities:

Hangars: Yes, 4; Recreation Aircraft Associaion;

H. Zeller & Associates; E. Mylmok; L.

Oddan

Chemicals Stored on site:

Operation and Maintenance Budget

1997 1998 1999 2000 2001

**Total Annual Maintenance Budget** 

**Economic Activity Information** 

Road Distance to Nearest Airport Sched. Pax Service: 165

Road Distance to Nearest Airport MedEvac Service: 0

Road Distance to Nearest Airport Cargo Service: 0

Road Distance to Nearest Airport AME Service: 0

Road Distance to Nearest Airport Fire Suppression Service: 5
Major Economic Industries in Region: Oil & Gas/Agri Food/Medical

Services/College/Chemical Manufacturing/Manufacturing-

equipment/transportation/rubber

How is the Airport Vital to the Region: Supports - Medevac/Local

**Airport Activity Info** 

1997 1998 1999 2000 2001

Annual Aircraft Movements:

Annual Passenger Movements:

#### **Commercial Airline Info**

Air Canada Jazz (Beech 1900 D, Scheduled Passenger/Cargo) Bar XH Air (BE20/PA31/J32/PA42, Charter/Medevac)

**Airport Revenue Data** 

1997 1998 1999 2000 2001

Total Annual Revenue:

Airport Expenditure Data

1997 1998 1999 2000 2001

**Total Annual Expenditure** 

## Medicine Hat Airport (YXH)

Year	Project Name	Funding Source	Description
2003		City	New Runway heavy equipment (winter maintenance)
1999		ACAP	New Aerodrome Beacon renewed ATB roo
1998	Lighting	ACAP	New runway edgelighting New addition of ODALS/PAPI's
1997	Loader	City	Larger loader required for new snowblowe
1996	Runway Overlay	ACAP	Mill & Overlay Runway & Taxiway
1996	Snow Blower	ACAP	
1980	New ATB	City/Prov	
1965	ATB	City	
1965	Runway 03-21	City/Prov/Federal	New Runway

## AIRPORT INFORMATION REPORT - 2002 MEDICINE HAT/SCHLENKER AIRPORT (CFZ3)





Medicine Hat/Schlenker Airport Aerial Photographs taken August 13, 2002

#### **Airport Contact Information:**

Mr. Aevult Schlenker Medicine Hat, AB T1B 4E3 Tel: (403) 527 8332 Fax: (403) N/A

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

General Info	
Medicine Hat/Schlenker (FZ3) Private - Public Use	Distance From Community (mile): 5 Latitude: 49.9667°, Longitude: -110.7167°
Owner and Operator Info Owner: same Operator: same Former Ownership: Date of Change:  Airport Organization	Contact Info  Mr. Aevult Schlenker  #7 Park Meadows Lane  Medicine Hat  T1B 4E3  (403) 527 8332(403) , Fax: N/A
Ownership Structure:  Private ownership	
Organizational Structure:	Primary: "06-24", 1700x65 (Turf) Good condition;
Role of Airport:	Secondary: "18-36", 1700x65 (Turf) Good condition;
Taxiway Data Primary:	
Trimaly	<b>☐Apron Data</b>
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
Landside Facility Data	ATB:
Entrance Road:	
	Disability Access:
Parking Lot:	
	Field Electrical Centre:
Fencing:	

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Caveat, and Right of Way
ARCAL: Type: Windsock: 1 windsocks; good condition	
□ Drainage Data □ □ □ □	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data					
FBO: No			AC Mair	ntenance:	No
Industrial Buildings: No			Crop Sp	oraying Act	tivities:
Hangars: No			Chemica	als Stored	on site:
Operation and Maintenance E	_	1000	1000	2000	2004
Total Annual Maintenance Budget	1997	1998	1999	2000	2001
Economic Activity Informatio	n —				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	1009	100	10	2000	2001
Total Annual Revenue:	1998	199	בי	2000	2001
Airport Expenditure Data	7 199	98 1	999	2000	2001
Total Annual Expenditure	, 1).	,,, 1		2000	2001

Year	Project Name	Funding Source	Description	
				-

## AIRPORT INFORMATION REPORT - 2002 MILK RIVER AIRPORT (CEW5)





Milk River Airport Aerial Photographs taken August 13, 2002

#### **Airport Contact Information:**

Ms. Lavinia Henderson Chief Administrative Officer Town of Milk River Milk River, AB T0K 1M0 Tel: (403) 647 3773

Fax: (403) 647 3773

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Milk River Airport (EW5)

General Info

Milk River (EW5)

Municipal

Distance From Community (mile): 1.5

Latitude: 49.1333°, Longitude: -112.0500°

Owner and Operator Info

Owner: Town Operator: Town

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Council

Organizational Structure:

Airport Committee - Advisory to Council

Role of Airport:

Crop Spraying/Medevac(local hospital)/Recreationa/Business

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1984; last rehabilitation 1996; Fair condition; replacement 2005 (\$34000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 10; type gravel; constructed

1984; good condition;

Parking Lot: ---

Fencing: size 4; type barb wire;

Contact Info

Ms. Lavinia Henderson Chief Administrative Officer

Town of Milk River

Box 270 Milk River T0K 1M0

(403) 647 3773(403), Fax: 647 3772

**Runway Data** 

Primary: "05-23", 2953x75 (Asphalt)

constructed 1984; last rehabilitation 1996; Fair condition; replacement 2005

(\$393000)

Secondary: ---

**Apron Data** 

Primary: ---

Secondary: ---

**Building Data** 

ATB: size 14x20; type wood frame; constructed

1985; good condition; replacement 2020

(\$100000)

Disability Access:

Field Electrical Centre: size 6x6; type garden shed;

constructed 1984; poor condition; replacement 2012

(\$150000)

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Milk River Airport (EW5)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1984; good condition; replacement 2012 (\$158000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1984; last rehabilitation 2001; good

condition; replacement 2012

Water / Sewer Data

Water Supply: Municipal Service; constructed

1985; good condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: Yes

**Drainage Data** 

Surface: constructed 1984; good condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Milk River Airport (EW5)

-Oneita Business Data -						
Onsite Business Data						
FBO: No			AC Ma	aintenance:	No	
Industrial Buildings: No			Crop	Spraying Ac	tivities: Perm	nanent; Floyd Coc
Hangars: Yes, 3;			Chemi	cals Stored	on site: No	
└────────────────────────────────────	ce Budae	t				
	199		8 1999	2000	2001	
Total Annual Maintenance Bud	lget					
Economic Activity Inform	ation —					
Road Distance to Nearest Airp Major Economic Industries in I How is the Airport Vital to the fly in for parts at local dealers  Airport Activity Info  Annual Aircraft Movements:  Annual Passenger Movements	ort Cargo Sort AME Secort Fire Sup Region: A Region: A hips. Mede	Service: 80 opression 9 griculture/Airport is Cevas, Borde	Service: 2 Tourism/Oi anpass app en Patrol, L	l & Gas proved, farn		
-						
Commercial Airline Info						
- Airport Povenus Data -						
Airport Revenue Data	997 :	1998	1999	2000	2001	
Total Annual Revenue:						
Airport Expenditure Data						
	1997	1998	1999	2000	2001	
Total Annual Expenditure						

## Milk River Airport (EW5)

Year	Project Name	Funding Source	Description
1996		Provincial	Fog seal asphalt surfaces
1985		Provincial	Terminal Building
1984		Provincial	Paving and airfield lighting
1982		Provincial	Drainage repairs
1980		Provincial	Temporary lighting
1979		Provincial	Land purchse (\$22,000), base and gravel

# **AIRPORT INFORMATION REPORT - 2002 MILK RIVER (MADGE) AIRPORT (CFQ3)**





Milk River (Madge) Airport Aerial Photographs taken August 13, 2002

#### **Airport Contact Information:**

Mr. Paul Madge Milk River, AB T0K 1M0 Tel: (403) 647 3812 Fax: (403) 647 3818

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 21, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

General Info Milk River (Madge) (FQ3)	Distance From Community (mile): 1.5				
(	Latitude: 49.1500°, Longitude: -112.0833°				
Owner and Operator Info Owner: County of Warner leased Operator: Paul Madge Former Ownership: Date of Change:	Mr. Paul Madge Box 299 - 412 - 3 Avenue NE Milk River TOK 1M0 (403) 647 3812(403) , Fax: 647 3818				
Airport Organization					
Ownership Structure:					
 Organizational Structure: 	Primary: "07-25", 3000x60 (Turf) constructed 1965; Good condition;				
Role of Airport:	Secondary:				
Taxiway Data Primary: Secondary:	Apron Data Primary:				
Third:	Secondary:				
Fourth:	Building Data				
Landside Facility Data	ATB:				
Entrance Road: type gravel;	Disability Access:				
Parking Lot: type 2 spaces;	Field Electrical Centre:				
encing:	rieiu ciecuicai centre:				

Lighting Data			Water / Sev	wer Data
Primary Edgelighting:			Water Suppl	y:
Approach Slope Indicator 1: -			Sewage:	-
Approach Slope Indicator 2: -				otection, d Right of Way rection: No
ARCAL: Type:			Caveat: No	)
Windsock: 1 windsocks; good condition	ո;		Right of Wa	y: NO
Drainage Data				
Surface:		Subsurfac	ce:	
Peak Period Info	Spring Summer	Fall Win	nter Average	
Peak Apron Aircraft Parked:				
Design Aircraft for Airport:				





Onsite Business Data				
FBO: No		AC I	Maintenance:	No
Industrial Buildings: No		Crop	o Spraying Ad	ctivities: Temporary;
Hangars: Yes, ; 1-2 planes		Cher	nicals Stored	on site:
Operation and Maintenance		1000 100	2000	2001
Total Annual Maintenance Budge	1997 et	1998 199	99 2000	2001
Economic Activity Informat	ion			
Airport Activity Info	1997	1998 199	9 2000	2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	7 1998	1999	2000	2001
Total Annual Revenue:	, 1990	1777	2000	2001
Airport Expenditure Data			<b>-</b>	
Total Annual Expenditure	997 19	98 1999	2000	2001

Year	Project Name	Funding Source	Description	

## AIRPORT INFORMATION REPORT - 2002 MOBIL BISTCHO AIRPORT (CFV3)





Mobil Bistcho Airport Aerial Photographs taken August 21, 2002

#### **Airport Contact Information:**

Mr. Jamie Lee
Fire Manager
Alberta Sustainable Resource Development - Land and Forest Division
High River, AB T0G 1Z0
Tel: (780) 926 5400
Fax: (780) 926 4224





Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

General Info	
Mobil Bistcho (FV3) Dista	nce From Community (mile):
Latitu	ude: 59.4833°, Longitude: -119.0167°
Owner and Operator Info	Contact Info
Owner:	Mr. Jamie Lee
Operator:	Fire Manager
Former Ownership: No Change Date of Change:	Alberta Sustainable Resource Development - Land and Forest Division
Date of Change.	Bag 900
Airport Organization	High River
Ownership Structure:	T0G 1Z0 (780) 926 5400(780) , Fax: 926 4224
	(700) 920 3400(700) , 1 ax. 920 4224
	┌Runway Data
Organizational Structure:	Primary: "10-28", 3600x100 (Turf)
	Fair condition; replacement 2008 (\$8000)
Role of Airport:	
	Secondary:
Taxiway Data	
Primary:	Apron Data
	Primary:
Secondary:	Filliary
Secondary.	
Third:	Secondary:
Familia	
Fourth:	
	Building Data
	□ ATB:
Landside Facility Data	
Entrance Road:	
	Disability Access:
Parking Lot:	
raiking Lot	
	Field Electrical Centre:
Fencing:	

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data				
FBO: No		A	AC Maintenanc	e: No
Industrial Buildings: No		(	Crop Spraying A	Activities:
Hangars: No		C	hemicals Store	ed on site:
Operation and Maintenance	_	1000	1000 2000	2004
Total Annual Maintenance Budg	1997 et	1998	1999 2000	2001
Economic Activity Information	tion			
Airport Activity Info	1997	1998 1	1999 2000	2001
Annual Aircraft Movements:		1330	2000	
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data				2004
Total Annual Revenue:	7 1998	3 1999	2000	2001
Airport Expenditure Data				
	997 19	998 199	99 2000	2001
Total Annual Expenditure				

Year	Project Name	Funding Source	Description	

## AIRPORT INFORMATION REPORT - 2002 MUSKEG TOWER AIRPORT (CFW4)





Muskeg Tower Airport Aerial Photographs taken August 7, 2002

#### **Airport Contact Information:**

Mr. Brian Stanton
W.A.O.O.
Alberta Sustainable Resource Development - Land and Forest Division
Lac La Biche, AB T0A 2C0
Tel: (780) 623 5240
Fax: (780) 623 2570

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

General Info	
Muskeg Tower (FW4)	Distance From Community (mile): Latitude: 57.1333°, Longitude: -110.9000°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Mr. Brian Stanton W.A.O.O. Alberta Sustainable Resource Development - Land and Forest Division Box 450
Airport Organization Ownership Structure:	Lac La Biche T0A 2C0 (780) 623 5240(780) , Fax: 623 2570
Organizational Structure:	Runway Data  Primary: "16-34", 2400x75 (Turf)
Role of Airport:	Secondary:
Taxiway Data Primary:	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data  ATB:
Landside Facility Data	AID
Entrance Road:	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

<b>□Lighting Data</b>	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Troumty 1 rotoonon,
ARCAL: Type: Windsock: 0 windsocks;	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





┌Onsite Business Data ──				
FBO: No		AC	Maintenance:	No
Industrial Buildings: No		Cr	op Spraying Ac	tivities:
Hangars: No		Che	emicals Stored	on site:
Operation and Maintenanc	_	1000 1/	200	2001
Total Annual Maintenance Budg	1997 let	1998 19	999 2000	2001
Economic Activity Informa	tion —			
Airport Activity Info	1997	1998 19	99 2000	2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	97 1998	1999	2000	2001
Total Annual Revenue:	1550	1999	2000	
Airport Expenditure Data	1007 10	00 1000	2000	2004
Total Annual Expenditure	1997 19	98 1999	2000	2001

Year	Project Name	Funding Source	Description	

## AIRPORT INFORMATION REPORT - 2002 NAMUR LAKE AIRPORT (CFB5)





Namur Lake Airport Aerial Photographs taken August 8, 2002

#### **Airport Contact Information:**

Namur Lake Lodge Fort McMurray, AB T9H 4V9 Tel: (780) 791 9299 Fax: (780) N/A

> Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

General Info				
	e From Community (mile): e: 57.3833°, Longitude: -112.8000°			
Owner and Operator Info	Contact Info			
Owner:	Namur Lake Lodge			
Operator:	Box 5941			
Former Ownership: Date of Change:	Fort McMurray T9H 4V9			
Date of Change.	(780) 791 9299(780) , Fax: N/A			
Airport Organization				
Ownership Structure:				
	Runway Data			
Organizational Structure:				
	Primary: "07-25", 2000x100 (Turf)			
Role of Airport:				
	Secondary:			
⊤Taxiway Data				
Primary:				
	Apron Data			
	Primary:			
Secondary:				
Third:	Secondary:			
Tilliu.	Secondary:			
Fourth:				
	Building Data			
	ATB:			
Landside Facility Data				
Entrance Road:				
	Disability Access:			
	Disability Access.			
Parking Lot:				
	Field Electrical Centre:			
Fencing:				

Lighting Data	□ Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Consite Business Data —				
FBO: No		AC N	laintenance:	No
Industrial Buildings: No		Crop	Spraying Ac	tivities:
Hangars: No		Chem	nicals Stored	on site:
Operation and Maintenanc	_	1000 100	2000	2004
Total Annual Maintenance Budg	1997 et	1998 199	9 2000	2001
Economic Activity Informa	tion			
Airport Activity Info	1997	1998 1999	2000	2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	97 1998	1999	2000	2001
Total Annual Revenue:	1930		2000	
Airport Expenditure Data				
	.997 19	98 1999	2000	2001
Total Annual Expenditure				

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 OLDS (NETOOK) AIRPORT (CFK6)





Olds (Netook) Airport Aerial Photographs taken October 24, 2002

#### **Airport Contact Information:**

Mr. Ross Hamilton Director Air Cadet League of Canada Olds, AB T4H 1P3 Tel: (403) 556 2874

Fax: (403) 556 1589

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Olds (Netook) Airport (FK6)

**General Info** 

Olds (Netook) (FK6)	Distance From Community (mile): 3.5 Latitude: 51.8500°, Longitude: -114.0667°			
Owner and Operator Info	Contact Info			
Owner: Alberta Prov. Committee Air Cadet Le Operator asarhe Former Ownership: Transport Canada Date of Change:				
┌Airport Organization ────	T4H 1P3			
Ownership Structure:	(403) 556 2874(403) , Fax: 556 1589			
Alberta Prov. Comm. Air Cadet League of Canada				
	┌Runway Data			
Organizational Structure:	Primary: "14-32", 4400x300 (Turf)			
Alberta Provincial Committee (Air Cadet League of Can				
Role of Airport:				
Air Cadet Gliding Centre	Secondary: "01-19", 3700x200 (Turf)			
	constructed 1993;			
⊤Taxiway Data				
Primary:	- Annon Data			
	Apron Data			
	Primary:			
Secondary:				
Third:	Secondary:			
11iii d	Secondary.			
Fourth:				
	Building Data			
□ I andeido Facility Data	ATB:			
Landside Facility Data				
Entrance Road: good condition;				
	Disability Access:			
Davidina Late				
Parking Lot:				
	Field Electrical Centre:			
Fencing:	Field Electrical Certain			

## Olds (Netook) Airport (FK6)

Lighting Data			Water / Se	wer Data	
Primary Edgelighting:			Water Suppl	y: Well; good condition;	
Approach Slope Indicator 1: -	. <b>-</b>		Sewage:	-	
Approach Slope Indicator 2: -			-	d Right of Way	
ADCAL. Tunos			Vicinity Protection: No Caveat: No		
ARCAL: Type: Windsock: 0 windsocks;			Right of Wa	y: No	
Drainage Data					
Surface:		Subsurfac	ce:		
Peak Period Info	Spring Summer	Fall Wir	nter Average		
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





### Olds (Netook) Airport (FK6)

FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: Yes, 1; Air Cadet	League			Chemic	cals Stored	on site:
│ │ │ │ │ │ │	ance B	udget 1997	1998	1999	2000	2001
Total Annual Maintenance E	Budget	1337	2330		2000	
Economic Activity Infor	rmatior	1				
- Airport Activity Info						
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movement	ts:					
Annual Passenger Movemer	nts:					
Commercial Airline Info	)					
 ⊢Airport Revenue Data						
	1997	1998		1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Da						
Total Annual Expenditure	1997	19	98	1999	2000	2001
Total Allitual Expellulture						

## Olds (Netook) Airport (FK6)

Year	Project Name	Funding Source	Description
2001		Grant + Prov. Comm	camp shelter for Gliding Centre
1998		Grant + Prov. Comm	concrete floor in main hanger
1995		Grant+ Prov. Comm	tractor mower for infield
1994		Prov. Comm	purchase of Netook Gliding Centrefrom DNI
1994		Grant + Prov. Comm	Construction of washroom
1993	classroom cross runway	Grant + Prov. Comm	purchase classroom/construct cross runway
1992	wingmower	Grant + Prov. Comm	wing mower for runway main

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 OLDS-DIDSBURY AIRPORT (CEA3)**





Olds-Didsbury Airport Aerial Photographs taken October 24, 2002

#### **Airport Contact Information:**

Mr. Dale Withage Chief Administrative Officer Town of Olds Olds, AB T4H 1R5 Tel: (403) 556 6981

Fax: (403) 556 6537

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 21, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877



Airport Summary Report



#### Olds-Didsbury Airport (EA3)

**General Info** 

Olds-Didsbury (EA3)

Distance From Community (mile): 4.3

Latitude: 51.7167°, Longitude: -114.1000°

Owner and Operator Info

Owner: Towns of Olds/Didsbury Operator: Towns of Olds/Didsbury Former Ownership: Province of Alberta

Date of Change: May 18, 1995

**Airport Organization** 

Ownership Structure:

Towns of Olds & Didsbury

Organizational Structure:

Town of Olds/Didsbury

Role of Airport:

Provides air travel for local business, Olds College, Government Officials and recreational flyers.

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1982; last rehabilitation 1996;

Good condition;

Secondary: "B"; (Asphalt)

constructed 1990; Good condition;

replacement 2010 (\$10000)

Third: "C"; (Asphalt)

constructed 1990; Good condition;

replacement 2010 (\$10000)

Fourth: "D"; (Asphalt)

constructed 1990; Good condition;

replacement 2010 (\$10000)

**Landside Facility Data** 

Entrance Road: constructed 1982; last rehabilitation

1998; fair condition;

Parking Lot: constructed 1982; last rehabilitation

1998; poor condition;

Fencing:

Contact Info

Mr. Dale Withage

Chief Administrative Officer

Town of Olds

4512 - 46th Street

Olds T4H 1R5

(403) 556 6981(403), Fax: 556 6537

**Runway Data** 

Primary: "10-28", 3650x75 (Asphalt)

constructed 1982; last rehabilitation 1996; Fair condition; replacement 2006

(\$400000)

Secondary: "04-22", 2000x50 (Turf)

constructed 1986; Good condition;

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1982; last rehabilitation 1996; fair condition; replacement 2006

(\$75000)

Secondary: ---

**Building Data** 

ATB: constructed 1982; last rehabilitation 2001;

good condition;

Disability Access: fair condition;

Field Electrical Centre: constructed 1982; fair

condition; replacement 2005

(\$150000)

Airport Summary Report

### Olds-Didsbury Airport (EA3)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1982; fair condition; replacement 2005 (\$156000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1982; fair condition; replacement 2

(\$10000)

Water / Sewer Data

Water Supply: Well; constructed 1983; good

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: Yes Right of Way: Yes

**Drainage Data** 

Surface: constructed 1982; fair condition; Subsurface: ---

Peak Period Info
Spring Summer Fall Winter Average
Peak Apron Aircraft Parked: 4 4 4 2 3.5
Design Aircraft for Airport: ---



PRYDE SCHROPP McCOMB INC.

### Olds-Didsbury Airport (EA3)

Onsite Business Data						
FBO: Yes, 2; Lots 4 and 14			AC Mair	itenance:	Yes, 1; Ruf's M	Naintenance - lot 14
Industrial Buildings: No			Crop Sp	raying Act	ivities: 1. Olds Accurat	College Aviation 2.
Hangars: Yes, 11; See attached	d list		Chemica	ls Stored o	on site: No	
Operation and Maintenanc	e Budget					
	1997	1998	1999	2000	2001	
Total Annual Maintenance Budg	jet					
Economic Activity Informa	tion					
Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Major Economic Industries in Road How is the Airport Vital to the Foundation of Standard Industries and Industries relocating. Recreational Industries relocating.	rt MedEvac Servi rt Cargo Servi rt AME Service rt Fire Suppre egion: Olds ( Region: The A s in the region	ervice: 60 ce: 60 e: 0 ssion Serv College/CO Airport ser	ice: 60 DN 88/Agi ves as a	transporta	ition	
Airport Activity Info	1997	1998	1999	2000	2001	
Annual Aircraft Movements:						
Annual Passenger Movements:						
Commercial Airline Info	1					
Airport Revenue Data						
Total Annual Revenue:	97 1998	199	99 2	2000	2001	
Total Allitual Nevellue.						
Airport Expenditure Data	1007 10	00 1	000	2000	2001	
Total Annual Expenditure	1997 19	98 1	.999	2000	2001	

## Olds-Didsbury Airport (EA3)

Year	Project Name	Funding Source	Description
1999		Provincial	Runway extension
1993		Provincial	Contribution towards taxiway paving
1992		Provincial	Slurry Seal asphalt surfaces
1984		Provincial	Supplementary Terminal Building
1983		Provincial	Terminal Building
1982		Provincial	Land purchase (\$125,000) construction, paving and lighting

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 OYEN MUNICIPAL AIRPORT (CED3)**





Oyen Municipal Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Ms. Debbie Kovitch Municipal Administrator Town of Oyen Oyen, AB T0J 2J0 Tel: (403) 664 3511 Fax: (403) 664 3585

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Oyen Municipal Airport (ED3)

**General Info** 

Oyen Municipal (ED3)

Municipal

Distance From Community (mile): 1

Latitude: 51.3333°, Longitude: -110.4833°

Owner and Operator Info

Owner: Town of Oyen Operator: Town of Oye

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

GA traffic/crop spraying

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1974; Fair condition; replacement 2005 (\$29000)

Secondary: "B"; (Asphalt)

constructed 1974; Poor condition;

replacement 2005 (\$5000)

Third: "to hangers"; (Gravel)

Fair condition;

**Landside Facility Data** 

Fourth: ---

ATPL circ

Entrance Road: size 10ft; type gravel; constructed

1977; fair condition;

Parking Lot: size 20 spaces; type grass; fair

condition; replacement 2020

Fencing: size 4ft; type 3 strand barb wire;

replacement 2020

Contact Info

Ms. Debbie Kovitch Municipal Administrator

Town of Oyen P.O. Box 360

Oyen

T0J 2J0

(403) 664 3511(403) , Fax: 664 3585

Runway Data

Primary: "14-32", 3000x75 (Asphalt)

constructed 1974; last rehabilitation 1990; Poor condition; replacement 2005

(\$397000)

Secondary: "04-22", 2200x75 (Sand)

constructed 1974; Poor condition;

replacement 2005 (\$60000)

**Apron Data** 

Primary: ---

Secondary: ---

**Building Data** 

ATB: size 24x24; type wood frane; constructed

1982; fair condition;

Disability Access:

Field Electrical Centre: size 6x8; type garden shed;

constructed 1977; fair

condition; replacement 2005

(\$150000)

Airport Summary Report

### Oyen Municipal Airport (ED3)

Lic	hting	Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1977; fair condition; replacement 2005 (\$124000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: ---

Windsock: 1 windsocks;

fair condition; replacement 2010

#### Water / Sewer Data

Water Supply: Other; constructed 1977; fair

condition;

Sewage: ---

#### Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Design Aircraft for Airport:

Surface: good condition; Subsurface: ---

# Peak Period Info Spring Summer Fall Winter Average Peak Apron Aircraft Parked:





### Oyen Municipal Airport (ED3)

**Onsite Business Data** 

FBO: No	A	C Maintenance: No	
Industrial Buildings: No	Cı	rop Spraying Activities	: Temporary; 2; Target Airspray; Strankman Air Spray
Hangars: Yes, 13; hangers are privately See air photo	owned: Ch	emicals Stored on site	e: no
Operation and Maintenance Budge		999 2000 200	01
Total Annual Maintenance Budget			<del></del>
Economic Activity Information			
Road Distance to Nearest Airport AME Set Major Economic Industries in Region: A How is the Airport Vital to the Region: from the larger centers, our airport is recemergency medical services ie: Medeva helicopter and fixed wing aircraft; crop services in the larger centers are made in the larger centers.	.griculture/Oil & G Because we are lo garded as a very i s/ Medicine Hat ar	cated great distances mportant- delivery of	
Airport Activity Info	7 1998 19	999 2000 200	1
Annual Aircraft Movements:	, 1330 1.	2000 2000	
Annual Passenger Movements:			
Commercial Airline Info			
Airport Revenue Data	1000 1000	2000 2001	
Total Annual Revenue:	1998 1999	2000 2001	<u>-</u>
Airport Expenditure Data			
Total Annual Expenditure	1998 199	9 2000 20	001

## Oyen Municipal Airport (ED3)

Year	Project Name	Funding Source	Description
1990		Federal	Runway repair and overlay
1985		Provincial	Supplementary Terminal Building
1982		Provincial	Terminal Building
1979		Provincial	Oil and asphalt supplied for 04-22 stabilize surface
1977		Provincial	Lighting
1976		Federal	Towards completion of paving (airport des and engineering assistance by DOT)
1976		Provincial	Paving
1974		Federal	Initial airport construction

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 PEACE RIVER AIRPORT (CYPE)





Peace River Airport Aerial Photographs taken July 24, 2002

#### **Airport Contact Information:**

Ms. Sally Beaven Airport Manager Peace River Airport Peace River, AB T8S 1S4 Tel: (780) 624 2867

Fax: (780) 624 3157

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Peace River Airport (YPE)

General Info

Peace River (YPE) Distance From Community (mile): 5

Latitude: 56.2333°, Longitude: -117.4500°

Owner and Operator Info

Owner: Town of Peace River
Operator: Town of Peace River

Former Ownership: Transport Canada Date of Change: August 31, 1996

**Airport Organization** 

Ownership Structure:

Municipal

Organizational Structure:

Municipal Government

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

Fair condition;

Secondary: "B"; (Asphalt)

Fair condition;

Third: "C"; (Asphalt)

Fair condition;

Fourth: ---

**Landside Facility Data** 

Entrance Road: type paved; fair condition;

Parking Lot: type paved; fair condition;

Fencing: size 6; type chain link;

Contact Info

Ms. Sally Beaven Airport Manager

Peace River Airport

Box 6600 Peace River T8S 1S4

(780) 624 2867(780), Fax: 624 3157

**Runway Data** 

Primary: "04-22", 5000x150 (Asphalt)

last rehabilitation 1998; Fair condition;

replacement 2008 (\$883000)

Secondary: "08-26", 1900x150 (Turf)

Fair condition; replacement 2007

(\$7000)

**Apron Data** 

Primary: "Main"; 800x300 (Asphalt)

fair condition; replacement 2005

(\$500000)

Secondary: ---

**Building Data** 

ATB: good condition;

Disability Access:

Field Electrical Centre: good condition;

Airport Summary Report

### Peace River Airport (YPE)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

fair condition; replacement 2006 (\$2130)

Approach Slope Indicator 1: P2 (PAPI - Aircraft up to 25')

good condition;

Approach Slope Indicator 2: P2 (PAPI - Aircraft up to 25')

good condition;

ARCAL: Type: ---

Windsock: 2 windsocks;

good condition;

Water / Sewer Data

Water Supply: Other; fair condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: fair condition; Subsurface: fair condition;

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

--





### Peace River Airport (YPE)

**Onsite Business Data** 

FBO: Yes, 2; Peace Air - ESSO and Northern

Air Charter - Shell

Industrial Buildings: No Crop Spraying Activities:

Hangars: Yes, 5; Peace Air (1), Northern Air

Charters (2), and Highland

Helicopter(1)

AC Maintenance: Yes, 3; Peace Air, Northern Air

Charters and Highland Helt

Chemicals Stored on site:

Operation and Maintenance Budget

1997 1998 1999 2000 2001

Total Annual Maintenance Budget

**Economic Activity Information** 

Major Economic Industries in Region: Daishowa-Marubeni International Ltd./Shell

Canada Ltd.

**Airport Activity Info** 

1997 1998 1999 2000 2001

**Annual Aircraft Movements:** 

Annual Passenger Movements:

**Commercial Airline Info** 

Air Canada Jazz (B1900, Schedule) PEACE Air (PC12, Schedule/Charter)

Northern Air Charter (BE10, Charter/Medevac)

**Airport Revenue Data** 

1997 1998 1999 2000 2001

Total Annual Revenue:

**Airport Expenditure Data** 

1997 1998 1999 2000 2001

**Total Annual Expenditure** 

## Peace River Airport (YPE)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 PELICAN AIRPORT (CFT8)





Pelican Airport Aerial Photographs taken August 9, 2002

#### **Airport Contact Information:**

Mr. Trevor Bryce
Dispatcher
Encana
Wabasca, AB T0G 2K0
Tel: (780) 891 4105
Fax: (780) 891 3438

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info					
	ce From Community (mile): 0 de: 56.1667°, Longitude: -113.4667°				
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:  Airport Organization	Contact Info  Mr. Trevor Bryce Dispatcher Encana Box 630 Wabasca T0G 2K0 (780) 891 4105(780), Fax: 891 3438				
Ownership Structure:					
Organizational Structure:	Runway Data Primary: "07-25", 3172x75 (Oiled Gravel)				
Role of Airport:	Secondary:				
⊤Taxiway Data					
Primary:	Apron Data				
Secondary:	Primary:				
Third:	Secondary:				
Fourth:					
	Building Data				
□ Landside Facility Data	ATB:				
Entrance Road:					
Entrance Road.	Disability Access:				
Parking Lot:	Field Electrical Centre:				
Fencing:					

Lighting Data	┌Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock:	
□ Drainage Data	
Surface:	Subsurface:
□Peak Period Info	

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





Onsite Business Data					
FBO: No			AC Main	itenance:	No
Industrial Buildings: No Crop Spraying Activities:					
Hangars: No			Chemica	ls Stored o	n site:
Operation and Maintenanc	e Budget				
Total Annual Maintenance Budg	1997 et	1998	1999	2000	2001
Economic Activity Informa	tion				
Airport Activity Info	1007	1000	1000	2000	2001
Annual Aircraft Movements:	1997	1998	1999	2000	2001
Annual Passenger Movements:					
Commercial Airline Info	<u>'</u>				
Airport Revenue Data	97 1998	3 199	99 5	2000	2001
Total Annual Revenue:					2001
Airport Expenditure Data					
Total Annual Expenditure	1997 19	998 1	1999	2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 PINCHER CREEK AIRPORT (CZPC)





Pincher Creek Airport Aerial Photographs taken August 12, 2002

#### **Airport Contact Information:**

Mr. Norm Minchau
Public Works Superintendent
Municipal District of Pincher Creek
Pincher Creek, AB T0K 1W0
Tel: (403) 627 3484

Fax: (403) 627 3484

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Pincher Creek Airport (ZPC)

General Info

Pincher Creek (ZPC)

Municipal

Distance From Community (mile): 3

Latitude: 49.5167°, Longitude: -114.0000°

Owner and Operator Info

Owner: M.D. of Pincher Creek No. 9 Operator: M.D. of Pincher Creek No. 9 Former Ownership: Province of Alberta

Date of Change: April 1, 1995

**Airport Organization** 

Ownership Structure:

Local Municipal Government

Organizational Structure:

Municipal Government

Role of Airport:

To service the needs of the Region

**Taxiway Data** 

Primary: "to main terminal"; 450x50 (Asphalt)

Fair condition; replacement 2008 (\$46000)

Secondary: "apron to East"; 1370x30 (Asphalt)

replacement 2004 (\$65000)

Third: "C-to Commercial hangers"; 350x75 (Asphalt)

Fair condition; replacement 2008 (\$32000)

Fourth: "Bomber Base"; 550x25

replacement 2004 (\$54000)

**Landside Facility Data** 

Entrance Road: size 2-Lane; type gravel; good

condition;

Parking Lot: size 20 Spaces; type gravel; good

condition;

Fencing: ---

Contact Info

Mr. Norm Minchau

Public Works Superintendent Municipal District of Pincher Creek

Box 279 Pincher Creek

TOK 1W0

(403) 627 3484(403), Fax: 627 3474

**Runway Data** 

Primary: "07-25", 6600x100 (Asphalt)

Fair condition; replacement 2008

(\$1165000)

Secondary: ---

**Apron Data** 

Primary: "Bomber Base"; 350x350

fair condition; replacement 2008

(\$210000)

Secondary: "ATB (main)"; 200x200 (Asphalt)

constructed 1977; fair condition; replacement 2008 (\$123000)

**Building Data** 

ATB: size 50'x125'; type single room; good

condition; replacement 2020 (\$100000)

Disability Access: ---

Field Electrical Centre: size 12x10; type in bsement

of ATB - room; good

condition; replacement 2022

(\$150000)

Airport Summary Report

### Pincher Creek Airport (ZPC)

-1	Li	a	hti	in	a	D	ata	

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1984; last rehabilitation 199 fair condition; replacement 2008 (\$3650)

Approach Slope Indicator 1: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1984; fair condition; replacement 2008 (\$30000)

Approach Slope Indicator 2: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1984; fair condition; replacement 2008 (\$60000)

ARCAL: Type: "K"; freq 123.2

Windsock: 2 windsocks;

fair condition; replacement 2008

#### Water / Sewer Data

Water Supply: Other;

Sewage: ---

#### Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: good condition; Subsurface: ---

#### Peak Period Info

Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Pincher Creek Airport (ZPC)

Onsite Business Data

FBO: No	AC Maintenance: No	AC Maintenance: No		
Industrial Buildings: No	Crop Spraying Activit	ties: Temporary; As required-very infrequent		
Hangars: Yes, 9;	Chemicals Stored on	site: none		
Operation and Mainter	_			
		2001		
Total Annual Maintenance	Budget			
Economic Activity Info	rmation			
Plant/Agriculture How is the Airport Vital to the Forest Reserve Area, u spraying & business, by N	in Region: Wind Energy/Shell Gas Processing the Region: By the Alberta Forest Service to protised for Medevacs, Agriculture Community for cropatural Resources for Wildlife Management Surviella or transport personel and parts.	1		
Airport Activity Info	1997 1998 1999 2000 2	2001		
Annual Aircraft Movemer				
Annual Passenger Moveme	nts:			
Commercial Airline Inf	0			
Airport Revenue Data	1997 1998 1999 2000 2	001		
Total Annual Revenue:	1557 1550 1559 2000 Z			
Airport Expenditure Da	1997 1998 1999 2000	2001		
Total Annual Expenditure	1557 1550 1555 2000	2001		

### Pincher Creek Airport (ZPC)

#### **Historic Capital Expenditures** Year Project Name **Funding Source** Description 1998 Provincial Fog and paint 1993 Provincial Fog seal pavement 1992 Provincial Install displaced threshold lighting 1991 Provincial Purchase additional airfield lighting 1987 Provincial Slurry seal runway 1987 Purchase and install NDB Provincial 1987 Provincial Purchase and install DME 1986 Provincial Drainage repairs Drainage repair and installation of VASIS 1985 Provincial 1984 Provincial Drainage and taxiway repairs 1979 Provincial Terminal Building 1978 Provincial Install airfield lighting 1977 Grading, base and paving, maintenance Provincial garage and fencing Land purchase 1977 Provincial

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## **AIRPORT INFORMATION REPORT - 2002 PONOKA INDUSTRIAL AIRPORT (CEH3)**





Ponoka Industrial Airport Aerial Photographs taken October 10, 2002

#### **Airport Contact Information:**

Mr. John Jeffries
Airport Manager
Ponoka Industrial Airport
Ponoka, AB T4J 1R3

Tel: (403) 783 4431 Fax: (403) 783 6745

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Ponoka Industrial Airport (EH3)

General Info

Ponoka Industrial (EH3)

Municipal

Distance From Community (mile): 1.5 Latitude: 52.6500°, Longitude: -113.6000°

Owner and Operator Info

Owner: Town of Ponoka Operator: Town of Ponoka Former Ownership: No Change

Date of Change: April 1, 1995

**Airport Organization** 

Ownership Structure:

Town of Ponoka

Organizational Structure:

Role of Airport:

To facilitate the following: Regional Transportation System, Regional Disaster Services System, Regional Economic

**Taxiway Data** 

Primary: "A"; 1500x (Asphalt)

constructed 1977; last rehabilitation 2000;

Fair condition;

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; fair condition;

Parking Lot: type gravel; fair condition;

Fencing: size 4; type barb wire around perimeter;

Contact Info

Mr. John Jeffries Airport Manager

Ponoka Industrial Airport Box 2, Site 20, RR3

Ponoka T4J 1R3

(403) 783 4431(403), Fax: 783 6745

**Runway Data** 

Primary: "16-34", 3097x75 (Asphalt)

constructed 1977; last rehabilitation 2000; Fair condition; replacement 2005

(\$397000)

Secondary: ---

**Apron Data** 

Primary: "part of taxiway"; 160x35 (Asphalt)

constructed 1977; fair condition; replacement 2003 (\$25000)

Secondary: ---

**Building Data** 

ATB: constructed 1980; last rehabilitation 2001; fair condition; replacement 2010 (\$100000)

Disability Access: ---

Field Electrical Centre: size 5x5; type shed; poor

condition; replacement 2005

(\$150000)

Airport Summary Report

#### Ponoka Industrial Airport (EH3)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1978; poor condition; replacement 2005 (\$269000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1977; last rehabilitation 2001; fair

condition; replacement 2005

Water / Sewer Data

Water Supply: Well; constructed 1970; good

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1977; poor condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Ponoka Industrial Airport (EH3)

**Onsite Business Data** 

FBO: Yes, ; Triad Aviation Ltd.			AC Maintenance: Yes, ; Triad Aviation Ltd			
Industrial Buildings: No		Crop Spraying Activities:				
Hangars: Yes, 17; Private, Commercial and Corprate Ownership			Chemical	ls Stored (	on site:	
Operation and Maintenand	•	1000	1000	2000	2001	
Total Annual Maintenance Bud	1997 get	1998	1999	2000	2001	
Economic Activity Informa	ation					
Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Road Distance to Nearest Airpo Major Economic Industries in R How is the Airport Vital to the Services, Economic Developme	ort MedEvac S ort Cargo Serviort AME Servio ort Fire Suppre egion: Agric Region: Trar	ervice: 0 ice: 80 ee: 0 ession Servi ulture/Oil 8	ce: 3 c Gas/Hea		evac	
Airport Activity Info	1997	1998	1999	2000	2001	
Annual Aircraft Movements:	2337	1330	1333	2000		
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data	07 1000	2 100	.0 2	2000	2001	
Total Annual Revenue:	97 1998	3 199	<del>''</del> 2	2000	2001	
Airport Expenditure Data	1007 10	000 1	000	2000	2001	_
Total Annual Expenditure	1997 19	998 1	999	2000	2001	_

## Ponoka Industrial Airport (EH3)

Year	Project Name	Funding Source	Description
2001		Provincial	Fog Coat
2000	Upgrade of Terminal Bldg	Grant 3,500.00; Flying Club	Gov't of AB
2000	Paving Taxiway	Grant-17,637;Res 4,150; Taxes 4,822	AB Infrustructure
2000	Upgrade of Terminal Bldg.	Grant 3500+ Flying Club	Gov't of AB
2000	Paving taxiway	Grant \$17,637+Res- \$4,150.00+Taxes \$4,822	AB Infrustructure
1995		Provincial	Fog seal asphalt surfaces
1985		Provincial	Overlay existing pavement
1983		Provincial	Funding of airport Master Plan
1983		Provincial	Terminal Building
1983		Provincial	Initial survey for pavement overlay
1980	_	Provincial	Survey and soils investigation
1980	_	Provincial	Runway and draingae repairs
1979		Provincial	Runway drainage improvements
1978		Provincial	Repaving runway, extend taxiway and pav Also expansion of building development a
1978		Federal	Paving
1978		Provincial	Land purchase plus survey fees budgeted for but not yet paid to Town.
1968		Federal	Initial Construction

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# AIRPORT INFORMATION REPORT - 2002 PROVOST AIRPORT (CEH6)





Provost Airport Aerial Photographs taken October 9, 2002

#### **Airport Contact Information:**

Mr. Thomas Schneider Reeve Municipal District of Provost Provost, AB T0B 3S0 Tel: (780) 753 2434

Fax: (780) 753 6432

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Provost Airport (EH6)

General Info

Provost (EH6) Distance From Community (mile): 1

Latitude: 52.3333°, Longitude: -110.2833°

Owner and Operator Info

Owner: MD of Provost Operator: Russel Gillert

Former Ownership: No Change

Date of Change: ---

Airport Organization

Ownership Structure:

The land is owned by the MD of Provost

Organizational Structure:

The Town of Provost/MD

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; 78x11 (Asphalt)

constructed 1977; last rehabilitation 1998; Good condition; replacement 2012 (\$19000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 20ft; type gravel; fair condition;

Parking Lot: size 20x40; type gravel; good

condition;

Fencing: size 4ft; type barb wire;

Contact Info

Mr. Thomas Schneider

Reeve

Municipal District of Provost

Box 300 Provost T0B 3S0

(780) 753 2434(780) , Fax: 753 6432

Runway Data

Primary: "12-30", 5001x75 (Asphalt)

constructed 1976; last rehabilitation 1998; Good condition; replacement 2012

(\$410000)

Secondary: ---

**Apron Data** 

Primary: "A"; 61x46 (Asphalt)

constructed 1977; last rehabilitation 1998; good condition; replacement 2012

(\$64000)

Secondary: ---

**Building Data** 

ATB: size 448sqft; type wood; constructed 1984;

last rehabilitation 2000;

Disability Access: type sidewalk;

Field Electrical Centre: size 6x6; type tool shed; fair

condition; replacement 2007

(\$150000)

## Provost Airport (EH6)

Lighting Data	Water / Sewer Data
	reshold and Runway End) Ucted 1977; fair condition; Ement 2006 (\$145000)  Water Supply: Well; constructed 1984; good condition;
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: "K"; fr	Vicinity Protection: Yes Caveat: No Right of Way: No
Windsock: 2 windsocks; good condition	n;
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





### Provost Airport (EH6)

Onsite Business Data		
FBO: No		AC Maintenance: No
Industrial Buildings: No		Crop Spraying Activities: Temporary; Operators work off the a/p, not registered
Menzies Farms l McElhinncy, Bria	geard Farms Ltd.,	Chemicals Stored on site: Temporaty only when spraying
Operation and Mainter	<u> </u>	1000 2000 2001
Total Annual Maintenance	1997 1998 Budget	1999 2000 2001
Economic Activity Info	ormation	
Major Economic Industries	Airport Fire Suppression Se s in Region: Farming/Rand the Region: THE AIRPOR L	ching/Oil & Gas
Airport Activity Info	1997 1998	1999 2000 2001
Annual Aircraft Moveme		1999 2000 2001
Annual Passenger Moveme	ents:	
Commercial Airline Inf	fo -	
Airport Revenue Data		
Total Annual Revenue:	1997 1998 1	999 2000 2001
Airport Expenditure D	ata —	
	1997 1998	1999 2000 2001
Total Annual Expenditure		

## Provost Airport (EH6)

Year	Project Name	Funding Source	Description
1999		Provincial	Pavement overlay
1999		Provincial	Runway extension (gravel, base and pavement)
1988		Provincial	Supply an dinstall NDB, equipment buildin and DME
1987		Provincial	Install medium-intensity airfield lighting system
1984		Provincial	Terminal Building
1984		Provincial	Repairs to NDB
1983		Provincial	Runway overlay
1976		Provincial	Completion of paving and installation of airport lighting
1974		Federal	Intial construction and paving

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 RAINBOW LAKE AIRPORT (CYOP)





Rainbow Lake Airport Aerial Photographs taken August 20, 2002

#### **Airport Contact Information:**

Ms. Anna Butler
Town Manager
Town of Rainbow Lake
Rainbow Lake, AB T0H 2Y0

Tel: (780) 956 3934 Fax: (780) 956 3570

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Rainbow Lake Airport (YOP)

General Info

Rainbow Lake (YOP) Distance From Community (mile): 0

Latitude: 58.5000°, Longitude: -119.4000°

Owner and Operator Info

Owner: Town of Rainbow Lake Operator: Town of Rainbow Lake Former Ownership: No Change

Date of Change: ---

Airport Organization

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1977; last rehabilitation 1998;

Good condition; replacement 2011

Secondary: "private Forestry";

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: good condition;

Parking Lot: last rehabilitation 1998; good

condition;

Fencing:

Contact Info

Ms. Anna Butler Town Manager

Town of Rainbow Lake

Box 149 Rainbow Lake TOH 2Y0

(780) 956 3934(780), Fax: 956 3570

**Runway Data** 

Primary: "09-27", 4500x100 (Asphalt)

constructed 1977; last rehabilitation 1998; replacement 2011 (\$900000)

Secondary: ---

**Apron Data** 

Primary: "1";

constructed 1977; last rehabilitation

1998; good condition;

Secondary: "Forestry";

Building Data

ATB: constructed 1980; last rehabilitation 1986;

good condition;

Disability Access:

Field Electrical Centre: ---

Airport Summary Report

#### Rainbow Lake Airport (YOP)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

last rehabilitation 1998; fair condition;

Approach Slope Indicator 1: P1 (PAPI - Aircraft up to 10')

constructed 1986; fair condition;

Approach Slope Indicator 2: P1 (PAPI - Aircraft up to 10')

constructed 1986; fair condition;

ARCAL: Type: "J"; freq 122.8

Windsock: 1 windsocks;

Water / Sewer Data

Water Supply: Municipal Service; constructed

1980; good condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: constructed 1960; last rehabilitation 1998; Subsurface: ---

fair condition;

Peak Period InfoSpringSummerFallWinterAveragePeak Apron Aircraft Parked:545106Design Aircraft for Airport:------



### Rainbow Lake Airport (YOP)

FBO: Yes, ; Swan Aero			AC Ma	intenance:	Yes, ; Airborne Energy ser own aircraft	vices their
Industrial Buildings: No			Crop S	Spraying Act	ivities:	
Hangars: Yes, ; Airborne En	ergy		Chemic	cals Stored (	on site:	
Operation and Maintena	_		1000	2000	2001	
Total Annual Maintenance B	199 udget	7 1998	1999	2000	2001	
Economic Activity Infor	mation —					
Airport Activity Info	1997	7 1998	1999	2000	2001	
Annual Aircraft Movements						
Annual Passenger Movemen	ts:					
Commercial Airline Info						
<sup>−</sup> Airport Revenue Data  −	1997	908	1999	2000	2001	
Airport Revenue Data  Total Annual Revenue:	1997 1	1998	1999	2000	2001	
		1998	1999	2000	2001	

## Rainbow Lake Airport (YOP)

Historic	Historic Capital Expenditures						
Year	Project Name	Funding Source	Description				
1999		Federal	ACAP grant asphalt o/lay - runway & taxiways				
1990		Federal	Supplementary funding to previous year's projects				
1989		Federal	Air terminal building expansion, aircraft parking apron extension, new airfield lighting				
1987		Provincial	Slurry seal runway				
1986		Provincial	Purchase and install DME				
1984		Provincial	Parking on apron expansion				
1984		Provincial	Slurry seal runway				
1980		Provincial	Air Terminal Building				
1979		Provincial	Runway lighting				
1977		Provincial	Grading, reshaping and drainage for existing runway				
1977		Provincial	Grading, base and paving				
1977		Provincial	Tree clearing				

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 RED DEER REGIONAL AIRPORT (CYQF)**





Red Deer Regional Airport Aerial Photographs taken October 10, 2002

#### **Airport Contact Information:**

Mr. Otto Epp Airport Manager Red Deer Regional Airport Penhold, AB T0M 1R0 Tel: (403) 886 4219

Fax: (403) 886 4211

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877



Airport Summary Report



#### Red Deer Regional Airport (YQF)

General Info

Distance From Community (mile): 6 Red Deer Regional (YOF)

Latitude: 52.1833°, Longitude: -113.9000°

Owner and Operator Info

Owner: Red Deer Regional Airport Authority Operator: Red Deer Regional Airport Authority Former Ownership: City of Red Deer 1998

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Organizational Structure:

Role of Airport:

**Taxiway Data** 

Primary: "A"; 600x75 (Asphalt)

last rehabilitation 2000; Fair condition;

replacement 2005 (\$500000)

Secondary: "B"; 3000x75 (Asphalt)

Good condition; replacement 2012

(\$96000)

Third: "C"; 1300x75 (Asphalt)

Fair condition; replacement 2005 (\$96000)

Fourth: "D"; 600x (Asphalt)

Fair condition; replacement 2004 (\$200000)

**Landside Facility Data** 

Entrance Road: type asphalt; poor condition;

replacement 2005 (\$49000)

type gravel; constructed 1980; poor Parking Lot:

condition;

Fencing: type varies; replacement 2008

Contact Info

Mr. Otto Epp Airport Manager

Red Deer Regional Airport

Box 370 Penhold T0M 1R0

(403) 886 4219(403), Fax: 886 4211

**Runway Data** 

Primary: "16-34", 5528x98 (Asphalt)

last rehabilitation 2000; Good condition;

replacement 2012 (\$1000000)

Secondary: "11-29", 3449x100 (Asphalt)

last rehabilitation 1980; Poor condition;

replacement 2006 (\$600000)

**Apron Data** 

Primary: "1"; 200x300 (Asphalt)

last rehabilitation 2000; good condition;

replacement 2012 (\$128000)

Secondary: ---

**Building Data** 

ATB: constructed 1980; fair condition; replacement

2010 (\$100000)

Disability Access: type sidewalk;

Field Electrical Centre: ---

Airport Summary Report

#### Red Deer Regional Airport (YQF)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

poor condition; replacement 2004 (\$383)

Approach Slope Indicator 1: V1 (2-BAR VASIS - Aircraft up to 1

poor condition; replacement 2004

(\$60000)

Approach Slope Indicator 2: V1 (2-BAR VASIS - Aircraft up to 1

poor condition; replacement 2004

(\$60000)

ARCAL: Type: ---

Windsock: 2 windsocks;

fair condition; replacement 2008

Water / Sewer Data

Water Supply: Municipal Service; fair

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: poor condition; Subsurface: poor condition;

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Red Deer Regional Airport (YQF)

Onsite Business Data				
FBO: Yes, 2;		AC M	laintenance:	Yes, 3;
Industrial Buildings: Yes, 6;		Crop	Spraying Ac	tivities: Temporary; 1
Hangars: Yes, 15;		Chem	icals Stored	on site: none on site
Operation and Maintenance	Budget -			
•	1997	1998 1999	9 2000	2001
Total Annual Maintenance Budget				
Economic Activity Information	on —			
Road Distance to Nearest Airport Road Distance to Nearest Airport Road Distance to Nearest Airport Major Economic Industries in Reg How is the Airport Vital to the Reg the region.	AME Service Fire Suppres ion: Oil & G	: 150 sion Service: 1 as	150 portation sei	vices for
Airport Activity Info	1997	1998 1999	2000	2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data				
Total Annual Revenue:	1998	1999	2000	2001
Airport Expenditure Data		0 1000	2000	2001
Total Annual Expenditure	97 199	8 1999	2000	2001

#### Red Deer Regional Airport (YQF)

#### **Historic Capital Expenditures** Year Project Name **Funding Source** Description 2002 Provincial Pavement o/lay of runway 16/34 & main taxiway 1995 Provincial Completion of drainage project 1994 Provincial Drainage improvements 1993 Additional drainage investigations Provincial Survey for field airfield drainage 1992 Provincial improvements Taxiway overlay of lots 10, 11, 12 1991 Provincial 1991 Provincial Air terminal heating modifications 1987 Provincial Supply and install DME 1986 Provincial Airport Master Plan 1986 Provincial Complete runway overlay (11-29) 1984 Provincial Remedial overlay of hangar ramp areas 1982 Provincial Funding by AT&U towards airport portion of a new regional sewage system Runway 16-34 construction and lighting 1981 Provincial 1980 Air terminal building Provincial 1978 Land purchase of 160 acres for Runway 16-Provincial 34 extension

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 RED EARTH CREEK AIRPORT (CEH5)





Red Earth Creek Airport Aerial Photographs taken August 9, 2002

#### **Airport Contact Information:**

Mr. Rob Guild Area Foreman Municipal District #17 Red Earth Creek, AB T0G 1X0 Tel: (780) 649 3427

Fax: (780) 649 3440/2562

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Revision No. 3 February 18, 2003 Project No. 11451

Airport Summary Report

#### Red Earth Creek Airport (EH5)

General Info

Red Earth Creek (EH5)

Municipal

Distance From Community (mile):

Latitude: 56.5500°, Longitude: -115.2667°

Box 50

T0G 1X0

Runway Data

Contact Info

Mr. Rob Guild

Area Foreman

Red Earth Creek

Municipal District #17

Primary: "12-30", 3540x75 (Asphalt)

2002; Good condition;

Owner and Operator Info

Owner: MD of Opportunity No. #17 Operator: MD of Opportunity No. #17 Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

Med-evac, local and commercial use

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1988; Poor condition; replacement 2003 (\$38000)

Secondary: ---

Third: ---

Fourth: ---

Apron Data

Secondary: ---

Primary: "1"; (Asphalt)

constructed 1988; last rehabilitation 2001; poor condition; replacement 2003

(780) 649 3427(780), Fax: 649 3440/2562

constructed 1988; last rehabilitation

(\$207000)

Secondary: ---

**Landside Facility Data** 

Entrance Road: type paved; constructed 1988; last

rehabilitation 1989; poor condition;

replacement 2003 (\$26000)

Parking Lot: type paved; constructed 1988; poor

condition; replacement 2003 (\$21000)

Fencing: type 4' barbed wire;

**Building Data** 

ATB: ---

Disability Access: ---

Field Electrical Centre: constructed 1988; good

condition:

## Red Earth Creek Airport (EH5)

Lighting Data		Water / Sewer Data
	nreshold and Runway End) ructed 1988; good condition; ement 2012 (\$203000)	Water Supply:
Approach Slope Indicator 1:		Sewage:
Approach Slope Indicator 2:		Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: "K"; fr	eq 123.2	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 2 windsocks; constructed 2012 (\$5000	1988; good condition; replacement	
Surface: good condition;	Subsurfa	ace:
Peak Period Info	Spring Summer Fall W	inter Average
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		





### Red Earth Creek Airport (EH5)

Onsite Business Data						
FBO: No				AC Ma	aintenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintenar	nce Bu	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	dget	1997	1990	1999	2000	
Economic Activity Inforn	nation	-				
Airport Activity Info		1997	1998	1999	2000	2001
Airport Activity Info  Annual Aircraft Movements		1997	1998	1999	2000	2001
	:	1997	1998	1999	2000	2001
Annual Aircraft Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	:	1997		1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info   Airport Revenue Data  Total Annual Revenue:	: s:					
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	: s:					

### Red Earth Creek Airport (EH5)

Year	Project Name	Funding Source	Description
1989		Provincial	Runway paving
1989		Provincial	Airfield lighting
1988		Provincial	Grading, base and paving
1988		Provincial	Installation of airfield lighting
1987		Provincial	Clearing work
1986		Provincial	Initial clearing for upgraded runway

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 RIMBEY AIRPORT (CFC7)





Rimbey Airport Aerial Photographs taken October 10, 2002

#### **Airport Contact Information:**

Mr. William Kostiw
Chief Administrative Officer
Town of Rimbey
Rimbey, AB T0C 2J0
Tel: (403) 843 2113

Fax: (403) 843 2113

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
	ce From Community (mile): 2 e: 52.6833°, Longitude: -114.2333°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Mr. William Kostiw Chief Administrative Officer Town of Rimbey Box 350 Rimbey
Airport Organization Ownership Structure:	T0C 2J0 (403) 843 2113(403) , Fax: 843 6599
Organizational Structure:	Runway Data Primary: "14-32", 2950x75 (Turf)
Role of Airport:	Secondary:
Taxiway Data Primary:	┌Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
Landside Facility Data	ATB:
Entrance Road:	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

Lighting Data			─Water / Se	wer Data
Primary Edgelighting: TE (Threshold and Runway End)			Water Suppl	ly:
Approach Slope Indicator 1:			Sewage:	
Approach Slope Indicator 2:			Vicinity Pi Caveat, ar	rotection, nd Right of Way
ARCAL: Type: "K"; fr Windsock: 1 windsocks;	•		Vicinity Pro Caveat: N Right of Wa	
Drainage Data				
Surface:		Subsurfa	ce:	
⊢Peak Period Info ───				7
	Spring Summer	Fall Wir	nter Average	
Peak Apron Aircraft Parked:				
Design Aircraft for Airport:				





Onsite Business Data						
FBO: No				AC Ma	aintenance:	No
Industrial Buildings: No				Crop S	Spraying Ad	ctivities:
Hangars: No				Chemi	cals Stored	on site:
Operation and Maintena	nce Bu	udget — 1997	1998	1999	2000	2001
Total Annual Maintenance Bu	dget	1997	1990	1999	2000	2001
Economic Activity Inforn	nation	-				
Airport Activity Info		1997	1998	1999	2000	2001
Airport Activity Info  Annual Aircraft Movements	:	1997	1998	1999	2000	2001
		1997	1998	1999	2000	2001
Annual Aircraft Movements		1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements		1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements		1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements		1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements		1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements Commercial Airline Info		1997		1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data  Total Annual Revenue:	s:   1997					
Annual Aircraft Movements Annual Passenger Movements Commercial Airline Info	s:   1997					

Year	Project Name	Funding Source	Description
1987		Provincial	Complete airfield lighting installation
1986		Provincial	Complete grading, initiate lighting installati
1986		Provincial	Air Terminal Grant
1985		Provincial	Grading truf runway, land purchases (\$101,265 for land purchase)
1984		Provincial	Preliminary survey, soils investigation

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 ROCKY MOUNTAIN HOUSE AIRPORT (CYRM)





Rocky Mountain House Airport Aerial Photographs taken October 10, 2002

#### **Airport Contact Information:**

Mr. Ken Fowler Airport Manager Rocky Mountain House & District Airport Rocky Mountain House, AB T4T 2A2

Tel: (403) 845 4742 Fax: (403) 845 3230

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

#### Rocky Mountain House Airport (YRM)

**General Info** 

Rocky Mountain House (YRM) Distance From Community (mile): 3

Municipal Latitude: 52.3667°, Longitude: -115.0667°

Owner and Operator Info

Owner: Rocky Mountain House

Operator: ---

Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Rocky Mountain House/MD. Of Clearwater

Organizational Structure:

Commission -Town/M.D/Forestry/Independent.

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; 1000x40 (Asphalt)

constructed 1978; last rehabilitation 1998; Good condition; replacement 2011 (\$57000)

Secondary: "B(6A)"; (Asphalt)

Good condition; replacement 2011

(\$33000)

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 2-lane; type paved; last

rehabilitation 1999; good condition;

replacement 2008 (\$48000)

Parking Lot: size 100x150; type asphalt; fair

condition; replacement 1998

Fencing: size 4ft; type page wire;

Contact Info

Mr. Ken Fowler Airport Manager

Rocky Mountain House & District Airport

Box 1509

Rocky Mountain House

**T4T 2A2** 

(403) 845 4742(403), Fax: 845 3230

**Runway Data** 

Primary: "13-31", 5500x100 (Asphalt)

constructed 1978; last rehabilitation 1998; Good condition; replacement 2011

(\$971000)

Secondary: ---

**Apron Data** 

Primary: "1"; 400x150 (Asphalt)

constructed 1978; last rehabilitation 1998; good condition; replacement 2011

(\$258000)

Secondary: "11Forestry"; (Asphalt)

last rehabilitation 1998; good condition; replacement 2011

**Building Data** 

ATB: size 50x75; type AB Gov't Bldg.; constructed

1978; fair condition;

Disability Access: ---

Field Electrical Centre: ---

Airport Summary Report

#### Rocky Mountain House Airport (YRM)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1978; last rehabilitation 199

good condition;

Approach Slope Indicator 1: V2 (2-BAR VASIS - Aircraft up to 2

constructed 1985; fair condition; replacement 2005 (\$60000)

Approach Slope Indicator 2: V2 (2-BAR VASIS - Aircraft up to 2

constructed 1985; good condition;

replacement 2005 (\$60000)

ARCAL: Type: "K"; freq 122.8

Windsock: 3 windsocks;

constructed 1978; last rehabilitation 1998; good

condition; replacement 1998

Water / Sewer Data

Water Supply: Well; constructed 1980; fair

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

Dra	inag	ae D	)ata

Surface: Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

---



Airport Summary Report



#### Rocky Mountain House Airport (YRM)

**Onsite Business Data** 

FBO: No AC Maintenance: Yes, 14; Aerocheck, Northern Air

Support, Airbourne, Avipro

Industrial Buildings: No Crop Spraying Activities:

Hangars: Yes, 14; Chemicals Stored on site:

Operation and Maintenance Budget

1997 1998 2000 2001 1999

Total Annual Maintenance Budget

**Economic Activity Information** 

Road Distance to Nearest Airport Sched. Pax Service: 220

Road Distance to Nearest Airport MedEvac Service: 220

Road Distance to Nearest Airport Cargo Service: 220

Road Distance to Nearest Airport Fire Suppression Service: 85

How is the Airport Vital to the Region: Tanker Base; Extensive Charter-Helicopter

and Fix-wing Aircraft

**Airport Activity Info** 

1997 1998 1999 2000 2001

**Annual Aircraft Movements:** 

Annual Passenger Movements:

**Commercial Airline Info** 

Rocky West (Navajo, Charter)

Airbourne (Helicopters, )

Northern Air Support (Helicopters, )

West Coast (Helicopters, )

**Airport Revenue Data** 

1997 1998 1999 2000 2001

Total Annual Revenue:

**Airport Expenditure Data** 

1997 2000 1998 1999 2001

**Total Annual Expenditure** 

### Rocky Mountain House Airport (YRM)

Year	Project Name	Funding Source	Description
1995		Provincial	Fog seal asphalt surfaces
1993		Provincial	Fog asphalt surfaces
1992		Provincial	Install displaced threshold lighting
1991		Provincial	Purchase of additional airfield lighting
1987		Provincial	Purchase and installation of NDB
1987		Provincial	Purchase and installation of DME
1985		Provincial	Installation of VASIS
1978		Provincial	Grading, base, paving, airfield lighting, Air Terminal Building
1977		Provincial	Preliminary survey and grading

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 ROCKYFORD AIRPORT (CFC6)





Rockyford Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Mr. Lambert Katterhagen President Rockyford, AB T0J 2R0 Tel: (403) 533 2232 Fax: (403) N/A

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

> Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc.

204-17707 105 Avenue Edmonton, AB T5S 1T1 Tel: 780-444-1133

Fax: 780-484-0877

## Rockyford Airport (FC6)

General Info			
Rockyford (FC6) Private	Distance From Community (mile): 1.5 Latitude: 51.2667°, Longitude: -113.1167°		
Owner and Operator Info Owner: Operator: Former Ownership: No Change Date of Change:	Contact Info  Mr. Lambert Katterhagen President Box 68 Rockyford T0J 2R0		
Airport Organization	(403) 533 2232(403) , Fax: N/A		
Ownership Structure: Private			
	Runway Data		
Organizational Structure:	Primary: "-", 2500x50 (Turf) constructed 1958; last rehabilitation 1995; Fair condition; replacement 2020		
Role of Airport:			
Farmer's strip	Secondary:		
Taxiway Data			
Primary:	- Annon Doto		
	Apron Data		
Secondary:	Primary:		
Third:	Secondary:		
Fourth:			
	Building Data		
	ATB:		
Landside Facility Data			
Entrance Road:			
	Disability Access:		
Parking Lot:			
	Field Electrical Centre:		
Fencing:			

## Rockyford Airport (FC6)

Lighting Data	┌Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	7.5, 1.5.5.5,
ARCAL: Type: Windsock:	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
┌Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





### Rockyford Airport (FC6)

Onsite Business Data					
FBO: No			AC Mair	ntenance:	No
Industrial Buildings: No			Crop Sp	raying Acti	vities:
Hangars: No			Chemica	ls Stored o	n site:
Operation and Maintenanc	e Budget				
Total Annual Maintenance Budg	1997 et	1998	1999	2000	2001
Economic Activity Informa	tion				
Airport Activity Info	1007	1000	1000	2000	2001
Annual Aircraft Movements:	1997	1998	1999	2000	2001
Annual Passenger Movements:					
Commercial Airline Info	<u>'</u>				
Airport Revenue Data	97 1998	3 199	90 °	2000	2001
Total Annual Revenue:		. 15			2001
Airport Expenditure Data					
Total Annual Expenditure	1997 19	998 :	1999	2000	2001

## Rockyford Airport (FC6)

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 SHERMAN MEADOWS AIRPORT (CFK7)





Sherman Meadows Airport Aerial Photographs taken August 24, 2002

#### **Airport Contact Information:**

Alberta Sustainable Resource Development - Land and Forest Division Grande Prairie, AB T8V 3J2

Tel: (780) 538 8080 Fax: (780) 538 1941

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info				
	nerman Meadows (FK7) Distance From Community (mile): Latitude: 54.2833°, Longitude: -119.8333°			
Owner and Operator Info	Contact Info			
Owner:	Alberta Sustainable Resource			
Operator:	Development - Land and Forest Division			
Former Ownership: Date of Change:	10811 - 84 Ave. Grande Prairie			
Date of Change.	T8V 3J2			
Airport Organization	(780) 538 8080(780) , Fax: 538 1941			
Ownership Structure:				
	Runway Data			
Organizational Structure:	Primary: "18-36", 3000x100 (Turf)			
	11mary: 10 50 / 5000x100 (14m)			
Role of Airport:				
	Secondary:			
Taxiway Data				
Primary:	Apron Data			
Secondary:	Primary:			
Secondary.				
Third:	Secondary:			
Fourth:				
	├Building Data			
	□ ATB:			
Landside Facility Data				
Entrance Road:				
	Disability Access:			
Parking Late				
Parking Lot:				
	Field Electrical Centre:			
Fencing:				

Lighting Data	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No
ARCAL: Type:	Caveat: No
Windsock: 0 windsocks;	Right of Way: No
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Consite Business Data —						
FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintena		_	1000	1000	2000	2001
Total Annual Maintenance Bu		1997	1998	3 1999	2000	2001
Economic Activity Inform	nation					
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movements						
Annual Passenger Movement	s:					
Commercial Airline Info						
Airport Revenue Data						
Total Annual Revenue:	1997	1998		1999	2000	2001
Airport Expenditure Data						
Total Annual Expenditure	1997	199	8	1999	2000	2001
·						

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 SLAVE LAKE AIRPORT (CYZH)





Slave Lake Airport Aerial Photographs taken August 15, 2002

#### **Airport Contact Information:**

Mr. Ken Skahl
Airport Manager
Slave Lake Airport Services Commission
Slave Lake, AB T0G 2A0
Tel: (780) 849 3089

Fax: (780) 849 3089

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Slave Lake Airport (YZH)

General Info

Distance From Community (mile): 0 Slave Lake (YZH) Latitude: 55,3000°, Longitude: -114,7833° Municipal

Owner and Operator Info

Owner: Slave Lake Airport Service Commission Operator: Slave Lake Airport Service Commission

Former Ownership: Province of Alberta

Date of Change: April 1, 1995

**Airport Organization** 

Ownership Structure:

Organizational Structure:

Role of Airport:

**Taxiway Data** 

Primary: "B"; 3940x60 (Asphalt)

constructed 2000; Good condition;

replacement 2015

Secondary: "A"; 280x50 (Asphalt)

constructed 1976; last rehabilitation 1983; Fair condition; replacement 2020

Third: "C"; 280x60 (Asphalt)

constructed 2000; Good condition;

replacement 2020

Fourth: "D"; 1140x45 (Asphalt)

constructed 1983; last rehabilitation 2002;

Fair condition; replacement 2017

**Landside Facility Data** 

Entrance Road: size 8.4mx400m; type Asphalt;

constructed 1982; last rehabilitation 2002; good condition; replacement

Parking Lot: size 1500 sqm; type Asphalt;

constructed 1973; last rehabilitation

2002; good condition;

Fencing: size 5'; type page wire/chain link;

Contact Info

Mr. Ken Skahl Airport Manager

Slave Lake Airport Services Commission

Box 1030 Slave Lake T0G 2A0

(780) 849 3089(780), Fax: 849 2633

**Runway Data** 

Primary: "10-28", 5558x100 (Asphalt)

constructed 1972; last rehabilitation 2001; Good condition; replacement 2013

(\$1000000)

Secondary: ---

**Apron Data** 

Primary: "General Aviation"; 470x190 (Asphalt)

constructed 1983; last rehabilitation

2001; good condition;

Secondary: "Private Forestry";

**Building Data** 

ATB: type Wood Frame; constructed 1973; poor

condition:

Disability Access: ---

Field Electrical Centre: constructed 2002;

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Slave Lake Airport (YZH)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

last rehabilitation 1986; fair condition;

Approach Slope Indicator 1: V1 (2-BAR VASIS - Aircraft up to 1 constructed 1983; last rehabilitatic

1999; fair condition;

Approach Slope Indicator 2: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1983; last rehabilitatic

2000;

ARCAL: Type: "K"; freq 123.2

Windsock: 2 windsocks;

constructed 1983; fair condition;

Water / Sewer Data

Water Supply: Municipal Service;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: poor condition;

Subsurface: ---

Peak Period Info

Winter Spring Summer Fall Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Slave Lake Airport (YZH)

Onsite Dusiness Data				_	
FBO: Yes, ; Slave Air Ltd.			AC Mai	ntenance:	No
Industrial Buildings: Yes, 1; Powell quipment Ltd. Crop Spraying Activities:				tivities:	
Hangars: Yes, 1; Slave Air Ltd Energy, Remote Heli Ebenani, L dean, De Olsen Equipment, Sl Helicopters, Dr. Iain	icopters, R. Ita Helicopter ave Lake	S,	Chemica	als Stored	on site:
Operation and Maintenan	ce Budget				
•	1997	1998	1999	2000	2001
Total Annual Maintenance Bud	get				_
Economic Activity Informa	ation				
Road Distance to Nearest Airport Road Distance to Nearest Airport Major Economic Industries in Form How is the Airport Vital to the care. Forest fire suppression by transportation link for oil and of the care.	ort Fire Supp Region: Fore Region: Pro ase which pro	ression Ser estry/Oil & vides acce otect forest	vice: 25 Gas/Tour ss to adva industrie	ism anced med	
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data					2224
Total Annual Revenue:	997 199	98 19	999	2000	2001
Airport Expenditure Data		.998	1999	2000	2001
Total Annual Expenditure	1001	.,,,,,	1,,,,	2000	2001

#### Slave Lake Airport (YZH)

#### **Historic Capital Expenditures** Project Name **Funding Source** Description Year 2002 Provincial Pavement o/lay - runway/taxiway/apron 2001 Provincial Major crack repairs (runway) Plow truck, Sewer line, 2001 Airport Commission see reprt for further information fencing Hold signs A&C 2000 Major crack repair CAP Grant see reprt for further information **OLS Obstruction** Removal of trees and other obstruction 1999 Airport Commission removal 1/2 ton truck Airport Commission Purchase 98 GMC 4x4 + Plow 1998 1997 Snow blower Airport Commission see reprt for further information 1994 Provincial Runway soils investigation Air tanker loading pad improvements 1990 Provincial 1988 Provincial Taxiway repairs 1987 Provincial Install new airfield lighting 1987 Provincial Purchase and installation of DME 1984 Provincial Runway overlay and installation of VASIS 1978 Expansion of hangar development area Provincial 1973 Contribution towards construction Federal Taxiway Construction Alberta Forest Service see reprt for further information Taxiway lights/terminal Airport Commission see reprt for further information bldg.Access Road

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 SPIRIT RIVER AIRPORT (CFS5)





Spirit River Airport Aerial Photographs taken July 23, 2002

#### **Airport Contact Information:**

Ms. Linda Wennerstrom Town Manager Town of Spirit River Spirit River, AB T0H 3G0 Tel: (780) 864 3998

Fax: (780) 864 3433

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Spirit River Airport (FS5)

General Info

Spirit River (FS5)

Municipal

Distance From Community (mile): 0

Latitude: 55.7833°, Longitude: -118.8333°

Owner and Operator Info

Owner: Town of Spirit River Operator: Town of Spirit River Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

last rehabilitation 2001; Good condition;

replacement 2016

Secondary: ---

Third: ---

Fourth: ---

Landside Facility Data

Entrance Road: size 33ft; type gravel; good

condition;

Parking Lot: type gravel; good condition;

Fencing: type 4' barbed wire;

Contact Info

Ms. Linda Wennerstrom

Town Manager Town of Spirit River

Box 130 Spirit River T0H 3G0

(780) 864 3998(780), Fax: 864 3433

**Runway Data** 

Primary: "06-24", 3000x75 (Asphalt)

last rehabilitation 2001; Good condition;

replacement 2016

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

last rehabilitation 2001; good condition;

replacement 2016

Secondary: ---

Building Data

ATB: size 12x40ft; type ATCO trailer; fair

condition:

Disability Access: type sidewalk;

Field Electrical Centre: size 8x8; type metal; poor

condition;

## Spirit River Airport (FS5)

Lighting Data	⊢Water / Sewer Data			
Primary Edgelighting: TE (The fair co	nreshold and Runway End) which is the standard of the standard Runway End) Water Supply: Well; which is the standard Runway End)			
Approach Slope Indicator 1:	Sewage:			
Approach Slope Indicator 2:	Caveat, and Right of Way			
ARCAL: Type: "K"; fr Windsock: 1 windsocks; fair condition	ragne of way. The			
Drainage Data				
Surface: fair condition;  Subsurface:				
Peak Period Info	Spring Summer Fall Winter Average			
Peak Apron Aircraft Parked:				
Design Aircraft for Airport:				





### Spirit River Airport (FS5)

Olisite Busiliess Data	
FBO: No	AC Maintenance: No
Industrial Buildings: No	Crop Spraying Activities: Temporary; Privately operated
Hangars: Yes, 2; Al Ross; Gary Kurys	Chemicals Stored on site: no
Operation and Maintenance Budget  1997 19	1998 1999 2000 2001
Total Annual Maintenance Budget	
Economic Activity Information	
Major Economic Industries in Region: Farming/C	'Oil & Gas
Airport Activity Info	998 1999 2000 2001
Annual Aircraft Movements:	996 1999 2000 2001
Annual Passenger Movements:	
Commercial Airline Info	
Airport Revenue Data	
1997 1998 Total Annual Revenue:	1999 2000 2001
Airport Expenditure Data	
1997 1998	1999 2000 2001
Total Annual Expenditure	

## Spirit River Airport (FS5)

Year	Project Name	Funding Source	Description
2002		Provincial	Proposed Pavement Overlay Project
1992		Provincial	Overlay pavement surface
1991		Provincial	Runway drainage improvements
1987		Provincial	Upgrade airfield lighting
1985		Provincial	Air Terminal Building Grant
1985		Provincial	Purchase and installation of NDB
1980		Provincial	Completion of paving and lighting
1979		Provincial	Purchase of additional 35 acres of land
1979		Provincial	Upgrade to a 3,000' X 75' paved and lighter runway and bury powerline on east approximately 10 to 10 t
1971		Federal	Upgrading of town land to provide a basic turf and gravel airstrip

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

# **AIRPORT INFORMATION REPORT - 2002 ST. FRANCIS/P.K. FARM AIRPORT (CFE6)**





St. Francis/P.K. Farm Airport Aerial Photographs taken October 8, 2002

#### **Airport Contact Information:**

Mr. Dennis Byrne Warburg, AB T0C 2T0 Tel: (780) 848 2264 Fax: (780) 848 2213

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
St. Francis/P.K. Farm (FE6)	Distance From Community (mile): 3.8
Private	Latitude: 53.2833°, Longitude: -114.4500°
Owner and Operator Info Owner: Dennis Byrne Operator: Denis Byrne Former Ownership: No Change Date of Change:	Contact Info  Mr. Dennis Byrne  RR1  Warburg  T0C 2T0  (780) 848 2264(780) , Fax: 848 2213
Airport Organization	
Ownership Structure:	
Owner/Operator	
Organizational Structure:	Primary: "18-36", 2800x100 (Turf) Good condition;
Role of Airport:	
Private	Secondary:
⊤Taxiway Data	
Primary: "hanger"; 300x30 (Asphalt)	
Fair condition;	Apron Data
	Primary:
Secondary:	
Third:	Secondary:
Time.	Jessendary.
Fourth:	
	Building Data
	ATB:
┌Landside Facility Data	
Entrance Road:	
2.13.3.166 (1604)	Disability Access:
	Disability Access
Parking Lot:	
	Field Electrical Centre:
Fencing:	

Lighting Data	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





─Onsite Business Data   ──────────────────────────────────				
FBO: No		ļ	AC Maintenand	ce: No
Industrial Buildings: No		(	Crop Spraying	Activities:
Hangars: No		C	hemicals Store	ed on site:
Operation and Maintenance	e Budget			
Total Annual Maintenance Budg	1997 et	1998	1999 200	0 2001
Economic Activity Information	tion			
Airport Activity Info	1997	1998 1	1999 2000	2001
Annual Aircraft Movements:	1997	1990	1999 2000	2001
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	97 1998	3 1999	2000	2001
Total Annual Revenue:	,, 1990	, 1999	2000	2001
Airport Expenditure Data	.007 10	100	00 2000	2001
Total Annual Expenditure	.997 19	98 19	99 2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 ST. PAUL AIRPORT (CEW3)





St. Paul Airport Aerial Photographs taken August 16, 2002

#### **Airport Contact Information:**

Mr. Dave Lashuk Chairman, St. Paul Municipal Airport Commission Town of St. Paul St. Paul, AB T0A 3A0 Tel: (780) 645 4481

Tel: (780) 645 4481 Fax: (780) 645 5076

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

> Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### St. Paul Airport (EW3)

**General Info** 

St. Paul (EW3)

Distance From Community (mile): 4

Municipal

Latitude: 54.0000°, Longitude: -111.3833°

Owner and Operator Info

Owner: St Paul Municipal

Operator: ---

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

St. Paul Airport Commission

Organizational Structure:

---

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1978; last rehabilitation 2000;

Good condition; replacement 2020

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; constructed 1978; fair

condition;

Parking Lot: type gravel; constructed 1978; fair

condition;

Fencing: type 4' barbed wire;

Contact Info

Mr. Dave Lashuk

Chairman, St. Paul Municipal Airport

Commission Town of St. Paul Box 1480 St. Paul

T0A 3A0

(780) 645 4481(780), Fax: 645 5076

**Runway Data** 

Primary: "08-26", 3500x100 (Asphalt)

constructed 1978; last rehabilitation 2000; Good condition; replacement 2020

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1978; last rehabilitation 2000; good condition; replacement 2020

Secondary: ---

**Building Data** 

ATB: size 40x20; constructed 1991; good

condition;

Disability Access: ---

Field Electrical Centre: constructed 1978; poor

condition; replacement 2006

(\$150000)

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### St. Paul Airport (EW3)

-1	Li	al	٦t	in	a	Da	ta	-

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1978; fair condition; replacement 2006 (\$187000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 122.8

Windsock: 1 windsocks;

constructed 1978; fair condition; replacement 2

#### Water / Sewer Data -

Water Supply: Well; constructed 1994; fair

condition;

Sewage: ---

#### Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: fair condition; Subsurface: ---

#### Peak Period Info

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

Spring Summer Fall Winter Average

---





### St. Paul Airport (EW3)

□Onsite Business Data ──					
FBO: No			AC Maintena	ance: No	
Industrial Buildings: No			Crop Sprayii	ng Activities:	
Hangars: No		•	Chemicals St	tored on site:	
Operation and Maintenanc	e Budget	1998	1999 2	000 2001	1
Total Annual Maintenance Budg		1990	1999 2	000 2001	
Economic Activity Informa	tion				
Airport Activity Info	1997	1998	1999 20	000 2001	
Annual Aircraft Movements:				<u></u>	
Annual Passenger Movements:					
Commercial Airline Info					]
Airport Revenue Data	97 199	8 1999	9 2000	) 2001	
Total Annual Revenue:	,, 199	<u> </u>	2000	, 2001	
Airport Expenditure Data	1997 1	998 19	999 20	000 2001	
Total Annual Expenditure	<u> </u>	<del>-</del> ·			_

### St. Paul Airport (EW3)

Year	Project Name	Funding Source	Description
2000		Provincial	Pav't overlay
1996		Provincial	Slurry seal
1995		Provincial	Fog seal asphalt surfaces
1991		Provincial	Air Terminal Building Grant
1979		Provincial	Ditching, drainage and clean-up
1978		Provincial	Total reconstruction of airport
1973		Federal	Initial development

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 STEEN RIVER AIRPORT (CFB7)





Steen River Airport Aerial Photographs taken August 21, 2002

#### **Airport Contact Information:**

Mr. Jamie Lee
Fire Manager
Alberta Sustainable Resource Development - Land and Forest Division
High Level, AB T0H 1Z0
Tel: (780) 926-5400

Fax: (780) 926-4224

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info	
	stance From Community (mile): 0
Ld	atitude: 59.6333°, Longitude: -117.1667°
Owner and Operator Info	Contact Info
Owner:	Mr. Jamie Lee
Operator: Former Ownership:	Fire Manager Alberta Sustainable Resource
Date of Change:	Development - Land and Forest Division
Date of Gridinger	Bag 900
Airport Organization	High Level
Ownership Structure:	T0H 1Z0 (780) 926-5400(780) , Fax: 926-4224
	(700) 920-3400(700), 1 dx. 920-4224
	Runway Data
Organizational Structure:	Primary: "17-35", 5000x100 (Turf)
	Fair condition; replacement 2010
	(\$12000)
Role of Airport:	
	Secondary:
Taxiway Data	
Primary:	
,	Apron Data
	Primary: "Forestry"; (Asphalt)
Secondary:	poor condition; replacement 2004
	Constant
Third:	Secondary:
Fourth:	
Tourin.	
	Building Data
- Landaida Facility Data	ATB:
Landside Facility Data	
Entrance Road:	
	Disability Access:
5.11	
Parking Lot:	
Fencing:	Field Liectrical Certife
. Changi	

Lighting Data	□ Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	,
ARCAL: Type: Windsock: 1 windsocks; poor condition	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
□Drainage Data	
Surface: poor condition;	Subsurface:
Peak Period Info	
 	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data					
FBO: No			AC Mair	ntenance:	No
Industrial Buildings: No			Crop Sp	oraying Act	tivities:
Hangars: No			Chemica	als Stored	on site:
Operation and Maintenance E	_	1000	1000	2000	2004
Total Annual Maintenance Budget	1997	1998	1999	2000	2001
Economic Activity Informatio	n —				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	1009	100	10	2000	2001
Total Annual Revenue:	1998	199	בי	2000	2001
Airport Expenditure Data	7 199	98 1	999	2000	2001
Total Annual Expenditure	, 1).	,,, 1		2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 STETTLER AIRPORT (CEJ3)





Stettler Airport Aerial Photographs taken October 9, 2002

#### **Airport Contact Information:**

Mr. Robert Stoutenberg Town Manager Town of Stettler Stettler, AB TOC 2L0 Tel: (403) 742 8305

Fax: (403) 742 8305

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Stettler Airport (EJ3)

#### General Info

Stettler (EJ3) Distance From Community (mile): 1.5
Municipal Latitude: 52.1836°, Longitude: -112.4514°

#### Owner and Operator Info

Owner: Town of Stettler Operator: Stettler Flying Club Former Ownership: No Change

Date of Change: ---

#### **Airport Organization**

#### Ownership Structure:

Town of Stettler - Registered Owner of a portion of South1/2 35-38-20W4

#### Organizational Structure:

Town of Stetter/Flying Club

#### Role of Airport:

To provide a safe, efficient and low cost airport transportation service facility for the Town and County of Stettler.

#### **Taxiway Data**

Primary: ---

Secondary: ---

Third: ---

Fourth: ---

#### **Landside Facility Data**

Entrance Road: type oil gravel road; constructed

1976; last rehabilitation 2001; fair

condition;

Parking Lot: type gravel; constructed 1976; fair

condition;

Fencing: size 4'; type barb wire;

#### Contact Info

Mr. Robert Stoutenberg

Town Manager Town of Stettler

Box 280 Stettler TOC 2L0

(403) 742 8305(403) , Fax: 742 1404

#### **Runway Data**

Primary: "07-25", 3000x75 (Asphalt)

constructed 1976; last rehabilitation 1998; Good condition; replacement 2006

(\$397000)

Secondary: ---

#### **Apron Data**

Primary: ---

Secondary: ---

#### **Building Data**

ATB: size 896; constructed 1977; last rehabilitation 1986; good condition; replacement 2012

(\$100000)

Disability Access: type sidewalk; constructed 1977;

Field Electrical Centre: size 6x6; type metal; poor

condition; replacement 2005

(\$150000)

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Stettler Airport (EJ3)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1976; last rehabilitation 198

fair condition; replacement 2005 (\$1710)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123

Windsock: 1 windsocks;

constructed 1976; last rehabilitation 2002; good

condition;

Water / Sewer Data

Water Supply: Well; constructed 1978; good

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: --- Subsurface: good condition;

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Stettler Airport (EJ3)

**Consite Business Data** 

FBO: No		A	C Maintenance:	: No
Industrial Buildings: Yes, 1; Airb Aviation	orne - Oilfield	d Cı	op Spraying A	ctivities: Seasona
Hangars: Yes, 16; 15 Private an	d 1 Industria	l Ch	emicals Stored	on site: No
Operation and Maintenance	e Budget - 1997	1998 1	999 2000	2001
Total Annual Maintenance Budge		1990 1	2000	2001
Economic Activity Informat	tion			
Major Economic Industries in Re Mining/Agriculture/Business/Studhow is the Airport Vital to the Retransportation service for busine radius within the region.	dents egion: Stett		Country Airpo lic for a 50 na	
Airport Activity Info				
Appured Airgraft Mayamanta	1997	1998 19	999 2000	2001
Annual Aircraft Movements:	1997	1998 19	999 2000	2001
	1997	1998 19	999 2000	2001
Annual Aircraft Movements:	1997	1998 19	999 2000	2001
Annual Aircraft Movements: Annual Passenger Movements:	1997	1998 19	999 2000	2001
Annual Aircraft Movements: Annual Passenger Movements:	1997	1998 19	999 2000	2001
Annual Aircraft Movements: Annual Passenger Movements:	1997	1998 19	999 2000	2001
Annual Aircraft Movements:  Annual Passenger Movements:  Commercial Airline Info  Airport Revenue Data				
Annual Aircraft Movements:  Annual Passenger Movements:  Commercial Airline Info			2000	2001
Annual Aircraft Movements:  Annual Passenger Movements:  Commercial Airline Info  Airport Revenue Data  199  Total Annual Revenue:  Airport Expenditure Data	7 1998		2000	

### Stettler Airport (EJ3)

Year	Project Name	Funding Source	Description
2000		Provincial	1
1999		Provincial	Major crack repair and micro-surfacing
1992		Provincial	Repair runway surface
1987		Provincial	Purchase and installation of NDB and rad equipment building
1987		Provincial	Purchase and installation of DME
1986		Provincial	Air Terminal Building Grant
1986		Provincial	Slurry seal runway
1984		Provincial	Airfield light repairs
1982		Provincial	Land and survey costs for 70 acres of airp
1978		Provincial	Extended runway, reconstruct and pave runway, taxiway and pariking apron. Insta
1977		Federal	Toward construction
1968		Federal	Initial construction of 2,100' X 75' runway

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 SUNDRE AIRPORT (CFN7)





Sundre Airport Aerial Photographs taken October 24, 2002

#### **Airport Contact Information:**

Mr. Tony Martens Assistant Commissioner Mountain View County Didsbury, AB T0M 0W0 Tel: (403) 335 3311

Fax: (403) 335 3311

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Sundre Airport (FN7)

General Info

Sundre (FN7) Distance From Community (mile): 2
Municipal Latitude: 51.7833°, Longitude: -114.6833°

Owner and Operator Info

Owner: Mountain View County Operator: Mountain View Countain

Former Ownership: change of Ownership 2002

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Mountain View County is the owner and concentrates on longterm planning and airport improvements and manintenance

Organizational Structure:

Airport Commission

Role of Airport:

The airport is used for industrial and recreational flying. The County sees it as playing a vital role in economic development.

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1985; last rehabilitation 2002;

Good condition;

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; fair condition;

Parking Lot: type chipseal/asphalt; constructed

1985; last rehabilitation 2002; good condition; replacement 2008 (\$17000)

Fencing: type brb wire;

Contact Info

Mr. Tony Martens Assistant Commissioner Mountain View County

Bag 100 Didsbury TOM 0W0

(403) 335 3311(403), Fax: 335 9207

**Runway Data** 

Primary: "14-32", 3773x75 (Asphalt)

constructed 1985; last rehabilitation 2002; Fair condition; replacement 2006

(\$393000)

Secondary: "05-23", 1968x75 (Gravel)

constructed 1985; Fair condition; replacement 2007 (\$21000)

**Apron Data** 

Primary: "1"; 40x80 (Asphalt)

constructed 1985; last rehabilitation

2002; good condition;

Secondary: ---

**Building Data** 

ATB: type wood frame; constructed 1985; good

condition; replacement 2011 (\$100000)

Disability Access: constructed 1985; good condition;

Field Electrical Centre: constructed 1985; fair

condition; replacement 2008

(\$150000)

Peak Apron Aircraft Parked:

undre Airport (FIN7)	
Lighting Data	┌Water / Sewer Data
Primary Edgelighting: TE (Threshold and Runway End) constructed 1986; poor condition; replacement 2008 (\$154000)	Water Supply: Well; constructed 1985; good condition;
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	┌Vicinity Protection,
, pp. 3337 376p 3.7433000	Caveat, and Right of Way
ARCAL: Type: "K"; freq 123.2 Windsock: 1 windsocks;	Vicinity Protection: Yes Caveat: No Right of Way: No
constructed 1986; fair condition; replacer	nent 2
Drainage Data	
Surface:	Subsurface:

<b>D. I.D. I. I.</b>					
Peak Period Info	Spring	Summer	Fall	Winter	Average

Design Aircraft for Airport:





### Sundre Airport (FN7)

Onsite Business Data							
FBO: No			AC Main	tenance:	No		
Industrial Buildings: No			Crop Spr	raying Act	ivities: 0		
Hangars: Yes, ; Privately owned			Chemical	ls Stored o	on site: 0		
Operation and Maintenance	Budget = 1997	1000	1000	2000	2001		
Total Annual Maintenance Budge		1998	1999	2000	2001		
Economic Activity Informati	ion						
Road Distance to Nearest Airport Sched. Pax Service: 85 Road Distance to Nearest Airport MedEvac Service: 85 Road Distance to Nearest Airport Cargo Service: 85 Road Distance to Nearest Airport AME Service: 85 Road Distance to Nearest Airport Fire Suppression Service: 60 Major Economic Industries in Region: Students/Oil & Gas/Logging/Recreation How is the Airport Vital to the Region: We see the airport as part of the County's transportation system as well as our economic development plans  Airport Activity Info  1997 1998 1999 2000 2001  Annual Aircraft Movements:							
Annual Passenger Movements:							
Commercial Airline Info							
Airport Revenue Data							
Total Annual Revenue:	7 1998	1999	9 2	2000	2001		
Airport Expenditure Data	997 19	ΩQ 1 <i>t</i>	999	2000	2001		
Total Annual Expenditure	19	טכ 1:	<b>シ</b> クフ	2000	2001		

### Sundre Airport (FN7)

Year	Project Name	Funding Source	Description
1994		Provincial	Paving of runway safety areas.
1990		Provincial	Gravel for runway improvements
1988		Provincial	Purchase and installation of NDB and Rac Equipment Building
1986		Provincial	Air Terminal Building Grant
1986		Provincial	Complete paving, install lighting
1985		Provincial	Grading, base & paving with airport lighting

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 SUNDRE/GOODWIN FARM AIRPORT (CFZ5)





Sundre/Goodwin Farm Airport Aerial Photographs taken October 24, 2002

#### **Airport Contact Information:**

Mr. Bruce Goodwin Sundre, AB T0M 1X0 Tel: (403) 638 3215 Fax: (403) 638 9046

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Sundre/Goodwin Farm (FZ5)	Distance From Community (mile): 4
Private	Latitude: 51.7333°, Longitude: -114.6667°
─Owner and Operator Info ────	Contact Info
Owner: Bruce & Mary Goodwin	Mr. Bruce Goodwin
Operator: Bruce & Mary Goodwin	RR2 Sundre
Former Ownership: No Change Date of Change:	TOM 1X0
2 4 4 5 1 4 1 5 1 4 1 5 1 5 1 5 1 5 1 5 1	(403) 638 3215(403) , Fax: 638 9046
─Airport Organization ────	
Ownership Structure:	
Family Farm	
	Runway Data
Organizational Structure:	Primary: "16-34", 2000x60 (Turf)
	constructed 1982; Good condition;
Role of Airport:	Cocondon
Private Farm Strip	Secondary:
Taxiway Data	
Primary:	┌Apron Data
	Primary:
Secondary:	1 Times y
,	
Third:	Secondary:
Fourth:	
1 out th	
	Building Data
└────────────────────────────────────	ATB:
Entrance Road:	
	Disability Access:
Parking Lot:	
	Field Electrical Centre:
Fencing:	

Lighting Data	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks; constructed 1982; last rehabilitation 2000; fa	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface: Subs	surface:
Peak Period Info Spring Summer Fall	Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Consite Business Data —						
FBO: No				AC Ma	intenance:	No
Industrial Buildings: No		Crop Spraying Activities:				
Hangars: Yes, 1; Bruce & Ma	Hangars: Yes, 1; Bruce & Mary Goodwin					on site:
Operation and Maintenar	nce Bu	_	1000	1000	2000	2001
Total Annual Maintenance Bu	dget	1997	1998	3 1999	2000	2001
Economic Activity Inform	nation					
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movements						
Annual Passenger Movements	s:					
Commercial Airline Info						
Airport Revenue Data	1997	1998		1999	2000	2001
Total Annual Revenue:		2330				
Airport Expenditure Data	1997	199	าย	1999	2000	2001
Total Annual Expenditure	1331	133	,,,	1,733	2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 SWAN HILLS AIRPORT (CEM5)





Swan Hills Airport Aerial Photographs taken August 22, 2002

#### **Airport Contact Information:**

Mr. John Eriksson Chief Administrative Officer Municipal District of Big Lakes High Prairie, AB T0G 1E0 Tel: (780) 523 5955

Fax: (780) 523 6566

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Swan Hills Airport (EM5)

**General Info** 

Swan Hills (EM5)

Distance From Community (mile): 2.5

Latitude: 54.6667°, Longitude: -115.4167°

Owner and Operator Info

Owner: MD of Big Lakes Operator: MD of Big Lakes

Former Ownership: Province of Alberta

Date of Change: August 7, 1995

**Airport Organization** 

Ownership Structure:

Owned by the MD of Big Lakes

Organizational Structure:

MD of Big Lakes

Role of Airport:

To provide service to the local swan hills residents.

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1980; last rehabilitation 1987;

Poor condition; replacement 2003

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type paved; constructed 1981; last

rehabilitation 1987; poor condition;

replacement 2003 (\$31000)

Parking Lot: type paved; constructed 1981; last

rehabilitation 1987; poor condition;

replacement 2003 (\$21000)

Fencing: type 4' barbed wire;

Contact Info

Mr. John Eriksson

Chief Administrative Officer Municipal District of Big Lakes

Box 239 High Prairie T0G 1E0

(780) 523 5955(780), Fax: 523 6566

Runway Data

Primary: "10-28", 4500x100 (Asphalt)

constructed 1980; last rehabilitation 1987; Poor condition; replacement 2003

(\$794000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

constructed 1987; last rehabilitation 1987; poor condition; replacement 2003

(\$136000)

Secondary: ---

**Building Data** 

ATB: constructed 1981; good condition;

Disability Access: type concrete ramp;

Field Electrical Centre: ---

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Swan Hills Airport (EM5)

### □Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1982; poor condition; replacement 2006 (\$227000)

Approach Slope Indicator 1: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1982; poor condition; replacement 2003 (\$60000)

Approach Slope Indicator 2: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1982; poor condition; replacement 2003 (\$60000)

ARCAL: Type: "K"; freq 123.2

Windsock: 2 windsocks;

constructed 1982; fair condition; replacement 2

#### Water / Sewer Data

Water Supply: Well; constructed 1981; fair

condition;

Sewage: ---

#### <sup>-</sup>Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: ---

# Peak Period Info Spring Summer Fall Winter Average Peak Apron Aircraft Parked: Design Aircraft for Airport: ---





### Swan Hills Airport (EM5)

Consite Business Data □							
FBO: No				AC Mai	ntenance:	No	
FBO. NO				AC Mai	illeriance:	INO	
Industrial Buildings: No			Crop Spraying Activities:				
Hangars: No				Chemica	als Stored	on site:	
Trangaror Tro				CHEITHE	ais stored	orr sicer	
-Operation and Mainten	anaa Dud						
Operation and Mainten		.997	1998	1999	2000	2001	
Total Annual Maintenance E		.997	1990	1999	2000	2001	
Economic Activity Info	rmation -						
Major Economic Industries How is the Airport Vital to the hill residents.					rdous Was industry a		
Airport Activity Info	19	997	1998	1999	2000	2001	
Annual Aircraft Movemen							
Annual Passenger Movemen	nts:						
Commercial Airline Info	<u> </u>						
	1997	1998	199	9	2000	2001	
Total Annual Revenue:							
 ─Airport Expenditure Da	ta						
	1997	1998	3 1	.999	2000	2001	
Total Annual Expenditure							

### Swan Hills Airport (EM5)

Year	Project Name	Funding Source	Description
1995		Provincial	Fog pavement surfaces
1993		Provincial	Fog pavement surfaces
1988		Provincial	Purchase and installation of AWOS (Automated Weather Observation System
1987		Provincial	runway overlay and repairs
1987		Provincial	Purchase and installation of DME
1986		Provincial	Purchase of NDB
1986		Provincial	Drainage improvements
1982		Provincial	Airfield lighting
1981		Provincial	Construction of Air Terminal Building (AHS Trust Fund)
1981		Provincial	Completion of paving
1980		Provincial	Grading and base, powerline relocation
1979		Provincial	Tree clearing and gravel stockpiling

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 TABER AIRPORT (CED5)





Taber Airport Aerial Photographs taken August 13, 2002

#### **Airport Contact Information:**

Mr. Ken Mundy Chief Administrative Officer Town of Taber Taber, AB T1G 1T1 Tel: (403) 223 5500

Fax: (403) 223 5500

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Taber Airport (ED5)

General Info

Taber (ED5) Distance From Community (mile): 4
Municipal Latitude: 49.8333°, Longitude: -112.1833°

Owner and Operator Info

Owner: M.D. of Taber Operator: M.D. of Taber Former Ownership: ---Date of Change: ---

**Airport Organization** 

Ownership Structure: M.D. of Taber/Town

Organizational Structure:

Commission/Town of Taber

Role of Airport:

Air Spray/Medevac/Oil Field/Potato Processing

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1973; last rehabilitation 1986; Good condition; replacement 2012 (\$31000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: constructed 1976; good condition;

Parking Lot: size 20 cars; type asphalt; constructed

1984; good condition; replacement

2020

Fencing: size 4ft; type 4 strand barb wire;

replacement 2020

Contact Info

Mr. Ken Mundy

Chief Administrative Officer

Town of Taber 4900 "A" 50 Street

Taber T1G 1T1

(403) 223 5500(403), Fax: 223 5530

Runway Data

Primary: "05-23", 3000x75 (Asphalt)

constructed 1973; last rehabilitation 1984; Good condition; replacement 2012

(\$397000)

Secondary: "13-31", 2000x75 (Oiled Gravel)

constructed 1980; last rehabilitation

1995; Good condition;

**Apron Data** 

Primary: "west half"; 300x150 (Asphalt)

constructed 1971; last rehabilitation 1984; good condition; replacement 2012

(\$87000)

Secondary: "east half";

constructed 1980; poor condition;

replacement 2003

Building Data

ATB: size 24x24; type wood frame; constructed

1996; good condition; replacement 2020

(\$100000)

Disability Access: ---

Field Electrical Centre: size 6x8; type wood/metal

frame; constructed 1984; good condition; replacement

2014 (\$150000)

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Taber Airport (ED5)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1984; good condition; replacement 2014 (\$255000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 122.8

Windsock: 2 windsocks;

constructed 1984; good condition; replacement

2014

Water / Sewer Data

Water Supply:

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1976; good condition; Subsurface: ---

Peak Period Info
Spring Summer Fall Winter Average
Peak Apron Aircraft Parked: 4 12 4 4 6
Design Aircraft for Airport: ---





### Taber Airport (ED5)

ſ	⁻Onsite Business Data  ̄							
	FBO: No			AC Ma	intenance:	No		
	Industrial Buildings: No				Crop Spraying Activities: Permanent;			
	Hangars: Yes, 4; Garth Harri Craig Miller, Kinnib See buildings			Chemic	cals Stored	•	C.P.I.C. Certified ehouse new (2002)	
	Operation and Maintena	nce Budget	1998	1999	2000	2001		
	Total Annual Maintenance Bu		1330	1333	2000			
1	Economic Activity Inforr	nation					]	
	Road Distance to Nearest Air Road Distance to Nearest Air Road Distance to Nearest Air Road Distance to Nearest Air Road Distance to Nearest Air Major Economic Industries in	port MedEvac S port Cargo Serv port AME Servic port Fire Suppre	Service: vice: 35 ce: 35 ession Se	0 rvice: 5				
	Airport Activity Info	1997	1998	1999	2000	2001		
	Annual Aircraft Movements	<b>;:</b>						
	Annual Passenger Movement	:s:						
	Commercial Airline Info							
	Airport Revenue Data	1997 199	<u>۶</u> 1	999	2000	2001		
	Total Annual Revenue:		<u> </u>		2000	2001		
	Airport Expenditure Data		998	1999	2000	2001	1	
	Total Annual Expenditure	199/ 1	<i>.</i>	1993	2000	2001	-	

### Taber Airport (ED5)

Year	Project Name	Funding Source	Description
1996		Provincial	Crack routing and sealing of asphalt surfa
1988		Provincial	Purchase and installation of NDB, DME an Radio Equipment Building
1984		Provincial	Overlay runway, install new airfield lighting
1984		Provincial	Supplementary air terminal building grant
1983		Provincial	Air Terminal Building Grant
1980		Provincial	Crosswind runway, expanded development area and tie down area.
1976		Provincial	Airport lighting, installed by Town
1973		Federal	Towards initial construction, completed Ju 1973

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 TEEPEE AIRPORT (CFM6)





Teepee Airport Aerial Photographs taken August 9, 2002

#### **Airport Contact Information:**

Mr. John Brewer
Fire Manager
Alberta Sustainable Resource Development - Land and Forest Division
Slave Lake, AB T0G 2A2
Tel: (780) 849-7411
Fax: (780) 849-6828

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451 Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info			
	e: 56.4667°, Longitude: -114.1167°		
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:  Airport Organization	Contact Info  Fire Manager Alberta Sustainable Resource Development - Land and Forest Division 301 Birch Road N.E. Slave Lake T0G 2A2 (780) 849-7411(780), Fax: 849-6828		
Ownership Structure:			
Organizational Structure:	Runway Data  Primary: "11-29", 2400x150 (Turf)		
Role of Airport:	Secondary:		
⊤Taxiway Data			
Primary:	Apron Data		
Secondary:	Primary:		
Third:	Secondary:		
Fourth:			
	Building Data		
Landside Facility Data	ATB:		
Entrance Road:			
Parking Lot:	Disability Access:		
Fencing:	Field Electrical Centre:		

<b>□Lighting Data</b>	⊤Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Troumty 1 rotoonon,
ARCAL: Type: Windsock: 0 windsocks;	Caveat, and Right of Way  Vicinity Protection: No Caveat: No Right of Way: No
□Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





─Onsite Business Data   ──────────────────────────────────				
FBO: No		ļ	AC Maintenand	ce: No
Industrial Buildings: No		(	Crop Spraying	Activities:
Hangars: No		C	hemicals Store	ed on site:
Operation and Maintenance	e Budget			
Total Annual Maintenance Budg	1997 et	1998	1999 200	0 2001
Economic Activity Information	tion			
Airport Activity Info	1997	1998 1	1999 2000	2001
Annual Aircraft Movements:	1997	1990	1999 2000	2001
Annual Passenger Movements:				
Commercial Airline Info				
Airport Revenue Data	97 1998	3 1999	2000	2001
Total Annual Revenue:	,, 1990	, 1999	2000	2001
Airport Expenditure Data	.007 10	100	00 2000	2001
Total Annual Expenditure	.997 19	98 19	99 2000	2001

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 THREE HILLS AIRPORT (CEN3)





Three Hills Airport Aerial Photographs taken October 24, 2002

#### **Airport Contact Information:**

Mr. Dan Thomas
Airport Manager
Kneehill County
Three Hills, AB T0M 2N0
Tel: (403) 443 2349

Fax: (403) 443 7172

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Three Hills Airport (EN3)

**General Info** 

Three Hills (EN3)

Distance From Community (mile): 2
Latitude: 51.7000°, Longitude: -113.2167°

Latitude: 51.7000-, Longitude: -115.2107-

Owner and Operator Info

Owner: Three Hills Airport Commission

Operator: ---

Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Three Hills Airport Commission/Town of Three Hills/County of

Kneehill

Organizational Structure:

Community owned

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1978; last rehabilitation 1997; Good condition; replacement 2012 (\$15000)

Secondary: "B"; 2000x (Asphalt)

constructed 1996; Poor condition;

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; fair condition;

Parking Lot: size 100x100; type gravel; fair

condition;

Fencing: type 4' barbed wire;

Contact Info

Mr. Dan Thomas Airport Manager Kneehill County

Box 400 Three Hills T0M 2N0

(403) 443 2349(403), Fax: 443 7172

**Runway Data** 

Primary: "11-29", 3000x75 (Asphalt)

constructed 1978; last rehabilitation 1997; Good condition; replacement 2012

(\$397000)

Secondary: ---

**Apron Data** 

Primary: "1"; 150x150 (Asphalt)

constructed 1978; last rehabilitation 1997; good condition; replacement 2012

(\$67000)

Secondary: ---

**Building Data** 

ATB: type Atco Trailer; constructed 1983; fair

condition; replacement 2010 (\$100000)

Disability Access: ---

Field Electrical Centre:

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Three Hills Airport (EN3)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1978; fair condition; replacement 2005 (\$156000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1978; fair condition; replacement 2

Water / Sewer Data

Water Supply: Municipal Service; constructed

1998; good condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: Subsurface: ---

Peak Period Info
Spring Summer Fall Winter Average
Peak Apron Aircraft Parked: 2 3 2 1 2
Design Aircraft for Airport: ---





### Three Hills Airport (EN3)

**Onsite Business Data** 

FBO: No		AC M	aintenance:	No	
Industrial Buildings: No		Crop	Spraying Ac		Гетрогагу; 3; Royco/Foxxcoulee
Hangars: Yes, 10; 9 Private Owne	rs/Bible College	Chemi	icals Stored	on site:	•
Operation and Maintenance I	_	00 1000	2000	2001	
Total Annual Maintenance Budget	1997 199	98 1999	2000	2001	_
Economic Activity Information	on —				
Road Distance to Nearest Airport S Major Economic Industries in Regi How is the Airport Vital to the Reg program and medevac services.	Cargo Service: AME Service: 6 Fire Suppression on: College/Oil	80 0 Service: 6 & Gas		ning	
Airport Activity Info	1997 199	8 1999	2000	2001	
Annual Aircraft Movements:	1997 199	0 1999	2000	2001	_
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data  1997	1998	1999	2000	2001	
Total Annual Revenue:	1330	1333	2000	2001	_
Airport Expenditure Data			0.5		
Total Annual Expenditure	97 1998	1999	2000	2001	·

### Three Hills Airport (EN3)

Year	Project Name	Funding Source	Description
1997		Provincial	Pavement overlay
1993		Provincial	Residual work for slurry seal project
1992		Provincial	Residual payment for slurry seal project
1991		Provincial	Slurry seal runway
1988		Provincial	Purchase and installation of NDB and Rac Equipment Building
1984		Provincial	Supplementary Air Terminal Building Gran
1983		Provincial	Air Terminal Building
1978		Provincial	Airport paving and airport lighting
1974		Federal	Inistial construction

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 TOFIELD AIRPORT (CEV7)





Tofield Airport Aerial Photographs taken July 10, 2002

#### **Airport Contact Information:**

Ms. Cindy Neufeld Administrator Town of Tofield Tofield, AB T0B 4J0 Tel: (780) 662 3269

Fax: (780) 662 3929

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

ofield Airport (EV7)	
General Info	
	nce From Community (mile): 0
Municipal Latitu	ide: 53.3667°, Longitude: -112.7000°
Owner and Operator Info	Contact Info
Owner: Town of Tofield	Ms. Cindy Neufeld
Operator: Town of Tofield	Administrator
Former Ownership: No Change	Town of Tofield
Date of Change:	Box 30
	Tofield
Airport Organization	TOB 430
Ownership Structure:	(780) 662 3269(780) , Fax: 662 3929
Town Owned and Operated	
Town Owned and Operated	- Punway Data
Organizational Structure:	Runway Data
Organizational Structure.	Primary: "10-28", 3000x75 (Asphalt)
	constructed 1979; Fair condition;
	replacement 2005 (\$397000)
Role of Airport:	
Public Use	Secondary:
Tubile occ	,
Taxiway Data	
Primary:	
············,	Apron Data
	Primary:
Secondary:	
Secondary.	
Third:	Secondary:
Fourth:	
	⊤Building Data
	ATB: size 3000 sq ft; type wood frame;
Landside Facility Data	constructed 1993; fair condition;
Entrance Road: type gravel; constructed 1993; good	
condition;	Disphility Assessed type sidewalls
·	Disability Access: type sidewalk;
Parking Lot: type gravel; constructed 1993; good	
condition;	
condition,	
	Field Electrical Centre: constructed 1979;
Fencing:	

### Tofield Airport (EV7)

Lighting Data			-Water / Sev	wer Data
	nreshold and Runway E ructed 1979; fair condit ement 2005 (\$128000)	ion;	Water Suppl	y: Well; constructed 1993; good condition;
Approach Slope Indicator 1:			Sewage:	-
Approach Slope Indicator 2:			Vicinity Prot	d Right of Way ection: No
ARCAL: Type: "K"; fr	ea 123.2		Caveat: No	
	•		Right of Wa	y: NO
Windsock: 1 windsocks;	; replacement 2005			
Tall Cortainor	, replacement 2005			
Drainage Data				
Surface:		Subsurfa	co.	
Surface.		Subsulia	ce	
Peak Period Info				
	Spring Summer	Fall Wir	nter Average	
Peak Apron Aircraft Parked:				
Design Aircraft for Airport:				





### Tofield Airport (EV7)

Consite Business Data —				
FBO: No			AC Maintenar	nce: No
Industrial Buildings: No			Crop Spraying	g Activities:
Hangars: Yes, 3; private		(	Chemicals Sto	red on site:
Operation and Maintenance	_	1000	1000 200	2001
Total Annual Maintenance Budg	1997 et	1998	1999 200	00 2001
Economic Activity Information	tion —			
Airport Activity Info	1997	1998	1999 200	0 2001
Annual Aircraft Movements:				
Annual Passenger Movements:				
Commercial Airline Info				
- Airm and Davis mus Data				
Airport Revenue Data	97 1998	3 1999	2000	2001
Total Annual Revenue:				
Airport Expenditure Data	007 10	100 10	100 200	0 2001
Total Annual Expenditure	.997 19	998 19	99 200	0 2001

### Tofield Airport (EV7)

Year	Project Name	Funding Source	Description
1994		Provincial	Funding for completion of airport development area
1989		Federal	Towards initial construction

## AIRPORT INFORMATION REPORT - 2002 TROUT LAKE AIRPORT (CFB4)





Trout Lake Airport Aerial Photographs taken August 9, 2002

#### **Airport Contact Information:**

Mr. Rob Guild Area Foreman Municipal District #17 Red Earth Creek, AB T0G 1X0 Tel: (780) 891 3778

Fax: (780) 649 3440/2562

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

General Info			
Trout Lake (FB4) Municipal	Distance From Community (mile): Latitude: 56.5000°, Longitude: -114.5500°		
Owner and Operator Info  Owner: MD of Opportunity No. #17  Operator: MD of Opportunity No. #17  Former Ownership: Province of Alberta  Date of Change:	Contact Info  Mr. Rob Guild Area Foreman  Municipal District #17  Box 50  Red Earth Creek		
Airport Organization Ownership Structure:	T0G 1X0 (780) 891 3778(780) , Fax: 649 3440/2562		
Organizational Structure:	Primary: "13-31", 2500x60 (Gravel)		
Role of Airport:  Med-vac/local/commercial use	Secondary:		
Taxiway Data Primary:	Apron Data		
Secondary:	Primary:		
Third:	Secondary:		
Fourth:	□ Building Data		
⊤Landside Facility Data	ATB:		
Entrance Road:	Disability Access:		
Parking Lot:			
Fencing:	Field Electrical Centre:		

Lighting Data	□ Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





Onsite Business Data						
FBO: No				AC Ma	aintenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintenar	nce Bu	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	dget	1997	1990	1999	2000	
Economic Activity Inforn	nation	-				
Airport Activity Info		1997	1998	1999	2000	2001
Airport Activity Info  Annual Aircraft Movements		1997	1998	1999	2000	2001
	:	1997	1998	1999	2000	2001
Annual Aircraft Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	:	1997		1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info   Airport Revenue Data  Total Annual Revenue:	: s:					
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	: s:					

Year	Project Name	Funding Source	Description
1986		Provincial	Installation of airfield lighting system completed
1985		Provincial	Purchase of airfield lighting system
1980		Provincial	Completion of airport development
1979		Provincial	Developing of connecting taxiway, parking apron and upgraded runway dimensions

### AIRPORT INFORMATION REPORT - 2002 TURNER VALLEY BAR N RANCH AIRPORT (CFY6)





Turner Valley Bar N Ranch Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Greg Noval
Bar N Ranch
Turner Valley, AB T0L 2A0
Tel: (403) 933 7230
Fax: (403) 933 7202

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451 Prepared by:



**Pryde Schropp McComb, Inc.** 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133

Fax: 780-484-0877

⊂General Info ───			
	nce From Community (mile): 2 ide: 50.6500°, Longitude: -114.3500°		
Owner and Operator Info Owner: as above Operator: as above Former Ownership: Date of Change:	Contact Info  Mr. Greg Noval  Bar N Ranch  Box 447  Turner Valley  T0L 2A0		
Airport Organization	(403) 933 7230(403) , Fax: 933 7202		
Ownership Structure: Private Farm strip			
	Runway Data		
Organizational Structure:	Primary: "06-24", 3825x75 (Oiled Gravel)		
Role of Airport:  Private Farm strip  Taxiway Data  Primary:	Secondary:		
Primary	┌Apron Data		
Secondary:	Primary:		
Third:	Secondary:		
Fourth:			
	┌Building Data		
	☐ ATB:		
Landside Facility Data			
Entrance Road:			
	Disability Access:		
Parking Lot:			
	Field Electrical Centre:		
Fencing:			

	• ` `	,	
Lighting Data			─Water / Sewer Data
Primary Edgelighting:			Water Supply:
Approach Slope Indicator 1:	-		Sewage:
Approach Slope Indicator 2:	-		Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:			Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 0 windsocks; poor condition	;		
⊤Drainage Data −			
Surface:		Sub	osurface:
Peak Period Info	Spring Sumr	ner Fall	Winter Average
Peak Apron Aircraft Parked:			
Design Aircraft for Airport:			





FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Act	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Mainten	ance B	u <b>dget</b> - 1997	1998	1999	2000	2001
Total Annual Maintenance E	Budget					
Economic Activity Info	rmation	1				
- Airport Activity Info						
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movement	ts:					
Annual Passenger Movemer	nts:					
Commercial Airline Info	)					
 ─Airport Revenue Data						
	1997	1998	:	1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Da		_		16	g	
Total Annual Expenditure	1997	19	98	1999	2000	2001
. Star / iii iaar Experiatore						

Year	Project Name	Funding Source	Description	

## AIRPORT INFORMATION REPORT - 2002 TWO HILLS AIRPORT (CEL6)





Two Hills Airport Aerial Photographs taken July 11, 2002

#### **Airport Contact Information:**

Mr. Gary Popowich Administrator County of Two Hills Two Hills, AB T0B 4K0 Tel: (780) 657 3358

Fax: (780) 657 3504

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Two Hills Airport (EL6)

General Info

Two Hills (EL6)

Distance From Community (mile): 2.5

Latitude: 53.7000°, Longitude: -111.7833°

Owner and Operator Info

Owner: Two Hill Town & Country Airport Commission Operator: Two Hill Town & Country Airport Commission

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Jointly owned and operated by the Two Hills Town and County

Organizational Structure:

Town of Two Hills/County

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

Fair condition; replacement 2005 (\$34000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 5m; type gravel; fair condition;

Parking Lot: type gravel; fair condition;

Fencing: type 4' barbed wire;

Contact Info

Mr. Gary Popowich Administrator

County of Two Hills

Box 490 Two Hills T0B 4K0

(780) 657 3358(780) , Fax: 657 3504

Runway Data

Primary: "12-30", 2900x75 (Asphalt)

Fair condition; replacement 2005

(\$384000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

fair condition; replacement 2005 (\$63000)

Secondary: ---

**Building Data** 

ATB: size ATCO trailer; fair condition;

Disability Access: ---

Field Electrical Centre: type tool shed; poor

condition; replacement 2005

(\$150000)

#### Two Hills Airport (EL6)

Design Aircraft for Airport:

1 ( /		
Lighting Data		Water / Sewer Data
Primary Edgelighting: TE (The fair co	nreshold and Runway End) ndition; replacement 2005 (\$1550)	Water Supply:
Approach Slope Indicator 1:		Sewage:
Approach Slope Indicator 2:		Vicinity Protection,
ARCAL: Type: "K"; fr Windsock: 1 windsocks; last rehabilita replacement	ation 2002; good condition;	Caveat, and Right of Way  Vicinity Protection: Yes Caveat: No Right of Way: No
Drainage Data		
Surface: poor condition;	Subsurfa	nce:
Peak Period Info	Spring Summer Fall Wi	inter Average
Peak Apron Aircraft Parked:		





### Two Hills Airport (EL6)

Onsite Business Data	
FBO: No	AC Maintenance: No
Industrial Buildings: No	Crop Spraying Activities: Temporary; 1; unknown
Hangars: Yes, 1; Commission	Chemicals Stored on site: no
Operation and Maintenance Budget  1997 1998	1999 2000 2001
Total Annual Maintenance Budget	
Economic Activity Information	
Major Economic Industries in Region: Agriculture How is the Airport Vital to the Region: crop spraying	
Airport Activity Info	1999 2000 2001
Annual Aircraft Movements:	
Annual Passenger Movements:	
Commercial Airline Info	
Airport Revenue Data	
1997 1998 19	99 2000 2001
Total Annual Revenue:	
Airport Expenditure Data	1000
Total Annual Expenditure 1997 1998	1999 2000 2001
rotal Alliual Experiulture	

## Two Hills Airport (EL6)

Year	Project Name	Funding Source	Description
1992		Provincial	Slurry seal asphalt surfaces
1984		Provincial	Air Terminal Building Grant
1979		Provincial	Airport construction, paving and lighting
1978		Provincial	Land acquisition

# AIRPORT INFORMATION REPORT - 2002 VALLEYVIEW AIRPORT (CEL5)





Valleyview Airport Aerial Photographs taken July 24, 2002

#### **Airport Contact Information:**

Mr. Garry Peterson Town Manager Town of Valleyview Valleyview, AB T0H 3N0 Tel: (780) 524 3193

Fax: (780) 524 4307

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Valleyview Airport (EL5)

General Info

Valleyview (EL5)

Distance From Community (mile): 1.9
Latitude: 55.0333°, Longitude: -117.3000°

Owner and Operator Info

Owner: Town of Valleyview Operator: Town of Valleyview Former Ownership: No Change

Date of Change: ---

Airport Organization

Ownership Structure:

Municipality

Organizational Structure:

Airport Commission

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

last rehabilitation 1992; Fair condition;

replacement 2008 (\$110000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel/paved; fair condition;

Parking Lot: type gravel; good condition;

Fencing: size 4ft. Barbed wire around perimeter,

chain link ATB;

Contact Info

Mr. Garry Peterson Town Manager Town of Valleyview

Box 270 Valleyview T0H 3N0

(780) 524 3193(780) , Fax: 524 4307

Runway Data

Primary: "07-25", 3300x75 (Asphalt)

last rehabilitation 1996; Fair condition;

replacement 2008 (\$794000)

Secondary: ---

**Apron Data** 

Primary: "1"; (Asphalt)

last rehabilitation 1992; fair condition;

replacement 2008 (\$110000)

Secondary: ---

**Building Data** 

ATB: constructed 1984; good condition;

Disability Access: type sidewalk;

Field Electrical Centre: type shed; poor condition;

replacement 2006 (\$150000)

## Valleyview Airport (EL5)

Lighting Data		⊤Water / Se	wer Data
	nreshold and Runway End ucted 1979; poor conditio ement 2006 (\$163000)		y: Well; fair condition;
Approach Slope Indicator 1:		Sewage:	-
Approach Slope Indicator 2:			nd Right of Way
ARCAL: Type: "K"; fr	eq 123.2	Caveat: Your Right of Wa	
Windsock: 1 windsocks; fair condition	; replacement 2006		
Drainage Data			
Surface:		Subsurface:	
Peak Period Info			
	Spring Summer I	Fall Winter Average	
Peak Apron Aircraft Parked:			
Design Aircraft for Airport:			





### Valleyview Airport (EL5)

FBO: No			AC Ma	intenance:	No
Industrial Buildings: No			Crop S	praying Ac	tivities: Temporai
Hangars: Yes, 4;			Chemic	als Stored	on site: none
Operation and Maintenance I	3udget 1997	1998	1999	2000	2001
Total Annual Maintenance Budget		1996	1999	2000	2001
Economic Activity Information	n —				
How is the Airport Vital to the Reg business traffic		ort is vital	: Medev	ac, private	and
Airport Activity Info	1007				2004
		1000	1000	2000	
Annual Aircraft Movements:	1997	1998	1999	2000	2001
Annual Aircraft Movements: Annual Passenger Movements:	1997	1998	1999	2000	
	199/	1998	1999	2000	2001
Annual Passenger Movements:	199/	1998	1999	2000	2001
Annual Passenger Movements:	1997	1998	1999	2000	
Annual Passenger Movements:	1997	1998	1999	2000	2001
Annual Passenger Movements:  Commercial Airline Info  Airport Revenue Data					
Annual Passenger Movements:  Commercial Airline Info	1997		1999	2000	2001
Annual Passenger Movements:  Commercial Airline Info  Airport Revenue Data  1997	1998				

## Valleyview Airport (EL5)

Year	Project Name	Funding Source	Description
2001		Provincial	Frost-heave/major crack repair
1996		Provincial	Overlay runway surface only
1992		Provincial	Overlay taxiway and aircraft parking apron
1990		Provincial	Pavement overlay, 300' runway extension and drainage improvements
1989		Provincial	Runway drainage improvements
1988		Provincial	Runway repairs
1988		Provincial	Airport right-of-way
1987		Provincial	Purchase and installation of NDB and Rad Equipment Building
1987		Provincial	Purchase and installation of DME
1986		Provincial	Slurry seal runway, complete developmentarea
1984		Provincial	Supplementary air terminal building grant
1982		Provincial	Air Terminal Building Grant
1981		Provincial	Purchase of 18 acres of land for zoning purposes
1981		Provincial	Paving of airport access road
1979		Provincial	Completion of paving and lighting
1978		Provincial	Grading and base work

## AIRPORT INFORMATION REPORT - 2002 VAUXHALL AIRPORT (CEN6)





Vauxhall Airport Aerial Photographs taken August 13, 2002

#### **Airport Contact Information:**

Mr. Tom Kinnibungh
Manager
Kinnibungh
Purple Springs, AB T0K 1X0

Tel: (403) 223-1314 Fax: (403) 223-1314

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Vauxhall Airport (EN6)

General Info

Vauxhall (EN6) Distance From Community (mile): 2.5
Municipal Latitude: 50.0333°, Longitude: -112.0833°

Owner and Operator Info

Owner: Town of Vauxhaul Operator: Kinnibungh

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Vauxhall/Kinnibungh Spraying

Organizational Structure:

Kinnibungh Air Spray controls operation of airport.

Maintenance is performed by the town and funded by
Kinnibungh

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1983; Good condition; replacement 2015 (\$13000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: ---

Parking Lot: ---

Fencing: size 4'; type barb; replacement 2020

Contact Info

Mr. Tom Kinnibungh

Manager Kinnibungh P.O. Box 25 Purple Springs TOK 1X0

(403) 223-1314(403) , Fax: 223-1314

Runway Data

Primary: "05-23", 2950x75 (Asphalt)

constructed 1983; Good condition; replacement 2014 (\$393000)

Secondary: ---

**Apron Data** 

Primary: "Main"; 300x150 (Asphalt)

constructed 1983; good condition; replacement 2015 (\$67000)

Secondary: ---

**Building Data** 

ATB: size 600ft^2; type wood frame; constructed

1984; good condition; replacement 2022

(\$100000)

Disability Access:

Field Electrical Centre: size 6'x8'; type wood frame;

constructed 1983; good condition; replacement 2015

(\$150000)

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Vauxhall Airport (EN6)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1983; good condition; replacement 2015 (\$148000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1983; good condition; replacement

2015

Water / Sewer Data

Water Supply: constructed 1983; good

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: good condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Vauxhall Airport (EN6)

**Onsite Business Data** 

FBO: No				AC Mai	intenance:	No	
Industrial Buildings: No				Crop S	praying Ac		Femporary; 4 companies operate off of apron/runway
Hangars: Yes, 1;				Chemic	als Stored		
Operation and Mainte	enance B	udget					
Total Annual Maintenanc	e Budget	1997	1998	1999	2000	2001	_
Economic Activity In		1					
		•					
Airport Activity Info		1997	1998	1999	2000	2001	
Annual Aircraft Movem							_
Annual Passenger Moven							
Commercial Airline II	nfo						
_	1997	1998	199	99	2000	2001	_
Total Annual Revenue:							
Airport Expenditure I	<b>Data</b> 1997	199	98 1	1999	2000	2001	
Total Annual Expenditure							

## Vauxhall Airport (EN6)

Year	Project Name	Funding Source	Description
1984		Provincial	Air Terminal Building Grant
1983		Provincial	Built on Crown land, base, gravel, pave an light runway, taxiway and apron areas.

## AIRPORT INFORMATION REPORT - 2002 VEGREVILLE AIRPORT (CEV3)





Vegreville Airport Aerial Photographs taken July 11, 2002

#### **Airport Contact Information:**

Mr. Dale Lefebvre Public Works Manager Town of Vegreville Vegreville, AB T9C 1R7 Tel: (780) 632 2606

Fax: (780) 632 2606

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Vegreville Airport (EV3)

General Info

Vegreville (EV3) Municipal Distance From Community (mile): 0

Latitude: 53.5167°, Longitude: -112.0333°

Owner and Operator Info

Owner: Town of Vegreville Operator: Town of Vegreville Former Ownership: No Change

Date of Change: ---

Airport Organization

Ownership Structure:

Municipal

Organizational Structure:

Municipal Government

Role of Airport:

To serve Regional Aviation/Transportation

**Taxiway Data** 

Primary: "A"; 700x50 (Asphalt)

constructed 1973; last rehabilitation 1988; Fair condition; replacement 2005 (\$84000)

Secondary: "B"; 1000x50 (Asphalt)

constructed 1973; last rehabilitation 1988; Good condition; replacement 2005

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type gravel; constructed 1973; fair

condition;

Parking Lot: type gravel; fair condition;

Fencing: type 3 strand barbwire;

Contact Info

Mr. Dale Lefebvre Public Works Manager Town of Vegreville P. O. Box 640

Vegreville T9C 1R7

(780) 632 2606(780), Fax: 632 3088

Runway Data

Primary: "13-31", 4000x100 (Asphalt)

constructed 1972; last rehabilitation 1988; Fair condition; replacement 2005

(\$1226000)

Secondary: ---

**Apron Data** 

Primary: "1"; 300x150 (Asphalt)

constructed 1973; last rehabilitation 1988; fair condition; replacement 2005

(\$152000)

Secondary: "fuel"; 150x75 (Concrete)

constructed 1975; last rehabilitation

1975; fair condition;

**Building Data** 

ATB: constructed 1988; good condition;

Disability Access: good condition;

Field Electrical Centre: type metal shed; constructed

1988;

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Vegreville Airport (EV3)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

last rehabilitation 1988; fair condition;

replacement 2005 (\$211000)

Approach Slope Indicator 1: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1973; fair condition; replacement 2005 (\$60000)

Approach Slope Indicator 2: V1 (2-BAR VASIS - Aircraft up to 1

constructed 1973; fair condition; replacement 2005 (\$60000)

ARCAL: Type: "J"; freq 122.8

Windsock: 1 windsocks;

constructed 1973; fair condition; replacement 2

Water / Sewer Data

Water Supply: Other; constructed 1988; good

condition; replacement 2008

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: fair condition; Subsurface: ---

Peak Period Info
Spring Summer Fall Winter Average
Peak Apron Aircraft Parked: 12 15 12 8 11.8
Design Aircraft for Airport: ---





### Vegreville Airport (EV3)

**□Onsite Business Data** 

FBO: No	AC Maintenance: No
Industrial Buildings: Yes, 1; Private owner	er Crop Spraying Activities: Permanent; Vegreville Airspray Services
Hangars: Yes, ; Private	Chemicals Stored on site: NIL
Operation and Maintenance Budg	et
Total Annual Maintenance Budget	97 1996 1999 2000 2001
Economic Activity Information	
Road Distance to Nearest Airport Sched. Road Distance to Nearest Airport MedEv Road Distance to Nearest Airport Cargo Road Distance to Nearest Airport AME Sched Distance to Nearest Airport Fire Sched Distance to Nearest Airport American Fire Sched Distance to Nearest Airport American Fire Sched Distance to Nearest Airport American Fire Sched Distance to Nearest Airport American Fire Sched Distance to Nearest Airport Fire Sched Distance to Near	vac Service: 2 Service: 110 Service: 110 Luppression Service: 2 Business/Oil & Gas/Machinery al/Immigration Processing-Federal
Airport Activity Info	97 1998 1999 2000 2001
Annual Aircraft Movements:	77 1990 1999 2000 2001
Annual Passenger Movements:	
Commercial Airline Info	
Airport Revenue Data	1000 1000 2000 2001
Total Annual Revenue:	1998 1999 2000 2001
Airport Expenditure Data	
Total Annual Expenditure	1998 1999 2000 2001

## Vegreville Airport (EV3)

-Historic	Capital Expen	ditures	
Year	Project Name	Funding Source	Description
1988		Provincial	Installation of navigational aides
1988		Federal	Grant for new air terminal building
1988		Federal	Purchase and installation of new airfield lighting.
1987		Provincial	Purchase of NDB and DME
1986		Provincial	Terminal Building
1975		Federal	Towards construction cost
1975		Provincial	Airport construction and lighting. Completion in 1976.

# AIRPORT INFORMATION REPORT - 2002 VERMILION AIRPORT (CYVG)





Vermilion Airport Aerial Photographs taken July 11, 2002

#### **Airport Contact Information:**

Mr. Dean Litke
Public Works Manager
Town of Vermilion
Vermilion, AB T9X 1X1
Tel: (780) 853 6763

Fax: (780) 853 6763

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Vermilion Airport (YVG)

General Info

Vermilion (YVG) Municipal Distance From Community (mile): 0 Latitude: 53.3500°, Longitude: -110.8333°

Owner and Operator Info

Owner: Town of Vermilion
Operator: Town of Vermilion

Former Ownership: --- Date of Change: ---

**Airport Organization** 

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

Fair condition; replacement 2006 (\$42000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size short; type paved; good

condition; replacement 2011 (\$33000)

Parking Lot: type gravel; good condition;

Fencing: size 6'; type chain link;

Contact Info

Mr. Dean Litke

Public Works Manager Town of Vermilion

5021 49 Ave. Vermilion

T9X 1X1

(780) 853 6763(780) , Fax: 853 4910

**Runway Data** 

Primary: "10-28", 3300x75 (Asphalt)

Fair condition; replacement 2006

(\$621000)

Secondary: ---

**Apron Data** 

Primary: "I"; (Asphalt)

fair condition; replacement 2006

(\$124000)

Secondary: ---

Building Data

ATB: fair condition;

Disability Access: ---

Field Electrical Centre: ---

## Vermilion Airport (YVG)

Lighting Data			<b>⊢Water / Se</b>	wer Data		
Primary Edgelighting: TE (Th fair cor	reshold and Runway Endition; replacement 20	Water Suppl	y:			
Approach Slope Indicator 1: -		Sewage:	-			
Approach Slope Indicator 2: -			Vicinity Pr Caveat, ar	rotection, ad Right of Way		
ARCAL: Type: "J"; fre	q 122.8	Vicinity Pro Caveat: N Right of Wa				
Windsock: 1 windsocks; fair condition;	; replacement 2006					
Drainage Data						
Surface: good condition; Subsurface:						
Peak Period Info				]		
	Spring Summer	Fall Wi	nter Average			
Peak Apron Aircraft Parked:						
Design Aircraft for Airport:						





### Vermilion Airport (YVG)

□Onsite Business Data ──					
FBO: No			AC Maintena	ance: No	
Industrial Buildings: No			Crop Sprayii	ng Activities:	
Hangars: No		•	Chemicals St	tored on site:	
Operation and Maintenanc	e Budget	1998	1999 2	000 2001	1
Total Annual Maintenance Budg		1990	1999 2	000 2001	
Economic Activity Informa	tion				
Airport Activity Info	1997	1998	1999 20	000 2001	
Annual Aircraft Movements:				<u></u>	
Annual Passenger Movements:					
Commercial Airline Info					]
Airport Revenue Data	97 199	8 1999	9 2000	) 2001	
Total Annual Revenue:	,, 133	<u> </u>	2000	, 2001	
Airport Expenditure Data	1997 1	998 19	999 20	000 2001	
Total Annual Expenditure	<u> </u>	<del>-</del> ·			_

## Vermilion Airport (YVG)

Historic	Historic Capital Expenditures					
Year	Project Name	Funding Source	Description			
1996		Provincial	Overlay existing asphalt surfaces			
1988		Provincial	Runway repairs and slurry seal			
1976		Provincial	Terminal building			
1976		Federal	Towards airport construction. Airport design and engineering assistance by Transport			
1976		Provincial	Airport construction			

## AIRPORT INFORMATION REPORT - 2002 VIKING AIRPORT (CEE8)





Viking Airport Aerial Photographs taken July 10, 2002

#### **Airport Contact Information:**

Mr. Rod Krips Chief Administrative Officer Town of Viking Viking, AB T0B 4N0 Tel: (780) 336 3466

Fax: (780) 336 3466

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Viking Airport (EE8)

General Info

Viking (EE8) Distance From Community (mile): 3
Municipal Latitude: 53.1000°, Longitude: -111.8667°

Owner and Operator Info

Owner: Town of Viking Operator: Town of Viking

Former Ownership: Province of Alberta

Date of Change: June 15, 1998

**Airport Organization** 

Ownership Structure:

Town of Viking

Organizational Structure:

Town of Viking

Role of Airport:

Provides service for small aircrafts.

**Taxiway Data** 

Primary: "A"; 75x15 (Asphalt)

constructed 1980; Poor condition; replacement 2005 (\$51000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 5.6m; type gravel; constructed

1980; fair condition;

Parking Lot: ---

Fencing: size 4ft; type Barb wire;

Contact Info

Mr. Rod Krips

Chief Administrative Officer

Town of Viking Box 369

Viking

T0B 4N0

(780) 336 3466(780), Fax: 336 2660

**Runway Data** 

Primary: "13-31", 2950x75 (Asphalt)

constructed 1980; last rehabilitation 1990; Fair condition; replacement 2005

(\$683000)

Secondary: ---

**Apron Data** 

Primary: "1"; 80x40 (Asphalt)

constructed 1980; poor condition; replacement 2005 (\$104000)

Secondary: ---

**Building Data** 

ATB: type Atco shack; constructed 1986; poor

condition:

Disability Access: ---

Field Electrical Centre: ---

Airport Summary Report

### Viking Airport (EE8)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1980; fair condition;

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.2

Windsock: 1 windsocks;

constructed 1980; last rehabilitation 1999; poor

condition; replacement 2005

Water / Sewer Data

Water Supply: Well; constructed 1986; poor

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1980; fair condition; Subsurface: ---

Peak Period Info
Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

H5-748

---





### Viking Airport (EE8)

Onsite Business Data					
FBO: No			AC Mai	ntenance:	No
Industrial Buildings: No			Crop S <sub>I</sub>	oraying Act	ivities: Temporary;
Hangars: Yes, 2; Eugene Miskew Cumming	; Dean		Chemica	als Stored (	on site: no
<b>☐</b> Operation and Maintenance	Budget -				
Total Annual Maintenance Budget	1997	1998	1999	2000	2001
Economic Activity Information	on				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	1998	2 10	999	2000	2001
Total Annual Revenue:	1990	) I:	)	2000	2001
Airport Expenditure Data	07 10	)00	1000	2000	2001
Total Annual Expenditure	9/ 19	998	1999	2000	2001

### Viking Airport (EE8)

Year	Project Name	Funding Source	Description
1991		Provincial	Runway repairs and overlay
1986		Provincial	Air Terminal Building Grant
1981		Provincial	Land acquisition (\$32,625 for land purchase), construction, paving and lighting

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 VULCAN AIRPORT (CFX6)





Vulcan Airport Aerial Photographs taken August 14, 2002

#### **Airport Contact Information:**

Mr. Wally Sholdice Municpal Administrator Vulcan, AB T0I 2B0 Tel: (403) 485 2417

Fax: (403) 485 2914

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue

Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc.

204-17707 105 Avenue Edmonton, AB T5S 1T1 Tel: 780-444-1133

Fax: 780-484-0877

Airport Summary Report

### Vulcan Airport (FX6)

General Info

Vulcan (FX6) Distance From Community (mile): 0

Latitude: 50.4000°, Longitude: -113.2833°

Owner and Operator Info

Owner: Vulcan Town & County Operator: Town of Vulcan Former Ownership: ---

Date of Change: --- Vu

**Airport Organization** 

Ownership Structure:

---

Organizational Structure:

---

Role of Airport:

---

**Taxiway Data** 

Primary: "A"; (Asphalt)

constructed 1982; last rehabilitation 2002; Good condition; replacement 2012 (\$45000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 33'; type gravel; constructed

1982; good condition;

Parking Lot: size 40 stalls; type gravel; constructed

1982; good condition;

Fencing: size 4'; type 3 strand;

Contact Info

Mr. Wally Sholdice Municpal Administrator

Box 360 Vulcan T0I 2B0

(403) 485 2417(403), Fax: 485 2914

Runway Data

Primary: "16-34", 2950x75 (Asphalt)

constructed 1982; last rehabilitation 1998; Good condition; replacement 2013

(\$393000)

Secondary: "05-23", 2100x135 (Turf)

constructed 1960; Fair condition;

replacement 2009 (\$7000)

**Apron Data** 

Primary: "Main"; 400x200 (Asphalt)

constructed 1982; last rehabilitation 2002; good condition; replacement 2012

(\$45000)

Secondary: ---

**Building Data** 

ATB: ---

Disability Access: good condition;

Field Electrical Centre: size 6'x8'; type wood frame;

constructed 1982; good condition; replacement 2012

(\$150000)

Airport Summary Report

### Vulcan Airport (FX6)

_ 1	 	ı_	4:				-4-	
	 $\mathbf{a}$	n	TI	n	~	1)	ata	

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1982; replacement 2012

(\$158000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 122.8

Windsock: 1 windsocks;

constructed 1982; fair condition; replacement 2

#### Water / Sewer Data

Water Supply: Municipal Service; constructed

1984; good condition; replacement 2020

Sewage: ---

#### Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

#### **Drainage Data**

Surface: --- Subsurface: ---

# Peak Period Info Spring Summer Fall Winter Average Peak Apron Aircraft Parked: Design Aircraft for Airport: ---





### Vulcan Airport (FX6)

Consite Business Data ——					
FBO: No			AC Mai	ntenance:	No
Industrial Buildings: No			Crop S	praying Ac	tivities: Temporary
Hangars: Yes, 4;			Chemic	als Stored	on site:
Operation and Maintenance	_	1000	1000	2000	2001
Total Annual Maintenance Budge	1997 et	1998	1999	2000	2001
Economic Activity Informati	ion				
Airport Activity Info	1997	1998	1999	2000	2001
Annual Aircraft Movements:					
Annual Passenger Movements:					
Commercial Airline Info					
Airport Revenue Data	7 1998	3 19 <sup>6</sup>	00	2000	2001
Total Annual Revenue:	, 1990	) 19	<i>33</i>	2000	2001
Airport Expenditure Data	207 40	.00	1000	2000	2001
Total Annual Expenditure	997 19	98 :	1999	2000	2001

### Vulcan Airport (FX6)

Year	Project Name	Funding Source	Description
1998		Provincial	pavement overlay-50 mm (25% coast share by munic)
1995		Provincial	Fog seal asphalt surfaces
1988		Provincial	Purchase and installation of NDB, Radio Equipment Building and DME
1984		Provincial	Air Terminal Building Grant
1982		Provincial	Land (\$131,000 for land purchase), construction, paving and lighting

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 WABASCA AIRPORT (CEE5)





Wabasca Airport Aerial Photographs taken August 9, 2002

#### **Airport Contact Information:**

Mr. Dwayne Calliou
Manager
Municipal District of Opportunity
Wabasca, AB T0G 2K0

Tel: (780) 891 3778 Fax: (780) 891 3772

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
Wabasca (EE5) Municipal	Distance From Community (mile): 2 Latitude: 55.9667°, Longitude: -113.8167°
Owner and Operator Info	□ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □
Owner: MD of Opportunity No. #17 Operator: MD of Opportunity No. #17 Former Ownership: Province of Alberta Date of Change:	Mr. Dwayne Calliou  Manager  Municipal District of Opportunity  Box 60  Wabasca
Airport Organization	TOG 2K0
Ownership Structure:	(780) 891 3778(780) , Fax: 891 3772
<del></del>	 ┌Runway Data
Organizational Structure:	Primary: "06-24", 3540x100 (Asphalt) Good condition;
Role of Airport:	
Med-vac/local/commercial use	Secondary:
Taxiway Data	
Primary:	☐ Apron Data
	Primary:
Secondary:	Filliary
7	Cocondom
Third:	Secondary:
Fourth:	
	□ Building Data □
	ATB: size 10'x12'; type wood frame; constructed
Landside Facility Data	2001; good condition;
Entrance Road: last rehabilitation 2001; good condition;	Disability Access:
Parking Lot: good condition;	
Fencing:	Field Electrical Centre: size '8x12'; type wood; constructed 2000; good condition;

abassa / iiiport (LLO)		
Lighting Data	⊤Water / Sewer Data	_
Primary Edgelighting: TE (Threshold and Runway End) constructed 1984; fair condition; replacement 2008 (\$186000)	Water Supply:	
Approach Slope Indicator 1:	Sewage:	
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way	
ARCAL: Type: "K"; freq 123.2 Windsock: 1 windsocks; good condition; replacement 2000	Vicinity Protection: No Caveat: No Right of Way: No	
Drainage Data		
Surface: constructed 2001; good condition; Subs	urface:	

Peak Period Info					
	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





Onsite Business Data	
FBO: No	AC Maintenance: No
Industrial Buildings: No	Crop Spraying Activities:
Hangars: Yes, 2; Slave Air (1988) Ltd., Yellowhead Helicopters	Chemicals Stored on site:
Operation and Maintenance Budget	
Total Annual Maintenance Budget	1999 2000 2001
Economic Activity Information	
Road Distance to Nearest Airport Fire Suppression S	ervice: 2
Airport Activity Info  1997 1998  Annual Aircraft Movements:	1999 2000 2001
Annual Passenger Movements:	
Commercial Airline Info	
Airport Revenue Data	1000 2000 2001
Total Annual Revenue:	1999 2000 2001
Airport Expenditure Data	1000 2000 2001
Total Annual Expenditure 1997 1998	1999 2000 2001

Year	Project Name	Funding Source	Description
2002		Provincial	Asphalt overlay of runway, taxiway and apro
1986		Provincial	Airfield lighting completion and installation on NDB
1986		Provincial	Purchase and installation of DME
1985		Provincial	Grading, base, paving, airfield lighting
1984		Provincial	Gravel crushing and grading
1983		Provincial	Gravel stockpiling, survey and soils test

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 WAINWRIGHT AIRPORT (CYWV)





Wainwright Airport Aerial Photographs taken July 12, 2002

#### **Airport Contact Information:**

Mr. Ray Poulin Administrator Town of Wainwright Wainwright, AB T9W 1R Tel: (780) 842 3381

Fax: (780) 842 2898

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Wainwright Airport (YWV)

General Info

Wainwright (YWV) Municipal Distance From Community (mile): 1.7 Latitude: 52.8000°, Longitude: -110.8500°

Owner and Operator Info

Owner: Town of Wainwright Operator: Town of Wainwright Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Town of Wainwright

Organizational Structure:

Town/Council Administrator

Role of Airport:

Provision of airport services for residents of Wainwright and

district

**Taxiway Data** 

Primary: "A"; 400x31 (Asphalt)

Fair condition; replacement 2006 (\$34000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: type Gravel; fair condition;

Parking Lot: type Gravel; fair condition;

Fencing: ---

Contact Info

Mr. Ray Poulin Administrator Town of Wainwright 1018 2nd Avenue

Wainwright T9W 1R

(780) 842 3381(780), Fax: 842 2898

Runway Data

Primary: "12-30", 3000x75 (Asphalt)

Fair condition; replacement 2006

(\$438000)

Secondary: ---

**Apron Data** 

Primary: ---

Secondary: ---

**Building Data** 

ATB: size 12' x 40'; type Pre-fab; constructed

1982; fair condition;

Disability Access: ---

Field Electrical Centre: type tool shed; fair condition;

Airport Summary Report

### Wainwright Airport (YWV)

**Lighting Data** 

Primary Edgelighting: TE (Threshold and Runway End)

fair condition; replacement 2006 (\$1690)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 122.8

Windsock: 1 windsocks;

fair condition; replacement 2006

Water / Sewer Data

Water Supply: Well; constructed 1982; fair

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: good condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter Average

Peak Apron Aircraft Parked:

Design Aircraft for Airport:





### Wainwright Airport (YWV)

Onsite Business Data

FBO: No			AC Mai	ntenance:	No	
Industrial Buildings: No			Crop S <sub>l</sub>	oraying Act	tivities: Tem	nporary; 2; Priebe Air
Hangars: Yes, 8; Alberta Hot Wainwright Flying Allan Schmitt, Larry Hiebert, Don Christ	Club, Frank Shi y Woodward, D	fflett,	Chemica	als Stored (	on site: Non	ie
Operation and Maintena	nce Budget					]
	1997	1998	1999	2000	2001	
Total Annual Maintenance Bu	ıdget					
Economic Activity Inform	nation					]
Major Economic Industries in National Defence	Region: Oil 8	ι Gas/Can <i>l</i>	Amera Foo	ods/Depart	ment of	
Airport Activity Info	1997	1998	1999	2000	2001	
Annual Aircraft Movements		1330	1999	2000	2001	
Annual Passenger Movement	s:					
Commercial Airline Info						
Airport Revenue Data	1007 100	0 10	200	2000	2001	
Total Annual Revenue:	1997 199	0 15	999	2000	2001	
Airport Expenditure Data						
Total Annual Expenditure	1997 1	998	1999	2000	2001	-
1						

### Wainwright Airport (YWV)

Year	Project Name	Funding Source	Description
1992		Provincial	Slurry sealy pavement
1987		Provincial	Installation of medium intensity airfield lighting
1984		Provincial	Supplementary air terminal building grant
1984		Provincial	Expand paved parking apron by 100' X 150
1982		Provincial	Air Terminal Building
1980		Provincial	Purchase of additional 6.72 acres for runwa extension
1980		Provincial	500' runway extension, paving and lighting
1976		Federal	Airport paving
1976		Provincial	Towards completion of airport paving. Contract supervision by AT&U
1967		Federal	Initial construction

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 WARBURG/ZAJES AIRPORT (CFH8)





Warburg/Zajes Airport Aerial Photographs taken October 8, 2002

#### **Airport Contact Information:**

Mr. Karl S. Zajes Warburg, AB T0C 2T0 Tel: (780) 848 2508 Fax: (780) 848 2508

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918



Prepared by:

Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info					
	ce From Community (mile): 2.4 e: 53.2167°, Longitude: -114.3333°				
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Mr. Karl S. Zajes Box 157 Warburg T0C 2T0 (780) 848 2508(780), Fax: 848 2508				
Airport Organization					
Ownership Structure:					
	Runway Data				
Organizational Structure:	Primary: "07-25", 2400x90 (Turf)				
Role of Airport:	Secondary:				
⊤Taxiway Data					
Primary:	Apron Data				
Secondary:	Primary:				
Third:	Secondary:				
Fourth:					
	Building Data				
Landaida Fasilita Data	ATB:				
Landside Facility Data					
Entrance Road:					
	Disability Access:				
Parking Lot:					
	Field Electrical Centre:				
Fencing:					

<b>□Lighting Data</b>	Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 0 windsocks;	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





FBO: No				AC Ma	intenance:	No
Industrial Buildings: No				Crop S	Spraying Act	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Mainten	ance B	u <b>dget</b> - 1997	1998	1999	2000	2001
Total Annual Maintenance E	Budget					
Economic Activity Info	rmation	1				
- Airport Activity Info						
Airport Activity Info		1997	1998	1999	2000	2001
Annual Aircraft Movement	ts:					
Annual Passenger Movemer	nts:					
Commercial Airline Info	)					
Airport Revenue Data						
	1997	1998	:	1999	2000	2001
Total Annual Revenue:						
Airport Expenditure Da		_		16	g	
Total Annual Expenditure	1997	19	98	1999	2000	2001
. Star / iii iaar Experiatore						

Year	Project Name	Funding Source	Description	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 WARNER AIRPORT (CEP6)





Warner Airport Aerial Photographs taken August 13, 2002

#### **Airport Contact Information:**

Ms. Lana Holt Village Administrator Village of Warner Warner, AB T0K 2L0 Tel: (403) 642 3877

Fax: (403) 642 3877

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Warner Airport (EP6)

General Info

Warner (EP6) Distance From Community (mile): 1

Latitude: 49.2833°, Longitude: -112.2000°

Owner and Operator Info

Owner: Village of Warner Operator: Village of Warner

Former Ownership: Transport Canada

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Council

Organizational Structure:

---

Role of Airport:

Crop Spraying/Recreation

**Taxiway Data** 

Primary: "A"; 300x150 (Asphalt)

constructed 1984; last rehabilitation 1997; Good condition; replacement 2013 (\$49000)

Secondary: ---

Third: ---

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 12; type gravel; fair condition;

Parking Lot: ---

Fencing:

Contact Info

Ms. Lana Holt Village Administrator Village of Warner P.O. Box 88 Warner

TOK 2L0

(403) 642 3877(403), Fax: 642 2011

**Runway Data** 

Primary: "06-24", 2952x75 (Asphalt)

constructed 1984; last rehabilitation 1997; Good condition; replacement 2013

(\$393000)

Secondary: ---

**Apron Data** 

Primary: "Main"; 300x150 (Asphalt)

constructed 1984; last rehabilitation

1997; good condition;

Secondary: ---

Building Data

ATB: constructed 1984; fair condition; replacement

2020 (\$100000)

Disability Access:

Field Electrical Centre: constructed 1984; fair

condition; replacement 2013

(\$150000)

### Warner Airport (EP6)

amer Airport (Li 0)	
Lighting Data	Water / Sewer Data
Primary Edgelighting: TE (Threshold and Runway End) constructed 1984; fair condition; replacement 2013 (\$165000)	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way Vicinity Protection: No
ARCAL: Type: "K"; freq 122.8	Caveat: No Right of Way: Yes
Windsock: 1 windsocks; constructed 1984; last rehabilitation 1997; good condition; replacement 2013	
Drainage Data	
Surface: constructed 1984; good condition; Subsurface	ace:

Diamay	e Dala	
Surface:	constructed 1984; good condition;	Subsurface:

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





### Warner Airport (EP6)

-Oneita Business Data						
Onsite Business Data						
FBO: No			AC Ma	intenance:	No	
Industrial Buildings: No			Crop S	praying Ac	tivities: local	crop dusting
Hangars: Yes, 2; 1 - part of ATB 2bays-(2-planes)	(1-plane)	1-	Chemic	als Stored	on site: none	<u>:</u>
Operation and Maintenance	Budget -					
	1997	1998	1999	2000	2001	
Total Annual Maintenance Budget	-					
Economic Activity Information	on					
Airport Activity Info  Annual Aircraft Movements:	1997	1998	1999	2000	2001	
Annual Passenger Movements:						
Commercial Airline Info						
Airport Revenue Data				2005	2004	
Total Annual Revenue:	1998	3 1	999	2000	2001	
Airport Expenditure Data	07 10	200	1000	2000	2001	
Total Annual Expenditure	97 19	998	1999	2000	2001	

### Warner Airport (EP6)

storic	Capital Expen	ditures		
Year	Project Name	Funding Source	Description	
1997		Provincial	Fog Seal	
1996		Provincial	Crack routing and sealing	
1984		Provincial	Grading, base and paving	
1984		Provincial	Permanent airfield lighting	
1984		Provincial	Terminal Building	
1983		Provincial	Preliminary earth work	
1980		Provincial	Re-compact base and replace gravel, oil surface and re-seeding	
1980		Provincial	Temporary lighting	
1979		Provincial	Grading and base work for gravel ru	
1979		Provincial	Purchase of airport land	

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 WESTLOCK AIRPORT (CES4)





Westlock Airport Aerial Photographs taken October 8, 2002

#### **Airport Contact Information:**

Mr. Bill Baker Airport Manager Westlock Municipal Airport Westlock, AB T7P 2K3 Tel: (780) 349 6606

Fax: (780) 349 6606

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Westlock Airport (ES4)

#### General Info

Westlock (ES4) Municipal Distance From Community (mile): 4

Latitude: 54.1500°, Longitude: -113.7333°

Contact Info

Mr. Bill Baker

Westlock T7P 2K3

Airport Manager

10003 106 Street

Primary: "10-28", 3000x75 (Asphalt)

(\$439000)

Westlock Municipal Airport

(780) 349 6606(780), Fax: 349 6606

constructed 1976; last rehabilitation 2000; Good condition; replacement 2010

#### Owner and Operator Info

Owner: Town of Westlock/Westock County Operator: Westlock Municipal Airport Authority

Former Ownership: --- Date of Change: ---

#### Airport Organization

Ownership Structure:

Municipality owned-Town of Westlock; Westlock County

Organizational Structure:

---

Role of Airport:

---

#### **Taxiway Data**

Primary: "A"; 1500x30 (Asphalt)

constructed 1976; last rehabilitation 2000; Good condition; replacement 2010 (\$38000)

Secondary: "B"; (Asphalt)

constructed 1991; Poor condition;

replacement 2005 (\$69000)

Third: ---

Fourth: ---

### Apron Data

Secondary: ---

**Runway Data** 

Primary: "1"; (Asphalt)

constructed 1976; last rehabilitation 2000; good condition; replacement 2010

(\$63000)

Secondary: ---

#### **Landside Facility Data**

**Entrance Road:** 

Parking Lot:

Fencing:

#### **Building Data**

ATB: size 60x80; type R1610 Metal; constructed 1976; fair condition; replacement 2010 (\$100000)

Disability Access:

Field Electrical Centre:

### Westlock Airport (ES4)

Lighting Data	⊤Water / Sewer Data
	whereshold and Runway End) Fucted 1983; fair condition; Freement 2007 (\$117000)  Water Supply: Other; good condition;
Approach Slope Indicator 1:	Sewage: Well;
Approach Slope Indicator 2:	Caveat, and Right of Way  Vicinity Protection: No
ARCAL: Type: "J"; fre	eq 122.8 Caveat: No Right of Way: No
Windsock: 1 windsocks;	ragic of way. To
Drainage Data	
Surface:	Subsurface:
Peak Period Info	Spring Summer Fall Winter Average
Peak Apron Aircraft Parked:	
Design Aircraft for Airport:	





### Westlock Airport (ES4)

FBO: No AC Maintenance: Yes, 1; arm Industrial Buildings: No Crop Spraying Activities: Perr Avia Hangars: Yes, 9; Chemicals Stored on site:  Operation and Maintenance Budget  1997 1998 1999 2000 2001  Total Annual Maintenance Budget  Economic Activity Information Road Distance to Nearest Airport Sched. Pax Service: 100 Road Distance to Nearest Airport MedEvac Service: 100 Road Distance to Nearest Airport Cargo Service: 100 Road Distance to Nearest Airport Gargo Service: 100 Rajor Economic Industries in Region: Economic Benefits-The Airshow and operation of the Skydiving Centre bring people to the area. Assess to proper facilities relative to agricultural services (airstrip for sprayer)  Airport Activity Info  1997 1998 1999 2000 2001  Annual Aircraft Movements:  Commercial Airline Info  1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data  1997 1998 1999 2000 2001  Total Annual Expenditure	┌Onsite Business Data ───					
Avia  Hangars: Yes, 9;  Chemicals Stored on site:  Coperation and Maintenance Budget  1997 1998 1999 2000 2001  Total Annual Maintenance Budget  Economic Activity Information  Road Distance to Nearest Airport Sched. Pax Service: 100 Road Distance to Nearest Airport MedEvac Service: 100 Road Distance to Nearest Airport Cargo Service: 100 Major Economic Industries in Region: Agriculture Retail/Oil & Gas/Lumber/Coal How is the Airport Vital to the Region: Economic Benefits-The Airshow and operation of the Skydiving Centre bring people to the area. Assess to proper facilities relative to agricultural services (airstrip for sprayer)  Airport Activity Info  1997 1998 1999 2000 2001  Annual Aircraft Movements:  Commercial Airline Info  1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data 1997 1998 1999 2000 2001				AC Ma	intenance:	Yes, 1; ar
Operation and Maintenance Budget  1997 1998 1999 2000 2001  Total Annual Maintenance Budget  Economic Activity Information  Road Distance to Nearest Airport Sched. Pax Service: 100 Road Distance to Nearest Airport MedEvac Service: 100 Road Distance to Nearest Airport Cargo Service: 100 Major Economic Industries in Region: Agriculture Retail/Oil & Gas/Lumber/Coal How is the Airport Vital to the Region: Economic Benefits-The Airshow and operation of the Skydiving Centre bring people to the area. Assess to proper facilities relative to agricultural services (airstrip for sprayer)  Airport Activity Info  1997 1998 1999 2000 2001  Annual Aircraft Movements:  Commercial Airline Info  1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data  1997 1998 1999 2000 2001	Industrial Buildings: No			Crop S	praying Ac	
Total Annual Maintenance Budget    Total Annual Maintenance Budget   Total Annual Maintenance Budget	Hangars: Yes, 9;			Chemic	als Stored	on site:
Total Annual Maintenance Budget    Total Annual Maintenance Budget   Total Annual Maintenance Budget						
Total Annual Maintenance Budget    Total Annual Maintenance Budget   Total Annual Maintenance Budget	Coneration and Maintenance I	Budget -				
Economic Activity Information	operation and maintenance i	_	1998	1999	2000	2001
Road Distance to Nearest Airport Sched. Pax Service: 100 Road Distance to Nearest Airport MedEvac Service: 100 Road Distance to Nearest Airport MedEvac Service: 100 Major Economic Industries in Region: Agriculture Retail/Oil & Gas/Lumber/Coal How is the Airport Vital to the Region: Economic Benefits-The Airshow and operation of the Skydiving Centre bring people to the area. Assess to proper facilities relative to agricultural services (airstrip for sprayer)  Airport Activity Info  1997 1998 1999 2000 2001  Annual Aircraft Movements:  Annual Passenger Movements:  Commercial Airline Info  1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data  1997 1998 1999 2000 2001	Total Annual Maintenance Budget			1333	2000	2001
Road Distance to Nearest Airport MedEvac Service: 100 Road Distance to Nearest Airport Cargo Service: 100 Major Economic Industries in Region: Agriculture Retail/Oil & Gas/Lumber/Coal How is the Airport Vital to the Region: Economic Benefits-The Airshow and operation of the Skydiving Centre bring people to the area. Assess to proper facilities relative to agricultural services (airstrip for sprayer)  Airport Activity Info  1997 1998 1999 2000 2001  Annual Aircraft Movements:  Annual Passenger Movements:  Commercial Airline Info   Airport Revenue Data  1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data  1997 1998 1999 2000 2001	Economic Activity Information	n				
1997 1998 1999 2000 2001	Road Distance to Nearest Airport ( Major Economic Industries in Regi How is the Airport Vital to the Reg operation of the Skydiving Centre	Cargo Servi on: Agricu jion: Econ bring peopl	ce: 100 ulture Reta omic Bena le to the a	ail/Oil & efits-The area. As	Airshow a	nd
Annual Aircraft Movements:  Annual Passenger Movements:  Commercial Airline Info  Airport Revenue Data  1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data  1997 1998 1999 2000 2001	Airport Activity Info	1997	1998	1999	2000	2001
Commercial Airline Info  Airport Revenue Data 1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data 1997 1998 1999 2000 2001	Annual Aircraft Movements:					
Airport Revenue Data  1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data  1997 1998 1999 2000 2001	Annual Passenger Movements:					
1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data  1997 1998 1999 2000 2001	Commercial Airline Info					
1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data  1997 1998 1999 2000 2001						
1997 1998 1999 2000 2001  Total Annual Revenue:  Airport Expenditure Data  1997 1998 1999 2000 2001						
Total Annual Revenue:  Airport Expenditure Data  1997 1998 1999 2000 2001	-	1998	19	99	2000	2001
1997 1998 1999 2000 2001						
		7 10	00	1000	2000	2001
·		<u>i/ 19</u>	90 .	1999	2000	2001

### Westlock Airport (ES4)

Year	Project Name	Funding Source	Description
2001		Provincial	Pavement overlay
1994		Federal	Fence construction
1991		Federal	Taxiway construction
1989		Provincial	Taxiway improvements
1987		Provincial	Install of NDB and Radio Equipment Build
1986		Provincial	Purchase of NDB and Radio Equipment Building
1986		Provincial	Purchase and install of DME
1984		Provincial	Terminal Building
1983		Provincial	Runway overlay and drainage improveme
1977		Federal	Construction
1976		Provincial	Construction
1975		Provincial	Land purchase

## ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 WETASKIWIN AIRPORT (CEX3)





Wetaskiwin Airport Aerial Photographs taken July 4, 2002

#### **Airport Contact Information:**

Mr. Brett Binnie Airport Manager Wetaskiwin Regional Airport Authority Wetaskiwin, AB T9A 2G2 Tel: (780) 352 5858

Fax: (780) 352 5858

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

> Tel: 780-444-1133 Fax: 780-484-0877

Airport Summary Report

### Wetaskiwin Airport (EX3)

General Info

Wetaskiwin (EX3) Distance From Community (mile): 0
Municipal Latitude: 52.9667°, Longitude: -113.4167°

Owner and Operator Info

Owner: City of Wetaskiwin

Operator: Wetaskiwin Regional Airport Authority

Former Ownership: No Change

Date of Change: ---

**Airport Organization** 

Ownership Structure:

City of Wetaskiwin

Organizational Structure:

City Council/Operator

Role of Airport:

Effective Gateway to Regional Community

**Taxiway Data** 

Primary: "A"; 100x11 (Asphalt)

constructed 1956; last rehabilitation 1982;

Poor condition; replacement 2005

Secondary: "B"; 100x11 (Asphalt)

last rehabilitation 1982; Poor condition;

replacement 2005

Third: "C"; 200x11 (Asphalt)

last rehabilitation 1982; Good condition;

replacement 2010

Fourth: "D"; 125x11 (Asphalt)

constructed 1992; Fair condition;

replacement 2005

**Landside Facility Data** 

Entrance Road: type gravel; good condition;

Parking Lot: size 50x50; type gravel; good

condition;

Fencing: size 4'; type Barbed Wire;

Contact Info

Mr. Brett Binnie Airport Manager

Wetaskiwin Regional Airport Authority

P.O. Box 6501 Wetaskiwin T9A 2G2

(780) 352 5858(780), Fax: 352 4018

**Runway Data** 

Primary: "12-30", 3876x100 (Asphalt)

constructed 1958; last rehabilitation 2002; Fair condition; replacement 2005

(\$1236000)

Secondary: ---

**Apron Data** 

Primary: "I"; 92x46 (Asphalt)

last rehabilitation 1982; fair condition;

replacement 2007 (\$175000)

Secondary: "II"; 289x25

poor condition; replacement 2004

**Building Data** 

ATB: size 4000sq ft; constructed 1984; good

condition;

Disability Access: type Wheelchair Ramp;

Field Electrical Centre: size 6' x 6'; type tool shed;

good condition;

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Wetaskiwin Airport (EX3)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1982; poor condition; replacement 2005 (\$227000)

Approach Slope Indicator 1: ---

Approach Slope Indicator 2: ---

ARCAL: Type: "K"; freq 123.5

Windsock: 1 windsocks;

last rehabilitation 1978; fair condition;

replacement 2005

Water / Sewer Data -

Water Supply: Municipal Service; good

condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: No

Caveat: No

Right of Way: No

**Drainage Data** 

Surface: constructed 1997; good condition; Subsurface: ---

Peak Period Info

Spring Summer Fall Winter

Peak Apron Aircraft Parked:

Design Aircraft for Airport:

---

Average





### Wetaskiwin Airport (EX3)

Onsite Business Data			
FBO: Yes, 2; Wetaskiwin Air Se Aviation	ervices, Central	AC Maintenance:	Yes, 3; Historic Aviation Services Wetaskiwin Air Service
Industrial Buildings: Yes, 3; Rey Museum, Ca	nolds Alberta anada's Aviation	Crop Spraying Ac	tivities: Permanent; 1; Wetaskiwir Aerial Applicators
Hangars: Yes, 39; Private and C Owned	Commerical	Chemicals Stored	on site: ???
Operation and Maintenance	e Budget		
Total Annual Maintenance Budg	1997 1998 et	1999 2000	2001
□ Economic Activity Information	tion		
Airport Activity Info	1997 1998	1999 2000	2001
Annual Aircraft Movements:			
Annual Passenger Movements:			
Commercial Airline Info			
Airport Revenue Data	1000	000 000	
Total Annual Revenue:	7 1998 1	999 2000	2001

1999

2000

2001

1998

1997

**Total Annual Expenditure** 

### Wetaskiwin Airport (EX3)

1991 Provincial Purchase and inst	stigation for drainage allation of NDB and DM Terminal Building work
Provincial Geotechnical investigation of air  Provincial Provincial Purchase and instance and instance are also provincial Completion of air  Provincial Provincial Airfiled lighting report and provincial Provincial Terminal Building	stigation for drainage allation of NDB and DM
1991 Provincial Purchase and instance 1985 Provincial Completion of air 1984 Provincial Airfiled lighting rep 1984 Provincial Terminal Building	allation of NDB and DM
1985 Provincial Completion of air  1984 Provincial Airfiled lighting rep  1984 Provincial Terminal Building	Terminal Building work
1984 Provincial Airfiled lighting rep 1984 Provincial Terminal Building	
1984 Provincial Terminal Building	pairs
1983 Provincial Additional taxiway	
	gravel
1983 Provincial Legal fees for land	d expropriation
1981 Provincial Additional land purchased), pavin	rchase (\$176,160 for lange and lighting
1974 Federal Initial airport cons	truction and paving

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

## AIRPORT INFORMATION REPORT - 2002 WHITECOURT AIRPORT (CYZU)





Whitecourt Airport Aerial Photographs taken July 22, 2002

#### **Airport Contact Information:**

Mr. Joffre Ouimet
Administrator
Woodlands County
Whitecourt, AB T7S 1N3
Tel: (780) 778 8662

Fax: (780) 778 4759

#### Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5

Tel: 780-452-9955 Fax: 780-413-9918

Revision No. 3 February 18, 2003 Project No. 11451

#### Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

#### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Whitecourt Airport (YZU)

General Info

Whitecourt (YZU) Distance From Community (mile): 3.5
Municipal Latitude: 54.1333°, Longitude: -115.6500°

Owner and Operator Info

Owner: Woodlands County Operator: Woodlands County

Former Ownership: Province of Alberta

Date of Change: ---

**Airport Organization** 

Ownership Structure:

Woodlands County

Organizational Structure:

Council/CAO/Director of Infrastructure Services/Airport

Manager

Role of Airport:

Forestry Bomber Base/1 fixed wing company/3 helicopter

companies/Corporate charters

Taxiway Data

Primary: "Carson/A"; 400x75 (Asphalt)

Secondary: "Berlin/B"; 475x50 (Asphalt)

Fair condition;

Third: "Athabasca/C"; 425x50 (Asphalt)

Fair condition;

Fourth: ---

**Landside Facility Data** 

Entrance Road: size 10meter top; type Pavement;

Parking Lot: size 50 Stalls; type Gravel;

Fencing: size 6' high; type page wire;

Contact Info

Mr. Joffre Ouimet Administrator Woodlands County

Box 60 #1 Woodlands Lane

Whitecourt T7S 1N3

(780) 778 8662(780), Fax: 778 4759

**Runway Data** 

Primary: "11-29", 5800x100 (Asphalt)

Fair condition; replacement 2005

(\$2048000)

Secondary: ---

**Apron Data** 

Primary: "Terminal"; 350x250 (Asphalt)

fair condition;

Secondary: "Bomber Base"; 560x200 (Asphalt)

**Building Data** 

ATB: size 51x63 ft; type wood frame;

Disability Access: ---

Field Electrical Centre: size 18x55 ft; type metal

frame;

### Alberta Regional/Local Airport Inventory Study

Airport Summary Report

#### Whitecourt Airport (YZU)

Lighting Data

Primary Edgelighting: TE (Threshold and Runway End)

constructed 1999; good condition; replacement 2005 (\$370000)

Approach Slope Indicator 1: V1 (2-BAR VASIS - Aircraft up to 1

Approach Slope Indicator 2: V1 (2-BAR VASIS - Aircraft up to 1

ARCAL: Type: "K"; freq 122.3

Windsock: 2 windsocks;

good condition; replacement 2005

Water / Sewer Data

Water Supply: Well; poor condition;

Sewage: ---

Vicinity Protection, Caveat, and Right of Way

Vicinity Protection: Yes

Caveat: Yes Right of Way: Yes

**Drainage Data** 

Surface: size 4; Subsurface: size 400;

Peak Period InfoSpringSummerFallWinterAveragePeak Apron Aircraft Parked:10101010Design Aircraft for Airport:---





### Whitecourt Airport (YZU)

• ` `	•							
Onsite Business Data	a							
FBO: Yes, 1; Airbourne				AC Ma	intenance:	Yes, 1; Airbo	orne Minor repairs	
Industrial Buildings: Yes, Shop		nd Count	У	Crop S	Spraying Ac	tivities: Temp	orary; 2; Taiga, High	land
Hangars: Yes, 10; Airbou Larry McConne			d,	Chemi	cals Stored	on site: none		
<sup>−</sup> Operation and Mainte	enance B	_	1000	1000	2000	2004		
Total Annual Maintenanc	e Budget	1997	1998	1999	2000	2001		
Road Distance to Neares Major Economic Industrie How is the Airport Vital to regional industry, which is base  Airport Activity Info	t Airport Mo t Airport Ca t Airport Al t Airport Fil es in Region o the Region	edEvac Servi argo Servi ME Servic re Suppre n: Oil & on: Tran	ice: 3 e: 3 ession Se Gas/Lur esporting	ervice: 3 mber/Fore i freight a	nd custome	ers for		
Annual Aircraft Movem	ents:							
Annual Passenger Moven	nents:							
Commercial Airline II	nfo							
Airport Revenue Data								
Total Annual Revenue:	1997	1998	} :	1999	2000	2001		
Airport Expenditure I		, ,-		1000	2000	2021		
Total Annual Expenditure	1997 e	19	998	1999	2000	2001		

### Whitecourt Airport (YZU)

Year	Project Name	Funding Source	Description
1994		Provincial	Timber clearing in approach areas
1993		Provincial	Installation of Microwave Landing System
1993		Provincial	Purchase and install additional displaced threshold lighting
1993		Provincial	Taxiway paving survey
1992		Provincial	Purchase Microwave Landing System
1988		Provincial	Runway overlay and drainage improvement
1987		Provincial	Runway drainage repairs
1986		Provincial	Expand parking apron and development a
1985		Provincial	Development area expansion
1984		Provincial	Development area, VASIS installation
1983		Provincial	Fencing, clearing and VASIS materials
1978		Provincial	Final paving, lighting, Maintenance Garagand Air Terminal Building
1977		Provincial	Completion of base preparation
1976		Provincial	Initial grading, base and air tanker base development

### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY ASSESSMENT OF FACILITIES

### AIRPORT INFORMATION REPORT - 2002 ZAMA AIRPORT (CEX5)





Zama Airport Aerial Photographs taken August 21, 2002

#### **Airport Contact Information:**

Municipal District #23 Zama, AB T0H 4E0 Tel: (780) 683 2378 Fax: (780) 683 2450

Prepared for:



Aviation Strategy Action Group 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955 Fax: 780-413-9918

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared by:



Pryde Schropp McComb, Inc. 204-17707 105 Avenue Edmonton, AB T5S 1T1

Tel: 780-444-1133 Fax: 780-484-0877

General Info	
	e From Community (mile): e: 59.1500°, Longitude: -118.7000°
Owner and Operator Info Owner: Operator: Former Ownership: Date of Change:	Contact Info  Municipal District #23  Box 11  Zama  T0H 4E0  (780) 683 2378(780) , Fax: 683 2450
Airport Organization Ownership Structure:	
Organizational Structure:	Primary: "16-34", 2460x100 (Oiled Gravel) Poor condition;
Role of Airport:	Secondary:
Taxiway Data Primary:	Apron Data
Secondary:	Primary:
Third:	Secondary:
Fourth:	
	Building Data
Landside Facility Data	ATB:
Entrance Road:	Disability Access:
Parking Lot:	
Fencing:	Field Electrical Centre:

Lighting Data	─Water / Sewer Data
Primary Edgelighting:	Water Supply:
Approach Slope Indicator 1:	Sewage:
Approach Slope Indicator 2:	Vicinity Protection, Caveat, and Right of Way
ARCAL: Type:	Vicinity Protection: No Caveat: No Right of Way: No
Windsock: 1 windsocks; fair condition;	Right of Way. No
Drainage Data	
Surface:	Subsurface:
Peak Period Info	

Peak Period Info	Spring	Summer	Fall	Winter	Average
Peak Apron Aircraft Parked:					
Design Aircraft for Airport:					





Onsite Business Data						
FBO: No				AC Ma	aintenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintenar	nce Bu	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	dget	1997	1990	1999	2000	
Economic Activity Inforn	nation	-				
Airport Activity Info		1997	1998	1999	2000	2001
Airport Activity Info  Annual Aircraft Movements		1997	1998	1999	2000	2001
	:	1997	1998	1999	2000	2001
Annual Aircraft Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	:	1997		1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info   Airport Revenue Data  Total Annual Revenue:	: s:					
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	: s:					

Year	Project Name	Funding Source	Description	

#### ALBERTA REGIONAL/LOCAL AIRPORT INVENTORY STUDY **ASSESSMENT OF FACILITIES**

### **AIRPORT INFORMATION REPORT - 2002 ZAMA LAKE AIRPORT (CFT9)**





Zama Lake Airport Aerial Photographs taken August 21, 2002

#### **Airport Contact Information:**

Ms. Wendy Woolf Apache Zama, AB T0H 4E0 Tel: (780) 683 8000 Fax: (780) 683 2251

> Revision No. 3 February 18, 2003 Project No. 11451

Prepared for:



**Aviation Strategy Action Group** 11810 Kingsway Avenue Edmonton, AB T5G 0X5 Tel: 780-452-9955

Fax: 780-413-9918



Prepared by:

Pryde Schropp McComb, Inc. 204-17707 105 Avenue

Edmonton, AB T5S 1T1 Tel: 780-444-1133

Fax: 780-484-0877

General Info Zama Lake (FT9)	Distance From Community (mile): Latitude: 59.0667°, Longitude: -118.8833°
Owner and Operator Info Owner: Apache Canada Operator: Same Former Ownership: Date of Change: January 1, 2001  Airport Organization Ownership Structure:	Contact Info  Ms. Wendy Woolf Apache P.O. Box 25 Zama T0H 4E0 (780) 683 8000(780) , Fax: 683 2251
Organizational Structure: Role of Airport:  Taxiway Data Primary:  Secondary:	Primary: "12-30", 4300x50 (Asphalt) Poor condition; replacement 2003 (\$759000)  Secondary:  Apron Data  Primary: "1"; poor condition; replacement 2003 (\$65000)  Secondary:
Fourth:  Landside Facility Data  Entrance Road:	Building Data  ATB:  Disability Access:
Parking Lot: Fencing:	Field Electrical Centre:

Lighting Data		┌Water / Sewer Data
Primary Edgelighting: T (Thr fair co	reshold (Green)) ndition; replacement 2005 (\$1310)	Water Supply:
Approach Slope Indicator 1:		Sewage:
Approach Slope Indicator 2:		Vicinity Protection, Caveat, and Right of Way
ARCAL: Type: Windsock: 1 windsocks; good condition	on; replacement 6	Vicinity Protection: No Caveat: No Right of Way: No
Drainage Data		
Surface:	Subsurfa	ace:
Peak Period Info	Spring Summer Fall W	/inter Average
Peak Apron Aircraft Parked:		
Design Aircraft for Airport:		





Onsite Business Data						
FBO: No				AC Ma	aintenance:	No
Industrial Buildings: No				Crop S	Spraying Ac	tivities:
Hangars: No				Chemic	cals Stored	on site:
Operation and Maintenar	nce Bu	1997	1998	1999	2000	2001
Total Annual Maintenance Bu	dget	1997	1990	1999	2000	
Economic Activity Inforn	nation	-				
Airport Activity Info		1997	1998	1999	2000	2001
Airport Activity Info  Annual Aircraft Movements		1997	1998	1999	2000	2001
	:	1997	1998	1999	2000	2001
Annual Aircraft Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements	:	1997	1998	1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	:	1997		1999	2000	2001
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info   Airport Revenue Data  Total Annual Revenue:	: s:					
Annual Aircraft Movements Annual Passenger Movements  Commercial Airline Info  Airport Revenue Data	: s:					

Year	Project Name	Funding Source	Description	